OWNER:	OUTPOST INTERNATIONAL LLC	OPERATOR:	OUTPOST INTERNATIONAL LLC
ADDRESS:	ATTN: N416BD NASHUA NH 03063	ADDRESS:	C/O JIM BROWN WOLFEBORO NH 03894
OFFICE:		OFFICE:	
FAX:		FAX:	

ANALYST:	LUIS MEIRA	514-636-2020 (OFFICE)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL:	LMEIRA@CAMPSYSTEMS.COM	514-636-7866 (FAX) WWW.CAMPSYSTEMS.COM	631-980-4222 (EFAX-CARDS)	

AIRCRAFT

SERIAL/REGNO: 9375/N416BD MODEL: GLOBAL EXPRESS XRS MANUFACTURER: BOMBARDIER AVIATION

CERTIFICATION DATE: 20-DEC-2009

LAST ACTUALS:

4101.3	A/C HRS	as of 02-FEB-2024
1225	AFL	as of 02-FEB-2024

APU

SERIAL/PART: P-503/WE3800714-1 MODEL: RE220 (GX) MANUFACTURER: HONEYWELL

INSTALLED ON: 20-DEC-2009

0	APU HRS	0 A/C HRS
0	APUS	

LAST ACTUALS:

2651	APU HRS	as of 19-MAR-2021
2348	APUS	as of 19-MAR-2021

ENGINE NO. 1

SERIAL/PART: 12843/BR710 MODEL: BR700-710A2-20 (CIMMS) MANUFACTURER: ROLLS-ROYCE DERBY PLC

INSTALLED ON: 20-DEC-2009

0	ENG. HRS	0 A/C HRS
0	ENC	

LAST ACTUALS:

4101.3	ENG. HRS	as of 02-FEB-2024
1228	ENC	as of 02-FEB-2024

ENGINE NO. 2

SERIAL/PART: 12844/BR710 MODEL: BR700-710A2-20 (CIMMS) MANUFACTURER: ROLLS-ROYCE DERBY PLC

INSTALLED ON: 20-DEC-2009

0	ENG. HRS	0 A/C HRS
0	ENC	

LAST ACTUALS:

4101.3	ENG. HRS	as of 02-FEB-2024
1228	ENC	as of 02-FEB-2024

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA GENERAL										
AD 1998-467 REV 4[U]	NO. 1 ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION								AD	ATA:--
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
AD 1998-467 REV 4[U]	NO. 2 ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION								AD	ATA:--
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
AD 2000-257 REV 2[U]	NO. 1 ENGINE - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431								AD	ATA:--
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
AD 2000-257 REV 2[U]	NO. 2 ENGINE - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431								AD	ATA:--
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
AD 2004-494[U]	NO. 1 ENGINE - REDUCTION OF LIFE LIMITATION FOR THE HIGH PRESSURE COMPRESSOR (HPC) FRONT DRUM TO AN INADVERTENT HEAT TREATMENT.								AD	ATA:--
	MOS/MSC	-	08-Jun-09						176.1	
	HRS									
	ENC									
AD 2004-494[U]	NO. 2 ENGINE - REDUCTION OF LIFE LIMITATION FOR THE HIGH PRESSURE COMPRESSOR (HPC) FRONT DRUM TO AN INADVERTENT HEAT TREATMENT.								AD	ATA:--
	MOS/MSC	-	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	
EASA 2007-0156[U]	COMMUNICATION - COMM UNITS & TRANSPONDERS - MODIFICATION / REPLACEMENT								AD	ATA:--
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
FAA 2009-21-10 R1[U]	INSPECT FOR AFFECTED P/N & S/N OF AVOX & BE AEROSPACE 02 BOTTLES								AD	ATA:--
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA GENERAL										
FAA 2010-01-03[U]	FIRE FIGHTING ENTERPRISES LIMITED PORTABLE HALON 1211 FIRE EXTINGUISHERS AS INSTALLED ON VARIOUS TRANSPORT AIRPLANES, SMALL AIRPLANES, AND ROTORCRAFT								AD	ATA:--
	DAYS/MSC	-	14-Feb-11						4745 d	
	HRS		7.4						4093.9	
	AFL		4						1221	
FAA 2010-04-16[U]	SICLI HALON 1211 PORTABLE FIRE EXTINGUISHERS AS INSTALLED ON VARIOUS AIRPLANES AND ROTORCRAFT								AD	ATA:--
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
LBA D-2008-222 REV 1[U]	NO. 1 ENGINE - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL								AD	ATA:--
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
LBA D-2008-222 REV 1[U]	NO. 2 ENGINE - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL								AD	ATA:--
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
TCCA CF-2011-03[U]	SECURITY CONCERNS WITH THE CHEMICAL OXYGEN GENERATORS INSTALLED IN THE LAVATORIES								AD	ATA:--
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
ATA 00 - INFORMATION										
112219-MRIP-MRBR	REVIEW AIRCRAFT ANNUAL UTILIZATION (HOURS) FOR PROGRAM SELECTION (MRIP OR MRBR) PER TLMC AND MPD REV 17								Service	ATA:00
	MOS/MSC	-	04-Feb-20						48.2	
	HRS									
	AFL									
				PROC. REF: RCF 00						
AC76-160609	APU - REVIEW RE220 (GX) CMM REV 6								Service	ATA:00
	MOS/MSC	-	28-Sep-16						88.5	
	HRS									
	APUS									
				PROC. REF: RCF AC76						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 00 - INFORMATION									
CAMP CODE CHANGE - NOTIFICATION LETTER-NAR	REVIEW AND ACKNOWLEDGE THIS NOTIFICATION LETTER AND RETURNING IT TO CAMP (NO APPROVAL REQ. OPERATORS)								Service ATA:00
	MOS/MSC	-							
	HRS								
	AFL								
				PROC. REF: RCF 00					
EC76-160515	NO. 1 ENGINE - REVIEW BR700-710A2-20 TLM REV 54								Service ATA:00
	MOS/MSC	-							
	HRS								
	ENC								
				PROC. REF: RCF EC76					
EC76-160515	NO. 2 ENGINE - REVIEW BR700-710A2-20 TLM REV 54								Service ATA:00
	MOS/MSC	-							
	HRS								
	ENC								
				PROC. REF: RCF EC76					
EC76-220707	NO. 1 ENGINE - REVIEW BR700-710A2-20 EMM REV 70								Service ATA:00
	MOS/MSC	-	EFF						
	HRS								
	ENC								
				PROC. REF: RCF EC76					
EC76-220707	NO. 2 ENGINE - REVIEW BR700-710A2-20 EMM REV 70								Service ATA:00
	MOS/MSC	-	EFF						
	HRS								
	ENC								
				PROC. REF: RCF EC76					
GXRS-160729	REVIEW BOMBARDIER GLOBAL EXPRESS XRS - TLMC REV. 14, DATED JULY 29/2016								Service ATA:00
	MOS/MSC	-	EFF						
	HRS								
	AFL								
				PROC. REF: RCF 00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 00 - INFORMATION										
GXRS-160729 (MPD)	REVIEW BOMBARDIER GLOBAL EXPRESS XRS - MPD REV. 14, DATED JULY 29/2016								Service	ATA:00
	MOS/MSC	-	EFF							
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-171113	REVIEW TLMC BD-700-1A10 TIME LIMITS/MAINTENANCE CHECKS REV 15								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-171206-TR-5-2-11	REVIEW TLMC _TEMPORARY REVISION NO. 5-2-11 DATED DEC 06/2017								Service	ATA:00
	MOS/MSC	-	20-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: RCF 00						
GXRS-180503-MPD[S]	REVIEW BOMBARDIER GLOBAL EXPRESS XRS - MPD REV. 16, DATED MAY 03/2018								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-180503-TLMC	REVIEW BOMBARDIER GLOBAL EXPRESS XRS TLMC REV 16 DATED MAY 03/2018								Service	ATA:00
	MOS/MSC	-	20-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: RCF 00						
GXRS-180504-TR5-2-12	REVIEW BOMBARDIER GLOBAL EXPRESS XRS TR5-2-12 DATED MAY 04/2018								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-191122 (MPD)	REVIEW GLOBAL EXPRESS XRS MPD REV 17 DATED NOV 22 2019								Service	ATA:00
	MOS/MSC	-	20-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: RCF GXRS						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 00 - INFORMATION										
GXRS-191122 (TLMC)	REVIEW TIME LIMITS / MAINTENANCE CHECKS - GLOBAL EXPRESS XRS (TLMC), REVISION 17, DATED NOV. 22ND, 2019								Service	ATA:00
	MOS/MSC	-	04-Feb-20						48.2	
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-200817-MPD	REVIEW BOMBARDIER GLOBAL EXPRESS XRS - MPD REV. 18, DATED AUG 17/2020								Service	ATA:00
	MOS/MSC	-	EFF							
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-200817-TLMC	REVIEW BOMBARDIER GLOBAL EXPRESS XRS - TLMC REV. 18, DATED AUG 17/2020								Service	ATA:00
	MOS/MSC	-	EFF							
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-200911-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM FOR TLMC REV 18 AND MPD REV 18, DATED AUG 17/2020								Service	ATA:00
	MOS/MSC	-	20-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: RCF 00						
GXRS-201209-TR	REVIEW BOMBARDIER GLOBAL EXPRESS XRS TLMC TR 5-2-13 DATED 09 DEC. 2020								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-210519-MPD	REVIEW GLOBAL XRS MAINTENANCE PLANNING DOCUMENT (MPD) REVISION 19 DATED MAY 19, 2021								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF 00						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 00 - INFORMATION										
GXRS-210519-TLMC	GLOBAL XRS TIME LIMITS/MAINTENANCE CHECKS (TLMC) REVISION 19 DATED MAY 19, 2021								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF 00						
GXRS-220817	REVIEW GLOBAL EXPRESS XRS TIME LIMITS/MAINTENANCE CHECKS TR 5-2-14 AND MAINTENANCE PLANNING DOCUMENT TR-83 DATED AUG 17, 2022								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF OO						
GXRS-230331-TRS	REVIEW GLOBAL EXPRESS XRS TIME LIMITS/MAINTENANCE CHECKS (TLMC) TR 5-2-15 AND MAINTENANCE PLANNING DOCUMENT (MPD) TR-84 DATED MAR 31, 2023								Service	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
				PROC. REF: RCF -						
SB 700-00-002 REV 05	SERVICE BULLETIN DESCRIPTION AND POLICY, SERVICE BULLETIN								Bulletin	ATA:00
	MOS/MSC	-								
	HRS									
	AFL									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-00-03-870-003	NO. 1 ENGINE - NO. 1 LP COMPRESSOR ROTOR BLADE								Component	ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7	
SN:RGE57792	HRS		0	TSN 0					4101.3	
WC#: 72.225	ENC	10000	0	TSN 0	(10000) 9997		8772		1228	
05-00-03-870-003	NO. 1 ENGINE - NO. 10 LP COMPRESSOR ROTOR BLADE								Component	ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7	
SN:RGE57915	HRS		0	TSN 0					4101.3	
WC#: 72.270	ENC	10000	0	TSN 0	(10000) 9997		8772		1228	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 11 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57783	HRS		0	TSN 0					4101.3
WC#: 72.275	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 12 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE58003	HRS		0	TSN 0					4101.3
WC#: 72.280	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 13 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57989	HRS		0	TSN 0					4101.3
WC#: 72.285	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 14 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57947	HRS		0	TSN 0					4101.3
WC#: 72.290	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 15 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57793	HRS		0	TSN 0					4101.3
WC#: 72.295	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 16 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57823	HRS		0	TSN 0					4101.3
WC#: 72.300	ENC	10000	0	TSN 0	(10000) 9997		8772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 17 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57812	HRS		0	TSN 0					4101.3
WC#: 72.305	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 18 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57971	HRS		0	TSN 0					4101.3
WC#: 72.310	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 19 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57809	HRS		0	TSN 0					4101.3
WC#: 72.315	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 2 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57808	HRS		0	TSN 0					4101.3
WC#: 72.230	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 20 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57942	HRS		0	TSN 0					4101.3
WC#: 72.320	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 21 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57962	HRS		0	TSN 0					4101.3
WC#: 72.325	ENC	10000	0	TSN 0	(10000) 9997		8772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 22 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57776	HRS		0	TSN 0					4101.3
WC#: 72.330	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 23 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57801	HRS		0	TSN 0					4101.3
WC#: 72.335	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 24 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57972	HRS		0	TSN 0					4101.3
WC#: 72.340	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 3 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57863	HRS		0	TSN 0					4101.3
WC#: 72.235	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 4 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57791	HRS		0	TSN 0					4101.3
WC#: 72.240	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 5 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57860	HRS		0	TSN 0					4101.3
WC#: 72.245	ENC	10000	0	TSN 0	(10000) 9997		8772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 1 ENGINE - NO. 6 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57880	HRS		0	TSN 0					4101.3
WC#: 72.250	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 7 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57779	HRS		0	TSN 0					4101.3
WC#: 72.255	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 8 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57898	HRS		0	TSN 0					4101.3
WC#: 72.260	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 1 ENGINE - NO. 9 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57769	HRS		0	TSN 0					4101.3
WC#: 72.265	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 1 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57923	HRS		0	TSN 0					4101.3
WC#: 72.225	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 10 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57952	HRS		0	TSN 0					4101.3
WC#: 72.270	ENC	10000	0	TSN 0	(10000) 9997		8772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 11 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57906	HRS		0	TSN 0					4101.3
WC#: 72.275	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 12 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE58168	HRS		0	TSN 0					4101.3
WC#: 72.280	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 13 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE58016	HRS		0	TSN 0					4101.3
WC#: 72.285	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 14 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE58146	HRS		0	TSN 0					4101.3
WC#: 72.290	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 15 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57676	HRS		0	TSN 0					4101.3
WC#: 72.295	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 16 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57886	HRS		0	TSN 0					4101.3
WC#: 72.300	ENC	10000	0	TSN 0	(10000) 9997		8772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 17 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57998	HRS		0	TSN 0					4101.3
WC#: 72.305	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 18 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57978	HRS		0	TSN 0					4101.3
WC#: 72.310	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 19 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57861	HRS		0	TSN 0					4101.3
WC#: 72.315	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 2 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57896	HRS		0	TSN 0					4101.3
WC#: 72.230	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 20 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57501	HRS		0	TSN 0					4101.3
WC#: 72.320	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 21 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57407	HRS		0	TSN 0					4101.3
WC#: 72.325	ENC	10000	0	TSN 0	(10000) 9997		8772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 22 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57936	HRS		0	TSN 0					4101.3
WC#: 72.330	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 23 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57366	HRS		0	TSN 0					4101.3
WC#: 72.335	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 24 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57931	HRS		0	TSN 0					4101.3
WC#: 72.340	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 3 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57590	HRS		0	TSN 0					4101.3
WC#: 72.235	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 4 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE58150	HRS		0	TSN 0					4101.3
WC#: 72.240	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 5 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57990	HRS		0	TSN 0					4101.3
WC#: 72.245	ENC	10000	0	TSN 0	(10000) 9997		8772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-003	NO. 2 ENGINE - NO. 6 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57961	HRS		0	TSN 0					4101.3
WC#: 72.250	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 7 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE57859	HRS		0	TSN 0					4101.3
WC#: 72.255	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 8 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE58147	HRS		0	TSN 0					4101.3
WC#: 72.260	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-003	NO. 2 ENGINE - NO. 9 LP COMPRESSOR ROTOR BLADE								Component ATA:05
PN:FW33513	MOS		20-Dec-09	TSN 0				20-Aug-2060	169.7
SN:RGE56011	HRS		0	TSN 0					4101.3
WC#: 72.265	ENC	10000	0	TSN 0	(10000) 9997		8772		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 1 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81845	HRS		0	TSN 0					4101.3
WC#: 72.100	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 10 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85652	HRS		0	TSN 0					4101.3
WC#: 72.145	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 1 ENGINE - NO. 11 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85661	HRS		0	TSN 0					4101.3
WC#: 72.150	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 12 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85665	HRS		0	TSN 0					4101.3
WC#: 72.155	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 13 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85668	HRS		0	TSN 0					4101.3
WC#: 72.160	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 14 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85669	HRS		0	TSN 0					4101.3
WC#: 72.165	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 15 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HALH85674	HRS		0	TSN 0					4101.3
WC#: 72.170	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 16 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85677	HRS		0	TSN 0					4101.3
WC#: 72.175	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 1 ENGINE - NO. 17 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85684	HRS		0	TSN 0					4101.3
WC#: 72.180	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 18 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85687	HRS		0	TSN 0					4101.3
WC#: 72.185	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 19 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85689	HRS		0	TSN 0					4101.3
WC#: 72.190	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 2 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81847	HRS		0	TSN 0					4101.3
WC#: 72.105	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 20 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85697	HRS		0	TSN 0					4101.3
WC#: 72.195	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 21 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85699	HRS		0	TSN 0					4101.3
WC#: 72.200	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 1 ENGINE - NO. 22 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85701	HRS		0	TSN 0					4101.3
WC#: 72.205	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 23 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85702	HRS		0	TSN 0					4101.3
WC#: 72.210	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 24 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85705	HRS		0	TSN 0					4101.3
WC#: 72.215	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 3 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81896	HRS		0	TSN 0					4101.3
WC#: 72.110	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 4 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85622	HRS		0	TSN 0					4101.3
WC#: 72.115	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 5 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85625	HRS		0	TSN 0					4101.3
WC#: 72.120	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 1 ENGINE - NO. 6 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85628	HRS		0	TSN 0					4101.3
WC#: 72.125	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 7 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85640	HRS		0	TSN 0					4101.3
WC#: 72.130	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 8 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85643	HRS		0	TSN 0					4101.3
WC#: 72.135	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 1 ENGINE - NO. 9 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85649	HRS		0	TSN 0					4101.3
WC#: 72.140	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 1 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81837	HRS		0	TSN 0					4101.3
WC#: 72.100	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 10 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81851	HRS		0	TSN 0					4101.3
WC#: 72.145	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 2 ENGINE - NO. 11 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81852	HRS		0	TSN 0					4101.3
WC#: 72.150	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 12 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81853	HRS		0	TSN 0					4101.3
WC#: 72.155	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 13 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS		08-Jun-18	TSN 2				27-Mar-2063	68.1
SN:200027LRE43571	HRS		2892.3	TSN 0					1209
WC#: 72.160	ENC	9700	924	TSN 0	(10624) 10621		9396		304
05-00-03-870-004	NO. 2 ENGINE - NO. 14 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS		11-Jun-18	TSN 0				27-Mar-2063	68
SN:200027LRE44052	HRS		2892.3	TSN 0					1209
WC#: 72.165	ENC	9700	924	TSN 0	(10624) 10621		9396		304
05-00-03-870-004	NO. 2 ENGINE - NO. 15 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81860	HRS		0	TSN 0					4101.3
WC#: 72.170	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 16 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81895	HRS		0	TSN 0					4101.3
WC#: 72.175	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 2 ENGINE - NO. 17 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81898	HRS		0	TSN 0					4101.3
WC#: 72.180	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 18 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81899	HRS		0	TSN 0					4101.3
WC#: 72.185	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 19 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81901	HRS		0	TSN 0					4101.3
WC#: 72.190	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 2 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81838	HRS		0	TSN 0					4101.3
WC#: 72.105	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 20 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81902	HRS		0	TSN 0					4101.3
WC#: 72.195	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 21 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81906	HRS		0	TSN 0					4101.3
WC#: 72.200	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 2 ENGINE - NO. 22 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81908	HRS		0	TSN 0					4101.3
WC#: 72.205	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 23 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH85629	HRS		0	TSN 0					4101.3
WC#: 72.210	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 24 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH58680	HRS		0	TSN 0					4101.3
WC#: 72.215	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 3 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81840	HRS		0	TSN 0					4101.3
WC#: 72.110	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 4 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81841	HRS		0	TSN 0					4101.3
WC#: 72.115	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 5 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81842	HRS		0	TSN 0					4101.3
WC#: 72.120	ENC	6300	0	TSN 0	(6300) 6297		5072		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-004	NO. 2 ENGINE - NO. 6 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81844	HRS		0	TSN 0					4101.3
WC#: 72.125	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 7 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:BRR22626	MOS		20-Dec-09	TSN 0				25-Mar-2045	169.7
SN:HLAH81846	HRS		0	TSN 0					4101.3
WC#: 72.130	ENC	6300	0	TSN 0	(6300) 6297		5072		1228
05-00-03-870-004	NO. 2 ENGINE - NO. 8 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS		11-Jun-18	TSN 0				27-Mar-2063	68
SN:200027LRE44512	HRS		2892.3	TSN 0					1209
WC#: 72.135	ENC	9700	924	TSN 0	(10624) 10621		9396		304
05-00-03-870-004	NO. 2 ENGINE - NO. 9 LP COMPRESSOR ANNULUS FILLER								Component ATA:05
PN:FW77117	MOS		08-Jun-18	TSN 2				27-Mar-2063	68.1
SN:200027LRE43523	HRS		2892.3	TSN 0					1209
WC#: 72.140	ENC	9700	924	TSN 0	(10624) 10621		9396		304
05-00-03-870-005	NO. 1 ENGINE - INTERMEDIATE CASE								Component ATA:05
PN:BRR22752	MOS		20-Dec-09	TSN 0				12-Apr-2102	169.7
SN:01602	HRS		0	TSN 0					4101.3
WC#: 72.350	ENC	20000	0	TSN 0	(20000) 19997	20000	18772		1228
05-00-03-870-005	NO. 2 ENGINE - INTERMEDIATE CASE								Component ATA:05
PN:BRR22752	MOS		20-Dec-09	TSN 0				12-Apr-2102	169.7
SN:01601	HRS		0	TSN 0					4101.3
WC#: 72.350	ENC	20000	0	TSN 0	(20000) 19997	20000	18772		1228
05-00-03-870-006	NO. 1 ENGINE - REAR BEARING SUPPORT STRUCTURE								Component ATA:05
PN:BRR23504	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:01641	HRS		0	TSN 0					4101.3
WC#: 72.355	ENC		0	TSN 0					1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-00-03-870-006	NO. 2 ENGINE - REAR BEARING SUPPORT STRUCTURE								Component ATA:05
PN:BRR23504	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:01588	HRS		0	TSN 0					4101.3
WC#: 72.355	ENC		0	TSN 0					1228
05-00-03-870-007	NO. 1 ENGINE - NO. 4 STUB SHAFT								Component ATA:05
PN:BRR24547	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1049	HRS		0	TSN 0					4101.3
WC#: 72.465	ENC		0	TSN 0					1228
05-00-03-870-007	NO. 2 ENGINE - NO. 4 STUB SHAFT								Component ATA:05
PN:BRR24545	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:916	HRS		0	TSN 0					4101.3
WC#: 72.465	ENC		0	TSN 0					1228
05-00-04-870-001	NO. 1 ENGINE - NOSE CONE FAIRING								Component ATA:05
PN:KH96766	MOS/MSC	O/C	24-Jan-24	TSN 0					.6
SN:20833531632393	HRS		4100.9	TSN 0					.4
WC#: 72.420	ENC		1227	TSN 0					1
05-00-04-870-001	NO. 2 ENGINE - NOSE CONE FAIRING								Component ATA:05
PN:BRR24368	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:BA82257	HRS		0	TSN 0					4101.3
WC#: 72.420	ENC		0	TSN 0					1228
05-00-04-870-002	NO. 1 ENGINE - NO. 1 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.430	ENC		0	TSN 0					1228
05-00-04-870-002	NO. 1 ENGINE - NO. 2 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.435	ENC		0	TSN 0					1228
05-00-04-870-002	NO. 1 ENGINE - NO. 3 STAGE 4 AIR PIPE								Component ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.440	ENC		0	TSN 0					1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-00-04-870-002	NO. 1 ENGINE - NO. 4 STAGE 4 AIR PIPE								Component	ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.445	ENC		0	TSN 0					1228	
05-00-04-870-002	NO. 2 ENGINE - NO. 1 STAGE 4 AIR PIPE								Component	ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.430	ENC		0	TSN 0					1228	
05-00-04-870-002	NO. 2 ENGINE - NO. 2 STAGE 4 AIR PIPE								Component	ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.435	ENC		0	TSN 0					1228	
05-00-04-870-002	NO. 2 ENGINE - NO. 3 STAGE 4 AIR PIPE								Component	ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.440	ENC		0	TSN 0					1228	
05-00-04-870-002	NO. 2 ENGINE - NO. 4 STAGE 4 AIR PIPE								Component	ATA:05
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.445	ENC		0	TSN 0					1228	
05-000-1000H	1000 HOUR CHECK								Package	ATA:05
	MOS		27-Dec-23					19-Jan-2026	1.5	
	HRS	1000 (+50/-50)	4099.1	Adj 50	5149.1	5199.1	1047.8 (+50)		2.2	
	AFL		1223						2	
				PROC. REF: MPD SECTION 2.1.1						PKG:4
05-000-1500H	1500 HOUR CHECK								Package	ATA:05
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500 (+50/-50)	3474.7	Adj 50	5024.7	5074.7	923.4 (+50)		626.6	
	AFL		1069						156	
				PROC. REF: MPD SECTION 2.1.1						PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-000-2250H	2250 HOUR CHECK - (2000 HOUR MPD INTERVAL)								Package	ATA:05
	MOS		19-Mar-21					30-Sep-2026	34.7	
	HRS	2000 (+50/-50)	3474.7	Adj 50	5524.7	5574.7	1423.4 (+50)		626.6	
	AFL		1069						156	
				PROC. REF: MPD SECTION 2.1.1						PKG:6
05-000-250H[U]	250 HOUR CHECK								Package	ATA:05
	MOS		28-Nov-23					27-Jul-2024	2.5	
	HRS	250 (+25/-25)	4099.1		4349.1	4374.1	247.8 (+25)		2.2	
	AFL		1223						2	
										PKG:63
05-000-3000H	3000 HOUR CHECK								Package	ATA:05
	MOS		11-Jul-18					09-Jul-2027	67	
	HRS	3000 (+50/-50)	2892.3	Adj 50	5942.3	5992.3	1841 (+50)		1209	
	AFL		921						304	
				PROC. REF: MPD SECTION 2.1.1						PKG:8
05-000-4500H	4500 HOUR CHECK								Package	ATA:05
	MOS		20-Dec-09					06-Nov-2024	169.7	
	HRS	4500 (+50/-50)	0		4500	4550	398.7 (+50)		4101.3	
	AFL		0						1225	
				PROC. REF: MPD SECTION 2.1.1						PKG:10
05-000-450L	450L CHECK								Package	ATA:05
	MOS		17-Jul-19					29-Mar-2025	54.8	
	HRS		3188.8						912.5	
	AFL	450 (+50/-50)	996	Adj 50	1496	1546	271 (+50)		229	
				PROC. REF: MPD SECTION 2.3.1						PKG:58
05-000-500H	500 HOUR CHECK								Package	ATA:05
	MOS		06-Dec-23					15-Feb-2025	2.2	
	HRS	500 (+50/-50)	4099.1	Adj 50	4649.1	4699.1	547.8 (+50)		2.2	
	AFL		1223						2	
				PROC. REF: MPD SECTION 2.1.1						PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-000-7500L	7500L CHECK								Package	ATA:05
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	7500 (+50/-50)	0		7500	7550	6275 (+50)		1225	
				PROC. REF: GENERIC NO REF, MPD SECTION 2.3.1						PKG:76
05-000-900L	900L CHECK								Package	ATA:05
	MOS		27-Jul-16					17-Dec-2025	90.5	
	HRS		2078.9						2022.4	
	AFL	900 (+50/-50)	719	Adj 50	1669	1719	444 (+50)		506	
				PROC. REF: MPD SECTION 2.3.1						PKG:60
05-001-120M	120 MONTH CHECK								Package	ATA:05
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 91d	30-Jun-31	18-Sep-31	2696 d (+80)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: MPD SECTION 2.2.1						PKG:38
05-001-15M	15 MONTH CHECK								Package	ATA:05
	MOS	15 (+3m/-3m)	29-Dec-23	Adj 92d	30-Jun-25	29-Sep-25	505 d (+91)	30-Jun-2025	1.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: MPD SECTION 2.2.1						PKG:31
05-001-180M	180 MONTH CHECK								Package	ATA:05
	MOS	180 (+3m/-3m)	19-Mar-21	Adj 91d	30-Jun-36	18-Sep-36	4523 d (+80)	30-Jun-2036	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: MPD SECTION 2.2.1						PKG:52
05-001-240M	240 MONTH CHECK								Package	ATA:05
	MOS	T:240 (+3m/-3m)	30-Jun-11		30-Jun-31	30-Sep-31	2696 d (+92)	30-Jun-2031	151.4	
	HRS									
	AFL									
				PROC. REF: MPD SECTION 2.2.1						PKG:56

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-001-30M	30 MONTH CHECK								Package	ATA:05
	MOS	30 (+3m/-3m)	30-Dec-22	Adj 92d	30-Sep-25	31-Dec-25	597 d (+92)	30-Sep-2025	13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
				PROC. REF: MPD SECTION 2.2.1						PKG:32
05-001-60M	60 MONTH CHECK								Package	ATA:05
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 91d	30-Jun-26	18-Sep-26	870 d (+80)	30-Jun-2026	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: MPD SECTION 2.2.1						PKG:34
05-10-01-870-002	NO. 1 ENGINE - LP COMPRESSOR DISK								Component	ATA:05
PN:FW33927	MOS		20-Dec-09	TSN 0				26-Dec-2038	169.7	
SN:STDK53007	HRS		0	TSN 0					4101.3	
WC#: 72.220	ENC	4800	0	TSN 0	(4800) 4797	4800	3572		1228	
05-10-01-870-002	NO. 2 ENGINE - LP COMPRESSOR DISK								Component	ATA:05
PN:FW33927	MOS		20-Dec-09	TSN 0				26-Dec-2038	169.7	
SN:STDK53127	HRS		0	TSN 0					4101.3	
WC#: 72.220	ENC	4800	0	TSN 0	(4800) 4797	4800	3572		1228	
05-10-01-870-003	NO. 1 ENGINE - FAN SHAFT								Component	ATA:05
PN:BRR23914	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7	
SN:CL25957	HRS		0	TSN 0					4101.3	
WC#: 72.345	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228	
05-10-01-870-003	NO. 2 ENGINE - FAN SHAFT								Component	ATA:05
PN:BRR23914	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7	
SN:CL27303	HRS		0	TSN 0					4101.3	
WC#: 72.345	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-10-01-870-004	NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK								Component ATA:05
PN:BRR24382	MOS		20-Dec-09	TSN 0				15-Jun-2081	169.7
SN:2948	HRS		0	TSN 0					4101.3
WC#: 72.405	ENC	15000	0	TSN 0	(15000) 14997	15000	13772		1228
05-10-01-870-004	NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK								Component ATA:05
PN:BRR24382	MOS		20-Dec-09	TSN 0				15-Jun-2081	169.7
SN:2985	HRS		0	TSN 0					4101.3
WC#: 72.405	ENC	15000	0	TSN 0	(15000) 14997	15000	13772		1228
05-10-01-870-005	NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK								Component ATA:05
PN:BRR24357	MOS		20-Dec-09	TSN 0				15-Jun-2081	169.7
SN:3845	HRS		0	TSN 0					4101.3
WC#: 72.410	ENC	15000	0	TSN 0	(15000) 14997	15000	13772		1228
05-10-01-870-005	NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK								Component ATA:05
PN:BRR24357	MOS		20-Dec-09	TSN 0				15-Jun-2081	169.7
SN:3894	HRS		0	TSN 0					4101.3
WC#: 72.410	ENC	15000	0	TSN 0	(15000) 14997	15000	13772		1228
05-10-01-870-006	NO. 1 ENGINE - CURVIC RING								Component ATA:05
PN:BRR20340	MOS		20-Dec-09	TSN 0				15-Jun-2081	169.7
SN:7096	HRS		0	TSN 0					4101.3
WC#: 72.450	ENC	15000	0	TSN 0	(15000) 14997	15000	13772		1228
05-10-01-870-006	NO. 2 ENGINE - CURVIC RING								Component ATA:05
PN:BRH20340	MOS		20-Dec-09	TSN 0				15-Jun-2081	169.7
SN:7102	HRS		0	TSN 0					4101.3
WC#: 72.450	ENC	15000	0	TSN 0	(15000) 14997	15000	13772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-10-01-870-007	NO. 1 ENGINE - HP TURBINE ROTOR STAGE 1 DISK								Component ATA:05
PN:BRR23952	MOS		20-Dec-09	TSN 0				24-Oct-2044	169.7
SN:LDRQA03712	HRS		0	TSN 0					4101.3
WC#: 72.455	ENC	6200	0	TSN 0	(6200) 6197		4972		1228
05-10-01-870-007	NO. 2 ENGINE - HP TURBINE ROTOR STAGE 1 DISK								Component ATA:05
PN:BRR23952	MOS		20-Dec-09	TSN 0				24-Oct-2044	169.7
SN:LDRQA03777	HRS		0	TSN 0					4101.3
WC#: 72.455	ENC	6200	0	TSN 0	(6200) 6197		4972		1228
05-10-01-870-008	NO. 1 ENGINE - HP TURBINE ROTOR STAGE 2 DISK								Component ATA:05
PN:BRR22008	MOS		20-Dec-09	TSN 0				20-Sep-2062	169.7
SN:LDRQA03725	HRS		0	TSN 0					4101.3
WC#: 72.460	ENC	10500	0	TSN 0	(10500) 10497		9272		1228
05-10-01-870-008	NO. 2 ENGINE - HP TURBINE ROTOR STAGE 2 DISK								Component ATA:05
PN:BRR22008	MOS		20-Dec-09	TSN 0				20-Sep-2062	169.7
SN:LDRQA03764	HRS		0	TSN 0					4101.3
WC#: 72.460	ENC	10500	0	TSN 0	(10500) 10497		9272		1228
05-10-01-870-009	NO. 1 ENGINE - LP TURBINE ROTOR STAGE 1 DISK								Component ATA:05
PN:BRR15535	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7
SN:6993	HRS		0	TSN 0					4101.3
WC#: 72.470	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228
05-10-01-870-009	NO. 2 ENGINE - LP TURBINE ROTOR STAGE 1 DISK								Component ATA:05
PN:BRR15535	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7
SN:6911	HRS		0	TSN 0					4101.3
WC#: 72.470	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
05-10-01-870-010	NO. 1 ENGINE - LP TURBINE ROTOR STAGE 2 DISK								Component ATA:05
PN:BRR11896	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7
SN:7004	HRS		0	TSN 0					4101.3
WC#: 72.475	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228
05-10-01-870-010	NO. 2 ENGINE - LP TURBINE ROTOR STAGE 2 DISK								Component ATA:05
PN:BRR11896	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7
SN:6921	HRS		0	TSN 0					4101.3
WC#: 72.475	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228
05-10-01-870-011	NO. 1 ENGINE - LP TURBINE ROTOR SHAFT								Component ATA:05
PN:BRR19612	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7
SN:SBAN1427	HRS		0	TSN 0					4101.3
WC#: 72.485	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228
05-10-01-870-011	NO. 2 ENGINE - LP TURBINE ROTOR SHAFT								Component ATA:05
PN:BRR19612	MOS		20-Dec-09	TSN 0				05-Feb-2123	169.7
SN:SBAN1402	HRS		0	TSN 0					4101.3
WC#: 72.485	ENC	25000	0	TSN 0	(25000) 24997	25000	23772		1228
05-10-05-870-001	NO. 1 ENGINE - FUEL PUMP VESPEL COUPLING								Component ATA:05
PN:39504900	MOS		19-Mar-21	TSN 0				06-Jun-2029	34.7
SN:UNKNOWN	HRS	3500	3474.7	TSN 0	(6974.7) 6974.7		2873.4		626.6
	ENC		1072	TSN 0					156
				PROC. REF: EMM 73-11-01, EMM 73-11-01					
05-10-05-870-001	NO. 2 ENGINE - FUEL PUMP VESPEL COUPLING								Component ATA:05
PN:39504900	MOS		19-Mar-21	TSN 0				06-Jun-2029	34.7
SN:UNKNOWN	HRS	3500	3474.7	TSN 0	(6974.7) 6974.7		2873.4		626.6
	ENC		1072	TSN 0					156
				PROC. REF: EMM 73-11-01, EMM 73-11-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-CUS-001 U	PERFORM MAX POWER TAKE OFF								Service	ATA:05
	MOS		27-May-23					07-May-2024	8.5	
	HRS		3972.5						128.8	
	AFL	100	1182		1282		57		43	
1000APU	APU - 1000 HOURS APU								Package	ATA:05
	MOS		17-Jul-19					28-May-2026	54.8	
	HRS	1000 (+50/-50)	2481.88	Adj 50	3531.88	3581.88	880.9 (+50)		169.12	
	APUS		2157						191	
										PKG:1000
1500APU	APU - 1500 HOUR APU								Package	ATA:05
	MOS		19-Mar-21					23-Feb-2028	34.7	
	HRS	1500 (+50/-50)	2651	Adj 50	4201	4251	1550 (+50)		0	
	APUS		2348						0	
										PKG:1500
750APU	APU - 750 HOUR APU								Package	ATA:05
	MOS		19-Mar-21					12-Mar-2026	34.7	
	HRS	750 (+50/-50)	2651	Adj 50	3451	3501	800 (+50)		0	
	APUS		2348						0	
										PKG:750
BR710-05-10-01-870-002	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK								Service	ATA:05
PN:FW33927	MOS/MSC	-	30-Jun-11						151.4	
SN:STDK53007	HRS		0						4101.3	
WC#: 72.505	ENC		0						1228	
				PROC. REF: EMM 72-31-01						
BR710-05-10-01-870-002	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK								Service	ATA:05
PN:FW33927	MOS/MSC	-	30-Jun-11						151.4	
SN:STDK53127	HRS		0						4101.3	
WC#: 72.505	ENC		0						1228	
				PROC. REF: EMM 72-31-01						
EASA 2022-0033	NO. 1 ENGINE - ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT								AD	ATA:05
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
EASA 2022-0033	NO. 2 ENGINE - ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT								AD	ATA:05
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									
FAA 2022-11-17	FLIGHT CONTROLS - INBOARD-FLAP SUSCEPTIBILITY TO CORROSION								AD	ATA:05
	DAYS/MSC	-	03-Jul-22						588 d	
	HRS		3790.6						310.7	
	AFL		1142						83	
FAA 2023-12-02	TIME LIMITS/MAINTENANCE CHECKS - REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM								AD	ATA:05
	DAYS/MSC	-	01-Aug-23						194 d	
	HRS		4002.9						98.4	
	AFL		1192						33	
ATA 08 - LEVELING AND WEIGHING										
08-CUS-001 U	AIRCRAFT WEIGHT CHECK (WEIGHT AND BALANCE)								Service	ATA:08
	MOS/MSC	O/C	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV										
AW AW000-10-0002 REV 01	PARKING RECOMMENDATIONS DURING THE INTERNATIONAL FLIGHT RESTRICTIONS, ADVISORY WIRE								Bulletin	ATA:10
	MOS/MSC	-	EFF							
	HRS									
	AFL									
ATA 11 - PLACARDS AND MARKINGS										
11-30-50-601 U S	GENERAL VISUAL INSPECTION OF CABIN PLACARDS-INTERNAL								Service	ATA:11
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
ASB A700-11-015	MODIFICATION - FLIGHT COMPARTMENT - ADDITION OF A COCKPIT PLACARD (A/C 9002 TO 9103), ALERT SERVICE BULLETIN								Bulletin	ATA:11
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 11 - PLACARDS AND MARKINGS									
MODSUM IS700-11-000[U] REV B	KIT - IDENTIFICATION PLATE INSTL, FWD DOOR SURROUND, MODIFICATION SUMMARY								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-007	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 95,000 LB (43,092 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-007 REV 01	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 95,000 LB (43,092 KG) (A/C 9002 TO 9158), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-11-008	MODIFICATION - INTERIOR PLACARDS - REPLACEMENT AND REPOSITIONING OF THE HYDRAULIC SYSTEM ACCUMULATOR CHARGING DECALS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	ADMIN							
	HRS								
	AFL								
SB 700-11-009	SPECIAL CHECK/MODIFICATION OF SPECIFIED AFT EQUIPMENT - COMPARTMENT DECALS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-011	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 96,000 LB (43,545 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-11-013	MODIFICATION - DOOR PLACARDS - ADDITION OF "CAUTION" MAINTENANCE PLACARD ON PASSENGER DOOR, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 11 - PLACARDS AND MARKINGS									
SB 700-11-014	MODIFICATION - EXTERIOR PLACARDS AND MARKINGS - INTRODUCTION OF NEW PLACARD PART NO. KGC991-1124-3 FOR THE REFUEL/DEFUEL CONTROL PANEL, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-016	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-016 REV 01	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-016 REV 02	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-016 REV 03	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-016 REV 04	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-016 REV 05	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-017	MODIFICATION - JAPANESE AIRWORTHINESS REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 11 - PLACARDS AND MARKINGS									
SB 700-11-018	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 01	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 02 PART (A)	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-11-018 REV 02 PART (B)	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-11-018 REV 03	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 03 PART (A)	ACCOMPLISH OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 74,955 LB (33,999 KG) MAXIMUM WEIGHT LIMITATION								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 03 PART (B)	ACCOMPLISH OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 75,000 LB (34,019 KG) MAXIMUM WEIGHT LIMITATION								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 11 - PLACARDS AND MARKINGS									
SB 700-11-018 REV 04	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 04 PART (A)	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 74,955 LB (33,999 KG) MAXIMUM WEIGHT LIMITATION								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 04 PART (B)	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 75,000 LB (34,019 KG) MAXIMUM WEIGHT LIMITATION								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 05	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 05 PART A	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 74,955 LB (33,999 KG) MAXIMUM WEIGHT LIMITATION								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-018 REV 05 PART B	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 75,000 LB (34,019 KG) MAXIMUM WEIGHT LIMITATION								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-020	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 99,500 LBS (CONTROLLED EFFECTIVITY), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 11 - PLACARDS AND MARKINGS									
SB 700-11-020 REV 01	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 99,500 LBS (CONTROLLED EFFECTIVITY), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-11-021	MODIFICATION - EXTERIOR PLACARDS AND MARKINGS - REPLACEMENT OF THE PRESSURE FUELING PLACARD ON THE REFUEL/DEFUEL DOOR AND THE PLACARDS AT THE WING GRAVITY FILLER CAPS (A/C 9002 TO 9205), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-11-023 PART (A)	MODIFICATION - INTERIOR PLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE (A/C 9002 TO 9106, 9108 TO 9122, 9124 TO 9126, 9128, 9129, 9133, 9134, 9136 TO 9139, 9141 TO 9148, 9150, 9151, 9153, 9159, 9162, 9163, 9165, 9167, 9169, 9171, 9173 AND 9179), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-023 PART (B)	MODIFICATION - INTERIOR PLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE (9003 TO 9009, 9012 TO 9015, 9017, 9018, 9021, 9026 TO 9030, 9032, 9033, 9035, 9037, 9038, 9040, 9045, 9047, 9050 TO 9053, 9055, 9057 TO 9062, 9066, 9068 TO 9071, 9074 TO 9076, 9079, 9081, 9083, 9084, 9086, 9088 TO 9090, 9092 TO 9097, 9099 TO 9104, 9109 TO 9122, 9124 TO 9126, 9128, 9129, 9133, 9134, 9136 TO 9139, 9141 TO 9148, 9150, 9151 AND 9153), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-023 REV 01 PART (A)	MODIFICATION - INTERIOR PLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE -INSTALLATION OF THE NO STORAGE PLACARDS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-11-023 REV 01 PART (B)	MODIFICATION - INTERIOR PLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE -INSTALLATION OF THE OVERRIDE PLACARDS (APPLICABLE TO AIRCRAFT WHICH HAVE BURKERT VALVES PART NO. 452808A INSTALLED), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 11 - PLACARDS AND MARKINGS									
SB 700-11-024	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-024 REV 01	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-024 REV 02	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-024 REV 03	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LBS (26,308 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-024 REV 04	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-025	OPERATIONS TO AND FROM AUSTRALIAN AIRPORTS WITH MAXIMUM TAKE-OFF WEIGHT RESTRICTIONS IN EFFECT DURING CURFEW PERIODS, SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-11-026	OPERATION AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS OF 95,000 LB (43, 091 KG), SERVICE BULLETIN								Bulletin ATA:11
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 20 - STANDARD PRACTICES - AIRFRAME										
SB 700-20-002 PART (A)	SPECIAL CHECK/REWORK/ MODIFICATION - WIRING - EXAMINE UNDERFLOOR WIRE HARNESS AT FS265 FOR DAMAGE AND REROUTE, SERVICE BULLETIN								Bulletin	ATA:20
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-20-002 PART (B)	SPECIAL CHECK/REWORK/ MODIFICATION - WIRING - EXAMINE UNDERFLOOR WIRE HARNESS AT FS265 FOR DAMAGE AND REROUTE, SERVICE BULLETIN								Bulletin	ATA:20
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-20-003 PART (A)	SPECIAL CHECK/REWORK - WIRES AND CABLES - REPLACEMENT OF TRANSITION ADAPTERS, SERVICE BULLETIN								Bulletin	ATA:20
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-20-003 PART (B)	SPECIAL CHECK/REWORK - WIRES AND CABLES - REPLACEMENT OF TRANSITION ADAPTERS, SERVICE BULLETIN								Bulletin	ATA:20
	MOS/MSC	-								
	HRS									
	AFL									
ATA 21 - AIR CONDITIONING										
21-21-00-201[S]	OPERATIONAL TEST OF THE RECIRC SWITCH								Service	ATA:21
	MOS		22-Nov-23						2.6	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 21.005	AFL		1223						2	
				PROC. REF: AMM 21 21 00 710 802						PKG:4
21-21-05-900-801-01	LH TRIM DUCT								Component	ATA:21
PN:GG438-2066-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:01166	HRS		0	TSN 0					4101.3	
WC#: 21.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 05 000 801, AMM 21 21 05 400 801						
21-21-05-900-801-02	RH TRIM DUCT								Component	ATA:21
PN:GG438-2066-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:01165	HRS		0	TSN 0					4101.3	
WC#: 21.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 05 000 801, AMM 21 21 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-21-05-900-801-03	CENTER TRIM DUCT								Component	ATA:21
PN:GG438-2066-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:01161	HRS		0	TSN 0					4101.3	
WC#: 21.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 05 000 801, AMM 21 21 05 400 801						
21-21-05-900-803-01	MIX MANIFOLD								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.080	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 05 000 801, AMM 21 21 05 400 801						
21-21-09-900-801-01	LH (MIX MANIFOLD) TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 09 000 801, AMM 21 21 09 400 801						
21-21-09-900-801-02	RH (MIX MANIFOLD) TEMPERATURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 09 000 801, AMM 21 21 09 400 801						
21-21-17-201[S]	OPERATIONAL TEST OF THE BULKHEAD CHECK VALVES								Service	ATA:21
	MOS		08-Jul-18						67.1	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 21.010	AFL		921						304	
				PROC. REF: AMM 21 21 17 710 801						PKG:8
21-21-17-900-801-01	LH BULKHEAD CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 17 000 801, AMM 21 21 17 400 801						
21-21-17-900-801-02	RH BULKHEAD CHECK VALVE								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 17 000 801, AMM 21 21 17 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-21-21-900-801-01	LH RECIRCULATION FAN								Component	ATA:21
PN:GG433-2030-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0935	HRS		0	TSN 0					4101.3	
WC#: 21.090	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 21 000 801, AMM 21 21 21 400 801						
21-21-21-900-801-02	RH RECIRCULATION FAN								Component	ATA:21
PN:GG433-2030-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0939	HRS		0	TSN 0					4101.3	
WC#: 21.090	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 21 21 000 801, AMM 21 21 21 400 801						
21-21-25-201[S]	DISCARD THE RECIRCULATION FILTERS								Service	ATA:21
	MOS		05-Dec-23						2.2	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 21.015	AFL		1223						2	
				PROC. REF: AMM 21 21 25 961 801						PKG:4
21-21-25-900-801-01	LH RECIRCULATION FILTER								Component	ATA:21
PN:GG431-2031-1	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7	
SN:9087	HRS		3474.7	TSN 0					626.6	
WC#: 21.095	AFL		1069	TSN 0					156	
				PROC. REF: AMM 21 21 25 000 801, AMM 21 21 25 400 801						
21-21-25-900-801-02	RH RECIRCULATION FILTER								Component	ATA:21
PN:GG431-2031-1	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7	
SN:9085	HRS		3474.7	TSN 0					626.6	
WC#: 21.095	AFL		1069	TSN 0					156	
				PROC. REF: AMM 21 21 25 000 801, AMM 21 21 25 400 801						
21-31-00-101	OPERATIONAL TEST OF THE EMERGENCY DEPRESSURIZATION FUNCTION								Service	ATA:21
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500 (+50/-50)	3474.7	Adj 50	5024.7	5074.7	923.4 (+50)		626.6	
WC#: 21.020	AFL		1069						156	
				PROC. REF: AMM 21 31 00 710 803						PKG:5
21-31-00-103	FUNCTIONAL TEST OF THE CABIN-PRESSURE LEAKAGE RATE								Service	ATA:21
	MOS	120 (+3m/-3m)	19-Mar-21	Adj -30d	28-Feb-31	17-May-31	2574 d (+78)	28-Feb-2031	34.7	
	HRS		3474.7						626.6	
WC#: 21.030	AFL		1069						156	
				PROC. REF: AMM 21 31 00 720 804						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-31-00-201[S]	OPERATIONAL TEST OF THE MANUAL MODE								Service	ATA:21
	MOS		19-Mar-21						34.7	
	HRS	2000 (+50/-50)	3474.7						626.6	
WC#: 21.035	AFL		1069						156	
				PROC. REF: AMM 21 31 00 710 802						PKG:6
21-31-00-203[S]	OPERATIONAL TEST OF THE DITCHING FUNCTION								Service	ATA:21
	MOS		06-Jul-18						67.2	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 21.040	AFL		921						304	
				PROC. REF: AMM 21 31 00 710 804						PKG:8
21-31-01-900-801-01	LH CABIN PRESSURE CONTROLLER								Component	ATA:21
PN:GG546-3001-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0920	HRS		0	TSN 0					4101.3	
WC#: 21.100	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 31 01 000 801, AMM 21 31 01 400 801						
21-31-01-900-801-02	RH CABIN PRESSURE CONTROLLER								Component	ATA:21
PN:GG546-3001-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0918	HRS		0	TSN 0					4101.3	
WC#: 21.100	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 31 01 000 801, AMM 21 31 01 400 801						
21-31-05-900-801-01	FWD OUTFLOW VALVE								Component	ATA:21
PN:GG435-3002-21	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:903	HRS		0	TSN 0					4101.3	
WC#: 21.105	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 31 05 000 801, AMM 21 31 05 400 801						
21-31-05-900-801-02	AFT OUTFLOW VALVE								Component	ATA:21
PN:GG435-3002-21	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:00930	HRS		0	TSN 0					4101.3	
WC#: 21.105	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 31 05 000 801, AMM 21 31 05 400 801						
21-31-09-101	FUNCTIONAL TEST OF THE SAFETY VALVES								Service	ATA:21
	MOS		19-Mar-21					06-Aug-2028	34.7	
	HRS	3000 (+50/-50)	3474.7	Adj 50	6524.7	6574.7	2423.4 (+50)		626.6	
WC#: 21.045	AFL		1069						156	
				PROC. REF: AMM 21 31 09 720 801						PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-31-09-900-801-01	LH SAFETY VALVE								Component ATA:21
PN:GG435-3006-3	MOS/MSC	O/C	19-Mar-21						34.7
SN:00202	HRS		3474.7						626.6
WC#: 21.110	AFL		1069						156
				PROC. REF: AMM 21 31 09 000 801, AMM 21 31 09 400 801					
21-31-09-900-801-02	RH SAFETY VALVE								Component ATA:21
PN:GG435-3006-3	MOS/MSC	O/C	19-Mar-21						34.7
SN:00426	HRS		3474.7						626.6
WC#: 21.110	AFL		1069						156
				PROC. REF: AMM 21 31 09 000 801, AMM 21 31 09 400 801					
21-31-11-201 S	DISCARD THE SAFETY VALVE FILTERS								Service ATA:21
	MOS		19-Mar-21						34.7
	HRS	3000 (+50/-50)	3474.7						626.6
WC#: 21.050	AFL		1069						156
				PROC. REF: AMM 21 31 11 961 801					PKG:8
21-41-50-601 U S	OPERATIONAL TEST OF THE ENTRY AREA HEAT								Service ATA:21
	MOS	15	22-Nov-23						2.6
	HRS		4099.1						2.2
	AFL		1223						2
									PKG:31
21-51-01-900-801-01	LH VENTURI FLOW SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.130	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 01 000 801, AMM 21 51 01 400 801					
21-51-01-900-801-02	RH VENTURI FLOW SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.130	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 01 000 801, AMM 21 51 01 400 801					
21-51-05-900-801-01	LH BLEED FILTER								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.135	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 05 000 801, AMM 21 51 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-51-05-900-801-02	RH BLEED FILTER								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.135	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 51 05 000 801, AMM 21 51 05 400 801						
21-51-09-201[S]	RESTORATION OF THE LH OZONE CONVERTER								Service	ATA:21
PN:GG431-2001-3	MOS		11-Jul-18						67	
SN:6340	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 21.055	AFL		921						304	
				PROC. REF: AMM 21 51 09 615 801						PKG:8
21-51-09-201[S]	RESTORATION OF THE RH OZONE CONVERTER								Service	ATA:21
PN:GG431-2001-3	MOS		11-Jul-18						67	
SN:6794	HRS	3000 (+50/-50)	2892.3						1209	
	AFL		921						304	
				PROC. REF: AMM 21 51 09 615 801						PKG:8
21-51-09-900-801-01	LH OZONE CONVERTER								Component	ATA:21
PN:GG431-2001-3	MOS/MSC	O/C	12-Jul-18						67	
SN:6340	HRS		2892.3	TSN 5252.5					1209	
WC#: 21.140	AFL		921						304	
				PROC. REF: CMM 21-51-12, AMM 21 51 09 000 801, AMM 21 51 09 400 801						
21-51-09-900-801-02	RH OZONE CONVERTER								Component	ATA:21
PN:GG431-2001-3	MOS/MSC	O/C	12-Jul-18						67	
SN:6794	HRS		2892.3	TSN 2907					1209	
WC#: 21.140	AFL		921						304	
				PROC. REF: CMM 21-51-12, AMM 21 51 09 000 801, AMM 21 51 09 400 801						
21-51-13-900-801-01	LH PACK INLET FLOW SENSOR								Component	ATA:21
PN:GG436-2003-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2408	HRS		0	TSN 0					4101.3	
WC#: 21.145	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 51 13 000 801, AMM 21 51 13 400 801						
21-51-13-900-801-02	RH PACK INLET FLOW SENSOR								Component	ATA:21
PN:GG436-2003-1	MOS/MSC	O/C	03-Nov-11	TSN 0					147.3	
SN:2730	HRS		227.8	TSN 0					3873.5	
WC#: 21.145	AFL		100	TSN 0					1125	
				PROC. REF: AMM 21 51 13 000 801, AMM 21 51 13 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-51-17-900-801-01	LH PACK INLET PRESSURE SENSOR								Component ATA:21
PN:GG436-2004-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2211	HRS		0	TSN 0					4101.3
WC#: 21.150	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 17 000 801, AMM 21 51 17 400 801					
21-51-17-900-801-02	RH PACK INLET PRESSURE SENSOR								Component ATA:21
PN:GG436-2004-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2180	HRS		0	TSN 0					4101.3
WC#: 21.150	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 17 000 801, AMM 21 51 17 400 801					
21-51-21-900-801-01	LH PACK INLET TEMPERATURE (INLET) SENSOR								Component ATA:21
PN:GG436-2005-5	MOS/MSC	O/C	05-Apr-19	TSN 0					58.2
SN:00201	HRS		3082.9	TSN 0					1018.4
	AFL		971	TSN 0					254
				PROC. REF: AMM 21 51 21 000 801, AMM 21 51 21 400 801					
21-51-21-900-801-02	RH PACK INLET TEMPERATURE (INLET) SENSOR								Component ATA:21
PN:GG436-2005-5	MOS/MSC	O/C	17-Jul-19	TSN 0					54.8
SN:00249	HRS		3188.8	TSN 0					912.5
	AFL		996	TSN 0					229
				PROC. REF: AMM 21 51 21 000 801, AMM 21 51 21 400 801					
21-51-25-900-802-01	LH SUPPLY DUCT								Component ATA:21
PN:GG468-4042-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0618	HRS		0	TSN 0					4101.3
WC#: 21.155	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801					
21-51-25-900-802-02	RH SUPPLY DUCT								Component ATA:21
PN:GG468-4042-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0619	HRS		0	TSN 0					4101.3
WC#: 21.155	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801					
21-51-25-900-803-01	LH SUPPLY DUCT ASSY								Component ATA:21
PN:GG468-4043-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0408	HRS		0	TSN 0					4101.3
WC#: 21.160	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-51-25-900-803-02	RH SUPPLY DUCT ASSY								Component	ATA:21
PN:GG468-4056-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0425	HRS		0	TSN 0					4101.3	
WC#: 21.160	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801						
21-51-25-900-804-01	LH SENSE LINE- TUBE ASSY								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.165	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801						
21-51-25-900-805-01	LH FLOW CONTROL VALVE								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.170	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801						
21-51-25-900-805-02	RH FLOW CONTROL VALVE								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.170	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801						
21-52-00-101	OPERATIONAL TEST OF THE MANUAL MODE OF THE AIR CONDITIONING SYSTEM								Service	ATA:21
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500 (+50/-50)	3474.7	Adj 50	5024.7	5074.7	923.4 (+50)		626.6	
WC#: 21.060	AFL		1069						156	
				PROC. REF: AMM 21 52 00 710 802						PKG:5
21-52-01-900-801-01	LH COOLING PACK								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.175	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
21-52-01-900-801-02	RH COOLING PACK								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.175	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-52-01-900-802-01	LH PLENUM								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.180	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 01 000 801, AMM 21 52 01 400 801					
21-52-01-900-802-02	RH PLENUM								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.180	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 01 000 801, AMM 21 52 01 400 801					
21-52-05-900-801-01	LH DUAL HEAT EXCHANGER								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.185	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 05 000 801, AMM 21 52 05 400 801					
21-52-05-900-801-02	RH DUAL HEAT EXCHANGER								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.185	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 05 000 801, AMM 21 52 05 400 801					
21-52-09-900-801-01	LH AIR CYCLE MACHINE ACM								Component ATA:21
PN:GG431-2010-3	MOS/MSC	O/C	13-Oct-19						51.9
SN:00342	HRS		3250.9						850.4
WC#: 21.190	AFL		1020						205
				PROC. REF: AMM 21 52 09 000 801, AMM 21 52 09 400 801					
21-52-09-900-801-02	RH AIR CYCLE MACHINE ACM								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.190	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 09 000 801, AMM 21 52 09 400 801					
21-52-13-900-801-01	LH PACK INLET TEMPERATURE (DISCHARGE) SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 13 000 801, AMM 21 52 13 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-52-13-900-801-02	RH PACK INLET TEMPERATURE (DISCHARGE) SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 13 000 801, AMM 21 52 13 400 801					
21-52-17-900-801-01	LH COMPRESSOR PNEUMATIC OVERHEAT SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.195	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 17 000 801, AMM 21 52 17 400 801					
21-52-17-900-801-02	RH COMPRESSOR PNEUMATIC OVERHEAT SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.195	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 17 000 801, AMM 21 52 17 400 801					
21-52-21-900-801-01	LH REHEATER CONDENSER								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.200	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 21 000 801, AMM 21 52 21 400 801					
21-52-21-900-801-02	RH REHEATER CONDENSER								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.200	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 21 000 801, AMM 21 52 21 400 801					
21-52-25-900-801-01	LH (PACK) TEMPERATURE SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 25 000 801, AMM 21 52 25 400 801					
21-52-25-900-801-02	RH (PACK) TEMPERATURE SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 25 000 801, AMM 21 52 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-52-29-900-801-01	LH WATER EXTRACTOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.205	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 29 000 801, AMM 21 52 29 400 801					
21-52-29-900-801-02	RH WATER EXTRACTOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.205	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 29 000 801, AMM 21 52 29 400 801					
21-52-33-900-801-01	LH TEMPERATURE CONTROL VALVE								Component ATA:21
PN:GG436-2017-5	MOS/MSC	O/C	17-Oct-16	TSR 0					87.8
SN:00337	HRS		2184.4	TSR 0					1916.9
WC#: 21.210	AFL		753	TSR 0					472
				PROC. REF: AMM 21 52 33 000 801, AMM 21 52 33 400 801					
21-52-33-900-801-02	RH TEMPERATURE CONTROL VALVE								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.210	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 33 000 801, AMM 21 52 33 400 801					
21-52-37-900-801-01	LH (PACK DISCHARGE) TEMPERATURE SENSOR								Component ATA:21
PN:GG436-2015-3	MOS/MSC	O/C	03-Oct-16						88.3
SN:18731	HRS		2154.6						1946.7
	AFL		745						480
				PROC. REF: AMM 21 52 37 000 801, AMM 21 52 37 400 801					
21-52-37-900-801-02	RH (PACK DISCHARGE) TEMPERATURE SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 52 37 000 801, AMM 21 52 37 400 801					
21-52-41-900-801-01	LH ANTI-ICING PRESSURE SENSOR								Component ATA:21
PN:GG436-2033-1	MOS/MSC	O/C	17-Oct-16						87.8
SN:10549	HRS		2184.4						1916.9
WC#: 21.215	AFL		753						472
				PROC. REF: AMM 21 52 41 000 801, AMM 21 52 41 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-52-41-900-801-02	RH ANTI-ICING PRESSURE SENSOR								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.215	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 52 41 000 801, AMM 21 52 41 400 801						
21-52-49-900-801-01	LH PACK DISCHARGE DUCT								Component	ATA:21
PN:GG438-2050-9	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7	
SN:1282	HRS		3474.7	TSN 0					626.6	
WC#: 21.220	AFL		1069	TSN 0					156	
				PROC. REF: AMM 21 52 49 000 801, AMM 21 52 49 400 801						
21-52-53-900-801-01	RH PACK DISCHARGE DUCT								Component	ATA:21
PN:GG438-2049-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0486	HRS		0	TSN 0					4101.3	
WC#: 21.220	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 52 53 000 801, AMM 21 52 53 400 801						
21-53-01-900-801-01	LH WATER SPRAYER								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.230	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 53 01 000 801, AMM 21 53 01 400 801						
21-53-01-900-801-02	RH WATER SPRAYER								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.230	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 53 01 000 801, AMM 21 53 01 400 801						
21-53-05-101	OPERATIONAL TEST OF THE RAM AIR VALVE								Service	ATA:21
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500 (+50/-50)	3474.7	Adj 50	5024.7	5074.7	923.4 (+50)		626.6	
WC#: 21.065	AFL		1069						156	
				PROC. REF: AMM 21 53 05 710 801						PKG:5
21-53-05-900-801-01	EMERGENCY RAM AIR VALVE								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.235	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 53 05 000 801, AMM 21 53 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-53-09-900-801-01	LH RAM AIR FLEXIBLE DUCT								Component ATA:21
PN:GG438-2056-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:00216	HRS		0	TSN 0					4101.3
WC#: 21.225	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 53 09 000 801, AMM 21 53 09 400 801					
21-53-09-900-801-02	RH RAM AIR FLEXIBLE DUCT								Component ATA:21
PN:GG438-2056-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:00213	HRS		0	TSN 0					4101.3
WC#: 21.225	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 53 09 000 801, AMM 21 53 09 400 801					
21-53-17-900-801-01	LH MAIN HEAT EXCHANGER DIFFUSER								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.240	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 53 17 000 801, AMM 21 53 17 400 801					
21-53-17-900-801-02	RH MAIN HEAT EXCHANGER DIFFUSER								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.240	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 53 17 000 801, AMM 21 53 17 400 801					
21-53-21-900-801-01	SPLITTER RAM AIR DUCT								Component ATA:21
PN:GG438-2055-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2973	HRS		0	TSN 0					4101.3
WC#: 21.245	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 53 21 000 801, AMM 21 53 21 400 801					
21-53-33-900-801-01	RAM-AIR CHECK VALVE								Component ATA:21
PN:GG436-2068-3	MOS/MSC	O/C	19-Mar-21						34.7
SN:01262	HRS		3474.7						626.6
WC#: 21.065	AFL		1069						156
				PROC. REF: AMM 21 53 33 000 801, AMM 21 53 33 400 801					
21-53-33-900-801-02	RAM-AIR INTAKE								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.250	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 53 33 000 801, AMM 21 53 33 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-54-01-900-802-01	NO. 1 COOLING IRS FAN								Component	ATA:21
PN:26012423-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:9101	HRS		0	TSN 0					4101.3	
WC#: 21.255	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802						
21-54-01-900-802-02	NO. 2 COOLING IRS FAN								Component	ATA:21
PN:26012423-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:9102	HRS		0	TSN 0					4101.3	
WC#: 21.255	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802						
21-54-01-900-802-03	NO. 3 COOLING IRS FAN								Component	ATA:21
PN:26012423-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:9104	HRS		0	TSN 0					4101.3	
WC#: 21.255	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802						
21-54-37-900-801-01	NO. 1 AVIONICS EXHAUST FAN								Component	ATA:21
PN:GG433-2047-1	MOS/MSC	O/C	06-May-22	TSN 0					21.2	
SN:22210012	HRS		3754.2	TSN 0					347.1	
WC#: 21.260	AFL		1133	TSN 0					92	
				PROC. REF: AMM 21 54 37 000 801, AMM 21 54 37 400 801						
21-54-37-900-801-02	NO. 2 AVIONICS EXHAUST FAN								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 21.260	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 54 37 000 801, AMM 21 54 37 400 801						
21-54-41-900-801-01	AVIONICS EXHAUST-FAN CONVERTER								Component	ATA:21
PN:GG433-2051-11	MOS/MSC	O/C	06-May-22	TSN 0					21.2	
SN:21210011	HRS		3754.2	TSN 0					347.1	
WC#: 21.265	AFL		1133	TSN 0					92	
				PROC. REF: AMM 21 54 41 000 801, AMM 21 54 41 400 801						
21-60-00-101	OPERATIONAL TEST OF THE AUXILIARY PRESSURIZATION FUNCTION								Service	ATA:21
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500 (+50/-50)	3474.7	Adj 50	5024.7	5074.7	923.4 (+50)		626.6	
WC#: 21.070	AFL		1069						156	
				PROC. REF: AMM 21 60 00 710 802						PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-60-01-900-801-01	EMERGENCY CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.270	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 01 000 801, AMM 21 60 01 400 801					
21-60-05-900-801-01	LH TRIM AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.275	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 05 000 801, AMM 21 60 05 400 801					
21-60-05-900-801-02	RH TRIM AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.275	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 05 000 801, AMM 21 60 05 400 801					
21-60-09-900-801-01	LH HOT AIR SHUT-OFF VALVE								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.280	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 09 000 801, AMM 21 60 09 400 801					
21-60-09-900-801-02	RH HOT AIR SHUT-OFF VALVE								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 21.280	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 09 000 801, AMM 21 60 09 400 801					
21-60-13-900-801-01	LH TRIM AIR VALVE								Component ATA:21
PN:GG436-2038-7	MOS/MSC	O/C	17-Oct-16						87.8
SN:00883	HRS		2184.4						1916.9
WC#: 21.285	AFL		753						472
				PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801					
21-60-13-900-801-02	RH TRIM AIR VALVE								Component ATA:21
PN:GG436-2038-7	MOS/MSC	O/C	17-Oct-16						87.8
SN:00758	HRS		2184.4						1916.9
WC#: 21.285	AFL		753						472
				PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
21-60-13-900-801-03	CENTER TRIM AIR VALVE								Component ATA:21
PN:GG436-2038-7	MOS/MSC	O/C	17-Oct-16						87.8
SN:00136	HRS		2184.4						1916.9
WC#: 21.285	AFL		753						472
				PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801					
21-60-17-900-801-01	LH (DUCT AFT CABIN) TEMPERATURE SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801					
21-60-17-900-801-02	RH (DUCT FWD CABIN) TEMPERATURE SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801					
21-60-17-900-801-03	CENTER (DUCT FLT COMPARTMENT) TEMPERATURE SENSOR								Component ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801					
21-60-21-900-801-01	LH AIR CONDITIONING SYSTEM CONTROLLER								Component ATA:21
PN:GG546-2040-15	MOS/MSC	O/C	06-May-22	TSR 37					21.2
SN:00881	HRS		3754.2	TSR 671.3					347.1
WC#: 21.290	AFL		1133	TSR 162					92
				PROC. REF: AMM 21 60 21 000 801, AMM 21 60 21 400 801					
21-60-21-900-801-02	RH AIR CONDITIONING SYSTEM CONTROLLER								Component ATA:21
PN:GG546-2040-15	MOS/MSC	O/C	06-May-22	TSR 37					21.2
SN:01473	HRS		3754.2	TSR 671.3					347.1
WC#: 21.290	AFL		1133	TSR 162					92
				PROC. REF: AMM 21 60 21 000 801, AMM 21 60 21 400 801					
21-60-25-900-801-01	AFT VENTILATED TEMPERATURE SENSOR								Component ATA:21
PN:GG436-2041-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:04586	HRS		0	TSN 0					4101.3
WC#: 21.295	AFL		0	TSN 0					1225
				PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
21-60-25-900-801-02	LH VENTILATED TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2041-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:04764	HRS		0	TSN 0					4101.3	
WC#: 21.295	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801						
21-60-25-900-801-03	FWD VENTILATED TEMPERATURE SENSOR								Component	ATA:21
PN:GG436-2041-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:04748	HRS		0	TSN 0					4101.3	
WC#: 21.295	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801						
21-71-17-101	DISCARD THE HUMIDIFIER CONTROL UNIT, PART NO. GG546-2088-3								Service	ATA:21
PN:PN	MOS/MSC	N/A	20-Dec-09						169.7	
SN:NOT INSTALLED	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: AMM 21 71 17 961 801						
21-71-17-900-801-01	HUMIDIFIER CONTROL UNIT								Component	ATA:21
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:NOT INSTALLED	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 71 17 000 801, AMM 21 71 17 400 801						
21-71-21-900-801-01	HUMIDIFIER LEVEL SENSOR								Component	ATA:21
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:NOT INSTALLED	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 71 21 000 801, AMM 21 71 21 400 801						
21-71-49-900-801-01	HUMIDIFIER CABIN SENSOR								Component	ATA:21
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:NOT INSTALLED	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 21 71 49 000 801, AMM 21 71 49 400 801						
210000-701 U	DUCT ASSEMBLY								Component	ATA:21
PN:BWT25651-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:361	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
210000-702 U	DUCT ASSEMBLY								Component ATA:21
PN:BWT25651-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:362	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210000-703 U	DUCT ASSEMBLY								Component ATA:21
PN:BWT25651-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:363	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210000-704 U	DUCT ASSEMBLY								Component ATA:21
PN:BWT25651-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:364	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210000-705 U	DUCT ASSEMBLY								Component ATA:21
PN:BWT25651-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:365	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210001-701 U	AIR DUCT DIFFUSER ASSEMBLY								Component ATA:21
PN:BWT25653-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:359	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210001-702 U	AIR DUCT DIFFUSER ASSEMBLY								Component ATA:21
PN:BWT25653-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:360	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210001-703 U	AIR DUCT DIFFUSER ASSEMBLY								Component ATA:21
PN:BWT25653-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:361	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210005-702 U	DUCT FLEXIBLE R/H FS737 ASSEMBLY								Component ATA:21
PN:BWT18683-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:279	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
210007-701 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5931	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-702 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5932	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-703 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5933	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-704 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5934	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-705 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5935	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-706 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5936	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-707 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5937	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-708 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5938	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
210007-709 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5705	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-710 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5706	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-711 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5707	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-712 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5708	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-713 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5709	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-714 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5710	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-715 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5711	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-716 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5712	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
210007-717 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5693	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-718 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5694	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-719 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5695	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210007-720 U	DUCT TEE 'Y' ASSEMBLY								Component ATA:21
PN:BWT7302-16-6	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5696	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210010-701 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16453-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:535	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210010-702 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16453-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:536	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210010-703 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16453-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:537	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210011-701 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:689	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
210011-702 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:690	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210011-703 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:691	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210011-704 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:692	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210012-703 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT18325-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:290	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210012-704 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT18325-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:291	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
210013-701 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT18876-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:126	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
212300-701 U	EXHAUST (GALLEY) ASSEMBLY								Component ATA:21
PN:011835000	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:I10261914	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
212302-701 U	FAN (AFT LAV) ASSEMBLY								Component ATA:21
PN:011836000	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:I109485723	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
212302-702 U	FAN ASSEMBLY								Component ATA:21
PN:011836000	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:I10261910	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
212302-703 U	FAN ASSEMBLY								Component ATA:21
PN:011836000	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:I10261911	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
212302-704 U	FAN (FWD LAV) ASSEMBLY								Component ATA:21
PN:011836000	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:I09316291	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
219000-701 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16453-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:554	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
219001-701 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:773	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
219001-702 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:774	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
219001-703 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:775	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
219001-704 U	DUCT FLEXIBLE ASSEMBLY								Component ATA:21
PN:BWT16637-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:776	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
219002-701 U	DUCT FLEXIBLE L/H FS437 ASSEMBLY								Component	ATA:21
PN:BWT18325-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:309	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
219002-702 U	DUCT FLEXIBLE R/H FS711 ASSEMBLY								Component	ATA:21
PN:BWT18325-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:310	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
219503-701 U	FAN ASSEMBLY, IFE UNIT								Component	ATA:21
PN:983-9049-201	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:3VJGX	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
219503-702 U	FAN ASSEMBLY, IFE UNIT								Component	ATA:21
PN:983-9049-201	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:3VJMG	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
MODSUM IS700-21-000 U REV A	KIT - INSTALLATION INSTRUCTIONS FOR NEW OUTFLOW VALVE GG435-3002-21, MODIFICATION SUMMARY								Bulletin	ATA:21
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-21-001	MODIFICATION - MOISTURE CONTROL - INSTALLATION OF A CABIN HUMIDIFIER SYSTEM, SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-21-020	MODIFICATION - MOISTURE CONTROL INSTALLATION OF THE CABIN HUMIDIFICATION SYSTEM, SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	A/R								
	HRS									
	AFL									
SB 700-21-021	MODIFICATION - AIR CONDITIONING - AVIONICS COOLING FAN CHANGES, SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
SB 700-21-022	SPECIAL CHECK/MODIFICATION - TEMPERATURE CONTROL - INSPECT TRIM AIR CHECK VALVE FOR PREFORMED PACKING AND INSTALL IF MISSING, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-21-023	MODIFICATION - AIR CONDITIONING SYSTEM - INTRODUCTION OF AIR CONDITIONING SYSTEM CONTROLLER (ACSC) SOFTWARE VERSION L92131AR, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-21-024	MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - INTRODUCTION OF CABIN PRESSURE CONTROLLER (CPC) SOFTWARE VERSION 92129BM, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-21-026	MODIFICATION - VENTILATION - REPLACE FLIGHT COMPARTMENT AIR VENT DUCTS, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-027	MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - ADDITION OF A SELF-ADHESIVE DECAL AROUND THE EMERGENCY DEPRESSURIZATION SWITCH FOR VISIBLE DISTINCTION FROM OTHER SWITCHES IN CLOSE VICINITY, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-028 PART (A)	SPECIAL CHECK/REWORK - CABIN PRESSURE CONTROL SYSTEM - INSPECT OUTFLOW VALVE SERIAL NUMBER AND REPLACE UNSATISFACTORY UNITS THAT HAVE POOR ELECTRICAL CONTACT ON ACTUATOR MOTHERBOARD, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-028 PART (B)	SPECIAL CHECK/REWORK - CABIN PRESSURE CONTROL SYSTEM - INSPECT OUTFLOW VALVE SERIAL NUMBER AND REPLACE UNSATISFACTORY UNITS THAT HAVE POOR ELECTRICAL CONTACT ON ACTUATOR MOTHERBOARD, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
SB 700-21-029	MODIFICATION - MOISTURE CONTROL - UPGRADE OF THE HUMIDIFIER SYSTEM FOR AIRCRAFT POST SB 700-21-001 OR SB 700-21-020, SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-21-030	MODIFICATION - MOISTURE CONTROL - INSTALLATION OF THE PROVISIONS FOR THE NEW AND IMPROVED CABIN HUMIDIFIER SYSTEM, PART NO. GG432-2105-11 (A/C 9002 TO 9166), SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-21-031	MODIFICATION - MOISTURE CONTROL - FINAL INSTALLATION FOR THE NEW AND IMPROVED CABIN HUMIDIFIER SYSTEM, PART NO. GG432-2105-11 (A/C 9002 TO 9166), SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-21-034	MODIFICATION - PRESSURIZATION CONTROL - CABIN ALTITUDE REDUCTION DURING FLIGHT FOR IMPROVED PASSENGER COMFORT (A/C 9002 TO 9158), SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-21-034 REV 01	MODIFICATION - PRESSURIZATION CONTROL - CABIN ALTITUDE REDUCTION DURING FLIGHT FOR IMPROVED PASSENGER COMFORT (A/C 9002 TO 9158), SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-21-035	MODIFICATION - INTERNAL DISTRIBUTION - ADDITION OF ICE FILTER ASSEMBLIES AT THE MIX MANIFOLD (A/C 9002 TO 9355), SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
SB 700-21-035 REV 01	MODIFICATION - INTERNAL DISTRIBUTION - ADDITION OF ICE FILTER ASSEMBLIES AT THE MIX MANIFOLD, SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	T:A/R								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
SB 700-21-036	MODIFICATION - PRESSURIZATION CONTROL - CABIN ALTITUDE REDUCTION DURING FLIGHT FOR IMPROVED PASSENGER COMFORT (A/C 9159 TO 9174), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-041 PART (A)	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - INSTALLATION OF NEW ACOUSTIC SHIELD ON FORWARD OUTFLOW VALVE TO EASE ACCESS (A/C 9002 TO 9159), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-041 PART (B)	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - INSTALLATION OF NEW ACOUSTIC SHIELD ON FORWARD OUTFLOW VALVE TO EASE ACCESS (A/C 9002 TO 9159), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-049 PART (A)	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-049 PART (B)	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-049 REV 01 PART (A)	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-21-049 REV 01 PART (B)	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 21 - AIR CONDITIONING									
SB 700-21-050	MODIFICATION - HUMIDIFIER SYSTEM - INSTALLATION OF NEW AND IMPROVED CABIN HUMIDIFICATION SYSTEM WITH AUTOMATED CONTROL (A/C 9159 TO 9999), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-21-050 REV 01	MODIFICATION - HUMIDIFIER SYSTEM - INSTALLATION OF NEW AND IMPROVED CABIN HUMIDIFICATION SYSTEM WITH AUTOMATED CONTROL, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-21-051	MODIFICATION - HUMIDIFIER SYSTEM - INSTALLATION OF THE NEW CABIN HUMIDIFICATION SYSTEM WITH AUTOMATED CONTROL, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-21-052	MODIFICATION - TEMPERATURE CONTROL - REPLACE SUSPECT PACKINGS AT HOT-AIR CHECK VALVE, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-	17-May-11						152.8
	HRS		28.5						4072.8
	AFL		9						1216
SB 700-21-054	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - MODIFICATION OF AIR GASPERS FOR NOISE REDUCTION, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-21-055	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF TRIM AIR VALVES PART NO. GG436-2038-5 WITH GG436-2038-7, SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-	17-Oct-16						87.8
	HRS		2184.4						1916.9
	AFL		753						472
SB 700-21-056	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF THE AIR-CONDITIONING SYSTEM CONTROLLER (ACSC), SERVICE BULLETIN								Bulletin ATA:21
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 21 - AIR CONDITIONING										
SB 700-21-056 REV 01	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF THE AIR-CONDITIONING SYSTEM CONTROLLER (ACSC), SERVICE BULLETIN								Bulletin	ATA:21
	MOS/MSC	-	17-Jul-19						54.8	
	HRS		3188.8						912.5	
	AFL		996						229	
ATA 22 - AUTO FLIGHT										
22-11-01-900-801-01	GUIDANCE PANEL								Component	ATA:22
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 22.005	AFL		0	TSN 0					1225	
				PROC. REF: AMM 22 11 01 000 801, AMM 22 11 01 400 801						
22-12-01-900-801-01	AILERON PARALLEL SERVO								Component	ATA:22
PN:4015373-823	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0812H262	HRS		0	TSN 0					4101.3	
WC#: 22.010	AFL		0	TSN 0					1225	
				PROC. REF: AMM 22 12 01 000 801, AMM 22 12 01 400 801						
22-12-05-900-801-01	LEFT MLG WHEEL WELL AILERON SERVO BRACKET								Component	ATA:22
PN:4015374-813	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0902H275	HRS		0	TSN 0					4101.3	
WC#: 22.015	AFL		0	TSN 0					1225	
				PROC. REF: AMM 22 12 05 000 801, AMM 22 12 05 400 801						
22-12-09-900-801-01	ELEVATOR PARALLEL SERVO								Component	ATA:22
PN:4015373-834	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0812H272	HRS		0	TSN 0					4101.3	
WC#: 22.020	AFL		0	TSN 0					1225	
				PROC. REF: AMM 22 12 09 000 801, AMM 22 12 09 400 801						
22-12-13-900-801-01	FS1076.0 WL203.8 ELEVATOR SERVO BRACKET								Component	ATA:22
PN:4015374-906	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0901H467	HRS		0	TSN 0					4101.3	
WC#: 22.025	AFL		0	TSN 0					1225	
				PROC. REF: AMM 22 12 13 000 801, AMM 22 12 13 400 801						
SB 700-22-001	MODIFICATION - YAW DAMPER SYSTEM - YAW DAMPER BACKDRIVE IMPROVEMENT, SERVICE BULLETIN								Bulletin	ATA:22
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 22 - AUTO FLIGHT									
SB 700-22-002	MODIFICATION - AUTOPILOT SYSTEM - ADDITION OF PROTECTIVE FOD SHIELD TO AILERON AUTOPILOT SERVO, SERVICE BULLETIN								Bulletin ATA:22
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-22-002 REV 01	MODIFICATION - AUTOPILOT SYSTEM - ADDITION OF PROTECTIVE FOD SHIELD TO AILERON AUTOPILOT SERVO (A/C 9002 AND 9004 TO 9080), SERVICE BULLETIN								Bulletin ATA:22
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-22-003	MODIFICATION - GENERAL - INTRODUCTION OF THE AUTOPILOT EMERGENCY DESCENT MODE, SERVICE BULLETIN								Bulletin ATA:22
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-22-003 REV 01	MODIFICATION - AUTOMATIC FLIGHT-CONTROL SYSTEM (AFCS) -INTRODUCTION OF THE AUTOPILOT EMERENCY DESCENT MODE, SERVICE BULLETIN								Bulletin ATA:22
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-22-005	MODIFICATION - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) - INTRODUCTION OF WINDSHEAR ESCAPE GUIDANCE, SERVICE BULLETIN								Bulletin ATA:22
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-22-005 REV 01	MODIFICATION - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) - INTRODUCTION OF WINDSHEAR ESCAPE GUIDANCE, SERVICE BULLETIN								Bulletin ATA:22
	MOS/MSC	-	04-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-22-006	SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN								Bulletin ATA:22
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 22 - AUTO FLIGHT									
SB 700-22-006 PART (A)	INSPECTION SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN OF THE CABLE KEEPERS AND MODIFICATION OF THE AILERON SERVO CABLE TENSION								Bulletin ATA:22
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-22-006 PART (B)	INSPECTION SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN OF THE CABLE KEEPERS AND MODIFICATION OF THE ELEVATOR SERVO CABLE TENSION								Bulletin ATA:22
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
ATA 23 - COMMUNICATIONS									
23-09039-01 U	INSPECT (GVI) EFB COMPONENTS (GDC-64'S, COCKPIT MOUNTS AND CONNECTION PORTS) FOR PROPER MOUNTING								Service ATA:23
	MOS	T:72	05-Jul-21		31-Jul-27		1266 d	31-Jul-2027	31.2
	HRS								
	AFL								
23-11-01-900-801-01	NO. 1 VHF COMMUNICATION RECEIVER								Component ATA:23
PN:7510733-666	MOS/MSC	O/C	09-Jan-20						49.1
SN:0612B117	HRS		3338.3						763
WC#: 23.020	AFL		1038						187
				PROC. REF: AMM 23 11 01 000 801, AMM 23 11 01 400 801					
23-11-01-900-801-02	NO. 2 VHF COMMUNICATION RECEIVER								Component ATA:23
PN:7510733-666	MOS/MSC	O/C	14-Dec-23	TSO 1					1.9
SN:0801B803	HRS		4099.1	TSO 0					2.2
WC#: 23.020	AFL		1223	TSO 0					2
				PROC. REF: AMM 23 11 01 000 801, AMM 23 11 01 400 801					
23-11-05-900-801-01	NO. 1 COMM VHF TOP ANTENNA								Component ATA:23
PN:S65-8280-10	MOS/MSC	O/C	11-Jul-17	TSN 0					79
SN:310-30783	HRS		2473.8	TSN 0					1627.5
WC#: 23.025	AFL		817	TSN 0					408
				PROC. REF: AMM 23 11 05 000 801, AMM 23 11 05 400 801					
23-11-05-900-801-02	NO. 2 COMM VHF BOTTOM ANTENNA								Component ATA:23
PN:S65-8280-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0544	HRS		0	TSN 0					4101.3
WC#: 23.025	AFL		0	TSN 0					1225
				PROC. REF: AMM 23 11 05 000 801, AMM 23 11 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
23-11-CA-200	RECERTIFY NO. 1 VHF COMMUNICATION RECEIVER PER 14 CFR 91.413								Service ATA:23
PN:7510733-666	MOS	24	14-Dec-23		31-Dec-25		689 d	31-Dec-2025	1.9
SN:0612B117	HRS		4099.1						2.2
	AFL		1223						2
				PROC. REF: GENERIC NO REF					
23-11-CA-200	RECERTIFY NO. 2 VHF COMMUNICATION RECEIVER PER 14 CFR 91.413								Service ATA:23
PN:7510733-666	MOS	24	14-Dec-23		31-Dec-25		689 d	31-Dec-2025	1.9
SN:0801B803	HRS		4099.1						2.2
	AFL		1223						2
				PROC. REF: GENERIC NO REF					
23-12-01-900-801-01	LH HF (HF9031A) RECEIVER								Component ATA:23
PN:822-0101-002	MOS/MSC	O/C	23-Aug-12						137.6
SN:4623	HRS		618.4						3482.9
WC#: 23.030	AFL		230						995
				PROC. REF: AMM 23 12 01 000 801, AMM 23 12 01 400 801					
23-12-01-900-801-02	RH HF (HF9031A) RECEIVER								Component ATA:23
PN:822-0101-002	MOS/MSC	O/C	23-Aug-12						137.6
SN:4543	HRS		618.4						3482.9
WC#: 23.030	AFL		230						995
				PROC. REF: AMM 23 12 01 000 801, AMM 23 12 01 400 801					
23-12-05-900-801-01	NO. 1 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER								Component ATA:23
PN:685-0350-002	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:9055	HRS		0	TSN 0					4101.3
WC#: 23.035	AFL		0	TSN 0					1225
				PROC. REF: AMM 23 12 05 000 801, AMM 23 12 05 400 801					
23-12-05-900-801-02	NO. 2 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER								Component ATA:23
PN:685-0350-002	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:9054	HRS		0	TSN 0					4101.3
WC#: 23.035	AFL		0	TSN 0					1225
				PROC. REF: AMM 23 12 05 000 801, AMM 23 12 05 400 801					
23-13-21-900-801-01	CONTROL UNIT ANTENNA								Component ATA:23
PN:0811-A-0001	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:1883	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
				PROC. REF: AMM NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 23 - COMMUNICATIONS										
23-22-01-900-801-01	SELCAL DECODER								Component	ATA:23
PN:1200008-002	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:6156	HRS		0	TSN 0					4101.3	
WC#: 23.040	AFL		0	TSN 0					1225	
				PROC. REF: AMM 23 22 01 000 801, AMM 23 22 01 400 801						
23-40-01-900-801-01	RH CREW INTERPHONE UNIT								Component	ATA:23
PN:600-59146-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:7333	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 23 40 01 000 801, AMM 23 40 01 400 801						
23-40-01-900-801-02	LH CREW INTERPHONE UNIT								Component	ATA:23
PN:600-59146-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:6658	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 23 40 01 000 801, AMM 23 40 01 400 801						
23-51-05-900-801-01	NO. 1 AUDIO CONTROL PANEL								Component	ATA:23
PN:7511001-985	MOS/MSC	O/C	23-Apr-21	TSR 0					33.6	
SN:0707C193	HRS		3533.7	TSR 0					567.6	
WC#: 23.045	AFL		1082	TSR 0					143	
				PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801						
23-51-05-900-801-02	NO. 2 AUDIO CONTROL PANEL								Component	ATA:23
PN:7511001-985	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0903D590	HRS		0	TSN 0					4101.3	
WC#: 23.045	AFL		0	TSN 0					1225	
				PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801						
23-51-05-900-801-03	NO. 3 AUDIO CONTROL PANEL								Component	ATA:23
PN:7511001-985	MOS/MSC	O/C	19-Apr-13	TSR 0					129.7	
SN:0904D612	HRS		930.5	TSR 0					3170.8	
WC#: 23.045	AFL		358	TSR 0					867	
				PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801						
23-61-01-201[S]	FUNCTIONAL TEST OF THE STATIC DISCHARGERS								Service	ATA:23
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 23.010	AFL		1069						156	
				PROC. REF: AMM 23 61 01 720 801						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 23 - COMMUNICATIONS										
23-71-00-201	OPERATIONAL TEST OF THE VOICE RECORDER SYSTEM								Service	ATA:23
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 23.015	AFL		690						535	
				PROC. REF: AMM 23 71 00 710 801						PKG:8
23-71-01-900-801-01	(CVR) COCKPIT VOICE RECORDER								Component	ATA:23
PN:980-6032-040	MOS/MSC	O/C	05-Aug-14	TSN 2					114.2	
SN:CVR-02647	HRS		1391.1	TSN 0					2710.2	
WC#: 23.050	AFL		537	TSN 0					688	
				PROC. REF: AMM 23 71 01 000 801, AMM 23 71 01 400 801						
23-71-05-900-801-01	CVR - CONTROL PANEL								Component	ATA:23
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 23 71 05 000 801, AMM 23 71 05 400 801						
23-71-09-900-801-01	MICROPHONE								Component	ATA:23
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 23.055	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
23-71-13-201	RESTORATION OF THE RECORDER INDEPENDENT POWER SUPPLY (RIPS)								Service	ATA:23
PN:PN	MOS/MSC	N/A								
SN:UNKNOWN	HRS									
	AFL									
23-71-17-900-801-01	IMPACT SWITCH								Component	ATA:23
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 23.060	AFL		0	TSN 0					1225	
				PROC. REF: AMM 23 71 17 000 801, AMM 23 71 17 400 801						
23-71-21-201	DISCARD CVR (ULB) UNDERWATER LOCATOR BEACON BATTERY (23-71-21-201)								Service	ATA:23
PN:DK120/90	MOS/MSC	DUE	12-Jul-18		01-Jul-25 (M)		506 d	01-Jul-2025	67	
SN:AT115198	HRS		2892.3						1209	
WC#: 23.065	AFL		921						304	
				PROC. REF: AMM 23 71 21 960 802						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 23 - COMMUNICATIONS										
23-71-21-202	OPERATIONAL TEST CVR (ULB) UNDERWATER LOCATOR BEACON (23-71-21-202)								Service	ATA:23
PN:DK120/90	MOS	30 (+3m/-3m)	30-Dec-22	Adj 3	30-Sep-25	31-Dec-25	597 d (+92)	30-Sep-2025	13.4	
SN:AT115198	HRS		3913.7						187.6	
WC#: 23.065	AFL		1171						54	
				PROC. REF: AMM 23 71 21 710 801						PKG:32
23-71-21-900-801-01	CVR (ULB) UNDERWATER LOCATOR BEACON								Component	ATA:23
PN:DK120/90	MOS/MSC	O/C	12-Jul-18	TSN 2					67	
SN:AT115198	HRS		2892.3	TSN 0					1209	
WC#: 23.065	AFL		921	TSN 0					304	
				PROC. REF: AMM 23 71 21 000 801, AMM 23 71 21 400 801						
23-81-01-900-802-01	LH RADIO MANAGEMENT UNIT								Component	ATA:23
PN:7013270-977	MOS/MSC	O/C	20-Jul-14						114.7	
SN:04124598	HRS		1391.1						2710.2	
WC#: 23.070	AFL		537						688	
				PROC. REF: AMM 23 81 01 000 802, AMM 23 81 01 400 802						
23-81-01-900-802-02	RH RADIO MANAGEMENT UNIT								Component	ATA:23
PN:7013270-977	MOS/MSC	O/C	20-Jul-14						114.7	
SN:05014652	HRS		1391.1						2710.2	
WC#: 23.070	AFL		537						688	
				PROC. REF: AMM 23 81 01 000 802, AMM 23 81 01 400 802						
230001-701 U	1.9 GHZ CORDLESS BLACK HANDSET								Component	ATA:23
PN:463092-110	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:3004313	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
230001-702 U	1.9 GHZ CORDLESS BLACK HANDSET								Component	ATA:23
PN:463092-110	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:3004320	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
230003-702 U	1.9 GHZ CORDLESS BASE STATION UNIT								Component	ATA:23
PN:463092-230	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:3001933	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
230003-703 U	1.9 GHZ CORDLESS BASE STATION UNIT								Component ATA:23
PN:463092-230	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:3002561	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
230005-710 U	JACK PANEL 1X2 RCA GAME PORT								Component ATA:23
PN:2600-2-15-T12SR	MOS/MSC	O/C							
SN:3T7HY	HRS								
	AFL								
230005-711 U	JACK PANEL, KIT RJ45 ETHERNET-COCKPIT # 1 LH ETHERNET								Component ATA:23
PN:2600-2-2	MOS/MSC	O/C	23-Mar-11						154.6
SN:3T6JL	HRS		15.6						4085.7
	AFL		7						1218
230005-712 U	JACK PANEL, KIT RJ45 ETHERNET-COCKPIT # 1 LH ETHERNET								Component ATA:23
PN:2600-2-2	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:3T6JM	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
230006-704 U	HANDSET (FS390 CREW REST) HANDSET								Component ATA:23
PN:744000-00-40	MOS/MSC	O/C	06-Jul-12						139.2
SN:1011-6405	HRS		541.7						3559.6
	AFL		200						1025
230006-705 U	COCKPIT PHONE								Component ATA:23
PN:744000-10-10	MOS/MSC	O/C	27-Jul-16	TSN 1					90.5
SN:0216-7893	HRS		2078.9	TSN 0					2022.4
	AFL		719	TSN 0					506
230008-701 U	1.9 GHZ BLACK CORDLESS CRADLE W POP UNIT								Component ATA:23
PN:463095-220	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:3001978	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
230008-702 U	1.9 GHZ BLACK CORDLESS CRADLE W POP UNIT								Component ATA:23
PN:463095-220	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:3002027	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
230009-701 U	COAX CABLE ASSY								Component ATA:23
PN:501525	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:E75332	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
231101-701 U	#3 VHF COMMUNICATION UNIT								Component ATA:23
PN:7510700-833	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:1005C698	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
231300-701 U	#1 FS945 RH HIGH SPEED TRANSCEIVER								Component ATA:23
PN:822-2232-020	MOS/MSC	O/C	08-May-15	TSN 50					105.1
SN:16PHCY	HRS		1661.7	TSN 1646.1					2439.6
	AFL		607	TSN 600					618
231300-702 U	#2 FS950 RH HIGH SPEED TRANSCEIVER								Component ATA:23
PN:822-2232-020	MOS/MSC	O/C	08-May-15	TSN 50					105.1
SN:16PHCV	HRS		1661.7	TSN 1646.1					2439.6
	AFL		607	TSN 600					618
231301-701 U	SATALLITE DATA UNIT								Component ATA:23
PN:822-1785-001	MOS/MSC	O/C	19-Feb-18	TSR 0					71.7
SN:183637	HRS		2738.7	TSR 0					1362.6
	AFL		888	TSR 0					337
231303-701 U	DIPLEXER/LNA UNIT								Component ATA:23
PN:1242-A-0006	MOS/MSC	O/C	19-Mar-21						34.7
SN:1248	HRS		3474.7						626.6
	AFL		1069						156
231304-701 U	CABIN NETWORK XCELERATOR								Component ATA:23
PN:1110-A-0501-20	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:961	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
231305-701 U	PA AMPLIFIER/FS295 RH UNIT								Component ATA:23
PN:251-003	MOS/MSC	O/C	03-Nov-11	TSN 0					147.3
SN:2105	HRS		227.8	TSN 0					3873.5
	AFL		100	TSN 0					1125

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
231306-701 U	AEROCOM 3000 CTU UNIT								Component ATA:23
PN:350000-10-010000	MOS/MSC	O/C	11-Apr-13	TSR 0					130
SN:AE3K-610	HRS		909.8	TSR 0					3191.5
	AFL		351	TSR 0					874
231310-701 U	SATCOM AMT-50 ANTENNA								Component ATA:23
PN:0476-A-00377	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:1913	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
231311-701 U	NOISE FILTER (AVIONICS BAY (F.S. 433 TOP) UNIT								Component ATA:23
PN:122253-10A	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:002-009954	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
231312-701 U	IRRIDIUM COM ANTENNA								Component ATA:23
PN:500644	MOS/MSC	O/C	01-Apr-11	TSN 0					154.3
SN:10994	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
231314-702 U	AEROCOM 3000 TRAY								Component ATA:23
PN:938500-200	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:1143	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
231315-701 U	ICS-100 SINGLE CHANNEL IRIDIUM XCVR,(ICG) UNIT								Component ATA:23
PN:500616-3	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:3515	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
231330-701 U	COMMUNICATION CONVERGENCE UNIT								Component ATA:23
PN:1233-A-0100	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:127	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218
232100-701 U	COCKPIT PRINTER UNIT								Component ATA:23
PN:706300-1111	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6
SN:48403881	HRS		15.6	TSN 0					4085.7
	AFL		7	TSN 0					1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 23 - COMMUNICATIONS										
232101-702 U	PRINT CONVERTER SERVER								Component	ATA:23
PN:ADI23900-000	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:240	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
232102-701 U	FAX/PRINTER SCANNER KIT UNIT								Component	ATA:23
PN:J7942A	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:SG471AF85E	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
232300-701 U	TELELINK (ADLU) UNIT								Component	ATA:23
PN:840021-03	MOS/MSC	O/C	17-Oct-16	TSR 0					87.8	
SN:10681	HRS		2184.4	TSR 0					1916.9	
	AFL		753	TSR 0					472	
237000-701 U	VIDEO CONTROL (VCU-05) UNIT								Component	ATA:23
PN:100-2415-01	MOS/MSC	O/C	23-Mar-11						154.6	
SN:1019895	HRS		15.6						4085.7	
	AFL		7						1218	
238101-003 U	A25 RMU PANEL								Component	ATA:23
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 23.075	AFL		0	TSN 0					1225	
238101-004 U	A26 RMU PANEL								Component	ATA:23
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 23.075	AFL		0	TSN 0					1225	
239000-701 U	SATCOM RF COAX CABLE UNIT								Component	ATA:23
PN:500-91946-102	MOS/MSC	O/C	23-Mar-11						154.6	
SN:E76665	HRS		15.6						4085.7	
	AFL		7						1218	
FAA 2006-19-04 PART (F)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REVISE AIRPLANE FLIGHT MANUAL (AFM)								AD	ATA:23
	DAYS/MSC	-	19-Dec-09						5167 d	
	HRS		0						4101.3	
	AFL		0						1225	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 23 - COMMUNICATIONS										
FAA 2006-19-04 PART (G)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF IDENTIFICATION PLATES FOR CERTAIN COM UNITS								AD	ATA:23
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
Category: APPLIANCE										
FAA 2006-19-04 PART (H)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF CERTAIN TRANSPONDERS								AD	ATA:23
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
Category: APPLIANCE										
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC								AD	ATA:23
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
MODSUM IS700-23-0001[U] REV A	GROUND SIGNAL ADDED ON COCKPIT PRINTER CONNECTOR (A/C 9002 - 9999), MODIFICATION SUMMARY								Bulletin	ATA:23
	MOS/MSC	T:A/R								
	HRS									
	AFL									
MODSUM IS700-23-0002[U] REV C	ACP WIRING CHANGE TO PREVENT COMM AUDIO BLEEDING ON HEADPHONE OUTPUTS - AUDIO INTEGRATING SYSTEM (A/C 9002 - 9269), MODIFICATION SUMMARY								Bulletin	ATA:23
	MOS/MSC	T:A/R								
	HRS									
	AFL									
MODSUM IS700-23-0004[U] REV B	INDICATING AND RECORDING SYSTEM - COCKPIT VOICE RECORDER - ADDITIONAL RECORDING CAPABILITY PROVISIONS, MODIFICATION SUMMARY								Bulletin	ATA:23
	MOS/MSC	T:A/R								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 23 - COMMUNICATIONS										
MODSUM IS700-23-0004U REV B1	INDICATING AND RECORDING SYSTEM - COCKPIT VOICE RECORDER - ADDITIONAL RECORDING CAPABILITY PROVISIONS, MODIFICATION SUMMARY								Bulletin	ATA:23
	MOS/MSC	-								
	HRS									
	AFL									
MODSUM IS700-23-0007U REV A	COMMUNICATIONS – COCKPIT VOICE RECORDER – PROVISIONS FOR ADDITIONAL RECORDING CAPABILITY, MODIFICATION SUMMARY								Bulletin	ATA:23
	MOS/MSC	-	08-Mar-13						131.1	
	HRS		850.3						3251	
	AFL		332						893	
SB 700-23-001	MODIFICATION - SATELLITE COMMUNICATIONS (SATCOM) SYSTEM - INSTALLATION (9002 TO 9139), SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-23-002	MODIFICATION - THIRD VERY HIGH FREQUENCY (VHF 3) COMMUNICATION SYSTEM - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-23-002 REV 01	MODIFICATION - THIRD VERY HIGH FREQUENCY (VHF 3) COMMUNICATION SYSTEM - INSTALLATION (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-23-002 REV 02	MODIFICATION - THIRD VERY HIGH FREQUENCY (VHF 3) COMMUNICATION SYSTEM - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
SB 700-23-003	MODIFICATION - CABIN COMMUNICATION SYSTEM (CCS) - "OFFICE IN THE SKY" INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 23 - COMMUNICATIONS										
SB 700-23-003 REV 01	MODIFICATION - CABIN COMMUNICATION SYSTEM (CCS) - "OFFICE IN THE SKY" INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	A/R								
	HRS									
	AFL									
SB 700-23-004	MODIFICATION - FLIGHT COMPARTMENT PRINTER - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-23-004 REV 01	MODIFICATION - FLIGHT COMPARTMENT PRINTER - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-23-004 REV 02	MODIFICATION - FLIGHT COMPARTMENT PRINTER - INSTALL, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	A/R	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
SB 700-23-005	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-23-005 REV 01	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-23-005 REV 02	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
SB 700-23-012	MODIFICATION - AUDIO INTEGRATING SYSTEM - INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FOR FULL FUNCTIONALITY, SERVICE BULLETIN								Bulletin	ATA:23
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
SB 700-23-013	MODIFICATION - HF COMMUNICATION SYSTEM - ADDITION OF WIRE HARNESS SUPPORT TO PREVENT FOULING WITH ADJACENT FUEL LINE, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-23-014	MODIFICATION - CABIN COMMUNICATION SYSTEM - ENABLE GPWS AURAL MESSAGES TO THE THIRD CREW AUDIO CONTROL PANEL, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-23-015	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - SOFTWARE UPGRADE OF THE ADLU TO PART NO. 8400021-01, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-23-017 PART (A)	AUDIO AND VIDEO MONITORING - CHECK FOR MHT REMOTE UNIT APPLICABILITY, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-23-017 PART (B)	AUDIO AND VIDEO MONITORING - MODIFICATION - INSTALLATION OF MODIFIED MHT REMOTE UNITS, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-23-017 REV 01	SPECIAL CHECK/MODIFICATION - AUDIO AND VIDEO MONITORING - CHECK FOR MHT REMOTE UNITS THAT ARE NOT MODIFIED (CAN CAUSE A SQUELCH BREAK ANOMALY) AND INSTALLATION OF MODIFIED MHT REMOTE UNITS, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-019	MODIFICATION - CABIN COMMUNICATION SYSTEM - "OFFICE IN THE SKY" INSTALLATION ON AIRCRAFT WITH PROVISIONS, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
SB 700-23-027	MODIFICATION - CABIN COMMUNICATION SYSTEM - INSTALLATION OF NEW BACKLIT TELEPHONE HANDSET, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-029	MODIFICATION – SATELLITE COMMUNICATIONS SYSTEM – INSTALLATION OF PROVISIONS FOR INMARSAT SWIFT BROADBAND HIGH SPEED SERVICE, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-033	MODIFICATION - VOICE RECORDER SYSTEM - INSTALLATION OF RECORDER INDEPENDENT POWER SUPPLY (RIPS) FOR COCKPIT VOICE RECORDER (CVR), SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-033 REV 01	MODIFICATION - VOICE RECORDER SYSTEM - INSTALLATION OF RECORDER INDEPENDENT POWER SUPPLY (RIPS) FOR COCKPIT VOICE RECORDER (CVR), SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-034	MODIFICATION – SATELLITE COMMUNICATIONS SYSTEM – INSTALLATION OF INMARSAT SWIFT BROADBAND HIGH SPEED SERVICE, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-034 REV 01	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - INSTALLATION OF INMARSAT SWIFT BROADBAND HIGH SPEED SERVICE, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-034 REV 02	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - INSTALLATION OF INMARSAT SWIFT BROADBAND HIGH SPEED SERVICE, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
SB 700-23-037	MODIFICATION - VOICE RECORDING SYSTEM - UPGRADE THE COCKPIT VOICE RECORDER SYSTEM TO STORE DATALINK MESSAGES, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-037 REV 01	MODIFICATION - VOICE RECORDER SYSTEM - UPGRADE THE COCKPIT VOICE RECORDER SYSTEM TO STORE DATALINK MESSAGES, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-	04-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-23-037 REV 02	MODIFICATION - VOICE RECORDER SYSTEM - UPGRADE THE COCKPIT VOICE RECORDER SYSTEM TO STORE DATALINK MESSAGES, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-037 REV 03	MODIFICATION - VOICE RECORDER SYSTEM - UPGRADE THE COCKPIT VOICE RECORDER SYSTEM TO STORE DATALINK MESSAGES, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-039	ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FOR FULL FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-039 REV 01	ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FOR FULL FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-039 REV 01 PART (A)	AIRCRAFT ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FOR FULL FUNCTIONALITY, SERVICE BULLETIN MODIFICATION								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
SB 700-23-039 REV 01 PART (B)	AIRCRAFT ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FOR FULL FUNCTIONALITY, SERVICE BULLETIN SETUP								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-040	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-040 REV 01	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-040 REV 02	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-041	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE KA-BAND RADOME FAIRING, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-041 REV 01	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE KA-BAND RADOME FAIRING, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-041 REV 02	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE KA-BAND RADOME FAIRING, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 23 - COMMUNICATIONS									
SB 700-23-041 REV 03	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE KA-BAND RADOME FAIRING, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-042	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF ICS 100/200 SERIES IRIDIUM TRANSCEIVER WITH ICS 120/220 A/AF/B/BF SERIES IRIDIUM TRANSCEIVER, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-043	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - UPGRADE TO HONEYWELL MCS-7000 SATCOM, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-043 REV 01	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - UPGRADE TO HONEYWELL MCS-7000 SATCOM, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-045	MODIFICATION - CABIN COMMUNICATION SYSTEM - DEACTIVATION OF OFFICE IN THE SKY UHF, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-046	MODIFICATION - CABIN COMMUNICATION SYSTEM - SIGMA 7 HANDSETS REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-23-046 REV 01	MODIFICATION - CABIN COMMUNICATION SYSTEM - SIGMA 7 HANDSETS REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	-							
	HRS								
	AFL								
SB 700D23-024 REV 2[U]	MODIFICATION - CABIN COMMUNICATION SYSTEM - ICS-100 TELEPHONE SYSTEM PROVISIONS, SERVICE BULLETIN								Bulletin ATA:23
	MOS/MSC	A/R	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
24-00-00-301 S	OPERATIONAL TEST (CYCLING) OF THERMAL CIRCUIT BREAKERS								Service	ATA:24
	MOS	15 (+3m/-3m)	05-Dec-23						2.2	
	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 24 00 00 710 802						PKG:31
24-00-01-900-801-01	JB3 JUNCTION BOX								Component	ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: CMM 24-00-01, AMM 24 00 01 000 801, AMM 24 00 01 400 801						
24-00-05-900-801-01	JB4 JUNCTION BOX								Component	ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: CMM 24-00-01, AMM 24 00 05 000 801, AMM 24 00 05 400 801						
24-00-09-900-801-01	JB5 JUNCTION BOX								Component	ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: CMM 24-00-01, AMM 24 00 09 000 801, AMM 24 00 09 400 801						
24-00-13-900-801-01	JB6 JUNCTION BOX								Component	ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: CMM 24-00-01, AMM 24 00 13 000 801, AMM 24 00 13 400 801						
24-00-50-601 U S	OPERATIONAL TEST OF THE CABIN POWER SHUT-OFF SWITCH								Service	ATA:24
	MOS	15	22-Nov-23						2.6	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
24-12-00-900-801-01	NO. 1 VFG OIL PIPE								Component	ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 24.035	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
24-12-00-900-801-02	NO. 2 VFG OIL PIPE								Component	ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 24.035	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
24-21-01-201 S	DETAILED INSPECTION OF THE VARIABLE FREQUENCYGENERATOR (VFG) OIL SUPPLY								Service	ATA:24
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 24.005	AFL		1223						2	
				PROC. REF: AMM 24 12 00 220 801						PKG:4
24-21-01-900-801-01	NO. 1 (LH OUTBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component	ATA:24
PN:GL511-1103-9	MOS/MSC	O/C	26-Jul-16						90.5	
SN:3004	HRS		2078.9						2022.4	
WC#: 24.040	AFL		719						506	
				PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801						
24-21-01-900-801-02	NO. 2 (LH INBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component	ATA:24
PN:GL511-1103-9	MOS/MSC	O/C	16-Jul-15						102.8	
SN:2759	HRS		1712.9						2388.4	
WC#: 24.040	AFL		624						601	
				PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801						
24-21-01-900-801-03	NO. 3 (RH OUTBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component	ATA:24
PN:GL511-1103-9	MOS/MSC	O/C	16-Jul-15						102.8	
SN:1123	HRS		1712.9						2388.4	
WC#: 24.040	AFL		624						601	
				PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801						
24-21-01-900-801-04	NO. 4 (RH INBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR								Component	ATA:24
PN:GL511-1103-9	MOS/MSC	O/C	16-Jul-15						102.8	
SN:4169	HRS		1712.9						2388.4	
WC#: 24.040	AFL		624						601	
				PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801						
24-22-01-900-801-01	NO.5 APU AC (40/45 KVA) GENERATOR								Component	ATA:24
PN:GL511-1204-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2221	HRS		0	TSN 0					4101.3	
WC#: 24.045	AFL		0	TSN 0					1225	
				PROC. REF: AMM 24 22 01 000 801, AMM 24 22 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
24-23-01-101	OPERATIONAL TEST OF THE RAM AIR TURBINE (RAT)								Service	ATA:24
	MOS	24 (+3m/-3m)	02-Feb-24	Adj 20d	28-Feb-26	22-May-26	748 d (+83)	28-Feb-2026	.3	
	HRS		4101.3						0	
WC#: 24.015	AFL		1225						0	
				PROC. REF: AMM 24 23 01 710 801						
24-23-01-102	FUNCTIONAL TEST RAM AIR TURBINE (RAT) HEATER								Service	ATA:24
PN:GL456-1101-7	MOS	24 (+3m/-3m)	30-Nov-23	Adj 3	28-Feb-26	31-May-26	748 d (+92)	28-Feb-2026	2.4	
SN:0467	HRS		4099.1						2.2	
WC#: 24.015	AFL		1223						2	
				PROC. REF: AMM 24 23 33 720 804						
24-23-01-900-801-01	RAM AIR TURBINE								Component	ATA:24
PN:GL456-1101-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0467	HRS		0	TSN 0					4101.3	
WC#: 24.015	AFL		0	TSN 0					1225	
				PROC. REF: CMM 24-23-01, AMM 24 23 01 000 801, AMM 24 23 01 400 801						
24-23-05-900-801-01	GENERATOR- RAT CONTROL								Component	ATA:24
PN:GL456-1201-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0481	HRS		0	TSN 0					4101.3	
WC#: 24.050	AFL		0	TSN 0					1225	
				PROC. REF: AMM 24 23 05 000 801, AMM 24 23 05 400 801						
24-23-09-900-801-01	DEPLOY RAT ACTUATOR								Component	ATA:24
PN:GL456-1301-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0486	HRS		0	TSN 0					4101.3	
WC#: 24.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 24 23 09 000 801, AMM 24 23 09 400 801						
24-23-13-900-801-01	RAT MANUAL RELEASE CABLE								Component	ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 24.060	AFL		0	TSN 0					1225	
				PROC. REF: AMM 24 23 13 000 801, AMM 24 23 13 400 801						
24-23-17-900-801-01	DOOR RAT LINK								Component	ATA:24
PN:GL456-1501-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0483	HRS		0	TSN 0					4101.3	
WC#: 24.065	AFL		0	TSN 0					1225	
				PROC. REF: AMM 24 23 17 000 801, AMM 24 23 17 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-23-21-900-801-01	RAT RETRACTION PUMP								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.070	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 23 21 000 801, AMM 24 23 21 400 801					
24-23-25-900-801-01	RAT UPLOCK								Component ATA:24
PN:GL456-1601-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0471	HRS		0	TSN 0					4101.3
WC#: 24.075	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 23 25 000 801, AMM 24 23 25 400 801					
24-24-01-900-801-01	NO.1 LH ENGINE GENERATOR CONTROL UNIT GCU								Component ATA:24
PN:GL511-3104-1	MOS/MSC	O/C	13-Apr-11						153.9
SN:2336	HRS		18.3						4083
WC#: 24.080	AFL		8						1217
				PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801					
24-24-01-900-801-02	NO.2 LH ENGINE GENERATOR CONTROL UNIT GCU								Component ATA:24
PN:GL511-3105-1	MOS/MSC	O/C	13-Aug-19	TSR 0					53.9
SN:6016	HRS		3206.3	TSN 4094.8, TSR 0					895
WC#: 24.080	AFL		1004	TSR 0					221
				PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801					
24-24-01-900-801-03	NO.3 RH ENGINE GENERATOR CONTROL UNIT GCU								Component ATA:24
PN:GL511-3105-1	MOS/MSC	O/C	13-Aug-19						53.9
SN:2400	HRS		3206.3						895
WC#: 24.085	AFL		1004						221
				PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801					
24-24-01-900-801-04	NO.4 RH ENGINE GENERATOR CONTROL UNIT GCU								Component ATA:24
PN:GL511-3104-1	MOS/MSC	O/C	13-Apr-11						153.9
SN:2403	HRS		18.3						4083
WC#: 24.085	AFL		8						1217
				PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801					
24-24-01-900-801-05	NO.5 APU GENERATOR CONTROL UNIT GCU								Component ATA:24
PN:GL511-3104-1	MOS/MSC	O/C	29-Jun-11						151.4
SN:2402	HRS		47.4						4053.9
WC#: 24.090	AFL		17						1208
				PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
24-25-00-201	DISCARD OF THE NO. 1 (LH OUTBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER								Service	ATA:24
	MOS		08-Jun-18					15-Jun-2027	68.1	
	HRS	3000 (+50/-50)	2857.6	Adj 50	5907.6	5957.6	1806.3 (+50)		1243.7	
	AFL		911						314	
			PROC. REF: AMM 24 12 03 961 801							
24-25-00-201	DISCARD OF THE NO. 2 (LH INBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER								Service	ATA:24
	MOS		08-Jun-18					15-Jun-2027	68.1	
	HRS	3000 (+50/-50)	2857.6	Adj 50	5907.6	5957.6	1806.3 (+50)		1243.7	
	AFL		911						314	
			PROC. REF: AMM 24 12 03 961 801							
24-25-00-201	DISCARD OF THE NO. 3 (RH OUTBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER								Service	ATA:24
	MOS		16-Jul-15					03-May-2025	102.8	
	HRS	3000 (+50/-50)	1712.9	Adj 50	4762.9	4812.9	661.6 (+50)		2388.4	
	AFL		624						601	
			PROC. REF: AMM 24 12 03 961 801							
24-25-00-201	DISCARD OF THE NO. 4 (RH INBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER								Service	ATA:24
	MOS		16-Jul-15					03-May-2025	102.8	
	HRS	3000 (+50/-50)	1712.9	Adj 50	4762.9	4812.9	661.6 (+50)		2388.4	
	AFL		624						601	
			PROC. REF: AMM 24 12 03 961 801							
24-25-00-202 S	VISUAL CHECK OF THE DIFFERENTIAL PRESSURE INDICATOR								Service	ATA:24
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 24.025	AFL		1223						2	
			PROC. REF: AMM 24 12 00 210 801							PKG:4
24-26-54-601 U S	OPERATIONAL TEST OF GROUND FAULT INTERRUPTERS								Service	ATA:24
	MOS	15	22-Nov-23						2.6	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-31-01-900-801-01	NO. 1 TRANSFORMER RECTIFIER UNIT TRU								Component ATA:24
PN:GL511-2102-1	MOS/MSC	O/C	01-Dec-18	TSN 108					62.3
SN:B1604	HRS			TSN 3006.7					
WC#: 24.095	AFL		949	TSN 949					276
				PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801					
24-31-01-900-801-02	NO. 2 TRANSFORMER RECTIFIER UNIT TRU-ESS TRU 1								Component ATA:24
PN:GL511-2102-1	MOS/MSC	O/C	15-Jul-20	TSR 0					42.9
SN:B1938	HRS		3416.1	TSN 1659.6, TSR 0					685.2
WC#: 24.095	AFL		1057	TSN 646, TSR 0					168
				PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801					
24-31-01-900-801-03	NO. 3 TRANSFORMER RECTIFIER UNIT TRU								Component ATA:24
PN:GL511-2102-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:B1607	HRS		0	TSN 0					4101.3
WC#: 24.095	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801					
24-31-01-900-801-04	NO. 4 TRANSFORMER RECTIFIER UNIT TRU								Component ATA:24
PN:GL511-2102-1	MOS/MSC	O/C	02-Jul-20	TSR 0					43.3
SN:B278	HRS		3401.2	TSR 0					700.1
WC#: 24.095	AFL		1052	TSR 0					173
				PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801					
24-32-01-203	RESTORATION AVIONICS BATTERY (24-32-01-203)								Service ATA:24
PN:257CH-9	MOS	8 (+10%/-10%)	22-Dec-23		31-Aug-24	15-Sep-24	202 d (+15)	31-Aug-2024	1.6
SN:09052000B2B2F	HRS								
WC#: 24.100	AFL								
				PROC. REF: BULLETINS , AMM 24 32 01 610 802					
24-32-01-900-801-01	AVIONICS BATTERY								Component ATA:24
PN:257CH-9	MOS/MSC	O/C	22-Dec-23	TSO 23					1.6
SN:09052000B2B2F	HRS		4099.1	TSO 409.5					2.2
WC#: 24.100	AFL		1223	TSO 106					2
				PROC. REF: AMM 24 32 01 000 801, AMM 24 32 01 400 801					
24-32-05-900-801-01	AVIONIC BAY BATTERY CHARGER								Component ATA:24
PN:GL511-2401-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:E937	HRS		0	TSN 0					4101.3
WC#: 24.105	AFL		0	TSN 0					1225
				PROC. REF: CMM 24-32-01, AMM 24 32 05 000 801, AMM 24 32 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-32-05-900-801-02	APU BATTERY CHARGER								Component ATA:24
PN:GL511-2401-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:E958	HRS		0	TSN 0					4101.3
WC#: 24.110	AFL		0	TSN 0					1225
				PROC. REF: CMM 24-32-01, AMM 24 32 05 000 801, AMM 24 32 05 400 801					
24-32-09-203	RESTORATION APU BATTERY (24-32-09-203)								Service ATA:24
PN:GL511-2301-5	MOS	8 (+10%/-10%)	22-Dec-23		31-Aug-24	15-Sep-24	202 d (+15)	31-Aug-2024	1.6
SN:090520026BB81	HRS								
WC#: 24.010	AFL								
				PROC. REF: BULLETINS , AMM 24 32 09 610 802					
24-32-09-900-801-01	APU BATTERY								Component ATA:24
PN:GL511-2301-5	MOS/MSC	O/C	22-Dec-23	TSN 40, TSO 24					1.6
SN:090520026BB81	HRS		4099.1	TSN 624.4, TSO 409.5					2.2
WC#: 24.010	AFL		1223	TSN 154, TSO 106					2
				PROC. REF: AMM 24 32 09 000 801, AMM 24 32 09 400 801					
24-41-01-900-801-01	CTA CURRENT TRANSFORMER								Component ATA:24
PN:GL516-1101-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1901	HRS		0	TSN 0					4101.3
WC#: 24.115	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 41 01 000 801, AMM 24 41 01 400 801					
24-51-17-900-801-01	AC TO DC CONVERTER								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 17 000 801, AMM 24 51 17 400 801					
24-51-17-900-801-02	FREQUENCY CONVERTER								Component ATA:24
PN:1-002-0102-1943	MOS/MSC	O/C	27-Jun-15	TSR 0					103.5
SN:HT003110	HRS		1703.6	TSR 0					2397.7
	AFL		615	TSR 0					610
				PROC. REF: GENERIC NO REF					
24-51-21-900-801-01	EPQM CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.125	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 21 000 801, AMM 24 51 21 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-51-33-000-801[U]	K5 ACPC L-SERIES CONTACTOR								Component ATA:24
PN:1714157	MOS/MSC	O/C	01-Dec-18	TSN 0					62.3
SN:07978	HRS		3006.2	TSN 0					1095.1
	AFL		949	TSN 0					276
24-51-33-000-802[U]	K4 ELECTRICAL CONTACTOR								Component ATA:24
PN:1714139	MOS/MSC	O/C	11-Nov-18						63
SN:04323	HRS		2995.9						1105.4
	AFL		948						277
24-51-37-900-801-01	K2 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:1714157	MOS/MSC	O/C	17-Oct-16	TSN 0					87.8
SN:07534	HRS		2184.4	TSN 0					1916.9
WC#: 24.130	AFL		753	TSN 0					472
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					
24-51-37-900-801-02	K3 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:1714138	MOS/MSC	O/C	07-Nov-18	TSN 0					63.1
SN:007681	HRS		2995.9	TSN 0					1105.4
WC#: 24.135	AFL		948	TSN 0					277
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					
24-51-37-900-801-03	K5 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.140	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					
24-51-37-900-801-04	K7 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.145	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					
24-51-37-900-801-05	K8 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:1714138	MOS/MSC	O/C	16-Aug-19	TSN 0					53.8
SN:08357	HRS		3206.3	TSN 0					895
WC#: 24.150	AFL		1004	TSN 0					221
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-51-37-900-801-06	K10 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.155	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					
24-51-37-900-801-07	K11 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:5911739-1	MOS/MSC	O/C	14-Jul-11	TSN 0					150.9
SN:02239	HRS			TSN 0					
WC#: 24.160	AFL			TSN 0					
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					
24-51-37-900-801-08	K13 ACPC ZC-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.165	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801					
24-51-41-900-801-01	K4 CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.170	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801					
24-51-41-900-801-02	K6 CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.175	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801					
24-51-41-900-801-03	K9 CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.180	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801					
24-51-41-900-801-04	K12 CONTACTOR								Component ATA:24
PN:1714139	MOS/MSC	O/C	10-Aug-23	TSN 0					6
SN:05627	HRS		4009.8	TSN 0					91.5
WC#: 24.185	AFL		1193	TSN 0					32
				PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-51-41-900-801-05	K1 CONTACTOR								Component ATA:24
PN:5911747-1	MOS/MSC	O/C	22-Oct-18	TSR 0					63.6
SN:01117	HRS		2978.9	TSR 0					1122.4
WC#: 24.190	AFL		946	TSR 0					279
				PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801					
24-51-53-900-801-01	AC POWER CENTER								Component ATA:24
PN:GL512-1101-19	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0603	HRS		0	TSN 0					4101.3
WC#: 24.195	AFL		0	TSN 0					1225
				PROC. REF: CMM 24-51-02, AMM 24 51 53 000 801, AMM 24 51 53 400 801					
24-52-01-900-801-01	CIRCUIT BREAKER PANEL								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.200	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 52 01 000 801, AMM 24 52 01 400 801					
24-52-05-900-801-01	CCBP H-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.205	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 52 05 000 801, AMM 24 52 05 400 801					
24-61-00-900-801-01	DCPC DC POWER CENTER								Component ATA:24
PN:GL512-3101-15	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0623	HRS		0	TSN 0					4101.3
WC#: 24.210	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 00 000 801, AMM 24 61 00 400 801					
24-61-00-900-801-02	DCPC DC POWER CENTER								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.210	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 00 000 801, AMM 24 61 00 400 801					
24-61-09-900-801-01	NO. 1 DCPC CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.215	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 09 000 801, AMM 24 61 09 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-61-09-900-801-02	NO. 2 DCPC CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.215	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 09 000 801, AMM 24 61 09 400 801					
24-61-09-900-801-03	NO. 3 DCPC CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.215	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 09 000 801, AMM 24 61 09 400 801					
24-61-13-900-801-01	NO. 1 DCPC DCPQM CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.220	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 13 000 801, AMM 24 61 13 400 801					
24-61-13-900-801-02	NO. 2 DCPC DCPQM CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.220	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 13 000 801, AMM 24 61 13 400 801					
24-61-33-900-801-01	DCPC BATTERY/RAT IF CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.225	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 33 000 801, AMM 24 61 33 400 801					
24-61-37-900-801-01	DCPC SPDA FEEDER CARD								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.230	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 37 000 801, AMM 24 61 37 400 801					
24-61-53-900-801-01	K1 DCPC L-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.235	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
24-61-53-900-801-02	K2 DCPC L-SERIES CONTACTOR								Component ATA:24
PN:5911746-1	MOS/MSC	O/C	03-Dec-18	TSN 0					62.3
SN:04982	HRS			TSN 0					
WC#: 24.240	AFL		949	TSN 0					276
				PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801					
24-61-53-900-801-03	K3 DCPC L-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.245	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801					
24-61-53-900-801-04	K4 DCPC L-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.250	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801					
24-61-53-900-801-05	K5 DCPC L-SERIES CONTACTOR								Component ATA:24
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 24.255	AFL		0	TSN 0					1225
				PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801					
24-62-01-900-801-01	NO. 1 SPDA SECONDARY POWER DISTRIBUTION								Component ATA:24
PN:GL512-3201-13	MOS/MSC	O/C	03-Sep-15	TSN 69					101.3
SN:1983	HRS		1748.9	TSN 1748.9					2352.4
WC#: 24.260	AFL		646	TSN 646					579
				PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801					
24-62-01-900-801-02	NO. 2 SPDA SECONDARY POWER DISTRIBUTION								Component ATA:24
PN:GL512-3201-13	MOS/MSC	O/C	21-Jun-11						151.7
SN:2128	HRS		43.3						4058
WC#: 24.260	AFL		15						1210
				PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801					
24-62-01-900-801-03	NO. 3 SPDA SECONDARY POWER DISTRIBUTION								Component ATA:24
PN:GL512-3201-13	MOS/MSC	O/C	06-Nov-18						63.2
SN:1053	HRS		2987.5						1113.8
WC#: 24.260	AFL		947						278
				PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
24-62-01-900-801-04	NO. 4 SPDA SECONDARY POWER DISTRIBUTION								Component	ATA:24
PN:GL512-3201-13	MOS/MSC	O/C	22-Oct-18						63.6	
SN:0628	HRS		2978.9						1122.4	
WC#: 24.260	AFL		946						279	
				PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801						
24-62-05-900-801-01	APU START (ASCA) CONTACTOR								Component	ATA:24
PN:GL512-3301-11	MOS/MSC	O/C	21-Jun-11	TSR 0					151.7	
SN:0680	HRS		43.3	TSR 0					4058	
WC#: 24.265	AFL		15	TSR 0					1210	
				PROC. REF: AMM 24 62 05 000 801, AMM 24 62 05 400 801						
24-64-00-201[S]	OPERATIONAL TEST OF THE DC OVERRIDE SYSTEM								Service	ATA:24
	MOS		30-Nov-23						2.4	
	HRS	500 (+50/-50)	4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 24 64 00 710 801						PKG:2
24-70-01-900-801-01	LH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT								Component	ATA:24
PN:GL542-3101-19	MOS/MSC	O/C	10-Apr-12						142	
SN:1238	HRS		435.8						3665.5	
WC#: 24.270	AFL		156						1069	
				PROC. REF: AMM 24 70 01 000 801, AMM 24 70 01 400 801						
24-70-01-900-801-02	RH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT								Component	ATA:24
PN:GL542-3101-19	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1520	HRS		0	TSN 0					4101.3	
WC#: 24.270	AFL		0	TSN 0					1225	
				PROC. REF: AMM 24 70 01 000 801, AMM 24 70 01 400 801						
241202-001	NO. 1 ENGINE - VFG OIL AIR COOLED COOLER								Component	ATA:24
PN:50043001-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:50043-1398	HRS		0	TSN 0					4101.3	
WC#: 24.005	ENC		0	TSN 0					1228	
				PROC. REF: GENERIC NO REF						
241202-001	NO. 2 ENGINE - VFG OIL AIR COOLED COOLER								Component	ATA:24
PN:50043001-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:50043-1400	HRS		0	TSN 0					4101.3	
WC#: 24.005	ENC		0	TSN 0					1228	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
241202-002	NO. 1 ENGINE - VFG OIL AIR COOLED COOLER								Component ATA:24
PN:50042001-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:50042-1375	HRS		0	TSN 0					4101.3
WC#: 24.005	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
241202-002	NO. 2 ENGINE - VFG OIL AIR COOLED COOLER								Component ATA:24
PN:50042001-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:50042-1374	HRS		0	TSN 0					4101.3
WC#: 24.005	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
246121-701 U	SSPC - K-8 SOLID STATE POWER CONTROLLER								Component ATA:24
PN:5915531	MOS/MSC	O/C	03-Dec-18	TSN 0					62.3
SN:007175	HRS		3006.2	TSN 0					1095.1
	AFL		949	TSN 0					276
247010-701 U	DC POWER DISTRIBUTION EQUIPMENT #1 UNIT								Component ATA:24
PN:10718B01E01	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051537A	HRS		15.6						4085.7
	AFL		7						1218
247010-702 U	DC POWER DISTRIBUTION EQUIPMENT #2 UNIT								Component ATA:24
PN:10718B01E01	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051538A	HRS		15.6						4085.7
	AFL		7						1218
247010-703 U	DC POWER DISTRIBUTION EQUIPMENT #3 UNIT								Component ATA:24
PN:10718B01E01	MOS/MSC	O/C	10-Nov-16						87
SN:14012894CA	HRS		2223.2						1878.1
	AFL		760						465
247010-704 U	DC POWER DISTRIBUTION EQUIPMENT #4 UNIT								Component ATA:24
PN:10718B01E01	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051549A	HRS		15.6						4085.7
	AFL		7						1218
247010-705 U	DC POWER DISTRIBUTION EQUIPMENT #5 UNIT								Component ATA:24
PN:10718B01E01	MOS/MSC	O/C	23-Mar-11						154.6
SN:10091641A	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
247010-706 U	DC POWER DISTRIBUTION EQUIPMENT #6 EQUIPMENT								Component ATA:24
PN:10718B01E01	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051548A	HRS		15.6						4085.7
	AFL		7						1218
247011-701 U	NO.1 DCPDE PERSONNALITY MODULE								Component ATA:24
PN:10720B01E00	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051569	HRS		15.6						4085.7
	AFL		7						1218
247011-702 U	NO.2 DCPDE PERSONNALITY MODULE								Component ATA:24
PN:10720B01E00	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051572	HRS		15.6						4085.7
	AFL		7						1218
247011-703 U	NO.3 DCPDE PERSONNALITY MODULE								Component ATA:24
PN:10720B01E00	MOS/MSC	O/C	10-Nov-16	TSN 0					87
SN:14043201	HRS		2223.2	TSN 0					1878.1
	AFL		760	TSN 0					465
247011-704 U	NO.4 DCPDE PERSONNALITY MODULE								Component ATA:24
PN:10720B01E00	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051586	HRS		15.6						4085.7
	AFL		7						1218
247011-705 U	NO.5 DCPDE PERSONNALITY MODULE								Component ATA:24
PN:10720B01E00	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051570	HRS		15.6						4085.7
	AFL		7						1218
247011-706 U	NO.6 DCPDE PERSONNALITY MODULE								Component ATA:24
PN:10720B01E00	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051582	HRS		15.6						4085.7
	AFL		7						1218
247012-701 U	#1 AC POWER DISTRIBUTION EQUIPMENT								Component ATA:24
PN:10719B01E01	MOS/MSC	O/C	13-Nov-12						134.9
SN:09091475CD	HRS		714.9						3386.4
	AFL		271						954

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
247012-702[U]	AC POWER DISTRIBUTION EQUIPMENT #2 UNIT								Component ATA:24
PN:10719B01E01	MOS/MSC	O/C	06-Jun-22	TSR 0					20.2
SN:08020995C	HRS		3781.1	TSR 0					320.2
	AFL		1141	TSR 0					84
247012-703[U]	AC POWER DISTRIBUTION EQUIPMENT #3 UNIT								Component ATA:24
PN:10719B01E01	MOS/MSC	O/C	13-Nov-12						134.9
SN:07020635BD	HRS		714.9						3386.4
	AFL		271						954
247012-704[U]	AC POWER DISTRIBUTION EQUIPMENT #4 UNIT								Component ATA:24
PN:10719B01E01	MOS/MSC	O/C	13-Nov-12						134.9
SN:10061650CD	HRS		714.9						3386.4
	AFL		271						954
247012-705[U]	AC POWER DISTRIBUTION EQUIPMENT #5 UNIT								Component ATA:24
PN:10719B01E01	MOS/MSC	O/C	13-Nov-12						134.9
SN:10061651CD	HRS		714.9						3386.4
	AFL		271						954
247013-701[U]	NO.1 ACPDE PERSONNALITY MODULE								Component ATA:24
PN:10722B01E00	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051408	HRS		15.6						4085.7
	AFL		7						1218
247013-702[U]	NO.2 ACPDE PERSONNALITY MODULE								Component ATA:24
PN:10722B01E00	MOS/MSC	O/C	06-Jun-22	TSN 0					20.2
SN:20114575	HRS		3781.1	TSN 0					320.2
	AFL		1141	TSN 0					84
247013-703[U]	NO.3 ACPDE PERSONNALITY MODULE								Component ATA:24
PN:10722B01E00	MOS/MSC	O/C	23-Mar-11						154.6
SN:10051522	HRS		15.6						4085.7
	AFL		7						1218
247013-704[U]	NO.4 ACPDE PERSONNALITY MODULE								Component ATA:24
PN:10722B01E00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:10051412	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
247013-705 U	NO.5 ACPDE PERSONNALITY MODULE								Component	ATA:24
PN:10722B01E00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:10051418	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
249500-701 U	POWER CONVERTER - LH F.S. 385.0 TOP MODULE								Component	ATA:24
PN:LT-55(F)	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:148	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
249500-702 U	POWER CONVERTER - F.S. 510.0 TOP MODULE								Component	ATA:24
PN:LT-55(F)	MOS/MSC	O/C	23-Mar-11	TSN 0					154.6	
SN:149	HRS		15.6	TSN 0					4085.7	
	AFL		7	TSN 0					1218	
249600-701 U	ELECTRONIC CONTROL MODULE								Component	ATA:24
PN:441-0038-100	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0912000314	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
AW AW700-24-030 U	VFG ROTOR DIODE FAILURE, ADVISORY WIRE								Bulletin	ATA:24
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
FAA 1972-19-04 U	NICKEL-CADMIUM BATTERY								AD	ATA:24
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
FAA 2010-23-08	INSPECT TO DETERMINE THE SERIAL NUMBER OF THE INSTALLED RAM AIR TURBINE (RAT)								AD	ATA:24
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
FAA 2019-12-02	ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR HARNESS LOW CLEARANCE TO HYDRAULIC/FUEL LINES								AD	ATA:24
	MOS/MSC	-	31-Aug-19						53.4	
	HRS		3206.3						895	
	AFL		1004						221	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
FAA 2020-12-14[S]	ELECTRICAL POWER - RAT DEPLOYMENT ACTUATOR - INSPECTION / REPLACEMENT								AD	ATA:24
	MOS/MSC	-	06-Aug-20						42.2	
	HRS		3440.5						660.8	
	AFL		1060						165	
FAA 2020-12-14 PARA (G)	INSPECTION TO DETERMINE THE SERIAL NUMBER (S/N) OF THE RAT DEPLOYMENT ACTUATOR, HAVING PART NUMBER (P/N) BZ02001-01 (GL456-1301-1)								AD	ATA:24
	MOS/MSC	-	06-Aug-20						42.2	
	HRS		3440.5						660.8	
	AFL		1060						165	
FAA 2020-12-14 PARA (H[S])	REPLACE THE RAT DEPLOYMENT ACTUATOR, HAVING P/N BZ02001-01 (GL456-1301-1), WITH AN UPGRADED PART (IF ANY RAT DEPLOYMENT ACTUATOR IS FOUND, POST PARA (G))								AD	ATA:24
	MOS/MSC	-	06-Aug-20						42.2	
	HRS		3440.5						660.8	
	AFL		1060						165	
FAA 2020-12-14 PARA (I)[S]	NO PERSON MAY INSTALL ON ANY AIRPLANE, A RAT DEPLOYMENT ACTUATOR HAVING P/N BZ02001-01 (GL456-1301-1) WITH A SERIAL NUMBER REFERRED TO IN PARAGRAPH 2.B., PART A-SPECIAL CHECK, OF THE ACCOMPLISHMENT INSTRUCTIONS, OF THE APPLICABLE BOMBARDIER SI SPECIFIED IN FIGURE 1 TO PARAS (G)(1) AND (2), (H), AND (I) OF THIS AD								AD	ATA:24
	MOS/MSC	-	06-Aug-20						42.2	
	HRS		3440.5						660.8	
	AFL		1060						165	
MODSUM IS700-24-000[U] REV B	EMS CDU - DISABLING UNUSED THERMAL CIRCUT BREAKER (A/C 9002 - 9184, 9186 - 9999), MODIFICATION SUMMARY								Bulletin	ATA:24
	MOS/MSC	T:A/R								
	HRS									
	AFL									
MODSUM IS700-24-000[U] REV D	EMS CDU - DISABLING UNUSED THERMAL CIRCUIT BREAKER, MODIFICATION SUMMARY								Bulletin	ATA:24
	MOS/MSC	T:A/R								
	HRS									
	AFL									
MODSUM IS700-24-000[U] REV A	CRAWLWAY FLOOR PANEL - ADDITION OF PROTECTIVE TAPE, MODIFICATION SUMMARY								Bulletin	ATA:24
	MOS/MSC	A/R								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-029	MODIFICATION - ELECTRICAL MANAGEMENT SYSTEM (EMS) - CONTROL AND DISPLAY UNIT (CDU) REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-030	SPECIAL CHECK - AC POWER CENTER (ACPC) - POSSIBLE CRACKING ON ACPC CHASSIS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-031	MODIFICATION - DC POWER CENTER (DCPC) - DCPC BLOCK 1A OR 1A+ HARDWARE MODIFICATION FOR BLOCK 2, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-032	MODIFICATION - SECONDARY POWER DISTRIBUTION - SECONDARY POWER DISTRIBUTION ASSEMBLY (SPDA) UNIT REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-033	MODIFICATION - SECONDARY POWER DISTRIBUTION - APU STARTER CONTACTOR ASSEMBLY (ASCA) HARDWARE MODIFICATION FOR BLOCK 2, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-034	MODIFICATION - AC POWER CENTER (ACPC) - ACPC BLOCK 1A OR 1A+ HARDWARE MODIFICATION FOR BLOCK 2, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-036	MODIFICATION - COCKPIT CIRCUIT BREAKER PANEL - RELOCATION OF WIRING AC BUS 1 AND AC BUS 3, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-037 PART (A)	MODIFICATION - BATTERY SYSTEM - REMOVAL OF APU BATTERY SUMP JAR AND ACCESS IMPROVEMENT TO THE APU BATTERY CONNECTOR, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-037 PART (B)	MODIFICATION - BATTERY SYSTEM - REMOVAL OF APU BATTERY SUMP JAR AND ACCESS IMPROVEMENT TO THE APU BATTERY CONNECTOR, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-038	MODIFICATION - EXTERNAL AC POWER - ELIMINATE STRESS ON AC POWER RECEPTACLE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-24-040	MODIFICATION - SECONDARY POWER DISTRIBUTION - INCREASED FUSE RATING FOR THE APU START-CONTACTOR ASSEMBLY (ASCA), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-041	MODIFICATION - ELECTRICAL POWER - BUILD 4 CABIN WIRING PROVISION, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-042	MODIFICATION - EMERGENCY AC-POWER SUPPLY - RESOLUTION OF RAT GENERATOR OVERRIDE ANOMALY, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-043 PART (A)	SPECIAL CHECK/MODIFICATION - GENERAL - VISUAL CHECK OF THE EMS CDU, ACPC, DCPC AND SPDA PART NUMBER/SERIAL NUMBER AND REPLACEMENT/MODIFICATION OF THE UNITS IDENTIFIED TO CONTAIN DEFECTIVE TRANSCEIVER MICROCIRCUITS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-043 PART (B)	SPECIAL CHECK/MODIFICATION - GENERAL - VISUAL CHECK OF THE EMS CDU, ACPC, DCPC AND SPDA PART NUMBER/SERIAL NUMBER AND REPLACEMENT/MODIFICATION OF THE UNITS IDENTIFIED TO CONTAIN DEFECTIVE TRANSCEIVER MICROCIRCUITS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-044	SPECIAL CHECK - DC POWER CENTER (DCPC) - CHECK FOR FOD INSIDE THE DC POWER CENTER (DCPC), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-044 REV 01	SPECIAL CHECK - DC POWER CENTER (DCPC) - CHECK FOR FOD INSIDE THE DC POWER CENTER (DCPC), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-045	MODIFICATION - AC AND DC POWER DISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-045 REV 01 PART 1	MODIFICATION - AC AND DC POWER DISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-045 REV 01 PART 2	MODIFICATION - AC AND DC POWER DISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-045 REV 02 PART 1	MODIFICATION - AC AND DC POWER DISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-045 REV 02 PART 2	MODIFICATION - AC AND DC POWER DISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM - (RETROACTIVE ACTION), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-046	SPECIAL CHECK/REWORK - BATTERY SYSTEM - INSPECT AVIONICS BATTERY WIRE LUGS AND REPLACE, IF NECESSARY, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-047	MODIFICATION - ELECTRICAL CONTROL - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS) SOFTWARE FOR GENERATOR CONTROL UNIT (GL511-3103), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-048	SPECIAL CHECK/REWORK - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAT LINE CONTACTOR (RATLC), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-049	MODIFICATION - SECONDARY POWER DISTRIBUTION - APU STARTER CONTACTOR ASSEMBLY (ASCA) ACCESS IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-049 REV 01	MODIFICATION - SECONDARY POWER DISTRIBUTION - APU STARTER CONTACTOR ASSEMBLY (ASCA) ACCESS IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-050	MODIFICATION - BATTERY SYSTEM - RE-ROUTING OF THE APU BATTERY VENT TUBE TO IMPROVE VENTILATION OF THE APU BATTERY GASES, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-050 REV 01	MODIFICATION - BATTERY SYSTEM - RE-ROUTING OF THE APU BATTERY VENT TUBE TO IMPROVE VENTILATION OF THE APU BATTERY GASES (A/C 9002 TO 9149), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-051 PART (A)	SPECIAL CHECK/REWORK - DC POWER CONVERSION - VERIFICATION OF ELECTRICAL TERMINAL LUGS INSTALLED ON THE AUXILIARY (AUX) TRANSFORMER RECTIFIER UNIT (TRU) WIRES AND REWORK OF THE POWER FEEDERS TO THE CABIN TRU BUS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-051 PART (B)	SPECIAL CHECK/REWORK - DC POWER CONVERSION - VERIFICATION OF ELECTRICAL TERMINAL LUGS INSTALLED ON THE AUXILIARY (AUX) TRANSFORMER RECTIFIER UNIT (TRU) WIRES AND REWORK OF THE POWER FEEDERS TO THE CABIN TRU BUS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-051 PART (C)	SPECIAL CHECK/REWORK - DC POWER CONVERSION - VERIFICATION OF ELECTRICAL TERMINAL LUGS INSTALLED ON THE AUXILIARY (AUX) TRANSFORMER RECTIFIER UNIT (TRU) WIRES AND REWORK OF THE POWER FEEDERS TO THE CABIN TRU BUS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-052	MODIFICATION - BATTERY SYSTEM - ADDITION OF A SPIGOT TO THE APU BATTERY VENT FITTING TO PREVENT FUEL FROM ENTERING THE BATTERY CASE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-053	MODIFICATION - BATTERY SYSTEM - COOLING INSTALLATION FOR THE FORWARD EQUIPMENT COMPARTMENT (A/C EFFECTIVITY : S/N 9002 TO 9164), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-054	SPECIAL CHECK/REWORK/MODIFICATION - DC POWER CONVERSION - TRU 2 FEEDER WIRE CHAFING (EFFECTIVITY A/C S/N 9002 TO 9070, 9126, 9128, 9129, 9131 TO 9139, 9141 TO 9148, 9150, 9151, 9153, 9159 AND 9162), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-056	MODIFICATION - BATTERY SYSTEM - DEACTIVATION OF THE AUXILIARY POWER UNIT (APU) AND AVIONICS BATTERY HEATER BLANKETS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-056 REV 01	MODIFICATION - BATTERY SYSTEM - DEACTIVATION OF THE AUXILIARY POWER UNIT (APU) AND AVIONICS BATTERY HEATER BLANKETS (A/C 9002 TO 9126, 9128, 9129, 9131 TO 9189), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-057	MODIFICATION - PRIMARY AC-POWER SUPPLY - UPGRADE VARIABLE FREQUENCY GENERATOR FROM PART NUMBER GL511-1103-1 TO GL511-1103-5 (A/C 9002 TO 9108), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-059	SPECIAL CHECK/MODIFICATION - ELECTRICAL CONTROL - VISUAL CHECK OF THE SERIAL NUMBER FOR THE GENERATOR CONTROL UNIT (GCU), P/N GL511-3104-1 AND REPLACEMENT OF THE AFFECTED UNITS (EFFECTIVITY 9117,9162 TO 9167,9169), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-061	MOD - AC AND DC POWER DISTRIBUTION - BUILD 6.0 ELECTRICAL SYSTEM UPGRADE (A/C S/N 9149 TO 9169), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-062	MODIFICATION - AC AND DC POWER DISTRIBUTION - REPLACEMENT OF UNITS FOR ACTIVATION OF BUILD 6.0 UPGRADE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-062 REV 01	MODIFICATION - AC AND DC POWER DISTRIBUTION - REPLACEMENT OF UNITS FOR ACTIVATION OF BUILD 6.0 UPGRADE (A/C 9002 TO 9148), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-063	MODIFICATION - AC AND DC POWER DISTRIBUTION - ACPC AND DCPC IMPROVEMENTS (A/C 9002 TO 9148), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-063 REV 01	AC AND DC POWER DISTRIBUTION - ACPC AND DCPC IMPROVEMENTS (A/C 9002 TO 9148), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-065	MODIFICATION - COCKPIT CIRCUIT-BREAKER PANEL (CCBP) AC CIRCUITS - REWORK OF THE CCBP FOR THE ENHANCED VISION SYSTEM (EVS). EFFECTIVITY S/N 9002 TO 9156., SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-24-066	MODIFICATION - BATTERY SYSTEM - UPGRADE BATTERY CHARGERS TO PART NO. GL511-2401-9 (A/C 9002 TO 9193), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-066 REV 01	MODIFICATION - BATTERY SYSTEM - UPGRADE BATTERY CHARGERS TO PART NO. GL511-2401-9, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-067	MODIFICATION - AC POWER CENTER (ACPC) - REPLACE DEFECTIVE AC TO DC CONVERTER ASSEMBLY (A/C 9149 TO 9169 POST SB 700-24-061 BASIC ISSUE, A/C 9002 TO 9149 POST SB 700-24-063 BASIC ISSUE, AND A/C 9170 TO 9218), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-068 PART (A)	MODIFICATION - EMERGENCY AC POWER SUPPLY - REPLACE RAM AIR TURBINE (RAT) WITH DEFECTIVE BEARING SHIELD (A/C 9002 TO 9234), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-068 PART (B)	MODIFICATION - EMERGENCY AC POWER SUPPLY - REPLACE RAM AIR TURBINE (RAT) WITH DEFECTIVE BEARING SHIELD (A/C 9002 TO 9234), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-068 REV 01	ICA - MODIFICATION - EMERGENCY AC POWER SUPPLY - REPLACE RAM AIR TURBINE (RAT) WITH DEFECTIVE BEARING SHIELD, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-069	MODIFICATION - EMERGENCY AC POWER SUPPLY - REPLACE UPLOCK ROLLER ASSEMBLY ON RAM AIR TURBINE (RAT) (A/C 9180 TO 9259), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-070	MODIFICATION - DC ELECTRICAL LOAD DISTRIBUTION - REROUTE WIRING TO SUPPLY CABIN POWER IN GROUND SERVICE MODE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-071 PART (A)	REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-071 PART (B)	REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-071 REV 01	REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-071 REV 01 PART (A)	REWORK REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE, SERVICE BULLETIN – GENERAL – PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-071 REV 01 PART (B)	REWORK REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE, SERVICE BULLETIN – GENERAL – PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-071 REV 02	ICA - REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-073 REV 02	MODIFICATION - SECONDARY POWER SYSTEM - REPLACE APU START CONTACTOR ASSEMBLY (ASCA) AND DC POWER CENTER (DCPC) DUE TO AN UNRELIABLE P700 SSPC, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-24-073 REV 1[U]	MODIFICATION - SECONDARY POWER SYSTEM - REPLACE APU START CONTACTOR ASSEMBLY (ASCA) AND DC POWER CENTER (DCPC) DUE TO AN UNRELIABLE P700 SSPC, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-24-074	MODIFICATION - POWER CONVERTER SYSTEM - INSTALLATION OF A NEW FUSE IN THE FREQUENCY GENERATOR OUTPUT LINE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-075	SPECIAL CHECK/REWORK - EMERGENCY AC-POWER - INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-075 PART (A)	PERFORM SPECIAL CHECK/REWORK - EMERGENCY AC-POWER - INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN - INSPECTION								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-075 PART (B)	PERFORM SPECIAL CHECK/REWORK - EMERGENCY AC-POWER - INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN - REPLACEMENT OF BALANCE SCREWS								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-075 REV 01	SPECIAL CHECK/REWORK - EMERGENCY AC-POWER - INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-075 REV 01 PART (A)	PERFORM SPECIAL CHECK/REWORK - EMERGENCY AC-POWER - INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN - INSPECTION								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-075 REV 01 PART (B)	PERFORM SPECIAL CHECK/REWORK - EMERGENCY AC-POWER - INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN - REPLACEMENT OF ALL BALANCE SCREWS								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-075 REV 02	SPECIAL CHECK/REWORK - EMERGENCY AC-POWER - INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-075 REV 02 PART (A)	INSPECT SPECIAL CHECK/REWORK - EMERGENCY AC-POWER -INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN SUSPECT BALANCE SCREWS ON RAT								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-075 REV 02 PART (B)	REPLACEMENT SPECIAL CHECK/REWORK - EMERGENCY AC-POWER -INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN OF ALL BALANCE SCREWS								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-076	ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-24-076 PART (A)	REWORK ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL, SERVICE BULLETIN ALL FOUR VFGS								Bulletin ATA:24
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-24-076 PART (B)	REWORK ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL, SERVICE BULLETIN THREE OR LESS VFGS								Bulletin ATA:24
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-24-076 PART (C)	MODIFICATION ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL, SERVICE BULLETIN OF THE VFG OIL PLATE								Bulletin ATA:24
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-24-077	MODIFICATION – MAIN GENERATOR OIL SYSTEM – INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
SB 700-24-077 REV 01	MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-24-077 REV 01 PART (A)	ACCOMPLISH MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN MODIFICATION								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-24-077 REV 01 PART (B)	ACCOMPLISH MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN MODIFICATION								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-24-077 REV 02	MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-24-077 REV 02 PART (A)	ACCOMPLISH MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN MODIFICATION								Bulletin	ATA:24
	MOS/MSC	-	27-Apr-12						141.5	
	HRS		443.4						3657.9	
	AFL		160						1065	
SB 700-24-077 REV 02 PART (B)	ACCOMPLISH MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN MODIFICATION								Bulletin	ATA:24
	MOS/MSC	-	04-Sep-12						137.2	
	HRS									
	AFL									
SB 700-24-077 REV 02 S PART (C)	ACCOMPLISH MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN MODIFICATION								Bulletin	ATA:24
	MOS									
	HRS	T:3000								
	AFL									

PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-077 REV 02 PART (D) S	ACCOMPLISH MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN MODIFICATION								Bulletin ATA:24
	MOS								
	HRS	T:3000							
	AFL								
									PKG:8
SB 700-24-078	MODIFICATION - MAIN GENERATOR OIL SYSTEM - ADDITION OF HIGH CONDUCTIVITY OIL TO DISSIPATE ELECTRO STATIC DISCHARGE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	03-Nov-11						147.3
	HRS		227.8						3873.5
	AFL		100						1125
SB 700-24-079	MODIFICATION - DC POWER CENTER (DCPC) - INSTALLATION OF A BRACKET TO THE CIRCUIT BREAKER BOX ASSEMBLY FOR THE TRU FEEDER CABLE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-080	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	06-Jul-12						139.2
	HRS		541.7						3559.6
	AFL		200						1025
SB 700-24-080 PART (A)	CHECK MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	06-Jul-12						139.2
	HRS		541.7						3559.6
	AFL		200						1025
SB 700-24-080 PART (B)	INSPECTION MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	06-Jul-12						139.2
	HRS		541.7						3559.6
	AFL		200						1025
SB 700-24-080 PART (C)	REPLACEMENT MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	06-Jul-12						139.2
	HRS		541.7						3559.6
	AFL		200						1025

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-081	MODIFICATION - ELECTRICAL POWER - BUS BAR HARNESS CLAMP REPLACEMENT IN THE LEFT HAND SIDE CIRCUIT BREAKER PANEL, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	13-Nov-12						134.9
	HRS		714.9						3386.4
	AFL		271						954
SB 700-24-082	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-082 REV 01	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	01-Aug-14						114.3
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-24-082 REV 02	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	30-Oct-14						111.4
	HRS		1448.1						2653.2
	AFL		555						670
SB 700-24-082 REV 03	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VARIABLE FREQUENCY GENERATOR (VFG) VIBRATION GROUND TEST, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-083	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	16-Jul-15						102.8
	HRS		1712.9						2388.4
	AFL		624						601
SB 700-24-084	SPECIAL CHECK/MODIFICATION - ELECTRICAL POWER - INSTALLATION OF BOOT COVER ON THE FREQUENCY CONVERTER CIRCUIT BREAKER INSTALLATION, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	18-Mar-14						118.8
	HRS		1278.5						2822.8
	AFL		496						729

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-085	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	26-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-24-085 PART (A)	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN SPECIAL CHECK								Bulletin ATA:24
	MOS/MSC	-	26-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-24-085 PART (B)	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN REPLACEMENT OF VFG(S)								Bulletin ATA:24
	MOS/MSC	-	26-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-24-086	MODIFICATION - DC POWER CENTER (DCPC) - ADD CBC1 TERMINAL INSULATOR ON CHASSIS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-24-086 REV 01	MODIFICATION - DC POWER CENTER (DCPC) - ADD CBC1 TERMINAL INSULATOR ON CHASSIS, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-087	SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	19-Dec-17						73.7
	HRS		2670.5						1430.8
	AFL		875						350
SB 700-24-087 PART A	ACCOMPLISH, SERVICE BULLETIN VFG TORQUE AND SERIAL NUMBER CHECK								Bulletin ATA:24
	MOS/MSC	-	17-Dec-17						73.8
	HRS		2670.5						1430.8
	AFL		875						350

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-087 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECT VFG HOUSING WALL THICKNESS								Bulletin ATA:24
	MOS/MSC	-	19-Dec-17						73.7
	HRS		2670.5						1430.8
	AFL		875						350
SB 700-24-087 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF VFG								Bulletin ATA:24
	MOS/MSC	-	19-Dec-17						73.7
	HRS		2670.5						1430.8
	AFL		875						350
SB 700-24-087 REV 01	SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-087 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN VFG TORQUE AND SERIAL NUMBER CHECK								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-087 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECT VFG HOUSING WALL THICKNESS								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-087 REV 01 S PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF VFG								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-088	MODIFICATION - CIRCUIT BREAKER - CABIN FIXED FREQUENCY MAIN CIRCUIT BREAKER, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
SB 700-24-088 REV 01	MODIFICATION - CIRCUIT BREAKER - CABIN FIXED FREQUENCY MAIN CIRCUIT BREAKER, SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-24-089	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-	14-Jul-18						66.9	
	HRS		2892.3						1209	
	AFL		921						304	
SB 700-24-089 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INSTALLATION OF ADDITIONAL CLAMPS								Bulletin	ATA:24
	MOS/MSC	-	14-Jul-18						66.9	
	HRS		2892.3						1209	
	AFL		921						304	
SB 700-24-089 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - CUTTING THE ELECTRICAL WIRES TO MEET INSTALLATION REQUIREMENTS (IF NECESSARY)								Bulletin	ATA:24
	MOS/MSC	-	14-Jul-18						66.9	
	HRS		2892.3						1209	
	AFL		921						304	
SB 700-24-089 REV 01	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-24-089 REV 01 PART A	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN MODIFICATION - INSTALLATION OF ADDITIONAL CLAMPS								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-24-089 REV 01 PART B	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN MODIFICATION - CUTTING THE ELECTRICAL WIRES TO MEET INSTALLATION REQUIREMENTS (IF NECESSARY)								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 24 - ELECTRICAL POWER									
SB 700-24-089 REV 02	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-089 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INSTALLATION OF ADDITIONAL CLAMPS								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-089 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - CUTTING THE ELECTRICAL WIRES TO MEET INSTALLATION REQUIREMENTS (IF NECESSARY)								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-24-090	SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1), SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-24-090 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1), SERVICE BULLETIN SPECIAL CHECK								Bulletin ATA:24
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-24-090 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1), SERVICE BULLETIN MODIFICATION								Bulletin ATA:24
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB BR700-24-100384 R01	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN								Bulletin ATA:24
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
SB BR700-24-100384 R01	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-24-102120	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR - INTRODUCTION OF TWO ALTERNATIVE SPAREABLE NUTS FOR THE V-CLAMP ASSEMBLY OF THE VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-24-102120	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR - INTRODUCTION OF TWO ALTERNATIVE SPAREABLE NUTS FOR THE V-CLAMP ASSEMBLY OF THE VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-24-102261	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR - INTRODUCTION OF A REVISED V-CLAMP ASSEMBLY FOR THE REARWARD INSTALLED VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-24-102261	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR - INTRODUCTION OF A REVISED V-CLAMP ASSEMBLY FOR THE REARWARD INSTALLED VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN								Bulletin	ATA:24
	MOS/MSC	-								
	HRS									
	ENC									
SPI PDE-6100-44-2 U	COLLINS S/B PDE-6100-44-2 STEPS 3A, 3B AND 3C, SPECIAL INSTRUCTION								Bulletin	ATA:24
	MOS/MSC	-	14-Nov-12						134.9	
	HRS		714.9						3386.4	
	AFL		271						954	
TCCA CF-1996-21 U	NICKEL-CADMIUM BATTERY								AD	ATA:24
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 24 - ELECTRICAL POWER										
TCCA CF-2010-01	RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS								AD	ATA:24
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
TCCA CF-2010-01 PART (I)	IDENTIFICATION RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS CHECK								AD	ATA:24
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
TCCA CF-2010-01 PART (II)	REPLACEMENT RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS OF THE BALANCE WASHER SCREWS AND IDENTIFICATION OF THE RAT								AD	ATA:24
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
ATA 25 - EQUIPMENT/FURNISHINGS										
25-00-CUS-001[U]	MONITORING GMU/HMU HEIGHT								Service	ATA:25
	MOS	24	28-May-23		31-May-25		475 d	31-May-2025	8.5	
	HRS	1000	3954.3		4954.3		853		147	
	AFL		1179						46	
25-01-52-602[U]	DISCARD PADDLE LATCH STRIKERS								Service	ATA:25
	MOS		20-Dec-09					29-Dec-2043	169.7	
	HRS		0						4101.3	
	AFL	6000	0		6000		4775		1225	
25-11-00-900-801-01	PILOT SEAT								Component	ATA:25
PN:GC721-1001-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:149-1400	HRS		0	TSN 0					4101.3	
WC#: 25.015	AFL		0	TSN 0					1225	
			PROC. REF: AMM 25 11 00 000 801, AMM 25 11 00 400 801							
25-11-00-900-801-02	COPILOT SEAT								Component	ATA:25
PN:GC721-1001-2	MOS/MSC	O/C	22-Aug-18						65.6	
SN:108-1400	HRS		2918.3						1183	
WC#: 25.015	AFL		930						295	
			PROC. REF: AMM 25 11 00 000 801, AMM 25 11 00 400 801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
25-11-05-201 S	OPERATIONAL TEST OF THE INERTIA REELS AND THE INERTIA REELS CONTROL								Service	ATA:25
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 25.005	AFL		1223						2	
				PROC. REF: AMM 25 11 05 710 801						PKG:4
25-11-09-201 S	GENERAL VISUAL INSPECTION OF THE SAFETY STRAPS								Service	ATA:25
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 25.010	AFL		1223						2	
				PROC. REF: AMM 25 11 09 210 801						PKG:4
25-13-01-900-801-01	LH PILOT FLOOR MAT HEATER								Component	ATA:25
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801						
25-13-01-900-801-02	RH PILOT FLOOR MAT HEATER								Component	ATA:25
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801						
25-13-01-900-801-03	LH COPILOT FLOOR MAT HEATER								Component	ATA:25
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801						
25-13-01-900-801-04	RH COPILOT FLOOR MAT HEATER								Component	ATA:25
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801						
25-13-50-601 U S	OPERATIONAL TEST OF JUMPSEAT INERTIA REELS								Service	ATA:25
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
25-13-50-602 U S	GENERAL VISUAL INSPECTION OF JUMPSEAT SAFETY STRAPS								Service	ATA:25
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
25-13-50-603 U S	OPERATIONAL TEST OF THE JUMPSEAT TRACKING AND LOCKING MECHANISMS								Service	ATA:25
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
25-21-00-601 U S	DETAILED INSPECTION OF PASSENGER SEATS (INCLUDING DIVANS) FOR ATTACHMENT AND LOCKING								Service	ATA:25
	MOS	30	30-Dec-22						13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
										PKG:32
25-21-00-602 U S	DETAILED INSPECTION OF PASSENGER SEATS RESTRAINTS								Service	ATA:25
	MOS	30	30-Dec-22						13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
										PKG:32
25-21-00-603 U S	OPERATIONAL CHECK OF PASSENGER SEAT INERTIA REELS (INCLUDING DIVANS)								Service	ATA:25
	MOS	30	30-Dec-22						13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
										PKG:32
25-30-50-601 U S	GENERAL VISUAL INSPECTION OF GALLEY WASTE CONTAINER								Service	ATA:25
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
25-30-50-602 U S	GENERAL VISUAL INSPECTION OF GALLEY APPLIANCES								Service	ATA:25
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
25-30-50-605 U S	REPLACEMENT OF THE GALLEY CHILLER AIR FILTER								Service	ATA:25
	MOS		06-Dec-23						2.2	
	HRS	500	4099.1						2.2	
	AFL		1223						2	
										PKG:2
25-40-50-601 U S	GENERAL VISUAL INSPECTION OF LAVATORY WASTE CONTAINER								Service	ATA:25
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
25-60-00-201	RESTORATION COPILOT LIFE VEST (25-60-00-201)								Service	ATA:25
PN:P0723E105PWC	MOS	60	27-Dec-23		31-Dec-28		1785 d	31-Dec-2028	1.5	
SN:10120010006	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 25 60 00 840 802						
25-60-00-201	RESTORATION PILOT LIFE VEST (25-60-00-201)								Service	ATA:25
PN:P0723E105PWC	MOS	60	27-Dec-23		31-Dec-28		1785 d	31-Dec-2028	1.5	
SN:10120010005	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 25 60 00 840 802						
25-60-00-202	RESTORATION COCKPIT (LH FS280) PROTECTIVE BREATHING EQUIPMENT - PBE (25-60-00-202)								Service	ATA:25
PN:119003-21	MOS	126	08-Jul-16		31-Jan-27		1085 d	31-Jan-2027	91.1	
SN:004-13452M	HRS									
	AFL									
				PROC. REF: AMM 25 60 00 840 801						
25-60-00-203	DISCARD COCKPIT (LH FS280) PROTECTIVE BREATHING EQUIPMENT - PBE (25-60-00-203)								Service	ATA:25
PN:119003-21	MOS	126	08-Jul-16		31-Jan-27		1085 d	31-Jan-2027	91.1	
SN:004-13452M	HRS									
	AFL									
				PROC. REF: AMM 25 60 00 960 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
25-60-00-208[S]	DETAILED INSPECTION COPILOT LIFE VEST (25-60-00-208)								Service	ATA:25
PN:P0723E105PWC	MOS		27-Dec-23						1.5	
SN:10120010006	HRS	1000 (+50/-50)	4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 25 60 00 220 801						PKG:4
25-60-00-208[S]	DETAILED INSPECTION PILOT LIFE VEST (25-60-00-208)								Service	ATA:25
PN:P0723E105PWC	MOS		27-Dec-23						1.5	
SN:10120010005	HRS	1000 (+50/-50)	4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 25 60 00 220 801						PKG:4
25-60-00-209[S]	DETAILED INSPECTION COCKPIT (LH FS280) PROTECTIVE BREATHING EQUIPMENT - PBE (25-60-00-209)								Service	ATA:25
PN:119003-21	MOS		06-Dec-23						2.2	
SN:004-13452M	HRS	1000 (+50/-50)	4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 25 60 00 220 802						PKG:4
25-60-00-601[U S]	DETAILED INSPECTION OF THE DITCHING LINES								Service	ATA:25
	MOS	15	06-Dec-23						2.2	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
25-60-00-602[U S]	DETAILED INSPECTION OF THE LIFE VESTS								Service	ATA:25
	MOS	15	29-Dec-23						1.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
25-60-00-604[U]	DETAILED INSPECTION OF THE LIFE RAFTS								Service	ATA:25
	MOS	15	06-Dec-23		31-Mar-25		414 d	31-Mar-2025	2.2	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
25-60-00-900-801-01	PILOT LIFE VEST								Component	ATA:25
PN:P0723E105PWC	MOS/MSC	O/C	29-Dec-23	TSN 156					1.4	
SN:10120010005	HRS		4099.1	TSN 4083.5, TSO 0					2.2	
	AFL		1223	TSN 1216, TSO 0					2	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
25-60-00-900-801-02	COPILOT LIFE VEST								Component ATA:25
PN:P0723E105PWC	MOS/MSC	O/C	29-Dec-23	TSN 156					1.4
SN:10120010006	HRS		4099.1	TSN 4083.5, TSO 0					2.2
	AFL		1223	TSN 1216, TSO 0					2
				PROC. REF: GENERIC NO REF					
25-60-00-900-802-01	COCKPIT (LH FS280) PROTECTIVE BREATHING EQUIPMENT - PBE								Component ATA:25
PN:119003-21	MOS/MSC	H/T	27-Jul-16	TSN 0					90.5
SN:004-13452M	HRS		2078.9	TSN 0					2022.4
	AFL		719	TSN 0					506
				PROC. REF: CMM 25-2499-200					
25-60-52-601[U]	DETAILED INSPECTION OF THE CREW FLASHLIGHTS								Service ATA:25
	MOS	12	22-Dec-23		31-Dec-24		324 d	31-Dec-2024	1.6
	HRS		4099.1						2.2
	AFL		1223						2
25-61-00-201	OPERATIONAL TEST EMERGENCY LOCATOR TRANSMITTER SYSTEM (25-61-00-201)								Service ATA:25
PN:453-5004	MOS	45 (+3m/-3m)	30-Dec-22	Adj 3	31-Dec-26	31-Mar-27	1054 d (+90)	31-Dec-2026	13.4
SN:170-11429	HRS		3913.7						187.6
WC#: 25.020	AFL		1171						54
				PROC. REF: AMM 25 61 00 710 801					
25-61-01-201	DISCARD ELT BATTERY (25-61-01-201)								Service ATA:25
PN:452-0133	MOS/MSC	DUE	14-Dec-23		01-Feb-29 (M)		1817 d	01-Feb-2029	1.9
SN:1005122-040	HRS		4099.1						2.2
WC#: 25.020	AFL		1223						2
				PROC. REF: AMM 25 61 01 961 801					
25-61-01-900-801-01	EMERGENCY LOCATOR TRANSMITTER								Component ATA:25
PN:453-5004	MOS/MSC	O/C	09-Jun-16	TSN 78					92.1
SN:170-11429	HRS		2046.9	TSN 2046.9					2054.4
WC#: 25.020	AFL		711	TSN 711					514
				PROC. REF: AMM 25 61 01 000 801, AMM 25 61 01 400 801					
25-61-01-900-802-01	ELT BATTERY								Component ATA:25
PN:452-0133	MOS/MSC	O/C	14-Dec-23						1.9
SN:1005122-040	HRS		4099.1						2.2
	AFL		1223						2
				PROC. REF: AMM 25 61 01 000 802, AMM 25 61 01 400 802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
25-61-05-900-801-01	ELT ANTENNA								Component ATA:25
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 25.025	AFL		0	TSN 0					1225
				PROC. REF: AMM 25 61 05 000 801, AMM 25 61 05 400 801					
25-61-17-900-801-01	L/H ELT NAV INTERFACE UNIT								Component ATA:25
PN:453-6500	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:08149	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 25 61 17 000 801, AMM 25 61 17 400 801					
25-65-52-601	FUNCTIONAL TEST OF THE UNDERWATER LOCATING DEVICE								Service ATA:25
	MOS	24 (+3m/-3m)	30-Dec-22	Adj 3	30-Mar-25	30-Jun-25	413 d (+92)	30-Mar-2025	13.4
	HRS		3913.7						187.6
	AFL		1171						54
				PROC. REF: GENERIC NO REF					
25-65-52-602	DISCARD THE UNDERWATER LOCATING DEVICE								Service ATA:25
PN:DK180	MOS	72 (+3m/-3m)	30-Dec-22		01-Jan-28 (M)	04-Jan-28	1420 d (+3)	01-Jan-2028	13.4
SN:DF17079	HRS		3913.7						187.6
	AFL		1171						54
				PROC. REF: GENERIC NO REF					
25-65-52-900-801-01	UNDERWATER LOCATING DEVICE - LOW FREQUENCY (8.8KHZ)								Component ATA:25
PN:DK180	MOS/MSC	H/T	30-Dec-22	TSN 0					13.4
SN:DF17079	HRS		3913.7	TSN 0					187.6
	AFL		1171	TSN 0					54
				PROC. REF: GENERIC NO REF					
250001-701 U	PBA HUD PANEL ASSY								Component ATA:25
PN:GC547-0295-3	MOS/MSC	O/C	14-Feb-11	TSN 0					155.9
SN:0077	HRS		7.4	TSN 0					4093.9
	AFL		4	TSN 0					1221
251001-701 U	SUN SHADE, LHS ASSEMBLY								Component ATA:25
PN:7002510364-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:281	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
251002-701 U	SUN SHADE, RHS ASSEMBLY								Component ATA:25
PN:7002510364-002	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:335	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251800-701 U	SWITCH PANEL								Component ATA:25
PN:2600-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74C	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251801-701 U	SWITCH PANEL								Component ATA:25
PN:2600-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74D	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251801-702 U	SWITCH PANEL								Component ATA:25
PN:2600-1-4-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T73X	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251802-701 U	SWITCH PANEL								Component ATA:25
PN:2600-1-2-T12SA	MOS/MSC	O/C	01-Aug-17	TSR 0					78.3
SN:3T73Y	HRS		2500.6	TSR 0					1600.7
	AFL		835	TSR 0					390
251802-702 U	SWITCH PANEL								Component ATA:25
PN:2600-1-38-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74B	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251803-701 U	SWITCH PANEL								Component ATA:25
PN:2600-1-10-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74M	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251804-701 U	SWITCH PANEL								Component ATA:25
PN:2600-1-5-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74F	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
251804-702 U	SWITCH PANEL								Component ATA:25
PN:2601-1-6-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75M	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251804-703 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T79J	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251804-704 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	11-Jul-17						79
SN:3T7HC	HRS		2473.8						1627.5
	AFL		817						408
251805-701 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T79L	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251805-702 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	11-Jul-17	TSN 73					79
SN:3T74G	HRS		2473.8	TSN 2426.4					1627.5
	AFL		817	TSN 800					408
251805-703 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T7HD	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251805-704 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74G	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251806-701 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74J	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
251806-702 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74K	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251806-703 U	FWD LAVATORY FLUSH SWITCH PANEL								Component ATA:25
PN:2600-1-1-T12SA	MOS/MSC	O/C	07-Jul-18	TSR 4					67.1
SN:3T74C	HRS		2892.3	TSR 0					1209
	AFL		921	TSR 0					304
251806-704 U	SWITCH PANEL								Component ATA:25
PN:2601-1-1-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74H	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251806-705 U	SWITCH PANEL								Component ATA:25
PN:2600-1-46-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6VD	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251806-706 U	SWITCH PANEL								Component ATA:25
PN:2601-1-5-T12SA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75N	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251814-701 U	SWITCH BOX ASSEMBLY								Component ATA:25
PN:2600-3-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3RYHK	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251815-702 U	SWITCH BOX (AFT LAVATORY) ASSEMBLY								Component ATA:25
PN:2600-3-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3RYHM	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
251816-703 U	SWITCH BOX (LH ENCLOSURE) ASSEMBLY								Component ATA:25
PN:2600-3-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3D5WH	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
252000-701 U	JUMP SEAT								Component ATA:25
PN:1513000-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:48510	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-702 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100604-163	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-703 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-29	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-704 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-30	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-705 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-31	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-706 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-32	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-707 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-33	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-708 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-34	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
252000-709 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-35	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-710 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-36	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-711 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-37	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252000-712 U	SINGLE SEAT - WIDE ASSEMBLY								Component ATA:25
PN:3ACF0107101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:100722-38	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252002-703 U	RHS F.S.485.45;HOUSING 27" TABLE								Component ATA:25
PN:55150Z-27	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:42004	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252002-705 U	RHS F.S.699.58; HOUSING 27" TABLE								Component ATA:25
PN:55150Z-27	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:42005	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252003-701 U	CONTACTOR (K671) - F.S.280 LHS UNIT								Component ATA:25
PN:S79	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N410	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252003-702 U	CONTACTOR (K672) - F.S.280 LHS UNIT								Component ATA:25
PN:S79	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N411	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
252003-703 U	CONTACTOR-DC PWR DISTR COCKPIT (K658) - F.S.280 UNIT								Component ATA:25
PN:S79	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:U134	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252004-701 U	HANDSET 10G COCKPIT JETPHONE (LOOSE EQUIPMENT) UNIT								Component ATA:25
PN:938810A-B	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3002103	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252102-702 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74X	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-701 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T74Y	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-702 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75B	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-703 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75C	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-704 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75D	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-705 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75F	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
252103-706 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75G	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-707 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3775H	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-708 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75J	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-709 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75K	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252103-710 U	ROUNDED HEADPHONE JACK PANEL								Component ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T75L	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-701 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YF	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-702 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YG	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-703 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YH	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
252105-705 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YJ	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-706 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YK	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-707 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YL	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-708 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YM	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-709 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YN	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-710 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T6YN	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252105-711 U	JACK PANEL RJ-45 CAT6 SHIELDED UNIT								Component ATA:25
PN:2600-2-21-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3T7JF	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-701 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP725769-140-031	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
252152-702 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP725769-140-043	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-703 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP725769-140-033	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-704 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP725769-140-032	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-705 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP725769-140-0	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-706 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP725769-140-045	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-707 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP693683-78-40	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-708 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP693683-78-42	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-709 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP693683-78-43	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
252152-710 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP726769-140-044	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
252152-711 U	BACKCYLER II CONTROLLER								Component ATA:25
PN:SP2222311C	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MP393683-78-41	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
253000-701 U	OVEN (MODEL 1545-3) UNIT								Component ATA:25
PN:400-1317-01-L	MOS/MSC	O/C	20-Jun-19	TSR 0					55.7
SN:10-05-47073	HRS		3159.6	TSR 0					941.7
	AFL		988	TSR 0					237
253001-701 U	OVEN CONTROLLER								Component ATA:25
PN:400-1962-02	MOS/MSC	O/C	20-Jun-19	TSN 96, TSR 0					55.7
SN:10-05-47071	HRS		3159.6	TSN 3112.2, TSR 0					941.7
	AFL		988	TSN 971, TSR 0					237
253002-701 U	MICROWAVE OVEN UNIT								Component ATA:25
PN:400-1409-01-L	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:08TA02229	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
253003-701 U	AIR CHILLER UNIT								Component ATA:25
PN:319-4	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:623	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
253004-701 U	EXPRESSO COFFEE MAKER MACHINE								Component ATA:25
PN:400-1794-06	MOS/MSC	O/C	24-Jul-19	TSN 97, TSR 0					54.6
SN:11-01-47922	HRS		3193.7	TSN 3146.3, TSR 0					907.6
	AFL		999	TSN 982, TSR 0					226
256080-701 U	(AED) AUTOMATED EXTERNAL DEFIBRILLATOR								Component ATA:25
PN:AED FRX	MOS/MSC	O/C	08-Jul-19						55.1
SN:B11D-02709	HRS		3188.8						912.5
	AFL		996						229

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
256080-701A U	DETAILED INSPECTION (AED) AUTOMATED EXTERNAL DEFIBRILLATOR								Service	ATA:25
PN:AED FRX	MOS	12	28-Nov-23		30-Nov-24		293 d	30-Nov-2024	2.5	
SN:B11D-02709	HRS		4099.1						2.2	
	AFL		1223						2	
256080-702 U	(AED) AUTOMATED EXTERNAL DEFIBRILLATOR BATTERY								Component	ATA:25
PN:M5070A	MOS/MSC	DUE	16-Oct-21		01-Apr-27 (M)		1145 d	01-Apr-2027	27.8	
SN:UNKNOWN	HRS		3663.4						437.9	
	AFL		1113						112	
		Expiry Date: : 01-Apr-27								
256080-703 U	(AED) AUTOMATED EXTERNAL DEFIBRILLATOR SPARE BATTERY								Component	ATA:25
PN:M5070A	MOS/MSC	DUE	21-Jan-22	TSN 0	28-Feb-27 (M)		1113 d	28-Feb-2027	24.7	
SN:NA	HRS		3689.6	TSN 0					411.7	
	AFL		1117	TSN 0					108	
		Expiry Date: : 28-Feb-27								
256080-704 U	(AED) AUTOMATED EXTERNAL DEFIBRILLATOR PADS								Component	ATA:25
PN:989803139261	MOS/MSC	DUE	16-Dec-22	TSN 0	03-Apr-25 (M)		417 d	03-Apr-2025	13.8	
SN:UNKNOWN	HRS		3913.7	TSN 0					187.6	
	AFL		1171	TSN 0					54	
		Expiry Date: : 03-Apr-25								
256080-705 U	(AED) AUTOMATED EXTERNAL DEFIBRILLATOR SPARE PADS								Component	ATA:25
PN:989803139261	MOS/MSC	DUE	04-Oct-23	TSN 0	04-Nov-25 (M)		632 d	04-Nov-2025	4.2	
SN:NA	HRS		4038.6	TSN 0					62.7	
	AFL		1206	TSN 0					19	
		Expiry Date: : 04-Nov-25								
256083-701 U	FIRST AID KIT								Component	ATA:25
PN:AFAK 1.0	MOS/MSC	DUE	12-Dec-23		31-Dec-24 (M)		324 d	31-Dec-2024	2	
SN:082222012	HRS		4099.1						2.2	
	AFL		1223						2	
		Expiry Date: : 31-Dec-24								
256083-701A U S	DETAILED INSPECTION FIRST AID KIT (DO NOT OPEN IF SEALED) (25-60-00-606)								Service	ATA:25
PN:AFAK 1.0	MOS	15	14-Dec-23						1.9	
SN:082222012	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
256083-702 U	EMK KIT								Component	ATA:25
PN:EMK	MOS/MSC	DUE	14-Dec-23		31-Dec-24 (M)		324 d	31-Dec-2024	1.9	
SN:120103005	HRS		4099.1						2.2	
	AFL		1223						2	
		Expiry Date: : 31-Dec-24								
256083-702A U S	DETAILED INSPECTION EMK KIT (25-60-00-606)								Service	ATA:25
PN:EMK	MOS	15	14-Dec-23						1.9	
SN:120103005	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
256101-701D U	PERFORM EMERGENCY LOCATOR TRANSMITTER FAA FAR 91.207 CHECKS								Service	ATA:25
PN:453-5004	MOS	12	14-Dec-23		14-Dec-24		307 d	14-Dec-2024	1.9	
SN:170-11429	HRS		4099.1						2.2	
	AFL		1223						2	
256117-001A U	TEST L/H ELT NAV INTERFACE UNIT								Service	ATA:25
PN:453-6500	MOS	12	14-Dec-23		31-Dec-24		324 d	31-Dec-2024	1.9	
SN:08149	HRS		4099.1						2.2	
	AFL		1223						2	
259001-701 U	HEADPHONE, JACK PANEL, SQUARE UNIT								Component	ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:3NL1J	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
259001-702 U	HEADPHONE, JACK PANEL, SQUARE, ARMREST AFT R/H UNIT								Component	ATA:25
PN:2600-2-19-T12SR	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:3T6YD	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
259100-701 U	IPOD DOCKING STATION, CRADLE UNIT								Component	ATA:25
PN:441-0050-100	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0906000125	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
259100-702[U]	IPOD DOCKING STATION, CRADLE UNIT								Component	ATA:25
PN:441-0050-100	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0906000119	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
259501-701[U]	LIFE RAFT								Component	ATA:25
PN:1218FAUL-630-3-174	MOS/MSC	O/C	05-Jan-23	TSO 1					13.2	
SN:12UL-01879	HRS		3915.7	TSO 0					185.6	
	AFL			TSO 0						
259501-701B[U]	RESTORE LIFE RAFT (25-60-00-605)								Service	ATA:25
PN:1218FAUL-630-3-174	MOS/MSC	DUE	05-Jan-23		01-Dec-25 (M)		659 d	01-Dec-2025	13.2	
SN:12UL-01879	HRS		3915.7						185.6	
	AFL									
259501-701C[U]	DISCARD LIFE RAFT (SRB-406) ELT BATTERY								Service	ATA:25
PN:1218FAUL-630-3-174	MOS/MSC	DUE	05-Jan-23		01-Aug-28 (M)		1633 d	01-Aug-2028	13.2	
SN:12UL-01879	HRS		3915.7						185.6	
	AFL									
259501-702[U]	LIFE RAFT								Component	ATA:25
PN:1218FAUL-630-1-159	MOS/MSC	O/C	05-Jan-23	TSO 1					13.2	
SN:12UL-01880	HRS		3915.7	TSO 0					185.6	
	AFL			TSO 0						
259501-702B[U]	RESTORE LIFE RAFT (25-60-00-605)								Service	ATA:25
PN:1218FAUL-630-1-159	MOS/MSC	DUE	05-Jan-23		01-Dec-25 (M)		659 d	01-Dec-2025	13.2	
SN:12UL-01880	HRS		3915.7						185.6	
	AFL									
259501-702C[U]	DISCARD LIFE RAFT (SRB-406) ELT BATTERY								Service	ATA:25
PN:1218FAUL-630-1-159	MOS/MSC	DUE	05-Jan-23		01-Aug-28 (M)		1633 d	01-Aug-2028	13.2	
SN:12UL-01880	HRS		3915.7						185.6	
	AFL									
259536-701[U]	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101CW	MOS/MSC	O/C	29-Dec-23						1.4	
SN:267105	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
259536-701B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101CW	MOS/MSC	DUE	27-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.5	
SN:267105	HRS		4099.1						2.2	
	AFL		1223						2	
259536-702 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101CW	MOS/MSC	O/C	29-Dec-23						1.4	
SN:267096	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-702B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101CW	MOS/MSC	DUE	27-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.5	
SN:267096	HRS		4099.1						2.2	
	AFL		1223						2	
259536-703 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345340	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-703B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345340	HRS		4099.1						2.2	
	AFL		1223						2	
259536-704 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345359	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-704B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345359	HRS		4099.1						2.2	
	AFL		1223						2	
259536-705 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345351	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
259536-705B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345351	HRS		4099.1						2.2	
	AFL		1223						2	
259536-706 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345353	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-706B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345353	HRS		4099.1						2.2	
	AFL		1223						2	
259536-707 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345362	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-707B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345362	HRS		4099.1						2.2	
	AFL		1223						2	
259536-708 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345344	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-708B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345344	HRS		4099.1						2.2	
	AFL		1223						2	
259536-709 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345350	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
259536-709B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345350	HRS		4099.1						2.2	
	AFL		1223						2	
259536-710 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345364	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-710B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		01-Dec-28 (M)		1755 d	01-Dec-2028	1.4	
SN:345364	HRS		4099.1						2.2	
	AFL		1223						2	
259536-711 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345331	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-711B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345331	HRS		4099.1						2.2	
	AFL		1223						2	
259536-712 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345363	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-712B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345363	HRS		4099.1						2.2	
	AFL		1223						2	
259536-713 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345360	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
259536-713B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345360	HRS		4099.1						2.2	
	AFL		1223						2	
259536-714 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345356	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-714B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345356	HRS		4099.1						2.2	
	AFL		1223						2	
259536-715 U	CABIN LIFE VEST								Component	ATA:25
PN:P01074-101W	MOS/MSC	O/C	29-Dec-23						1.4	
SN:345358	HRS		4099.1	TSO 0					2.2	
	AFL		1223	TSO 0					2	
259536-715B U	RESTORE CABIN LIFE VEST (25-60-00-603)								Service	ATA:25
PN:P01074-101W	MOS/MSC	DUE	29-Dec-23		31-Dec-28 (M)		1785 d	31-Dec-2028	1.4	
SN:345358	HRS		4099.1						2.2	
	AFL		1223						2	
259574-704 U	QUAD CAMERA - CAM 14 UNIT								Component	ATA:25
PN:100-1078-01	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1019992	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
259930-701 U	TRANSMITTER MODULE, HIGH SPEED - HCM-210 UNIT								Component	ATA:25
PN:822-2248-001	MOS/MSC	O/C	20-Aug-15						101.7	
SN:448PGR	HRS		1731.4						2369.9	
	AFL		635						590	
259940-701 U	BOSE HEADPHONES								Component	ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6	
SN:051346Z02190632AC	HRS		15.6						4085.7	
	AFL		7						1218	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
259940-702 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190630AC	HRS		15.6						4085.7
	AFL		7						1218
259940-703 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190636AC	HRS		15.6						4085.7
	AFL		7						1218
259940-704 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190635AC	HRS		15.6						4085.7
	AFL		7						1218
259940-705 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190633AC	HRS		15.6						4085.7
	AFL		7						1218
259940-706 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190642AC	HRS		15.6						4085.7
	AFL		7						1218
259940-707 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190641AC	HRS		15.6						4085.7
	AFL		7						1218
259940-708 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190620AC	HRS		15.6						4085.7
	AFL		7						1218
259940-709 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190623AC	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
259940-710 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190622AC	HRS		15.6						4085.7
	AFL		7						1218
259940-711 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190631AC	HRS		15.6						4085.7
	AFL		7						1218
259940-712 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190629AC	HRS		15.6						4085.7
	AFL		7						1218
259940-713 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190619AC	HRS		15.6						4085.7
	AFL		7						1218
259940-714 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190637AC	HRS		15.6						4085.7
	AFL		7						1218
259940-715 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190621AC	HRS		15.6						4085.7
	AFL		7						1218
259940-716 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190618AC	HRS		15.6						4085.7
	AFL		7						1218
259940-717 U	BOSE HEADPHONES								Component ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6
SN:051346Z02190626AC	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
259940-718 U	BOSE HEADPHONES								Component	ATA:25
PN:322403-0010	MOS/MSC	O/C	23-Mar-11						154.6	
SN:051346Z02190634AC	HRS		15.6						4085.7	
	AFL		7						1218	
259955-701 U	OVERLAY "XRS" ENTRANCE PANEL								Component	ATA:25
PN:70025206485-101	MOS/MSC	O/C	23-Mar-11						154.6	
SN:67	HRS		15.6						4085.7	
	AFL		7						1218	
259990-701 U	AIRMAN 750 FEATHERWEIGHT HEADSET								Component	ATA:25
PN:64300-200	MOS/MSC	O/C	23-Mar-11						154.6	
SN:1021103	HRS		15.6						4085.7	
	AFL		7						1218	
ASB A700-25-008 REV 01 PART (A)	SPECIAL CHECK/REWORK OF PILOT AND COPILOT SEAT TRACK STOP FITTING (A/C 9002 TO 9073), ALERT SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-25-008 REV 01 PART (B)	MODIFICATION -PERMANENT REPAIR OF PILOT AND COPILOT SEAT TRACK STOP FITTING (A/C 9002 TO 9105), ALERT SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-25-008 REV 01 PART (C)	RETROACTIVE ACTION-MODIFICATION OF THE PILOT AND COPILOT SEAT TRACK STOP FITTING (A/C 9002 TO 9105 POST SB 700-25-008, PART B (BASIC ISSUE) AND A/C 9106 TO 9134), ALERT SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-25-008 REV 02 PART (A)	SPECIAL CHECK/REWORK OF THE PILOT AND CO-PILOT SEAT-TRACK STOP-FITTINGS (A/C 9002 TO 9073), ALERT SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
ASB A700-25-008 REV 02 PART (B)	MODIFICATION (PERMANENT REPAIR) OF THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9105), ALERT SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-25-008 REV 02 PART (C)	MODIFICATION (RETROACTIVE ACTION FOR AIRCRAFT THAT COMPLY TO PART B OF THE BASIC ISSUE OF THIS SB) OF THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9105 POST SB A700-25-008, BASIC ISSUE PART B AND A/C 9106 TO 9134), ALERT SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-25-008 REV 02 PART (D)	SPECIAL CHECK/REWORK OF THE OLD BOLT ON THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9105 POST SB A700-25-008, PART B BASIC ISSUE OR REV 1), ALERT SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-25-008 REV 02 PART (E)	SPECIAL CHECK/REWORK OF SLOTTED PLATES ON THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9160), ALERT SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-25-008 REV 02 PART (F)	MODIFICATION - ADDITION OF NEW SERRATED PLATES ON THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9165 & 9169), ALERT SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-25-014	SPECIAL CHECK - PASSENGER COMPARTMENT - INSPECT SEAT BELTS ON 16G DIVAN FOR PROPER INSTALLATION, ALERT SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-25-017 PART (A)	SPECIAL CHECK/REWORK - FLIGHT CREW SEATS - CHECK THE ENGAGMENT OF THE FLIGHT CREW SEAT FORE AND AFT TRACK LOCK PINS AND REPLACEMENT OF DEFECTIVE LEVER ASSEMBLIES (A/C 9002 TO 9126, 9128, 9129, 9131, TO 9139, 9141 TO 9148, 9150, 9153 TO 9159), ALERT SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
ASB A700-25-017 PART (B)	SPECIAL CHECK/REWORK - FLIGHT CREW SEATS - CHECK THE ENGAGMENT OF THE FLIGHT CREW SEAT FORE AND AFT TRACK LOCK PINS AND REPLACEMENT OF DEFECTIVE LEVER ASSEMBLIES (A/C 9002 TO 9126, 9128, 9129, 9131, TO 9139, 9141 TO 9148, 9150, 9153 TO 9159), ALERT SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
EASA 2011-0094[U]	LIFE JACKET VACUUM BAG - MODIFICATION								AD	ATA:25
	MOS/MSC	-	02-Jun-11						152.3	
	HRS		35.5						4065.8	
	AFL		13						1212	
FAA 1974-08-09 R02	APPLIANCE AD - LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)								AD	ATA:25
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
Category: APPLIANCE										
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION								AD	ATA:25
	MOS		28-Nov-23					16-Dec-2025	2.5	
	HRS	1000	4099.1		5099.1		997.8		2.2	
	AFL		1223						2	
FAA 2011-07-05[U]	SICMA AERO SEATS - INSPECTION								AD	ATA:25
	MOS/MSC	-	17-May-11						152.8	
	HRS		28.5						4072.8	
	AFL		9						1216	
FAA 2011-12-01[U]	SEATS AND SEATING SYSTEMS - KOITO INDUSTRIES LTD.								AD	ATA:25
	MOS/MSC	-	17-Jun-11						151.8	
	HRS		43.3						4058	
	AFL		15						1210	
FAA 2012-08-07	APPLIANCE AD - DETECT AND CORRECT CRACKING OF CENTRAL AND LATERAL SPREADERS ON SICMA SEAT ASSEMBLIES.								AD	ATA:25
	MOS/MSC	A/R	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT								AD	ATA:25
	MOS/MSC	-	04-Aug-15						102.2	
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2								AD	ATA:25
	MOS/MSC	-	04-Aug-15						102.2	
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK								AD	ATA:25
	MOS/MSC	-	04-Aug-15						102.2	
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS								AD	ATA:25
	MOS/MSC	-	04-Aug-15						102.2	
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS								AD	ATA:25
	MOS/MSC	-	18-Oct-17						75.8	
	HRS		2584.6						1516.7	
	AFL		860						365	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS								AD	ATA:25
	MOS/MSC	-	18-Oct-17						75.8	
	HRS		2584.6						1516.7	
	AFL		860						365	
Category: APPLIANCE										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT								AD	ATA:25
	MOS/MSC	-	18-Oct-17						75.8	
	HRS		2584.6						1516.7	
	AFL		860						365	
Category: APPLIANCE										
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-16-13 PARA (G)	INSPECT SAFETY BELT WEBBING, MODIFY AND RE-MARK EACH AFFECTED CABIN ATTENDANT SEAT USING ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-16-13 PARA (H)	DO NOT INSTALL ANY AFFECTED ZODIAC SEATS FRANCE CABIN ATTENDANT SEAT ON ANY AIRCRAFT								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-19-15	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-23-01 PARA (G)	INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-23-01 PARA (H)	INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-07-03	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-07-03 PARA (G)	REMOVE THE SEAT FROM THE AIRCRAFT AND PERFORM A DETAILED VISUAL INSPECTION; IF CORROSION OR OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT OR BEFORE (RE)INSTALLATION OF THE SEAT ON AN AIRCRAFT, AS APPLICABLE, REPAIR THE SEAT								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2019-07-03 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEAT THAT HAS ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON ANY AIRCRAFT, UNLESS IT HAS PASSED AN INSPECTION IAW THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.B., OF ZODIAC SEATS FRANCE SB NO. 536-25-002, REVISION 3, DATED NOVEMBER 2, 2016								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
FAA 2019-07-03 PARA (I)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.A., OF ZODIAC SEATS FRANCE SB NO. 536-25-004, REV. 0, DATED OCTOBER 19, 2017, CONSTITUTES A TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-08-01	APPLIANCE AD - EQUIPEMENT AND FURNISHINGS - MODIFICATION AND RE-IDENTIFICATION OF ALL AFFECTED RECARO AIRCRAFT SEATING GMBH & CO. KG MODEL PASSENGER SEATS								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-08-01 PARA (G)	MODIFY THE AFFECTED PASSENGER SEAT AND RE-IDENTIFY EACH MODIFIED PASSENGER SEAT								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-08-01 PARA (H)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED RECARO MODEL PASSENGER SEAT ON ANY AIRCRAFT, UNLESS THE SEAT HAS BEEN MODIFIED AND RE-IDENTIFIED IN ACCORDANCE WITH PARAGRAPH (G)(2), (3), OR (4) OF THIS AD								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-15-10[S]	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR								AD	ATA:25
	MOS/MSC	-	01-Sep-19						53.3	
	HRS		3223.4						877.9	
	AFL		1011						214	
Category: APPLIANCE										
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION								AD	ATA:25
	MOS/MSC	-	01-Sep-19						53.3	
	HRS		3223.4						877.9	
	AFL		1011						214	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
FAA 2019-15-10 PARA (F[S])	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA								AD	ATA:25
	MOS/MSC	-	01-Sep-19						53.3	
	HRS		3223.4						877.9	
	AFL		1011						214	
Category: APPLIANCE										
FAA 2019-21-06	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-21-06 PARA (G) (1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (RESTATEMENT OF FAA 2017-22-02)								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-21-06 PARA (G) (2)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-21-06 PARA (G) (3)	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO AT TECHNICALSUPPORT@IPECO.COM								AD	ATA:25
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
FAA 2019-21-06 PARA (H)	DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C)(1)(I) OF THIS AD UNLESS THE SEAT IS MODIFIED AND RE-IDENTIFIED AS SPECIFIED IN PARAGRAPH (G)(1) OF THIS AD								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-21-09	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION / REPLACEMENT								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-21-09 PARA (G)	INSPECT THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY; IF, DURING THE INSPECTION A LIFE VEST POUCH VELCRO STRIP IS FOUND DAMAGED OR WORN OR A LIFE VEST POUCH INSTALLATION IS NOT FOUND ACCEPTABLE, BEFORE FURTHER FLIGHT, REMOVE THE LIFE VEST POUCH FROM SERVICE AND REPLACE IT WITH A PART ELIGIBLE FOR INSTALLATION								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-21-09 PARA (I)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AVIOINTERIORS CENTAURUS ECONOMY CLASS PASSENGER SEAT WITH A P/N IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY HAS BEEN INSPECTED IN ACCORDANCE WITH PARAGRAPH (G)(1) OF THIS AD								AD	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT								AD	ATA:25
	MOS/MSC	-	21-Apr-21						33.7	
	HRS		3533.7						567.6	
	AFL		1082						143	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
FAA 2021-07-13 PARA (E) (1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE								AD	ATA:25
	MOS/MSC	-	21-Apr-21						33.7	
	HRS		3533.7						567.6	
	AFL		1082						143	
Category: APPLIANCE										
FAA 2021-07-13 PARA (E) (2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE								AD	ATA:25
	MOS/MSC	-	21-Apr-21						33.7	
	HRS		3533.7						567.6	
	AFL		1082						143	
Category: APPLIANCE										
FAA 2021-07-13 PARA (E) (3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER								AD	ATA:25
	MOS/MSC	-	21-Apr-21						33.7	
	HRS		3533.7						567.6	
	AFL		1082						143	
Category: APPLIANCE										
SB 700-25-003	MODIFICATION - ADDITION OF THE EMERGENCY LOCATOR SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-25-004	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INSTALLATION AND TRANSMITTER LOCATION CHANGE, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	N/R								
	HRS									
	AFL									
SB 700-25-004 REV 01	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INSTALLATION AND TRANSMITTER LOCATION CHANGE, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	A/R								
	HRS									
	AFL									
SB 700-25-008 PART (A)	SPECIAL CHECK/REWORK OF PILOT/, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-008 PART (B)	MODIFICATION(PERMANENT REPAIR), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-25-010 PART (A)	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FOR MOISTURE CONTROL, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-25-010 PART (B)	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FOR MOISTURE CONTROL, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-25-010 REV 01 PART (A)	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FOR MOISTURE CONTROL (A/C 9002 TO 9023, 9025 TO 9069, 9071 TO 9073, 9076 TO 9139), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-25-010 REV 01 PART (B)	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FOR MOISTURE CONTROL (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-25-022	MODIFICATION - BUFFET/GALLEY - SEALING OF GALLEY FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR (A/C 9002, 9011, 9016, 9020, 9022, 9024, 9034, 9036, 9041, 9042, 9049, 9050, 9052, 9054, 9055, 9060, 9062, 9070 TO 9072,9074, 9075, 9077, 9078, 9080, 9082, 9085, 9089, 9091, 9094 TO 9096, 9101, 9102, 9105, 9106, 9108, 9110, 9111, 9116, 9117, 9121, 9145, 9147 AND 9148), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-25-023	MODIFICATION - FLIGHT CREW SEATS - INSTALLATION OF A STOP FOR THE FORE/AFT ADJUSTMENT CABLE (A/C 9002 TO 9126 AND 9128 TO 9281), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-024	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-024 REV 01	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-024 REV 02	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-024 REV 02 PART (A)	MODIFICATION MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN OF THE PILOT SEAT								Bulletin ATA:25
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-25-024 REV 02 PART (B)	MODIFICATION MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN OF THE COPILOT SEAT								Bulletin ATA:25
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-25-025	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF THICKER FORE/AFT CABLE FOR CREW SEAT (A/C 9002 TO 9314), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-25-025 REV 01	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF THICKER FORE/AFT CABLE FOR CREW SEAT (A/C 9002 TO 9314), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-025 REV 02	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF THICKER FORE/AFT CABLE FOR CREW SEAT, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026	MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 PART (A)	ACCESS MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN THE ENTRANCE AREA FLOOR PANELS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 PART (B)	ACCESS MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN THE FORWARD CABIN FLOOR PANELS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 PART (C)	ACCESS MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN THE MID CABIN FLOOR PANELS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 PART (D)	ACCESS MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN THE AFT CABIN FLOOR PANELS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 PART (E)	ACCESS MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN THE AFT LAVATORY AND BAGGAGE AREA FLOOR PANELS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-026 REV 01	MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 REV 01 PART (A)	MODIFICATION MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN - SEALING OF THE ENTRANCE AREA FLOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 REV 01 PART (B)	MODIFICATION MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN - SEALING OF THE FORWARD CABIN FLOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 REV 01 PART (C)	MODIFICATION MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN - SEALING OF THE MID CABIN FLOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 REV 01 PART (D)	MODIFICATION MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN - SEALING OF THE AFT CABIN FLOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-026 REV 01 PART (E)	MODIFICATION MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN - SEALING OF THE AFT LAV AND BAGGAGE AREA FLOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-027	MODIFICATION - BUFFET/GALLEY - SEALING OF GALLEY FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-028	MODIFICATION - CABIN INTERIOR - INTRODUCTION OF NEW DOOR LATCH FOR THE INTERIOR DOORS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-029	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF A STOP FOR THE GOODRICH COPILOT SEAT, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-25-030	MODIFICATION - PASSENGER COMPARTMENT - REPLACE PASSENGER SERVICE UNIT (PSU) LATCH WITH A MORE ROBUST LATCH, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-030 REV 01	MODIFICATION - PASSENGER COMPARTMENT - REPLACE PASSENGER SERVICE UNIT (PSU) LATCH WITH A MORE ROBUST LATCH, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-25-030 REV 02	MODIFICATION - PASSENGER COMPARTMENT - REPLACE PASSENGER SERVICE UNIT (PSU) LATCH WITH A MORE ROBUST LATCH, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-031	MODIFICATION - PASSENGER COMPARTMENT - NEW ROLLER AND GUIDE INSTALLATION FOR THE CABIN DOORS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-25-032	MODIFICATION - BUFFET/GALLEY - INSTALLATION OF INLET AND OUTLET GRILLS ON THE GALLEY CHILLER, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
SB 700-25-032 REV 01	MODIFICATION - BUFFET/GALLEY - INSTALLATION OF INLET AND OUTLET GRILLS ON THE GALLEY CHILLER, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-25-033	MODIFICATION- FLIGHT CREW SEATS - INTRODUCTION OF A STOP FOR THE GOODRICH COPILOT SEAT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-25-034	MODIFICATION - BUFFET/GALLEY - ADDITIONAL COOLING MODIFICATION FOR MICROWAVE, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-035	MODIFICATION – PASSENGER SEATING – REPLACE SUSPECT SWIVEL ASSEMBLY ON PASSENGER SEAT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-036	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW SEAT CUSHION, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-036 PART (A)	MODIFICATION MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW SEAT CUSHION, SERVICE BULLETIN OF THE PILOT SEAT								Bulletin	ATA:25
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-25-036 PART (B)	MODIFICATION MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW SEAT CUSHION, SERVICE BULLETIN OF THE COPILOT SEAT								Bulletin	ATA:25
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-25-037	SPECIAL CHECK/REWORK - GALLEY - REWORK OF THE COFFEE BREWER, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-	28-Mar-13						130.5	
	HRS		896.8						3204.5	
	AFL		345						880	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-039	MODIFICATION - CABIN INTERIOR - REPLACEMENT OF STRIKER LATCH ON CABINETS (SUPERSEDED BY SB 700-25-055), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-040	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF MICROWAVE OVEN PART NO. 400-1409-01-L OR 400-1409-01-R, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-	EFF						
	HRS								
	AFL								
SB 700-25-041	MODIFICATION - WARDROBE CABINETS - REPLACEMENT OF THE MAXIMUM WEIGHT LIMITATION PLACARD IN THE LEFT HAND BAGGAGE COMPARTMENT, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-043	MODIFICATION - FORWARD AND AFT LAVATORY - IMPROVEMENT OF THE SIDE LATCHES, HANDLE INSTALLATIONS AND STOPPERS ON THE DOORS DECOMPRESSION TYPE, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-044	MODIFICATION - EMERGENCY LOCATOR SYSTEM (ELT) - EMERGENCY LOCATOR TRANSMITTER REMOVAL/INSTALLATION IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-045	MODIFICATION - GALLEY - HOT CUP PLACARD INSTALLATION, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-047	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-047 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-047 REV 02	MODIFICATION – PASSENGER COMPARTMENT – MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-047 REV 03	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-048	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-048 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-048 REV 02	MODIFICATION – PASSENGER COMPARTMENT – MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-048 REV 03	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
SB 700-25-048 REV 04	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-049	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-049 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-050	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-050 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-051	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF MICROSWITCH IN ELECTRICAL CONTROLS, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-	22-Jul-14						114.6	
	HRS									
	AFL									
SB 700-25-051 REV 01	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF MICROSWITCH IN ELECTRICAL CONTROLS, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-052	ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-052 PART (A)	VERIFICATION ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF INSTALLED PARTS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-052 PART (B)	REPLACEMENT ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF THE EJECTOR BASE								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-052 REV 01	ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-	EFF						
	HRS								
	AFL								
SB 700-25-052 REV 01 PART (A)	VERIFICATION ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF INSTALLED PARTS								Bulletin ATA:25
	MOS/MSC	-	EFF						
	HRS		EFF						
	AFL								
SB 700-25-052 REV 01 PART (B)	REPLACEMENT ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF THE EJECTOR BASE								Bulletin ATA:25
	MOS/MSC	-	EFF						
	HRS		EFF						
	AFL								
SB 700-25-053	MODIFICATION - FORWARD AND AFT LAVATORY - IMPROVEMENT OF THE HANDLE INSTALLATIONS, LATCH AND STOPPERS ON THE DOORS DECOMPRESSION TYPE, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-053 PART (A)	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE FORWARD CABIN DOOR, AIRCRAFT PRE SB 700-25-028								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-053 PART (B)	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE FORWARD LAVATORY DOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-053 PART (C)	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE AFT LAVATORY DOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-053 PART (D)	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE BAGGAGE DOOR								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-054	MODIFICATION - ENTRY AREA HEADLINER - IMPROVEMENT OF MAIN ENTRANCE HEADLINER ATTACHMENTS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-055	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-055 PART (A)	ACCOMPLISH, SERVICE BULLETIN LATCH AND WIRE STRIKER INSPECTION								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-055 PART (B)	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE LATCHES								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-055 PART (C)	ACCOMPLISH MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS, SERVICE BULLETIN REPLACEMENT AND RIGGING OF THE WIRE STRIKERS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-055 REV 01	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-055 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN LATCH AND WIRE STRIKER INSPECTION								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-055 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE LATCHES								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-055 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT AND RIGGING OF THE WIRE STRIKERS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-057	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-057 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
SB 700-25-057 REV 02	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-058	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE FWD LAVATORY DOOR HINGES, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-059	MODIFICATION - MISCELLANEOUS EQUIPMENT- REPLACEMENT OF THE AIRSTAIR ANTI-SLIP MAT (ON HOLD), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-059 REV 01	MODIFICATION - MISCELLANEOUS EQUIPMENT - REPLACEMENT OF THE AIRSTAIR ANTI-SLIP MAT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-059 REV 02	MODIFICATION - MISCELLANEOUS EQUIPMENT - REPLACEMENT OF THE AIRSTAIR ANTI-SLIP MAT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-060	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INTRODUCTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATOR DEVICE, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-060 REV 01	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INTRODUCTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATOR DEVICE, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-	08-Jun-18						68.1	
	HRS		2892.3						1209	
	AFL		921						304	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
SB 700-25-060 REV 02	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INTRODUCTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATOR DEVICE, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-061	INSPECTION - EMERGENCY EQUIPMENT - REPLACEMENT OF THE CREWMEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS WITH PART NO. 119003-11 OR PART NO. 119003-21 (WITHIN SPECIFIED SERIAL NUMBER FOR -21 ONLY), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-	02-Jan-18						73.3	
	HRS		2694.7						1406.6	
	AFL		882						343	
SB 700-25-061 PART A	ACCOMPLISH INSPECTION - EMERGENCY EQUIPMENT - REPLACEMENT OF THE CREWMEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS WITH PART NO. 119003-11 OR PART NO. 119003-21 (WITHIN SPECIFIED SERIAL NUMBER FOR -21 ONLY), SERVICE BULLETIN REPLACEMENT OF PBE UNITS, PART NO. 119003-11								Bulletin	ATA:25
	MOS/MSC	-	02-Jan-18						73.3	
	HRS		2694.7						1406.6	
	AFL		882						343	
SB 700-25-061 PART B	ACCOMPLISH INSPECTION - EMERGENCY EQUIPMENT - REPLACEMENT OF THE CREWMEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS WITH PART NO. 119003-11 OR PART NO. 119003-21 (WITHIN SPECIFIED SERIAL NUMBER FOR -21 ONLY), SERVICE BULLETIN REPLACEMENT OF PBE UNITS, PART NO. 119003-21								Bulletin	ATA:25
	MOS/MSC	-	02-Jan-18						73.3	
	HRS		2694.7						1406.6	
	AFL		882						343	
SB 700-25-062	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF THE GALLEY MICROWAVE COMPARTMENT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-062 REV 01	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF THE GALLEY MICROWAVE COMPARTMENT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-25-062 REV 02	MODIFICATION - GALLEY - MODIFICATION OF THE MICROWAVE COMPARTMENT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 25 - EQUIPMENT/FURNISHINGS									
SB 700-25-063	MODIFICATION - PASSENGER SEATING - INSTALLATION OF ADDITIONAL GROMMETS TO PREVENT INTERFERENCE BETWEEN SEAT ARMREST AND DADO MOLDING, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-064	MODIFICATION - DOOR STOPPER - IMPROVEMENT OF THE DOOR STOPPER AND STAY OPEN FOR THE AFTLAVATORY DOOR AND THE BAGGAGE COMPARTMENT DOOR, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-065	SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF THE SEAT BELT EJECTOR BASE, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-065 PART A	ACCOMPLISH, SERVICE BULLETIN VERIFICATION OF INSTALLED SEAT BELTS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-065 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SEAT BELTS WITH THE TEMPORARY PARTS /MODIFIED SEAT BELTS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-065 PART C	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE TEMPORARY PART WITH THE MODIFIED SEAT BELTS								Bulletin ATA:25
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-25-065 REV 01	SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF THE SEAT BELT EJECTOR BASE, SERVICE BULLETIN								Bulletin ATA:25
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
SB 700-25-065 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN VERIFICATION OF INSTALLED SEAT BELTS								Bulletin	ATA:25
	MOS/MSC	-	17-Jul-19						54.8	
	HRS		3188.8						912.5	
	AFL		996						229	
SB 700-25-065 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SEAT BELTS WITH THE TEMPORARY PARTS /MODIFIED SEAT BELTS								Bulletin	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-25-065 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE TEMPORARY PART WITH THE MODIFIED SEAT BELTS								Bulletin	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-25-069	SPECIAL CHECK/MODIFICATION - UNDERWATER LOCATING DEVICE - INSPECTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATING DEVICE (LF-ULD), SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-25-069 PART A	ACCOMPLISH, SERVICE BULLETIN SPECIAL CHECK - INSPECTION OF THE SERIAL NUMBER ON LF-ULD								Bulletin	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-25-069 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF THE LF-ULD								Bulletin	ATA:25
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700D25-015 REV 01	MODIFICATION - MISCELLANEOUS EQUIPMENT - INSTALLATION OF SPARE NOSE WHEEL STOWAGE PROVISIONS, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 25 - EQUIPMENT/FURNISHINGS										
SB 700D25-015 REV 02	MODIFICATION - MISCELLANEOUS EQUIPMENT - INSTALLATION OF SPARE NOSE WHEEL STOWAGE PROVISIONS, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	-								
	HRS									
	AFL									
SB 700D25-018 REV 3[U]	MODIFICATION - CARGO COMPARTMENT - MODIFICATION TO ALLOW INSTALLATION OF BAGGAGE COMPARTMENT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	A/R	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
SB 700D25-021[U]	MODIFICATION - PROVISIONS - CARGO COMPARTMENT - INSTALLATION OF NET AND SHELF IN THE BAGGAGE COMPARTMENT, SERVICE BULLETIN								Bulletin	ATA:25
	MOS/MSC	A/R	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
ATA 26 - FIRE PROTECTION										
26-10-01-201[S]	OPERATIONAL TEST OF THE FIRE-DETECTION-AND- EXTINGUISHING (FIDEEX) CONTROL-CIRCUITS, ARM AND DISCHARGE CIRCUITS								Service	ATA:26
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 26.005	AFL		1069						156	
				PROC. REF: AMM 26 10 01 710 802						PKG:34
26-10-01-900-801-01	FS987 ALARM FIDEEX CONTROL UNIT								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.045	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 10 01 000 801, AMM 26 10 01 400 801						
26-12-00-201[S]	FUNCTIONAL TEST OF THE APU FIRE DETECTION SYSTEM								Service	ATA:26
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 26.010	AFL		1171						54	
				PROC. REF: AMM 26 12 00 720 801						PKG:32
26-12-01-900-801-01	EDUCTOR LOOP A SENSING ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.050	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 12 01 000 801, AMM 26 12 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
26-12-01-900-801-02	EDUCTOR LOOP B SENSING ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.050	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 12 01 000 801, AMM 26 12 01 400 801						
26-12-05-900-801-01	RIGHT HATCH LOOP A SENSING ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 12 05 000 801, AMM 26 12 05 400 801						
26-12-05-900-801-02	RIGHT HATCH LOOP B SENSING ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 12 05 000 801, AMM 26 12 05 400 801						
26-12-09-900-801-01	LEFT STRUT LOOP A SENSING ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 12 09 000 801, AMM 26 12 09 400 801						
26-12-09-900-801-02	LEFT STRUT LOOP B SENSING ELEMENT								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 12 09 000 801, AMM 26 12 09 400 801						
26-13-00-201[S]	FUNCTIONAL TEST OF THE MAIN LANDING GEAR (MLG) OVERHEAT-DETECTION SYSTEM								Service	ATA:26
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 26.015	AFL		1171						54	
				PROC. REF: AMM 26 13 00 720 801						PKG:32
26-13-01-900-801-01	LEFT MLG WHEEL WELL SENSING ELEMENT								Component	ATA:26
PN:GK774-0023-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:009	HRS		0	TSN 0					4101.3	
WC#: 26.060	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 13 01 000 801, AMM 26 13 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
26-13-01-900-801-02	RIGHT MLG WHEEL WELL SENSING ELEMENT								Component	ATA:26
PN:GK774-0023-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:032	HRS		0	TSN 0					4101.3	
WC#: 26.060	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 13 01 000 801, AMM 26 13 01 400 801						
26-21-00-201	GENERAL VISUAL INSPECTION OF THE SINGLE-PATH DISCHARGE LINES								Service	ATA:26
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 26.020	AFL		690						535	
				PROC. REF: AMM 26 21 00 210 801						PKG:8
26-21-01-201	FUNCTIONAL TEST (HYDROSTATIC TEST) NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Service	ATA:26
PN:GK774-0020-3	MOS	120	14-Jan-21		31-Jan-31		2546 d	31-Jan-2031	36.9	
SN:0519BD	HRS									
WC#: 26.065	AFL									
				PROC. REF: AMM 26 21 01 790 801						PKG:38
26-21-01-201	FUNCTIONAL TEST (HYDROSTATIC TEST) NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Service	ATA:26
PN:GK774-0020-3	MOS	120	01-Dec-20		31-Dec-30		2515 d	31-Dec-2030	38.3	
SN:0415BD	HRS									
WC#: 26.070	AFL									
				PROC. REF: AMM 26 21 01 790 801						PKG:38
26-21-01-202	FUNCTIONAL TEST NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH								Service	ATA:26
PN:GK774-0020-3	MOS	120 (+3m/-3m)	14-Jan-21		31-Jan-31	31-Jan-31	2546 d	31-Jan-2031	36.9	
SN:0519BD	HRS									
	AFL									
				PROC. REF: AMM 26 21 01 720 801						PKG:38
26-21-01-202	FUNCTIONAL TEST NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH								Service	ATA:26
PN:GK774-0020-3	MOS	120 (+3m/-3m)	06-Jan-21		31-Jan-31	31-Jan-31	2546 d	31-Jan-2031	37.2	
SN:0415BD	HRS									
	AFL									
				PROC. REF: AMM 26 21 01 720 801						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
26-21-01-203	FUNCTIONAL TEST NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT								Service	ATA:26
PN:GK774-0020-3	MOS	60 (+3m/-3m)	14-Jan-21		31-Jan-26	31-Jan-26	720 d	31-Jan-2026	36.9	
SN:0519BD	HRS									
	AFL									
				PROC. REF: AMM 26 21 01 720 802						PKG:34
26-21-01-203	FUNCTIONAL TEST NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT								Service	ATA:26
PN:GK774-0020-3	MOS	60 (+3m/-3m)	06-Jan-21		31-Jan-26	31-Jan-26	720 d	31-Jan-2026	37.2	
SN:0415BD	HRS									
	AFL									
				PROC. REF: AMM 26 21 01 720 802						PKG:34
26-21-01-900-801-01	NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:GK774-0020-3	MOS/MSC	O/C	19-Mar-21	TSO 2					34.7	
SN:0519BD	HRS		3474.7	TSN 3246, TSO 0					626.6	
WC#: 26.065	AFL		1069	TSN 982, TSO 0					156	
				PROC. REF: CMM 26-21-65, AMM 26 21 01 000 801, AMM 26 21 01 400 801						
26-21-01-900-801-02	NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:GK774-0020-3	MOS/MSC	O/C	19-Mar-21	TSO 0					34.7	
SN:0415BD	HRS		3474.7	TSN 4061, TSO 0					626.6	
WC#: 26.070	AFL		1069	TSN 1649, TSO 0					156	
				PROC. REF: CMM 26-21-65, AMM 26 21 01 000 801, AMM 26 21 01 400 801						
26-21-05-201	DISCARD OF APU FWD THE DISCHARGE CARTRIDGE								Service	ATA:26
PN:446518-1	MOS	120	01-Aug-18		29-Jul-28 (M)		1630 d	29-Jul-2028	66.3	
SN:AEZ8336	HRS									
	AFL									
				PROC. REF: AMM 26 21 05 961 801						
26-21-05-201	DISCARD OF THE APU AFT DISCHARGE CARTRIDGE								Service	ATA:26
PN:446518-1	MOS	120	01-Aug-18		29-Jul-28 (M)		1630 d	29-Jul-2028	66.3	
SN:AEZ8328	HRS									
	AFL									
				PROC. REF: AMM 26 21 05 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
26-21-05-201	DISCARD OF THE ENG. 1 AFT DISCHARGE CARTRIDGE								Service	ATA:26
PN:446518-1	MOS	120	17-Jul-19		31-Jul-29		1997 d	31-Jul-2029	54.8	
SN:AEZ8350	HRS		3188.8						912.5	
	AFL		996						229	
				PROC. REF: AMM 26 21 05 961 801						
26-21-05-201	DISCARD OF THE ENG. 1 FWD DISCHARGE CARTRIDGE								Service	ATA:26
PN:446518-1	MOS	120	01-Aug-18		29-Jul-28 (M)		1630 d	29-Jul-2028	66.3	
SN:AEZ8334	HRS									
	AFL									
				PROC. REF: AMM 26 21 05 961 801						
26-21-05-201	DISCARD OF THE ENG. 2 AFT DISCHARGE CARTRIDGE								Service	ATA:26
PN:446518-1	MOS	120	01-Aug-18		29-Jul-28 (M)		1630 d	29-Jul-2028	66.3	
SN:AEZ8320	HRS									
	AFL									
				PROC. REF: AMM 26 21 05 961 801						
26-21-05-201	DISCARD OF THE ENG. 2 FWD DISCHARGE CARTRIDGE								Service	ATA:26
PN:446518-1	MOS	120	01-Aug-18		29-Jul-28 (M)		1630 d	29-Jul-2028	66.3	
SN:AEZ8337	HRS									
	AFL									
				PROC. REF: AMM 26 21 05 961 801						
26-21-05-900-801-01	ENG. 1 FWD DISCHARGE CARTRIDGE								Component	ATA:26
PN:446518-1	MOS/MSC	H/T	17-Jul-19	TSN 11					54.8	
SN:AEZ8334	HRS		3188.8	TSN 0					912.5	
WC#: 26.075	AFL		996	TSN 0					229	
				PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801						
26-21-05-900-801-02	ENG. 1 AFT DISCHARGE CARTRIDGE								Component	ATA:26
PN:446518-1	MOS/MSC	H/T	17-Jul-19	TSN 11					54.8	
SN:AEZ8350	HRS		3188.8	TSN 0					912.5	
WC#: 26.075	AFL		996	TSN 0					229	
				PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
26-21-05-900-801-03	ENG. 2 FWD DISCHARGE CARTRIDGE								Component	ATA:26
PN:446518-1	MOS/MSC	H/T	17-Jul-19	TSN 11					54.8	
SN:AEZ8337	HRS		3188.8	TSN 0					912.5	
WC#: 26.080	AFL		996	TSN 0					229	
				PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801						
26-21-05-900-801-04	ENG. 2 AFT DISCHARGE CARTRIDGE								Component	ATA:26
PN:446518-1	MOS/MSC	H/T	17-Jul-19						54.8	
SN:AEZ8320	HRS		3188.8	TSN 0					912.5	
WC#: 26.080	AFL		996	TSN 0					229	
		Manufacture Date:: 01-Aug-18		PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801						
26-21-05-900-801-05	APU FWD DISCHARGE CARTRIDGE								Component	ATA:26
PN:446518-1	MOS/MSC	H/T	17-Jul-19	TSN 11					54.8	
SN:AEZ8336	HRS		3188.8	TSN 0					912.5	
WC#: 26.085	AFL		996	TSN 0					229	
				PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801						
26-21-05-900-801-06	APU AFT DISCHARGE CARTRIDGE								Component	ATA:26
PN:446518-1	MOS/MSC	H/T	17-Jul-19						54.8	
SN:AEZ8328	HRS		3188.8	TSN 0					912.5	
WC#: 26.085	AFL		996	TSN 0					229	
		Manufacture Date:: 01-Aug-18		PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801						
26-21-13-201	OPERATIONAL TEST OF THE ENGINE FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS								Service	ATA:26
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 26.030	AFL		690						535	
				PROC. REF: AMM 26 21 13 710 811						PKG:8
26-21-13-202	OPERATIONAL TEST OF THE APU FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS								Service	ATA:26
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 26.035	AFL		690						535	
				PROC. REF: AMM 26 21 13 710 812						PKG:8
26-21-13-900-801-01	FIRE S/O ENGINE LH HANDLE								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.090	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
26-21-13-900-801-02	FIRE S/O ENGINE RH HANDLE								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.090	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801						
26-21-13-900-801-03	FIRE S/O ENGINE APU HANDLE								Component	ATA:26
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 26.090	AFL		0	TSN 0					1225	
				PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801						
26-21-45-201[S]	OPERATIONAL TEST OF THE DISCHARGE CHECK VALVES								Service	ATA:26
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 26.040	AFL		1069						156	
				PROC. REF: AMM 26 21 45 710 801						PKG:34
26-23-00-201[S]	FUNCTIONAL TEST FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE (WEIGHT TEST) (26-23-00-201)								Service	ATA:26
PN:30H673	MOS	15 (+3m/-3m)	30-Nov-23						2.4	
SN:E-68637110	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 26 23 01 720 801						PKG:31
26-23-01-900-801-01	FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE								Component	ATA:26
PN:30H673	MOS/MSC	O/C	17-Jul-19	TSN 16					54.8	
SN:E-68637110	HRS		3188.8	TSN 296.5					912.5	
	AFL		996	TSN 75					229	
				PROC. REF: AMM 26 23 01 000 801, AMM 26 23 01 400 801						
26-23-CA-200	PERFORM FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE 6YRS MAINTENANCE REQUIREMENTS AS PER NFPA-10								Service	ATA:26
PN:30H673	MOS	72	15-Dec-23		31-Dec-29		2150 d	31-Dec-2029	1.9	
SN:E-68637110	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: GENERIC NO REF						
261000-701[U]	SMOKE DETECTOR (AFT LAV. HEADLINER) DETECTOR								Component	ATA:26
PN:473597-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:3657	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
261000-702 U	SMOKE DETECTOR (BAGGAGE) DETECTOR								Component	ATA:26
PN:473597-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:3658	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
261000-703 U	SMOKE DETECTOR (FWD LAV HEADLINER) DETECTOR								Component	ATA:26
PN:473597-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:3659	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
261000-704 U	SMOKE DETECTOR								Component	ATA:26
PN:473597-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:3552	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
261117-001	NO. 1 ENGINE - FIRE CORE WIRE								Component	ATA:26
PN:473899	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0719	HRS		0	TSN 0					4101.3	
WC#: 26.010	ENC		0	TSN 0					1228	
				PROC. REF: EMM 26-11-17, EMM 26-11-17						
261117-001	NO. 2 ENGINE - FIRE CORE WIRE								Component	ATA:26
PN:473899	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0720	HRS		0	TSN 0					4101.3	
WC#: 26.010	ENC		0	TSN 0					1228	
				PROC. REF: EMM 26-11-17, EMM 26-11-17						
262301-701 U	PORTABLE FIRE EXTINGUISHER								Component	ATA:26
PN:BA21741SR-5	MOS/MSC	O/C	19-Mar-21	TSN 8					34.7	
SN:118091	HRS		3474.7	TSN 0					626.6	
	AFL		1069	TSN 0					156	
262301-701A U	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER (26-21-50-601)								Service	ATA:26
PN:BA21741SR-5	MOS	12	30-Nov-23		30-Nov-24		293 d	30-Nov-2024	2.4	
SN:118091	HRS		4099.1						2.2	
	AFL		1223						2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
262301-701B U	RESTORE PORTABLE FIRE EXTINGUISHER (26-21-50-602)								Service	ATA:26
PN:BA21741SR-5	MOS	72	30-Jul-20		31-Jul-26		901 d	31-Jul-2026	42.4	
SN:118091	HRS									
	AFL									
262301-702 U	PORTABLE FIRE EXTINGUISHER								Component	ATA:26
PN:BA21741SR-5	MOS/MSC	O/C	19-Mar-21	TSN 8					34.7	
SN:118094	HRS		3474.7	TSN 0					626.6	
	AFL		1069	TSN 0					156	
262301-702A U	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER (26-21-50-601)								Service	ATA:26
PN:BA21741SR-5	MOS	12	30-Nov-23		30-Nov-24		293 d	30-Nov-2024	2.4	
SN:118094	HRS		4099.1						2.2	
	AFL		1223						2	
262301-702B U	RESTORE PORTABLE FIRE EXTINGUISHER (26-21-50-602)								Service	ATA:26
PN:BA21741SR-5	MOS	72	30-Jul-20		31-Jul-26		901 d	31-Jul-2026	42.4	
SN:118094	HRS									
	AFL									
262311-701 U	PORTABLE FIRE EXTINGUISHER								Component	ATA:26
PN:466090A	MOS/MSC	O/C	21-Jan-22	TSN 0					24.7	
SN:G39178662	HRS		3689.6	TSN 0					411.7	
	AFL		1117	TSN 0					108	
262311-701A U	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER (26-21-50-601)								Service	ATA:26
PN:466090A	MOS	12	30-Nov-23		30-Nov-24		293 d	30-Nov-2024	2.4	
SN:G39178662	HRS		4099.1						2.2	
	AFL		1223						2	
262311-701B U	RESTORE PORTABLE FIRE EXTINGUISHER (26-21-50-602)								Service	ATA:26
PN:466090A	MOS	144	21-Jan-22		31-Jan-34		3642 d	31-Jan-2034	24.7	
SN:G39178662	HRS		3689.6						411.7	
	AFL		1117						108	
ASB A700-26-006 PART (A)	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 26 - FIRE PROTECTION									
ASB A700-26-006 PART (B)	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-006 REV 01	SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-006 REV 01 PART (A)	ACCOMPLISH SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-006 REV 01 PART (B)	ACCOMPLISH SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-006 REV 02	SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-006 REV 02 PART (A)	ACCOMPLISH SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-006 REV 02 PART (B)	ACCOMPLISH SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 26 - FIRE PROTECTION									
ASB A700-26-006 REV 03 PART (A)	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-006 REV 03 PART (B)	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-010	SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-	23-Oct-14						111.6
	HRS		1448.1						2653.2
	AFL		555						670
ASB A700-26-010 PART (A)	- SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN SERIAL NUMBER VERIFICATION								Bulletin ATA:26
	MOS/MSC	-	23-Oct-14						111.6
	HRS		1448.1						2653.2
	AFL		555						670
ASB A700-26-010 PART (B)	INSPECTION SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN AND/OR REPLACEMENT OF CHECK TEE FITTING(S)								Bulletin ATA:26
	MOS/MSC	-	23-Oct-14						111.6
	HRS		1448.1						2653.2
	AFL		555						670
ASB A700-26-010 REV 01	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-26-010 REV 01 PART (A)	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN SERIAL NUMBER VERIFICATION								Bulletin ATA:26
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
ASB A700-26-010 REV 01 PART (B)	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN INSPECTION AND/OR REPLACEMENT OF CHECK TEE FITTING(S)								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									
EASA 2009-0262 REV 1 U	FIRE EXTINGUISHER - PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT								AD	ATA:26
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
EASA 2009-0278 U	FIRE EXTINGUISHER - PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT								AD	ATA:26
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
EASA 2010-0062 REV 1 U	PORTABLE HALON 1211 FIRE EXTINGUISHER - IDENTIFICATION/REPLACEMENT								AD	ATA:26
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
FAA 1993-24-16 U	TO PREVENT FAILURE OF A PBE UNIT DUE TO DETERIORATED NECK SEAL								AD	ATA:26
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
FAA 2014-20-03	FIRE PROTECTION - INSPECT TO DETERMINE THE PART NUMBER AND FOR ALL AFFECTED CHECK TEE FITTINGS MEASURE FOR CORRECT DEPTH, AND REPLACE IF NECESSARY								AD	ATA:26
	DAYS/MSC	-	23-Oct-14						3398 d	
	HRS		1448.1						2653.2	
	AFL		555						670	
FAA 2015-16-04	APPLIANCE AD - FIRE PROTECTION - MODIFY ALL KIDDE GRAVINER HAND-OPERATED FIRE EXTINGUISHERS HAVING PART NUMBERS 56412-001 (34H), 56411-001 (35H), AND 56412-002 (38H)								AD	ATA:26
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
FAA 2017-19-05	APPLIANCE AD - APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT								AD	ATA:26
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2017-19-05 PARA (F) (1)	INSPECT EACH SIEMENS SMOKE DETECTOR, OR REVIEW YOUR MAINTENANCE RECORDS, TO DETERMINE IF AN AFFECTED DETECTOR IS INSTALLED								AD	ATA:26
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2017-19-05 PARA (F) (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURES 2 AND 3								AD	ATA:26
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2017-19-05 PARA (F) (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURE 4								AD	ATA:26
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2017-19-05 PARA (F) (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN PARAGRAPH (C)(2), SPECIFIED FIGURE 1								AD	ATA:26
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2017-19-05 PARA (G)	DO NOT INSTALL ON ANY AIRPLANE A SMOKE DETECTOR WITH A MANUFACTURING DATE AND P/N LISTED IN FIGURE 2 OR 3 OR LISTED IN FIGURE 4 TO PARAGRAPH (F) OF THIS AD UNLESS THE DETECTOR IS MARKED "SIL PMC-26-002"								AD	ATA:26
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
FAA 2018-22-08	FIRE PROTECTION - VISUAL INSPECTION OF CONNECTIONS BETWEEN THE FIREX SQUIB WIRE HARNESS CONNECTORS AND FIREX BOTTLE CONNECTORS, AND CORRECTIVE ACTION IF NECESSARY								AD	ATA:26
	MOS/MSC	-	19-Nov-18						62.7	
	HRS		3006.2						1095.1	
	AFL		949						276	
FAA 2020-21-02	APPLIANCE AD - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT								AD	ATA:26
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
SB 700-26-008	MODIFICATION - FIRE EXTINGUISHING SYSTEM - REPLACEMENT OF FIRE EXTINGUISHER CONTAINER PART NO. 473776-2, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-	06-Jul-12						139.2	
	HRS		541.7						3559.6	
	AFL		200						1025	
SB 700-26-009	MODIFICATION - SMOKE DETECTION SYSTEM - MODIFICATION TO THE FIDEEX SMOKE DETECTOR WIRING, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-	26-Apr-12						141.5	
	HRS		443.4						3657.9	
	AFL		160						1065	
SB 700-26-009 REV 01	MODIFICATION - SMOKE DETECTION SYSTEM - MODIFICATION TO THE FIDEEX SMOKE DETECTOR WIRING, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-26-011	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (SUPERSEDED BY 700-26-011 REV 01), SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-26-011 REV 01	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-	07-Jul-18						67.1	
	HRS		2892.3						1209	
	AFL		921						304	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 26 - FIRE PROTECTION										
SB 700-26-011 REV 02	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2,A112P1 AND A11P3 WIRE LENGTHS, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-26-011 REV 03	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2,A112P1 AND A11P3 WIRE LENGTHS, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-26-012	MODIFICATION - PORTABLE FIRE EXTINGUISHERS - WASTE CONTAINER FIRE-EXTINGUISHERS REMOVAL, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-26-012 REV 01	MODIFICATION - PORTABLE FIRE EXTINGUISHERS - WASTE CONTAINER FIRE-EXTINGUISHERS REMOVAL, SERVICE BULLETIN								Bulletin	ATA:26
	MOS/MSC	-								
	HRS									
	AFL									
ATA 27 - FLIGHT CONTROLS										
27-00-00-201[S]	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE FORWARD AVIONICS COMPARTMENT, FS202.75 TO FS280.00								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.005	AFL		1069						156	
				PROC. REF: AMM 27 00 00 220 802						PKG:34
27-00-00-202[S]	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MAIN AVIONICS COMPARTMENT, FS280.00 TO FS557.00								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.010	AFL		1069						156	
				PROC. REF: AMM 27 00 00 220 803						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-00-00-203[S]	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MID- LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00								Service	ATA:27
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.015	AFL		1069						156	
				PROC. REF: AMM 27 00 00 220 804						PKG:38
27-00-00-204[S]	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL AND MID WING-TO-FUSELAGE FAIRING								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.020	AFL		1069						156	
				PROC. REF: AMM 27 10 00 220 801						PKG:34
27-00-00-205[S]	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE FLIGHT COMPARTMENT, FS202.75 TO FS280.00								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.025	AFL		1069						156	
				PROC. REF: AMM 27 10 00 220 802						PKG:34
27-00-00-206[S]	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MID AND OUTBOARD WING BOX, WS178.00 TO WS536.50								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.030	AFL		1069						156	
				PROC. REF: AMM 27 10 00 220 803						PKG:34
27-00-00-207[S]	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD WING TRAILING EDGE, WS47.62 TO WS178.00								Service	ATA:27
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 27.035	AFL		1171						54	
				PROC. REF: AMM 27 10 00 220 804						PKG:32
27-00-00-208[S]	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT POWER DISTRIBUTION/ECS COMPARTMENT, FS781.00 TO FS861.00								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.040	AFL		1069						156	
				PROC. REF: AMM 27 00 00 220 807						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-00-00-209[S]	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT, FS861.00 TO FS987.55								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.045	AFL		1069						156	
				PROC. REF: AMM 27 00 00 220 808						PKG:34
27-00-00-210[S]	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE FUSELAGE/STABILIZER SECTION, FS987.55 TO REAR SPAR								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.050	AFL		1069						156	
				PROC. REF: AMM 27 00 00 220 809						PKG:34
27-00-00-211[S]	DETAILED INSPECTION OF THE ELEVATOR CONTROL CABLES IN THE VERTICAL STABILIZER, FRONT SPAR TO REAR SPAR								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.055	AFL		1069						156	
				PROC. REF: AMM 27 30 00 220 801						PKG:34
27-00-00-212[S]	OPERATIONAL TEST OF THE AILERON, ELEVATOR AND RUDDER CONTROL POWER-CONTROL UNITS (PCU)								Service	ATA:27
	MOS		28-Nov-23						2.5	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 27.060	AFL		1223						2	
				PROC. REF: AMM 27 00 00 710 801						PKG:4
27-10-00-201[S]	LUBRICATION OF THE AILERON POWER-CONTROL UNIT (PCU) TOGGLE-LINK SLOTTED BEARINGS								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 838						PKG:34
27-11-00-900-801-01	LH MLG WHEEL WELL ROD								Component	ATA:27
PN:GC415-0030-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:TY-12655	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-11-00-900-801-02	RH MLG WHEEL WELL ROD								Component	ATA:27
PN:GC415-0030-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:TY-12662	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-11-00-900-801-03	MLG WHEEL WELL ROD								Component	ATA:27
PN:GC415-0030-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:TY-11941	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-11-01-900-801-01	PILOT CONTROL WHEEL								Component	ATA:27
PN:GC415-1100-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0234	HRS		0	TSN 0					4101.3	
WC#: 27.410	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 01 000 801, AMM 27 11 01 400 801						
27-11-01-900-801-02	COPILOT CONTROL WHEEL								Component	ATA:27
PN:GC415-1100-8	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0244	HRS		0	TSN 0					4101.3	
WC#: 27.410	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 01 000 801, AMM 27 11 01 400 801						
27-11-05-201	FUNCTIONAL TEST OF THE ROLL DISCONNECT MECHANISM								Service	ATA:27
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 27.065	AFL		690						535	
				PROC. REF: AMM 27 11 05 720 801						PKG:8
27-11-05-202[S]	OPERATIONAL TEST OF THE ROLL DISCONNECT MECHANISM								Service	ATA:27
	MOS		28-Nov-23						2.5	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 27.070	AFL		1223						2	
				PROC. REF: AMM 27 11 05 710 801						PKG:4
27-11-05-900-801-01	ROLL DISCONNECT ASSEMBLY								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.215	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-11-13-900-801-01	LH ROLL SPOILER TRANSDUCER								Component ATA:27
PN:GT415-6006-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N8874	HRS		0	TSN 0					4101.3
WC#: 27.220	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 11 13 000 801, AMM 27 11 13 400 801, AMM 27 11 13 720 801, AMM 27 11 13 820 801					
27-11-13-900-801-02	RH ROLL SPOILER TRANSDUCER								Component ATA:27
PN:GT415-6006-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N8879	HRS		0	TSN 0					4101.3
WC#: 27.220	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 11 13 000 801, AMM 27 11 13 400 801, AMM 27 11 13 720 801, AMM 27 11 13 820 801					
27-11-13-900-802-01	AILERON TORQUE TUBE								Component ATA:27
PN:GC413-1200-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:E061538	HRS		0	TSN 0					4101.3
WC#: 27.225	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-11-17-900-801-01	LH TENSION AILERON REGULATOR								Component ATA:27
PN:GC415-1600-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:FR294	HRS		0	TSN 0					4101.3
WC#: 27.235	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 11 17 000 801, AMM 27 11 17 400 801					
27-11-17-900-801-02	RH TENSION AILERON REGULATOR								Component ATA:27
PN:GC415-1600-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:FR295	HRS		0	TSN 0					4101.3
WC#: 27.235	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 11 17 000 801, AMM 27 11 17 400 801					
27-11-21-900-801-01	LEFT AILERON POSITION TRANSDUCER								Component ATA:27
PN:GT415-0200-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:M9435	HRS		0	TSN 0					4101.3
WC#: 27.240	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 11 21 000 801, AMM 27 11 21 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-11-21-900-801-02	RIGHT AILERON POSITION TRANSDUCER								Component	ATA:27
PN:GT415-0200-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:M9440	HRS		0	TSN 0					4101.3	
WC#: 27.240	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 21 000 801, AMM 27 11 21 400 801						
27-11-25-101	FUNCTIONAL TEST OF THE AILERON POWER-CONTROL UNIT (PCU)								Service	ATA:27
	MOS		19-Mar-21					23-Sep-2025	34.7	
	HRS	1500	3474.7		4974.7		873.4		626.6	
WC#: 27.080	AFL		1069						156	
				PROC. REF: AMM 27 11 25 720 801						PKG:5
27-11-25-102	FUNCTIONAL TEST OF THE AILERON PCU BUNGEE								Service	ATA:27
	MOS		05-Jul-18					09-Jul-2027	67.2	
	HRS	3000 (+50/-50)	2892.3	Adj 50	5942.3	5992.3	1841 (+50)		1209	
WC#: 27.085	AFL		921						304	
				PROC. REF: AMM 27 11 25 720 802						PKG:8
27-11-25-900-801-01	NO. 1 AILERON PCU								Component	ATA:27
PN:GT411-1700-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1566	HRS		0	TSN 0					4101.3	
WC#: 27.245	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801						
27-11-25-900-801-02	NO. 2 AILERON PCU								Component	ATA:27
PN:GT411-1700-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1564	HRS		0	TSN 0					4101.3	
WC#: 27.245	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801						
27-11-25-900-801-03	NO. 3 AILERON PCU								Component	ATA:27
PN:GT411-1700-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1553	HRS		0	TSN 0					4101.3	
WC#: 27.245	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801						
27-11-25-900-801-04	NO. 4 AILERON PCU								Component	ATA:27
PN:GT411-1700-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1554	HRS		0	TSN 0					4101.3	
WC#: 27.245	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-11-25-900-802-01	LH OUTBD WING ROD CONTROL								Component	ATA:27
PN:GC415-0030-45	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:TY-13753	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-11-25-900-802-02	RH OUTBD WING ROD CONTROL								Component	ATA:27
PN:GC415-0030-45	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:TY-13752	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-11-35-101	FUNCTIONAL TEST OF THE AILERON CABLE TENSION - FLIGHT COMPARTMENT CABLES								Service	ATA:27
	MOS	30 (+3m/-3m)	30-Dec-22	Adj 3	30-Sep-25	31-Dec-25	597 d (+92)	30-Sep-2025	13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
				PROC. REF: AMM 27 11 35 720 801						PKG:32
27-11-35-102	FUNCTIONAL TEST OF THE AILERON CABLE TENSION - FUSELAGE CABLES								Service	ATA:27
	MOS	30 (+3m/-3m)	30-Dec-22	Adj 3	30-Sep-25	31-Dec-25	597 d (+92)	30-Sep-2025	13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
				PROC. REF: AMM 27 11 35 720 802						PKG:32
27-11-35-103	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL (POST SB 700-27-086 PART I OR PART J OR PART K OR PART L OR PART M OR PART N OR PART O OR PART P)								Service	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									
				PROC. REF: AMM 27 11 35 220 801						
27-11-35-104	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE WING TRAILING EDGE, AT THE INNER, MID AND OUTER FLAP AREAS (POST SB 700-27-086 PART M OR PART N OR PART O OR PART P)								Service	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									
				PROC. REF: AMM 27 11 35 220 802						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-11-35-201	FUNCTIONAL TEST OF THE AILERON CABLE - WING CABLES								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-26	19-Sep-26	870 d (+81)	30-Jun-2026	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 27 11 35 720 803						PKG:34
27-12-05-900-801-01	AILERON-MLG WHEEL WELL TRIM ACTUATOR								Component	ATA:27
PN:GT412-1500-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3077	HRS		0	TSN 0					4101.3	
WC#: 27.250	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 12 05 000 801, AMM 27 12 05 400 801						
27-20-00-201[S]	LUBRICATION OF THE RUDDER POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 839						PKG:34
27-21-00-201[S]	GENERAL VISUAL INSPECTION OF THE SINGLE-RUDDER CONTROL-PATH AND PCU LINKAGE CENTERING-SPRINGS								Service	ATA:27
	MOS									
	HRS	4500 (+50/-50)	0						4101.3	
WC#: 27.090	AFL									
				PROC. REF: AMM 27 21 00 210 802						PKG:10
27-21-00-900-801-01	LH FWD AVIONICS BAY ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-00-900-801-02	RH FWD AVIONICS BAY ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-00-900-802-01	FWD AVIONICS BAY INTERCONNECT CONTROL ROD ASSEMBLY								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-21-00-900-803-01	RUDDER								Component	ATA:27
PN:GS268-0001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B380	HRS		0	TSN 0					4101.3	
WC#: 27.290	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 21 13 000 801, AMM 27 21 13 400 801						
27-21-01-900-801-01	RUDDER (STABILIXER QUARDANT) ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-01-900-802-01	RUDDER LINEAR FEEL UNIT								Component	ATA:27
PN:GC415-2360-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:FR1151	HRS		0	TSN 0					4101.3	
WC#: 27.255	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801, AMM 27 21 01 000 802, AMM 27 21 01 400 802						
27-21-05-201[S]	OPERATIONAL TEST OF THE RUDDER LOAD LIMITER								Service	ATA:27
	MOS									
	HRS	4500 (+50/-50)	0						4101.3	
WC#: 27.095	AFL									
				PROC. REF: AMM 27 21 05 710 801						PKG:10
27-21-05-900-801-01	RUDDER LIMITER								Component	ATA:27
PN:GC415-2400-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:FR0343	HRS		0	TSN 0					4101.3	
WC#: 27.265	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 21 05 000 801, AMM 27 21 05 400 801						
27-21-05-900-801-02	RUDDER LIMITER UNIT								Component	ATA:27
PN:GC413-2600-7/03	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:D935624	HRS		0	TSN 0					4101.3	
WC#: 27.305	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 21 05 000 801, AMM 27 21 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-21-05-900-802-01	LH LINEAR YAW DAMPER ACTUATOR ASSEMBLY								Component	ATA:27
PN:GC415-2565-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0811H426	HRS		0	TSN 0					4101.3	
WC#: 27.270	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-05-900-802-02	RH LINEAR YAW DAMPER ACTUATOR ASSEMBLY								Component	ATA:27
PN:GC415-2565-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0812H437	HRS		0	TSN 0					4101.3	
WC#: 27.270	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-09-101	OPERATIONAL TEST OF THE RUDDER POWER-CONTROL UNIT (PCU) INPUT LIMITERS								Service	ATA:27
	MOS		10-Jul-18					09-Jul-2027	67	
	HRS	3000 (+50/-50)	2892.3	Adj 50	5942.3	5992.3	1841 (+50)		1209	
WC#: 27.100	AFL		921						304	
				PROC. REF: AMM 27 21 09 710 801						PKG:8
27-21-09-900-801-01	NO. 1 LOAD LIMITER								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.275	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801						
27-21-09-900-801-02	NO. 2 LOAD LIMITER								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.275	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801						
27-21-09-900-801-03	NO. 3 LOAD LIMITER								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.275	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801						
27-21-13-101	FUNCTIONAL TEST OF THE RUDDER POWER-CONTROL UNITS (PCU)								Service	ATA:27
	MOS		11-Jul-18					09-Jul-2027	67	
	HRS	3000 (+50/-50)	2892.3	Adj 50	5942.3	5992.3	1841 (+50)		1209	
WC#: 27.105	AFL		921						304	
				PROC. REF: AMM 27 21 13 720 801						PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-21-17-900-801-01	RUDDER POSITION TRANSDUCER								Component ATA:27
PN:GT415-0200-5	MOS/MSC	O/C	21-Jun-21	TSN 0					31.7
SN:82558	HRS		3606	TSN 0					495.3
WC#: 27.280	AFL		1100	TSN 0					125
				PROC. REF: AMM 27 21 17 000 801, AMM 27 21 17 400 801					
27-21-21-900-801-01	NO. 1 RUDDER PCU								Component ATA:27
PN:GT411-2800-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1158	HRS		0	TSN 0					4101.3
WC#: 27.285	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 21 13 000 801, AMM 27 21 13 400 801					
27-21-21-900-801-02	NO. 2 RUDDER PCU								Component ATA:27
PN:GT411-2800-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1151	HRS		0	TSN 0					4101.3
WC#: 27.285	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 21 13 000 801, AMM 27 21 13 400 801					
27-21-21-900-801-03	NO. 3 RUDDER PCU								Component ATA:27
PN:GT411-2800-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1153	HRS		0	TSN 0					4101.3
WC#: 27.285	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 21 13 000 801, AMM 27 21 13 400 801					
27-21-25-900-801-01	LOB PEDAL PILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-21-25-900-801-02	LIB PEDAL PILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-21-25-900-801-03	RIB PEDAL COPILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-21-25-900-801-04	ROB PEDAL COPILOT CONTROL ROD ASSY - (RUDDER PEDAL)								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-25-900-802-01	LOB PEDAL PILOT ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-25-900-802-02	LIB PEDAL PILOT ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-25-900-802-03	RIB PEDAL COPILOT ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-25-900-802-04	ROB PEDAL COPILOT ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-21-27-101	FUNCTIONAL TEST OF THE RUDDER CABLE TENSION								Service	ATA:27
	MOS	30 (+3m/-3m)	30-Dec-22	Adj 3	30-Sep-25	31-Dec-25	597 d (+92)	30-Sep-2025	13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
				PROC. REF: AMM 27 21 27 720 801						PKG:32
27-22-05-900-801-01	RUDDER FS1047, WL54 TRIM ACTUATOR								Component	ATA:27
PN:GT412-2550-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2207	HRS		0	TSN 0					4101.3	
WC#: 27.295	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 22 05 000 801, AMM 27 22 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-23-00-201[S]	VISUAL CHECK OF THE RUDDER TRAVEL-LIMITING SYSTEM								Service ATA:27
	MOS								
	HRS	4500 (+50/-50)	0						4101.3
WC#: 27.110	AFL								
				PROC. REF: AMM 27 23 00 210 801					PKG:10
27-23-01-900-801-01	LEFT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR								Component ATA:27
PN:GT412-1500-5	MOS/MSC	O/C	17-Jul-18	TSN 148					66.8
SN:2188	HRS		2892.3	TSN 4925					1209
WC#: 27.300	AFL		921	TSN 546					304
				PROC. REF: AMM 27 23 01 000 801, AMM 27 23 01 400 801					
27-23-01-900-801-02	RIGHT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR								Component ATA:27
PN:GT412-1500-5	MOS/MSC	O/C	20-Aug-18	TSR 0					65.7
SN:5182	HRS		2918.3	TSR 0					1183
WC#: 27.300	AFL		930	TSR 0					295
				PROC. REF: AMM 27 23 01 000 801, AMM 27 23 01 400 801					
27-23-05-900-801-01	MID VERTICAL. STAB - RIB NO. 4 - NO. 5 ROD CONTROL								Component ATA:27
PN:GC415-0030-41	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:TY-13173	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-23-05-900-801-02	LIMITER OUTPUT ROD CONTROL								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-23-09-900-801-01	LH RUDDER POSITION TRANSDUCER								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.310	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 23 09 000 801, AMM 27 23 09 400 801					
27-23-09-900-801-02	RH RUDDER POSITION TRANSDUCER								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.310	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 23 09 000 801, AMM 27 23 09 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-30-00-201[S]	LUBRICATION OF THE ELEVATOR POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 840						PKG:34
27-31-00-900-801-01	LH FORWARD QUADRANT								Component	ATA:27
PN:GC413-3300-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E401690	HRS		0	TSN 0					4101.3	
WC#: 27.315	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-00-900-801-02	RH FORWARD QUADRANT								Component	ATA:27
PN:GC413-3350-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E401827	HRS		0	TSN 0					4101.3	
WC#: 27.315	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-00-900-802-01	LH ELEVATOR MID VERTICAL STAB ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-00-900-802-02	RH ELEVATOR MID VERTICAL STAB ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-00-900-803-01	LH MID VERTICAL STABILZER ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-00-900-803-02	RH MID VERTICAL STABILZER ROD CONTROL								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-31-05-201	FUNCTIONAL TEST OF THE PITCH DISCONNECT MECHANISM								Service	ATA:27
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 27.115	AFL		690						535	
				PROC. REF: AMM 27 31 05 720 801						PKG:8
27-31-05-202 S	OPERATIONAL TEST OF THE PITCH DISCONNECT MECHANISM								Service	ATA:27
	MOS		28-Nov-23						2.5	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 27.120	AFL		1223						2	
				PROC. REF: AMM 27 31 05 710 801						PKG:4
27-31-05-900-801-01	PITCH DISCONNECT								Component	ATA:27
PN:GC415-3250-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.325	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 31 05 000 801, AMM 27 31 05 400 801						
27-31-09-900-801-01	LH ASSEMBLY COLUMN								Component	ATA:27
PN:GC415-3149-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09375	HRS		0	TSN 0					4101.3	
WC#: 27.320	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-09-900-801-02	RH ASSEMBLY COLUMN								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.320	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-09-900-802-01	PITCH LOCK SOLENOID								Component	ATA:27
PN:GC415-3230-1	MOS/MSC	O/C	02-Mar-15	TSN 3					107.3	
SN:1136	HRS		1589.8	TSN 0					2511.5	
WC#: 27.330	AFL		590	TSN 0					635	
				PROC. REF: AMM 27 31 09 000 802, AMM 27 31 09 400 802						
27-31-13-900-801-01	LEFT ELEVATOR LOAD LIMITER								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.340	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 31 13 000 801, AMM 27 31 13 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-31-13-900-801-02	RIGHT ELEVATOR LOAD LIMITER								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.340	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 13 000 801, AMM 27 31 13 400 801					
27-31-13-900-802-01	LH ELEVATOR CONTROL ROD								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-31-13-900-802-02	RH ELEVATOR CONTROL ROD								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-31-13-900-803-01	LH HORIZONTAL STAB ROD CONTROL								Component ATA:27
PN:GC415-0030-31	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:TY-13308	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-31-13-900-803-02	RH HORIZONTAL STAB ROD CONTROL								Component ATA:27
PN:GC415-0030-31	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:TY-13313	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-31-13-900-803-04	LH HORIZONTAL STAB ROD CONTROL								Component ATA:27
PN:GC415-0030-25	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:TY-13784	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-31-13-900-803-05	RH HORIZONTAL STAB ROD CONTROL								Component ATA:27
PN:GC415-0030-39	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:TY-13562	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-31-17-201	OPERATIONAL TEST OF THE ELEVATOR POWER-CONTROL UNIT (PCU) LOAD LIMITERS								Service ATA:27
	MOS		19-Mar-16					26-Sep-2025	94.7
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3
WC#: 27.125	AFL		690						535
				PROC. REF: AMM 27 31 17 710 801					PKG:8
27-31-17-900-801-01	NO. 1 LOAD LIMITER								Component ATA:27
PN:GC415-3790-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:FR1381	HRS		0	TSN 0					4101.3
WC#: 27.345	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801					
27-31-17-900-801-02	NO. 2 LOAD LIMITER								Component ATA:27
PN:GC415-3790-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:FR1382	HRS		0	TSN 0					4101.3
WC#: 27.345	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801					
27-31-17-900-801-03	NO. 3 LOAD LIMITER								Component ATA:27
PN:GC415-3790-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:FR1390	HRS		0	TSN 0					4101.3
WC#: 27.345	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801					
27-31-17-900-801-04	NO. 4 LOAD LIMITER								Component ATA:27
PN:GC415-3790-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:FR1390	HRS		0	TSN 0					4101.3
WC#: 27.345	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801					
27-31-19-101	DETAILED INSPECTION OF THE BEARING IN THE ELEVATOR TORQUE TUBE ASSEMBLY								Service ATA:27
	MOS	60 (+3m/-3m)	20-Dec-09		31-Mar-26 (M)	30-Jun-26	779 d (+91)	31-Mar-2026	169.7
	HRS		0						4101.3
	AFL		0						1225
				PROC. REF: AMM 27 31 19 220 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-31-21-101	FUNCTIONAL TEST OF THE ELEVATOR POWER-CONTROL UNITS (PCU)								Service ATA:27
	MOS		19-Mar-21					23-Sep-2025	34.7
	HRS	1500	3474.7		4974.7		873.4		626.6
WC#: 27.130	AFL		1069						156
				PROC. REF: AMM 27 31 21 720 801					PKG:5
27-31-21-900-801-01	NO. 1 ELEVATOR PCU								Component ATA:27
PN:GT411-3800-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SN1421	HRS		0	TSN 0					4101.3
WC#: 27.350	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801					
27-31-21-900-801-02	NO. 2 ELEVATOR PCU								Component ATA:27
PN:GT411-3800-9	MOS/MSC	O/C	28-Jul-14						114.5
SN:0486	HRS		1391.1						2710.2
WC#: 27.350	AFL		537						688
				PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801					
27-31-21-900-801-03	NO. 3 ELEVATOR PCU								Component ATA:27
PN:GT411-3800-9	MOS/MSC	O/C	19-Mar-21						34.7
SN:0026	HRS		3474.7						626.6
WC#: 27.350	AFL		1069						156
				PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801					
27-31-21-900-801-04	NO. 4 ELEVATOR PCU								Component ATA:27
PN:GT411-3800-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SN1560	HRS		0	TSN 0					4101.3
WC#: 27.350	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801					
27-31-25-900-801-01	LEFT ELEVATOR POSITION TRANSDUCER								Component ATA:27
PN:GT415-0200-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N9533	HRS		0	TSN 0					4101.3
WC#: 27.355	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 25 000 801, AMM 27 31 25 400 801					
27-31-25-900-801-02	RIGHT ELEVATOR POSITION TRANSDUCER								Component ATA:27
PN:GT415-0200-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N9155	HRS		0	TSN 0					4101.3
WC#: 27.355	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 31 25 000 801, AMM 27 31 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-31-29-900-801-01	LH ELEVATOR								Component	ATA:27
PN:GS278-0001-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B375	HRS		0	TSN 0					4101.3	
WC#: 27.360	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 31 29 000 801, AMM 27 31 29 400 801						
27-31-29-900-801-02	RH ELEVATOR								Component	ATA:27
PN:GS278-0001-8	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B374	HRS		0	TSN 0					4101.3	
WC#: 27.360	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 31 29 000 801, AMM 27 31 29 400 801						
27-31-33-900-801-01	LH FWD QUADRANT ELEVATOR CONTROL ROD								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-33-900-801-02	RH FWD QUADRANT ELEVATOR CONTROL ROD								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-31-33-900-803-01	LH ELEVATOR TENSION REGULATOR								Component	ATA:27
PN:GC415-3305-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:FR441	HRS		0	TSN 0					4101.3	
WC#: 27.365	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 31 33 000 801, AMM 27 31 33 400 801						
27-31-33-900-803-02	RH ELEVATOR TENSION REGULATOR								Component	ATA:27
PN:GC415-3305-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:FR420	HRS		0	TSN 0					4101.3	
WC#: 27.365	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 31 33 000 801, AMM 27 31 33 400 801						
27-31-35-201	FUNCTIONAL TEST OF THE ELEVATOR CABLE TENSION								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-26	19-Sep-26	870 d (+81)	30-Jun-2026	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 27 31 35 720 801						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-32-01-900-801-01	RIGHT FORWARD STALL PROTECTION COMPUTER								Component ATA:27
PN:GH582-3001-17	MOS/MSC	O/C	04-Feb-15	TSR 0					108.2
SN:522	HRS		1558.6	TSR 0					2542.7
WC#: 27.370	AFL		582	TSR 0					643
				PROC. REF: AMM 27 32 01 000 801, AMM 27 32 01 400 801					
27-32-05-900-801-01	PILOT STICK SHAKER								Component ATA:27
PN:GH582-3003-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1424	HRS		0	TSN 0					4101.3
WC#: 27.375	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 32 05 000 801, AMM 27 32 05 400 801					
27-32-05-900-801-02	COPILOT STICK SHAKER								Component ATA:27
PN:GH582-3003-1	MOS/MSC	O/C	17-Dec-14	TSN 0					109.8
SN:2775	HRS		1509.9	TSN 0					2591.4
WC#: 27.375	AFL		562	TSN 0					663
				PROC. REF: AMM 27 32 05 000 801, AMM 27 32 05 400 801					
27-32-09-900-801-01	LH AOA SENSOR								Component ATA:27
PN:GH582-3002-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:828	HRS		0	TSN 0					4101.3
WC#: 27.380	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 32 09 000 801, AMM 27 32 09 400 801					
27-32-09-900-801-02	RH AOA SENSOR								Component ATA:27
PN:GH582-3002-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:828	HRS		0	TSN 0					4101.3
WC#: 27.380	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 32 09 000 801, AMM 27 32 09 400 801					
27-32-13-900-801-01	MACH TRANSDUCER								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.385	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-32-17-900-801-01	LH STICK PUSHER ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.390	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 32 17 000 801, AMM 27 32 17 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-32-17-900-801-02	RH STICK PUSHER ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.390	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 32 17 000 801, AMM 27 32 17 400 801					
27-32-21-900-801-01	ASSY CAPSTAN								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.395	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 32 21 000 801, AMM 27 32 21 400 801					
27-33-00-900-803-01	LH ELEVATOR ROD CONTROL								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-33-00-900-803-02	RH ELEVATOR ROD CONTROL								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-33-01-900-801-01	LH PITCH WHEEL SIMULATOR								Component ATA:27
PN:GC415-3490-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:779	HRS		0	TSN 0					4101.3
WC#: 27.400	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 33 01 000 801, AMM 27 33 01 400 801					
27-33-01-900-801-02	RH PITCH WHEEL SIMULATOR								Component ATA:27
PN:GC415-3490-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:734	HRS		0	TSN 0					4101.3
WC#: 27.400	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 33 01 000 801, AMM 27 33 01 400 801					
27-33-05-900-801-01	LEFT PITCH FEEL TRIM ACTUATOR								Component ATA:27
PN:GT412-1500-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2989	HRS		0	TSN 0					4101.3
WC#: 27.405	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 33 05 000 801, AMM 27 33 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-33-05-900-801-02	RIGHT PITCH FEEL TRIM ACTUATOR								Component	ATA:27
PN:GT412-1500-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2984	HRS		0	TSN 0					4101.3	
WC#: 27.405	AFL		0	TSN 0					1225	
			PROC. REF: AMM 27 33 05 000 801, AMM 27 33 05 400 801							
27-41-00-201	LUBRICATION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR								Service	ATA:27
	MOS	15 (+3m/-3m)	28-Nov-23	Adj 3	31-May-25	31-Aug-25	475 d (+92)	15-Feb-2025	2.5	
	HRS	500 (+50/-50)	4099.1	Adj 50	4649.1	4699.1	547.8 (+50)		2.2	
	AFL		1223						2	
			PROC. REF: AMM 12 22 00 640 812							PKG:2
27-41-00-202 S	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.135	AFL		1069						156	
			PROC. REF: AMM 27 41 09 220 802							PKG:34
27-41-09-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (EXCLUDING AIRCRAFT ATTACHMENT PINS)								Service	ATA:27
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 27.140	AFL	T:7500	0		7500		6275		1225	
			PROC. REF: AMM 27 41 09 280 801							PKG:76
27-41-09-103	DETAILED INSPECTION OF PITCH TRIM ACTUATOR								Service	ATA:27
	MOS		28-Nov-23					12-Jan-2025	2.5	
	HRS	500	4099.1		4599.1		497.8		2.2	
WC#: 27.145	AFL		1223						2	
			PROC. REF: AMM 27 41 09 220 801							PKG:2
27-41-09-104	DISCARD THE PITCH TRIM ACTUATOR, PART NO. GT412-4001-3								Service	ATA:27
PN:GT412-4001-7	MOS/MSC	O/C	20-Dec-09						169.7	
SN:0405	HRS		0						4101.3	
	AFL		0						1225	
			PROC. REF: AMM 27 41 09 961 801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-41-09-105	DISCARD THE PITCH TRIM ACTUATOR, PART NO. GT412-4001-5/7								Service	ATA:27
PN:GT412-4001-7	MOS/MSC	O/C							169.7	
SN:0405	HRS		EFF						4101.3	
	AFL								1225	
				PROC. REF: AMM 27 41 09 961 801						
27-41-09-106	RESTORATION OF THE PITCH TRIM ACTUATOR (GEAR HOUSINGREPLACEMENT), PART NO. GT412-4001-5								Service	ATA:27
PN:GT412-4001-7	MOS/MSC	N/A	20-Dec-09						169.7	
SN:0405	HRS		0						4101.3	
WC#: 27.150	AFL		0						1225	
				PROC. REF: AMM 27 41 29 610 801						
27-41-09-107	RESTORATION OF THE PITCH TRIM ACTUATOR, PART NO. GT412-4001-7								Service	ATA:27
PN:GT412-4001-7	MOS		20-Dec-09					29-Mar-2050	169.7	
SN:0405	HRS		0						4101.3	
	AFL	7500	0		7500 (M)		6275		1225	
				PROC. REF: AMM 27 41 09 840 801						
27-41-09-900-801-01	PITCH TRIM ACTUATOR								Component	ATA:27
PN:GT412-4001-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0405	HRS		0	TSN 0					4101.3	
WC#: 27.145	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 41 09 000 801, AMM 27 41 09 400 801						
27-41-17-900-801-01	DRIVE UNIT - HORIZONTAL STAB MOTOR								Component	ATA:27
PN:GT415-4002-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3181	HRS		0	TSN 0					4101.3	
WC#: 27.415	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 41 17 000 801, AMM 27 41 17 400 801						
27-50-00-201[S]	LUBRICATION OF THE FLAP DRIVE TORQUE-TUBE SPLINES								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.155	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 827						PKG:34
27-50-00-202[S]	LUBRICATION OF THE SLAT DRIVE TORQUE-TUBE SPLINES								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.160	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 828						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-50-00-203 S	LUBRICATION OF THE FLAP ACTUATOR BALLSCREWS AND BALLNUTS								Service	ATA:27
	MOS	15 (+3m/-3m)	28-Nov-23						2.5	
	HRS		4099.1						2.2	
WC#: 27.165	AFL		1223						2	
				PROC. REF: AMM 12 22 00 640 829						PKG:31
27-50-00-204 S	LUBRICATION OF THE SLAT ACTUATOR BALLSCREWS								Service	ATA:27
	MOS	15 (+3m/-3m)	27-Nov-23						2.5	
	HRS		4099.1						2.2	
WC#: 27.170	AFL		1223						2	
				PROC. REF: AMM 12 22 00 640 830						PKG:31
27-50-00-205 S	LUBRICATION OF THE FLAP ROLLERS								Service	ATA:27
	MOS		19-Mar-21						34.7	
	HRS	1500 (+50/-50)	3474.7						626.6	
WC#: 27.175	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 831						PKG:5
27-50-00-206 S	LUBRICATION OF THE SLAT ROLLERS								Service	ATA:27
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 27.180	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 832						PKG:34
27-50-00-207 S	LUBRICATION OF THE FLAP SKEW SENSOR NO.1 (A/C 9001 AND SUBS), AND FLAP SKEW SENSORS NO. 2, 3 AND 4, (A/C 9002 TO 9126 AND 9128 TO 9178, PRE SB 700-27-049)								Service	ATA:27
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 27.185	AFL	450 (+50/-50)	996						229	
				PROC. REF: AMM 12 22 00 640 835						PKG:58
27-51-01-900-801-01	FLAP/SLAT LEVER								Component	ATA:27
PN:GT415-5600-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E0422	HRS		0	TSN 0					4101.3	
WC#: 27.420	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 51 01 000 801, AMM 27 51 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-51-05-900-801-01	LH SFCU FAN								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.425	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801					
27-51-05-900-801-02	RH SFCU FAN								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.425	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801					
27-51-05-900-802-01	LH FLAP/SLAT CONTROL UNIT								Component ATA:27
PN:GT415-5900-17	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1435	HRS		0	TSN 0					4101.3
WC#: 27.430	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801					
27-51-05-900-802-02	RH FLAP/SLAT CONTROL UNIT								Component ATA:27
PN:GT415-5900-17	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1426	HRS		0	TSN 0					4101.3
WC#: 27.430	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801					
27-52-01-900-801-01	LEFT MLG WHEEL WELL FLAP TORQUE TUBE								Component ATA:27
PN:GT415-5201-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2739	HRS		0	TSN 0					4101.3
WC#: 27.435	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801					
27-52-01-900-801-02	LIB FLAP TORQUE TUBE								Component ATA:27
PN:GT415-5201-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2975	HRS		0	TSN 0					4101.3
WC#: 27.440	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801					
27-52-01-900-801-03	RIB FLAP TORQUE TUBE								Component ATA:27
PN:GT415-5201-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2971	HRS		0	TSN 0					4101.3
WC#: 27.440	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-52-09-900-801-01	LEFT NO.1 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.445	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-09-900-801-02	LEFT NO.2 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.445	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-09-900-801-03	LEFT NO.3 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.445	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-09-900-801-04	LEFT NO.4 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:GT412-5011-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:4282	HRS		0	TSN 0					4101.3
WC#: 27.445	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-09-900-801-05	RIGHT NO.1 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.450	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-09-900-801-06	RIGHT NO.2 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:GT412-5008-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2889	HRS		0	TSN 0					4101.3
WC#: 27.450	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-09-900-801-07	RIGHT NO.3 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.450	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-52-09-900-801-08	RIGHT NO.4 FLAP ACTUATOR GEARBOX								Component ATA:27
PN:GT412-5011-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:4290	HRS		0	TSN 0					4101.3
WC#: 27.450	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-09-900-802-01	LH NO.1 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:GT412-5002-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2898	HRS		0	TSN 0					4101.3
WC#: 27.455	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					
27-52-09-900-802-02	RH NO.1 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:GT412-5002-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2893	HRS		0	TSN 0					4101.3
WC#: 27.460	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					
27-52-09-900-802-03	LH NO.2 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:GT412-5005-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2850	HRS		0	TSN 0					4101.3
WC#: 27.465	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					
27-52-09-900-802-04	RH NO.2 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:GT412-5004-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2847	HRS		0	TSN 0					4101.3
WC#: 27.470	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					
27-52-09-900-802-05	LH NO.3 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:GT412-5006-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2890	HRS		0	TSN 0					4101.3
WC#: 27.475	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					
27-52-09-900-802-06	RH NO.3 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:GT412-5006-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2874	HRS		0	TSN 0					4101.3
WC#: 27.480	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-52-09-900-802-07	LH NO.4 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.485	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					
27-52-09-900-802-08	RH NO.4 FLAP ACTUATOR ASSEMBLY								Component ATA:27
PN:GT412-5008-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2895	HRS		0	TSN 0					4101.3
WC#: 27.490	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801					
27-52-13-900-801-01	FLAP LH WS131.500 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5101-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3750	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-52-13-900-801-02	FLAP LH WS199.000 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5101-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3751	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-52-13-900-801-03	FLAP RH WS131.500 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5101-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3677	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-52-13-900-801-04	FLAP RH WS199.000 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5101-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3679	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-52-21-900-801-01	LH INBOARD FLAP								Component ATA:27
PN:GM148-1001-33	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0379	HRS		0	TSN 0					4101.3
WC#: 57.720	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-52-21-900-801-02	RH INBOARD FLAP								Component ATA:27
PN:GM148-1001-34	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0376	HRS		0	TSN 0					4101.3
WC#: 57.720	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-25-900-801-01	LH MIDDLE FLAP								Component ATA:27
PN:GM148-1002-29	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0377	HRS		0	TSN 0					4101.3
WC#: 57.715	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-25-900-801-02	RH MIDDLE FLAP								Component ATA:27
PN:GM148-1002-30	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0375	HRS		0	TSN 0					4101.3
WC#: 57.715	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-29-900-801-01	LH OUTBOARD FLAP								Component ATA:27
PN:GM148-1003-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0377	HRS		0	TSN 0					4101.3
WC#: 57.710	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-29-900-801-02	RH OUTBOARD FLAP								Component ATA:27
PN:GM148-1003-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0375	HRS		0	TSN 0					4101.3
WC#: 57.710	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-52-41-900-801-01	LH ELECTRICAL SLAT/FLAP PDU MOTOR								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.575	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 41 000 801, AMM 27 52 41 400 801, AMM 27 53 37 000 801, AMM 27 53 37 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-52-41-900-801-02	RH ELECTRICAL SLAT/FLAP PDU MOTOR								Component	ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 27.575	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 52 41 000 801, AMM 27 52 41 400 801, AMM 27 53 37 000 801, AMM 27 53 37 400 801						
27-52-49-900-801-01	LEFT FLAP (FLAP/SLAT) RESOLVER								Component	ATA:27
PN:GT415-5300-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B1771	HRS		0	TSN 0					4101.3	
WC#: 27.495	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 41 820 801, AMM 27 52 49 000 801, AMM 27 52 49 400 801						
27-52-49-900-801-02	RIGHT FLAP (FLAP/SLAT) RESOLVER								Component	ATA:27
PN:GT415-5300-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B1780	HRS		0	TSN 0					4101.3	
WC#: 27.495	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 41 820 801, AMM 27 52 49 000 801, AMM 27 52 49 400 801						
27-52-53-900-801-01	LEFT FLAP ASSYMETRY BRAKE								Component	ATA:27
PN:GT415-5500-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2916	HRS		0	TSN 0					4101.3	
WC#: 27.500	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 52 53 000 801, AMM 27 52 53 400 801						
27-52-53-900-801-02	RIGHT FLAP ASSYMETRY BRAKE								Component	ATA:27
PN:GT415-5500-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2988	HRS		0	TSN 0					4101.3	
WC#: 27.500	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 52 53 000 801, AMM 27 52 53 400 801						
27-52-57-101	DETAILED INSPECTION OF THE FLAP ROLLERS								Service	ATA:27
	MOS		09-Jul-18					09-Jul-2027	67.1	
	HRS	3000 (+50/-50)	2892.3	Adj 50	5942.3	5992.3	1841 (+50)		1209	
WC#: 27.190	AFL		921						304	
				PROC. REF: AMM 27 52 57 220 801						PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-53-01-900-801-01	LH SLAT NO. 3 SLAT TORQUE TUBE								Component ATA:27
PN:GT415-5200-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2953	HRS		0	TSN 0					4101.3
WC#: 27.505	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801					
27-53-01-900-801-02	RIGHT SLAT NO. 3 SLAT TORQUE TUBE								Component ATA:27
PN:GT415-5200-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2980	HRS		0	TSN 0					4101.3
WC#: 27.505	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801					
27-53-01-900-801-03	LEFT SLAT NO.1 SLAT TORQUE TUBE								Component ATA:27
PN:GT415-5207-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2932	HRS		0	TSN 0					4101.3
WC#: 27.510	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801					
27-53-01-900-801-04	RIGHT SLAT NO. 1 SLAT TORQUE TUBE								Component ATA:27
PN:GT415-5207-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2941	HRS		0	TSN 0					4101.3
WC#: 27.510	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801					
27-53-01-900-801-05	LH SLAT NO. 4 SLAT TORQUE TUBE								Component ATA:27
PN:GT415-5200-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2966	HRS		0	TSN 0					4101.3
WC#: 27.515	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801					
27-53-01-900-801-06	RIGHT SLAT NO. 4 SLAT TORQUE TUBE								Component ATA:27
PN:GT415-5200-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2969	HRS		0	TSN 0					4101.3
WC#: 27.515	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801					
27-53-01-900-801-07	LH SLAT NO. 1 TORQUE TUBE								Component ATA:27
PN:GT415-5200-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2951	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-53-01-900-801-08	RH SLAT NO. 2 TORQUE TUBE								Component	ATA:27
PN:GT415-5200-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2944	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801						
27-53-01-900-801-09	LH SLAT NO. 1 TORQUE TUBE								Component	ATA:27
PN:GT415-5201-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2969	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801						
27-53-01-900-801-10	RH SLAT NO. 2 TORQUE TUBE								Component	ATA:27
PN:GT415-5201-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2970	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801						
27-53-01-900-801-11	LH SLAT NO. 1 TORQUE TUBE								Component	ATA:27
PN:GT415-5201-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2952	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801						
27-53-01-900-801-12	RH SLAT NO. 2 TORQUE TUBE								Component	ATA:27
PN:GT415-5201-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2955	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801						
27-53-09-101	FUNCTIONAL TEST OF THE SLAT SYSTEM ACTUATORS								Service	ATA:27
	MOS		10-Jul-18					09-Jul-2027	67	
	HRS	3000 (+50/-50)	2892.3	Adj 50	5942.3	5992.3	1841 (+50)		1209	
WC#: 27.195	AFL		921						304	
				PROC. REF: AMM 27 53 09 720 804						PKG:8
27-53-09-900-803-01	LEFT NO.1 SLAT ACTUATOR								Component	ATA:27
PN:GT412-5601-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2880	HRS		0	TSN 0					4101.3	
WC#: 27.520	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-53-09-900-803-02	RIGHT NO. 1 SLAT ACTUATOR								Component ATA:27
PN:GT412-5601-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2849	HRS		0	TSN 0					4101.3
WC#: 27.520	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-03	LEFT NO.2 SLAT ACTUATOR								Component ATA:27
PN:GT412-5602-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2872	HRS		0	TSN 0					4101.3
WC#: 27.525	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-04	RIGHT NO. 2 SLAT ACTUATOR								Component ATA:27
PN:GT412-5602-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2881	HRS		0	TSN 0					4101.3
WC#: 27.525	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-05	LEFT NO.3 SLAT ACTUATOR								Component ATA:27
PN:GT412-5603-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2899	HRS		0	TSN 0					4101.3
WC#: 27.530	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-06	RIGHT NO. 3 SLAT ACTUATOR								Component ATA:27
PN:GT412-5603-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2890	HRS		0	TSN 0					4101.3
WC#: 27.530	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-07	LEFT NO.4 SLAT ACTUATOR								Component ATA:27
PN:GT412-5604-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2887	HRS		0	TSN 0					4101.3
WC#: 27.535	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-08	RIGHT NO. 4 SLAT ACTUATOR								Component ATA:27
PN:GT412-5604-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2873	HRS		0	TSN 0					4101.3
WC#: 27.535	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-53-09-900-803-09	LEFT NO.5 SLAT ACTUATOR								Component ATA:27
PN:GT412-5605-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2874	HRS		0	TSN 0					4101.3
WC#: 27.540	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-10	RIGHT NO. 5 SLAT ACTUATOR								Component ATA:27
PN:GT412-5605-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2891	HRS		0	TSN 0					4101.3
WC#: 27.540	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-11	LEFT NO.6 SLAT ACTUATOR								Component ATA:27
PN:GT412-5606-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2842	HRS		0	TSN 0					4101.3
WC#: 27.545	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-12	RIGHT NO. 6 SLAT ACTUATOR								Component ATA:27
PN:GT412-5606-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2883	HRS		0	TSN 0					4101.3
WC#: 27.545	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-13	LEFT NO.7 SLAT ACTUATOR								Component ATA:27
PN:GT412-5607-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2884	HRS		0	TSN 0					4101.3
WC#: 27.550	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-14	RIGHT NO. 7 SLAT ACTUATOR								Component ATA:27
PN:GT412-5607-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2841	HRS		0	TSN 0					4101.3
WC#: 27.550	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-09-900-803-15	LEFT NO.8 SLAT ACTUATOR								Component ATA:27
PN:GT412-5609-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2842	HRS		0	TSN 0					4101.3
WC#: 27.555	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-53-09-900-803-16	RIGHT NO. 8 SLAT ACTUATOR								Component ATA:27
PN:GT412-5608-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2849	HRS		0	TSN 0					4101.3
WC#: 27.555	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801					
27-53-13-900-801-01	FLAP LH WS163.416 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6500	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-53-13-900-801-02	FLAP LH WS250.000 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6507	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-53-13-900-801-03	FLAP LH WS420.911 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6508	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-53-13-900-801-04	FLAP RH WS163.416 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6492	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-53-13-900-801-05	FLAP RH WS250.000 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6504	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					
27-53-13-900-801-06	FLAP RH WS420.911 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6506	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 52 13 000 801, AMM 27 52 13 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-53-13-900-801-07	SLAT LH WS92.954 L/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6478	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801					
27-53-13-900-801-08	SLAT LH WS265.000 L/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6483	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801					
27-53-13-900-801-09	SLAT LH WS391.000 L/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6505	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801					
27-53-13-900-801-10	SLAT RH WS92.954 L/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6510	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801					
27-53-13-900-801-11	SLAT RH WS265.000 L/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6512	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801					
27-53-13-900-801-12	SLAT RH WS391.000 L/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6514	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801					
27-53-17-900-801-01	LH NO.1 SLAT								Component ATA:27
PN:GM128-1011-21	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SB0212	HRS		0	TSN 0					4101.3
WC#: 27.560	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 17 000 801, AMM 27 53 17 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-53-17-900-801-02	RH NO.1 SLAT								Component ATA:27
PN:GM128-1011-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SB0213	HRS		0	TSN 0					4101.3
WC#: 27.560	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 17 000 801, AMM 27 53 17 400 801					
27-53-21-900-801-01	LH NO.2 SLAT								Component ATA:27
PN:GM128-1012-17	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SB0219	HRS		0	TSN 0					4101.3
WC#: 27.565	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 21 000 801, AMM 27 53 21 400 801					
27-53-21-900-801-02	RH NO.2 SLAT								Component ATA:27
PN:GM128-1012-18	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SB0219	HRS		0	TSN 0					4101.3
WC#: 27.565	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 21 000 801, AMM 27 53 21 400 801					
27-53-25-900-801-01	LH NO.3 SLAT								Component ATA:27
PN:GM128-1013-15	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SB0217	HRS		0	TSN 0					4101.3
WC#: 27.570	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 25 000 801, AMM 27 53 25 400 801					
27-53-25-900-801-02	RH NO.3 SLAT								Component ATA:27
PN:GM128-1013-16	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SB0216	HRS		0	TSN 0					4101.3
WC#: 27.570	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 25 000 801, AMM 27 53 25 400 801					
27-53-29-900-801-01	LH NO.4 SLAT								Component ATA:27
PN:GM128-1014-23	MOS/MSC	O/C	20-Jan-20	TSN 0					48.7
SN:60025	HRS		3338.3	TSN 0					763
WC#: 27.580	AFL		1038	TSN 0					187
				PROC. REF: AMM 27 53 29 000 801, AMM 27 53 29 400 801					
27-53-29-900-801-02	RH NO.4 SLAT								Component ATA:27
PN:GM128-1014-24	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:SB0230	HRS		0	TSN 0					4101.3
WC#: 27.580	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 53 29 000 801, AMM 27 53 29 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-53-33-900-801-01	SLAT FLAP/SLAT PDU								Component	ATA:27
PN:GT415-5001-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2862	HRS		0	TSN 0					4101.3	
WC#: 27.585	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 33 000 801, AMM 27 53 33 400 801						
27-53-33-900-801-02	FLAP FLAP/SLAT PDU								Component	ATA:27
PN:GT415-5001-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2863	HRS		0	TSN 0					4101.3	
WC#: 27.590	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 33 000 801, AMM 27 53 33 400 801						
27-53-41-900-801-01	LEFT SLAT (FLAP/SLAT) RESOLVER								Component	ATA:27
PN:GT412-5300-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B1760	HRS		0	TSN 0					4101.3	
WC#: 27.595	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 41 820 801, AMM 27 53 41 000 801, AMM 27 53 41 400 801						
27-53-41-900-801-02	RIGHT SLAT (FLAP/SLAT) RESOLVER								Component	ATA:27
PN:GT412-5300-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B1774	HRS		0	TSN 0					4101.3	
WC#: 27.595	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 41 820 801, AMM 27 53 41 000 801, AMM 27 53 41 400 801						
27-53-45-900-801-01	LEFT SLAT ASSYMETRY BRAKE								Component	ATA:27
PN:GT415-5500-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2980	HRS		0	TSN 0					4101.3	
WC#: 27.600	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 45 000 801, AMM 27 53 45 400 801						
27-53-45-900-801-02	RIGHT SLAT ASSYMETRY BRAKE								Component	ATA:27
PN:GT415-5500-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2926	HRS		0	TSN 0					4101.3	
WC#: 27.600	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 53 45 000 801, AMM 27 53 45 400 801						
27-60-00-101	OPERATIONAL TEST OF THE SPOILER POWER-CONTROL UNITS (PCU)								Service	ATA:27
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500 (+50/-50)	3474.7	Adj 50	5024.7	5074.7	923.4 (+50)		626.6	
WC#: 27.200	AFL		1069						156	
				PROC. REF: AMM 27 60 00 710 801						PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-61-01-900-801-01	FLIGHT SPOILER CONTROL LEVER (FS235 WL89 LBL2)								Component	ATA:27
PN:GT415-6004-9	MOS/MSC	O/C	10-Apr-12	TSR 0					142	
SN:FR230	HRS		435.8	TSR 0					3665.5	
WC#: 27.605	AFL		156	TSR 0					1069	
				PROC. REF: AMM 27 61 01 000 801, AMM 27 61 01 400 801						
27-61-05-201[S]	OPERATIONAL TEST OF THE FLIGHT-CONTROL UNIT (FCU) BACK-UP MODULES								Service	ATA:27
	MOS		11-Jul-18						67	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 27.205	AFL		921						304	
				PROC. REF: AMM 27 61 05 710 801						PKG:8
27-61-05-900-801-01	NO. 1 FLIGHT CONTROL UNIT FCU								Component	ATA:27
PN:GT415-0100-9	MOS/MSC	O/C	20-Aug-18						65.7	
SN:423	HRS		2918.3						1183	
WC#: 27.610	AFL		930						295	
				PROC. REF: AMM 27 61 05 000 801, AMM 27 61 05 400 801						
27-61-05-900-801-02	NO. 2 FLIGHT CONTROL UNIT FCU								Component	ATA:27
PN:GT415-0100-9	MOS/MSC	O/C	20-Aug-18						65.7	
SN:966	HRS		2918.3						1183	
WC#: 27.610	AFL		930						295	
				PROC. REF: AMM 27 61 05 000 801, AMM 27 61 05 400 801						
27-61-17-101	OPERATIONAL TEST OF THE GROUND LIFT DUMPING								Service	ATA:27
	MOS/MSC	O/C	09-Jul-18						67.1	
	HRS		2892.3						1209	
WC#: 27.210	AFL		921						304	
				PROC. REF: AMM 27 61 00 710 802						
27-62-01-900-801-01	LOB MULTIFUNCTION SPOILER PCU								Component	ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3150A	HRS		0	TSN 0					4101.3	
WC#: 27.615	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801						
27-62-01-900-801-02	LOB MULTIFUNCTION FLIGHT SPOILER PCU								Component	ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3242A	HRS		0	TSN 0					4101.3	
WC#: 27.620	AFL		0	TSN 0					1225	
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-62-01-900-801-03	LIB MULTIFUNCTION SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3118A	HRS		0	TSN 0					4101.3
WC#: 27.625	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801					
27-62-01-900-801-04	LIB MULTIFUNCTION FLIGHT SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2194A	HRS		0	TSN 0					4101.3
WC#: 27.630	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801					
27-62-01-900-801-05	RIB MULTIFUNCTION SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3189A	HRS		0	TSN 0					4101.3
WC#: 27.635	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801					
27-62-01-900-801-06	RIB MULTIFUNCTION FLIGHT SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3188A	HRS		0	TSN 0					4101.3
WC#: 27.640	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801					
27-62-01-900-801-07	ROB MULTIFUNCTION SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3179A	HRS		0	TSN 0					4101.3
WC#: 27.645	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801					
27-62-01-900-801-08	ROB MULTIFUNCTION FLIGHT SPOILER PCU								Component ATA:27
PN:GT411-6001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3152A	HRS		0	TSN 0					4101.3
WC#: 27.650	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801					
27-62-09-900-801-01	LOB FLIGHT SPOILER								Component ATA:27
PN:GM168-1500-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0376	HRS		0	TSN 0					4101.3
WC#: 27.655	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
27-62-09-900-801-02	LIB FLIGHT SPOILER								Component ATA:27
PN:GM168-1400-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0383	HRS		0	TSN 0					4101.3
WC#: 27.660	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801					
27-62-09-900-801-03	RIB FLIGHT SPOILER								Component ATA:27
PN:GM168-1400-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0384	HRS		0	TSN 0					4101.3
WC#: 27.665	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801					
27-62-09-900-801-04	ROB FLIGHT SPOILER								Component ATA:27
PN:GM168-1500-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0382	HRS		0	TSN 0					4101.3
WC#: 27.670	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801					
27-63-01-900-801-01	INBOARD SELECTOR, GROUND SPOILER VALVE								Component ATA:27
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 27.675	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 63 01 000 801, AMM 27 63 01 400 801					
27-63-01-900-801-02	OUTBOARD SELECTOR, GROUND SPOILER VALVE								Component ATA:27
PN:GT411-6003-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0785	HRS		0	TSN 0					4101.3
WC#: 27.680	AFL		0	TSN 0					1225
				PROC. REF: AMM 27 63 01 000 801, AMM 27 63 01 400 801					
27-63-05-900-801-01	LOB GROUND SPOILER ACTUATOR								Component ATA:27
PN:GT411-6002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1564	HRS		0	TSN 0					4101.3
WC#: 27.685	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
27-63-05-900-801-02	LIB GROUND SPOILER ACTUATOR								Component ATA:27
PN:GT411-6002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1562	HRS		0	TSN 0					4101.3
WC#: 27.690	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
27-63-05-900-801-03	RIB GROUND SPOILER ACTUATOR								Component	ATA:27
PN:GT411-6002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1587	HRS		0	TSN 0					4101.3	
WC#: 27.695	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
27-63-05-900-801-04	ROB GROUND SPOILER ACTUATOR								Component	ATA:27
PN:GT411-6002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1586	HRS		0	TSN 0					4101.3	
WC#: 27.670	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
272105-001 U	AFT FUSELAGE RUDDER TRIM ACTUATOR								Component	ATA:27
PN:PN	MOS		20-Dec-09	TSN 0				10-Oct-2025	169.7	
SN:UNKNOWN	HRS	5000	0	TSN 0	5000		898.7		4101.3	
WC#: 27.260	AFL		0	TSN 0					1225	
ASB A700-27-032	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSOR, ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-27-032 REV 01	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSOR, ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-27-032 REV 02	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSOR, ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-27-032 REV 03	REWORK-FLAP SYSTEM-APPLICATION OF MOISTURE PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSORS, ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	A/R								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
ASB A700-27-035 PART (A)	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - VISUAL CHECK OF THE SLAT/FLAP CONTROL UNITS (SFCU) AND REPLACEMENT OF UNSATISFACTORY SFCU WITH UNITS THAT HAVE BETTER POWER MONITORING CIRCUITRY AND POWER MODULE CONFIGURATION, ALERT SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-27-035 PART (B)	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - VISUAL CHECK OF THE SLAT/FLAP CONTROL UNITS (SFCU) AND REPLACEMENT OF UNSATISFACTORY SFCU WITH UNITS THAT HAVE BETTER POWER MONITORING CIRCUITRY AND POWER MODULE CONFIGURATION, ALERT SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-27-043	SPECIAL CHECK - CONTROL AND INDICATION SYSTEMS - VISUALLY EXAMINE LEAD WIRE OF RESISTOR R1 ON POWER ASSEMBLY A4 INSIDE SLAT/FLAP CONTROL UNIT (SFCU), ALERT SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-27-055 PART (A)	MODIFICATION - ELEVATOR CONTROL SYSTEM - REPLACE ELEVATOR LOAD LIMITERS THAT HAVE LOCKING NUTS WHICH HAVE LOOSENED (A/C 9139, 9142, 9148, 9151 AND 9153), ALERT SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-27-055 PART (B)	MODIFICATION - ELEVATOR CONTROL SYSTEM - REPLACE ELEVATOR LOAD LIMITERS THAT HAVE LOCKING NUTS WHICH HAVE LOOSENED (A/C 9143 AND 9150), ALERT SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-27-056	MODIFICATION - RUDDER CONTROL SYSTEM - REPLACE RUDDER LOAD LIMITERS THAT HAVE LOCKING NUTS WHICH HAVE LOOSENED (A/C 9144, 9145, 9150, 9151, 9153, AND 9159), ALERT SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
ASB A700-27-062	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSORS NO.1, ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
ASB A700-27-066	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - INSPECTION OF ELEVATOR PCU, P/N GT411-3800-7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-27-066 REV 01	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - INSPECTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	22-Aug-11						149.6	
	HRS									
	AFL									
ASB A700-27-066 REV 02	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - INSPECTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), ALERT SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	22-Aug-11						149.6	
	HRS									
	AFL									
AW AW700-27-0268[U]	LUBRICATION - LUBRICATE AILERON TOGGLE LINKS AND ELEVATOR AND RUDDER PCU SLOTTED BEARINGS, ADVISORY WIRE								Bulletin	ATA:27
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
FAA 2008-24-12	INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS								AD	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2009-15-03	INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS								AD	ATA:27
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
FAA 2009-15-03 PARA (G) (1)	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES IDENTIFIED IN PARAGRAPH (F)								AD	ATA:27
	DAYS/MSC	-	19-Dec-09						5167 d	
	HRS		0						4101.3	
	AFL		0						1225	
FAA 2009-15-03 PARA (G) (2)	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES NOT IDENTIFIED IN PARAGRAPH (F)								AD	ATA:27
	DAYS/MSC	-	19-Dec-09						5167 d	
	HRS		0						4101.3	
	AFL		0						1225	
FAA 2015-17-05	FLIGHT CONTROLS - INSPECTING FOR CORRECT CLEARANCE AND REWORK IF NECESSARY, AND, FOR CERTAIN OTHER AIRPLANES, INSTALLING A COVER FOR THE AILERON PULLEY ASSEMBLY								AD	ATA:27
	MOS/MSC	-	05-Oct-15						100.2	
	HRS		1796.5						2304.8	
	AFL		657						568	
FAA 2015-17-05 PARA (G)	INSTALL A COVER FOR THE NO. 1 AILERON PULLEY, INCLUDING DOING A GVI FOR CORRECT CLEARANCE AND REWORK AS APPLICABLE								AD	ATA:27
	MOS/MSC	-	05-Oct-15						100.2	
	HRS		1796.5						2304.8	
	AFL		657						568	
FAA 2015-17-05 PARA (H)	ACCOMPLISH A GVI FOR CORRECT CLEARANCE AND, REWORK, AS APPLICABLE								AD	ATA:27
	MOS/MSC	-	05-Oct-15						100.2	
	HRS		1796.5						2304.8	
	AFL		657						568	
FAA 2015-17-05 PARA (I)	DO THE RE-IDENTIFICATION OF THE OVERWING PANELS								AD	ATA:27
	MOS/MSC	-	05-Oct-15						100.2	
	HRS		1796.5						2304.8	
	AFL		657						568	
FAA 2017-14-15	FLIGHT CONTROLS - A REVISION TO THE MAINTENANCE OR INSPECTION PROGRAM TO INCORPORATE CERTIFICATION MAINTENANCE REQUIREMENT TASKS THAT INTRODUCE FUNCTIONAL TESTS OF THE CONTROL CABLE TENSION								AD	ATA:27
	MOS/MSC	-	29-Aug-17						77.4	
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
FAA 2017-14-15 PARA (G)	REVISE THE MAINTENANCE OR INSPECTION PROGRAM								AD	ATA:27
	DAYS/MSC	-	29-Aug-17						2357 d	
	HRS									
	AFL									
FAA 2017-14-15 PARA (H)	ACCOMPLISH CERTIFICATION MAINTENANCE REQUIREMENT (CMR) TASKS								AD	ATA:27
	MOS/MSC	-	29-Aug-17						77.4	
	HRS									
	AFL									
FAA 2017-19-11	FLIGHT CONTROLS - AN OPERATIONAL TEST OF THE FCU BACK-UP MODULES AND REPAIR (IF ANY FCU FAILS ANY OPERATIONAL TEST REQUIRED BY THIS AD)								AD	ATA:27
	MOS/MSC	-	17-Dec-17						73.8	
	HRS		2670.5						1430.8	
	AFL		875						350	
FAA 2018-20-20	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM BRACKET CRACKING								AD	ATA:27
	MOS/MSC	-	19-Nov-18						62.7	
	HRS		3006.7						1094.6	
	AFL		949						276	
FAA 2021-08-11	FLIGHT CONTROLS - ROLL CONTROL INPUT MODULES (RCIM) MAINTENANCE MANUAL / INSPECTION MANUAL INCORPORATION								AD	ATA:27
	DAYS/MSC	-	21-Apr-21						1026 d	
	HRS		3533.7						567.6	
	AFL		1082						143	
FAA 2021-10-02[S]	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM - VERTICAL TORQUE TUBE SEIZURE - SAND CONTAMINATION OF BEARING								AD	ATA:27
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2021-10-02 PARA (G)	PERFORM A GENERAL VISUAL INSPECTION OF THE LEFT AND RIGHT-HAND ELEVATOR TORQUE TUBE BEARINGS FOR ANY SAND, DUST, OR CORROSION, PERFORM A FUNCTIONAL TEST OF THE ELEVATOR CONTROL SYSTEM AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS								AD	ATA:27
	MOS	63	19-Mar-21		19-Jun-26		859 d	19-Jun-2026	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
FAA 2021-10-02 PARA (I[S])	SUBMIT A REPORT OF ALL FINDINGS, POSITIVE AND NEGATIVE, OF EACH OF THE FIRST THREE INSPECTIONS								AD	ATA:27
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2022-24-01	REVISING THE EXISTING AFM TO CORRECT THE AFFECTED PERFORMANCE CHARTS								AD	ATA:27
	DAYS/MSC	-	02-Mar-23						346 d	
	HRS		3954.3						147	
	AFL		1179						46	
FAA 2023-05-11	FLIGHT CONTROLS - AIRPLANE FLIGHT MANUAL - REVISION								AD	ATA:27
	DAYS/MSC	-	19-Apr-23						298 d	
	HRS		3954.3						147	
	AFL		1179						46	
FAA 2023-08-01	REVISE THE EXISTING AFM								AD	ATA:27
	MOS/MSC	-	01-Jun-23						8.3	
	HRS		3974						127.3	
	AFL		1183						42	
SB 700-27-015	MODIFICATION - STALL PROTECTION SYSTEM - INTRODUCTION OF STALL PROTECTION COMPUTER (SPC), PART NO. GH582-3001-5, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-27-016	SPECIAL CHECK/MODIFICATION - GROUND SPOILERS - REPLACEMENT OF GROUND SPOILER SELECTOR VALVE TO PREVENT POSSIBLE FAILURE OF GROUND SPOILER, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-27-018	MODIFICATION - FLAPS AND SLATS - SOFTWARE UPGRADE OF THE SLAT/FLAP CONTROL UNIT TO PREVENT UNNECESSARY FLAP SYSTEM SHUTDOWN DURING FLIGHT, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-019	MODIFICATION - PITCH TRIM SYSTEM - INCORPORATION OF MOTORS WITH IMPROVED BRAKE MATERIAL ON THE HORIZONTAL STABILIZER TRIM-ACTUATOR (HSTA), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-019 REV 01	MODIFICATION - PITCH TRIM SYSTEM - INCORPORATION OF MOTORS WITH IMPROVED BRAKE MATERIAL ON THE HORIZONTAL STABILIZER TRIM-ACTUATOR (HSTA), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-020	MODIFICATION - FLAP SYSTEM - ADDITION OF ALIGNMENT PLATES ON FLAP FAIRINGS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-021	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-021 REV 01	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-021 REV 02	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-021 REV 03	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-022	SPECIAL CHECK/REWORK - FLAP SYSTEM - REPLACEMENT OF DEFECTIVE SKEW SENSORS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-023	MODIFICATION - RUDDER - RUDDER LEADING EDGE EXTENSION TO PREVENT DAMAGE TO RUDDER, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-024	MODIFICATION - AILERON CONTROL SYSTEM - AERODYNAMIC IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-024 REV 01	MODIFICATION - AILERON CONTROL SYSTEM - AERODYNAMIC IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-025	MODIFICATION - STALL PROTECTION - DISABLE STICK PUSHER CANCEL FUNCTION FROM AUTOPILOT MASTER DISCONNECT SWITCH FOR JAA AIRCRAFT (SUPERSEDED BY 700-27-025 REV 01), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-025 REV 01	MODIFICATION - STALL PROTECTION SYSTEM - DISABLE STICK PUSHER CANCEL FUNCTION FROM AUTOPILOT MASTER DISCONNECT SWITCH FOR JAA AIRCRAFT (SUPERSEDED BY 700-27-025 REV 02), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-025 REV 02	MODIFICATION - STALL PROTECTION SYSTEM - DISABLE STICK PUSHER CANCEL FUNCTION FROM AUTOPILOT MASTER DISCONNECT SWITCH FOR JAA AIRCRAFT, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-026 PART (A)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZER TRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-026 PART (B)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZER TRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-026 PART (C)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZER TRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-026 REV 01 PART (A)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZER TRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-026 REV 01 PART (B)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZER TRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134) SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-026 REV 01 PART (C)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZER TRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134) SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-027	SPECIAL CHECK/REWORK - LEADING EDGE SLAT-SYSTEM - VERIFICATION OF THE SLAT CONNECTOR PINS FOR CORRECT INSTALLATION, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-027 REV 01	SPECIAL CHECK/REWORK - LEADING EDGE SLAT-SYSTEM - VERIFICATION OF THE SLAT CONNECTOR PINS FOR CORRECT INSTALLATION, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-029	SPECIAL CHECK/REWORK - CONTROL AND INDICATION SYSTEMS - EXAMINE SLAT/FLAP SYSTEM WIRING FOR DAMAGE AND SLAT/FLAP CONTROL UNIT CONNECTOR FOR CORRECT INSTALLATION, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-030	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - RUDDER CABLE AND QUADRANT GUARD PIN CLEARANCE LIMITS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-031 PART (A)	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - CHECK FOR DEFECTIVE LOCK SOLENOID AND PITCH DISCONNECT MECHANISM AND REPLACEMENT OF DEFECTIVE PITCH DISCONNECT MECHANISM (A/C 9002 TO 9085 AND 9091), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-031 PART (B)	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - CHECK FOR DEFECTIVE LOCK SOLENOID AND PITCH DISCONNECT MECHANISM AND REPLACEMENT OF DEFECTIVE PITCH DISCONNECT MECHANISM (A/C 9002 TO 9085 AND 9091), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-036	MODIFICATION - CONTROL AND INDICATING SYSTEMS - UPGRADE OF THE FLIGHT CONTROL UNIT (FCU) "SOFTWARE STANDARD 1102", SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-036 REV 01	MODIFICATION - CONTROL AND INDICATING SYSTEMS - UPGRADE OF THE FLIGHT CONTROL UNIT (FCU) "SOFTWARE STANDARD 1102" (A/C 9002 TO 9124), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-039	SPECIAL CHECK/MODIFICATION - FLIGHT CONTROLS - REPLACEMENT OF THE MULTI-FUNCTION SPOILER POWER CONTROL UNIT CONNECTOR AND CONDUIT. (EFFECTIVITY: A/C S/N 9002 - 9113), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-040	SPECIAL CHECK/MODIFICATION - PITCH TRIM SYSTEM - INSPECT THE PITCH-TRIM ACTUATOR MOTOR DRIVE-UNIT (MDU) AND REPLACE, IF NECESSARY, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-042 PART (A)	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWER DRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-042 PART (B)	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWER DRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-042 PART (C)	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWER DRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-042 REV 01 PART (A)	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWER DRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-042 REV 01 PART (B)	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWER DRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-044	MODIFICATION - FLAP SYSTEM - IMPROVED THE RIGIDITY OF THE FLAP SEAL PLATE ASSEMBLIES TO PREVENT FOULING BETWEEN THE FLAP AND FUSELAGE FAIRINGS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-045	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP RESOLVER CHECK AND SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO GT415-5900-13, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-045 REV 01	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP RESOLVER CHECK AND SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO GT415-5900-13, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-047	SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - INSPECT, CLEAN AND GREASE AILERON TOGGLE LINK ASSEMBLY, ROD END ASSEMBLY AND BEARING ASSEMBLY (A/C 9002 TO 9126 AND 9128 TO 9160), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-047 REV 01	SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - INSPECT, CLEAN AND GREASE AILERON TOGGLE LINK ASSEMBLY, ROD END ASSEMBLY AND BEARING ASSEMBLY (A/C 9002 TO 9126 AND 9128 TO 9160), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-048	MODIFICATION - STALL PROTECTION SYSTEM - SOFTWARE UPGRADE OF THE STALL PROTECTION COMPUTER (A/C 9002 TO 9175), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-049	MODIFICATION - FLAP SYSTEM - REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-049 REV 01	MODIFICATION - FLAP SYSTEM - REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-049 REV 02	MODIFICATION - FLAP SYSTEM - REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-049 REV 03	MODIFICATION – FLAP SYSTEM – REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-050	MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO PART NO. GT415-5900-15 (A/C 9002 TO 9181), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-050 REV 01	MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO PART NO. GT415-5900-15 (A/C 9002 TO 9181), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-051	MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO GT415-5900-13 MOD-10. REF. HAMILTON SUNDSTRAND VSB NO. FAS02C-27-10., SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-052	SPECIAL CHECK - FLAPS AND SLATS - CHECK OF THE SLAT AND FLAP TORQUE TUBES FOR CORRECT ENGAGEMENT (A/C 9002 TO 9126 AND 9128 TO 9211), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-053	MODIFICATION - CONTROL AND INDICATION SYSTEMS - FLIGHT CONTROL UNIT (FCU) UPGRADE TO PART NO. GT415-0100-9 (A/C 9002 TO 9169), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-054	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO-FLAP TAKE-OFF CAPABILITY, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-057	MODIFICATION - AILERON CONTROL SYSTEM - INTRODUCTION OF NEW TOGGLE LINK PART NO. 376046-103(A/C 9002 TO 9203), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-057 REV 01	MODIFICATION - AILERON CONTROL SYSTEM - INTRODUCTION OF NEW TOGGLE LINK PART NO. 376046-103 (A/C 9002 TO 9203), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-058	MODIFICATION - PITCH TRIM SYSTEM - INTRODUCTION OF NEW MOTOR DRIVE UNIT (MDU) PART NO. GT415-4002-11 TO CORRECT DUAL CHANNEL FAILURES (A/C 9002 TO 9126 AND 9128 TO 9192), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-058 REV 01	MODIFICATION - PITCH TRIM SYSTEM - INTRODUCTION OF NEW MOTOR DRIVE UNIT (MDU) PART NO. GT415-4002-11 TO CORRECT DUAL CHANNEL FAILURES (A/C 9002 TO 9126 AND 9128 TO 9192), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-059 PART (A)	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO-FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE (A/C 9159 TO 9207), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-059 PART (B)	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO-FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE (A/C 9159 TO 9304), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-059 PART (C)	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO-FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE (PRE SB 700-11-020, A/C 9159, 9162, 9163, 9165, 9167, 9169, 9171, 9173, 9175, 9177, 9179, 9181, 9183 TO 9185, 9187, 9189, 9191, 9193 TO 9197, 9199, 9200, 9202, 9203 AND 9205.), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-059 REV 01	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-059 REV 01 PART (A)	MODIFICATION MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE, SERVICE BULLETIN – SFCU STRAPPING (AIRCRAFT, SERIAL NO. 9159 TO 9207)								Bulletin ATA:27
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-27-059 REV 01 PART (B)	MODIFICATION MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE, SERVICE BULLETIN - REPLACEMENT OF WHEEL SPEED TRANSDUCERS (AIRCRAFT, SERIAL NO. 9159 TO 9304)								Bulletin ATA:27
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-27-059 REV 01 PART (C)	MODIFICATION MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE, SERVICE BULLETIN – MLG TIRE REPLACEMENT (AIRCRAFT, SERIAL NO. 9159 TO 9205 PRE SB 700-11-020)								Bulletin ATA:27
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-061	MODIFICATION - CONTROL AND INDICATION SYSTEMS - REPLACEMENT OF SFCU WITH PART NO. GT415-5900-17 (A/C 9002 TO 9312 AND 9314 TO 9317), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-27-063	SPECIAL CHECK/REWORK - FLAP SYSTEM - INSPECT OUTBOARD FLAP CARRIAGE ASSEMBLY FOR INVERSE INSTALLATION OF BOLTS (A/C 9002 TO 9050 AND 9188 TO 9190), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-064 PART (A)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - UPGRADE OF MDU P/N GT415-4002-11 TO MOD STRIKE 1 TO PREVENT NUISANCE MESSAGES (9193 TO 9271 AND 9002 TO 9192 POST SB 700-27-058, BASIC ISSUE), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-064 PART (B)	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - UPGRADE OF MDU P/N GT415-4002-11 TO MOD STRIKE 1 TO PREVENT NUISANCE MESSAGES (9193 TO 9271 AND 9002 TO 9192 POST SB 700-27-058, BASIC ISSUE), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-065	SPECIAL CHECK/REWORK - FLAPS AND SLATS - CHECK FLAP AND SLAT ACTUATORS FOR CORRECT GREASE (A/C 9002 TO 9282), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-067	REWORK - ELEVATOR CONTROL SYSTEM - CORROSION PREVENTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-27-067 REV 01	REWORK - ELEVATOR CONTROL SYSTEM - CORROSION PREVENTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-	22-Aug-11						149.6
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-068	REWORK - RUDDER CONTROL SYSTEM - INSPECTION AND CORROSION PREVENTION OF PCU SLOTTED ENTRY BEARINGS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-069	REWORK - AILERON CONTROL SYSTEM - REPLACEMENT OF THE FLANGED BUSHINGS AND HINGE BOLT ASSEMBLY ON THE INBOARD AND OUTBOARD SIDES OF THE AILERON (9002 TO 9126 AND 9128 TO 9999), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-27-069 REV 01	REWORK - AILERON CONTROL SYSTEM - REPLACEMENT OF THE FLANGED BUSHINGS AND HINGE BOLT ASSEMBLY ON THE INBOARD AND OUTBOARD SIDES OF THE AILERON, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-070	SPECIAL CHECK/REWORK - RUDDER CONTROL SYSTEM - EXAMINE YAW DAMPER FOR CORRECT INSTALLATION, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-070 REV 01	SPECIAL CHECK/REWORK – RUDDER CONTROL SYSTEM – EXAMINE YAW DAMPER FOR CORRECT INSTALLATION, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-071	MODIFICATION - STALL PROTECTION SYSTEM - INTRODUCTION OF THE STALL PROTECTION COMPUTER PART NO. GH582-3001-17 TO CORRECT LOOPBACK ARINC 429 ISSUE, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-27-072	MODIFICATION – PITCH TRIM SYSTEM – RELOCATE EVS SWITCH TO PREVENT FOULING CONDITION WITH PITCH TRIM SWITCH, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
SB 700-27-073	REWORK - PITCH TRIM SYSTEM - LUBRICATE HORIZONTAL-STABILIZER PIVOT-FITTINGS, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-074	MODIFICATION – MULTI FUNCTION SPOILERS – REPLACE UNITS WITH POSSIBLE THIN WALL CONDITION, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-075	CHECK/MODIFICATION - FLAPS AND SLATS - CHECK SLAT/FLAP ASYMMETRY BRAKE DECAL COVER FOR CORRECT INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	03-Nov-11						147.3	
	HRS		227.8						3873.5	
	AFL		100						1125	
SB 700-27-076	MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	24-Apr-12						141.6	
	HRS		443.4						3657.9	
	AFL		160						1065	
SB 700-27-076 REV 01	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	19-Jul-12						138.7	
	HRS		561.2						3540.1	
	AFL		212						1013	
SB 700-27-076 REV 01 PART (A)	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN AND REWORK								Bulletin	ATA:27
	MOS/MSC	-	19-Jul-12						138.7	
	HRS		561.2						3540.1	
	AFL		212						1013	
SB 700-27-076 REV 01 PART (B)	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	19-Jul-12						138.7	
	HRS		561.2						3540.1	
	AFL		212						1013	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
SB 700-27-076 REV 02	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	01-Jul-14						115.3	
	HRS		1377.6						2723.7	
	AFL		522						703	
SB 700-27-076 REV 02 PART (A)	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN AND REWORK								Bulletin	ATA:27
	MOS/MSC	-	01-Jul-14						115.3	
	HRS		1377.6						2723.7	
	AFL		522						703	
SB 700-27-076 REV 02 PART (B)	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	01-Jul-14						115.3	
	HRS		1377.6						2723.7	
	AFL		522						703	
SB 700-27-076 REV 03	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-076 REV 03 PART (A)	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN AND REWORK								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-076 REV 03 PART (B)	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-076 REV 04	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-	05-Oct-15						100.2	
	HRS		1796.5						2304.8	
	AFL		657						568	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-076 REV 04 PART (A)	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN AND REWORK								Bulletin ATA:27
	MOS/MSC	-	05-Oct-15						100.2
	HRS		1796.5						2304.8
	AFL		657						568
SB 700-27-076 REV 04 PART (B)	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-	05-Oct-15						100.2
	HRS		1796.5						2304.8
	AFL		657						568
SB 700-27-077	SPECIAL CHECK / MODIFICATION – RUDDER TRAVEL LIMITING SYSTEM – REPLACEMENT OF RUDDER-LIMITER POSITION TRANSDUCER (RLPT), SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-079	SPECIAL CHECK/REWORK - ELEVATOR CONTROL -INSPECTION OF ELEVATOR AND APPLICATION OF SEALANT, IF NECESSARY, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-079 PART (A)	SPECIAL CHECK/REWORK - ELEVATOR CONTROL -INSPECTION OF ELEVATOR AND APPLICATION OF SEALANT, IF NECESSARY, SERVICE BULLETIN INSPECTION OF THE INBOARD AND OUTBOARD TRAILING-EDGE TAPERED FITTINGS								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-079 PART (B)	SPECIAL CHECK/REWORK - ELEVATOR CONTROL -INSPECTION OF ELEVATOR AND APPLICATION OF SEALANT, IF NECESSARY, SERVICE BULLETIN SEALING OF THE INBOARD AND OUTBOARD TRAILING-EDGE TAPERED FITTINGS								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-081	MODIFICATION - STALL PROTECTION SYSTEM - ENABLE THE STICK PUSHER OVERRIDE FUNCTION OF THE MASTER DISCONNECT SWITCH FOR CONFIGURATIONS OTHER THAN JAA, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-082	MODIFICATION - FLAP SYSTEM - MLG FLAP TORQUE TUBE FLAP CONTAINMENT IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-27-083	SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-083 REV 01	SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-27-083 REV 01 PART A	ACCOMPLISH SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN BEARINGS INSPECTION								Bulletin ATA:27
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-27-083 REV 01 S PART B	ACCOMPLISH SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN BEARINGS REPLACEMENT								Bulletin ATA:27
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-27-083 REV 02	SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-083 REV 02 PART A	ACCOMPLISH SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN BEARINGS INSPECTION								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-083 REV 02 PART B	ACCOMPLISH SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN BEARINGS REPLACEMENT								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-085	SPECIAL CHECK - FLAP SYSTEM - INSPECTION OF FORWARD AND AFT INBOARD FLAP SPIGOT TUBES FOR CORROSION, SERVICE BULLETIN								Bulletin ATA:27
	MOS	T:60	EFF		31-Mar-26 *		779 d	31-Mar-2026	
	HRS								
	AFL								
SB 700-27-086	MODIFICATION - AILERON CONTROL SYSTEM - INTRODUCTION OF ZINC-ONLY COATED CONTROL CABLES, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1111 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART AA	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1107 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART AB	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1107 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1111 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1541 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-086 PART D	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1541 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART E	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1155 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART F	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1155 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART G	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1557 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART H	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1557 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART I	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1115 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART J	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1115 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART K	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1113 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-086 PART L	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1113 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART M	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1159 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART N	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1129 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART O	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1123 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART P	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1127 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART Q	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1147 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART R	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1151 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART S	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1153 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-086 PART T	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1149 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART U	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1101 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART V	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1101 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART W	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1103 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART X	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1103 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART Y	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1105 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-086 PART Z	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0011N1105 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087	MODIFICATION - RUDDER CONTROL SYSTEM - INTRODUCTION OF ZINC-ONLY COATED CONTROL CABLES, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-087 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1233								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1203								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1505								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART D	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1537								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART E	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1209 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART F	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1209 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART G	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1211								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART H	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1213								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-087 PART I	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1515								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART J	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1517								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART K	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1519								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART L	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1521								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART M	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1223								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART N	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1225								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART O	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1227								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART P	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1229								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-087 PART Q	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1201								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-087 PART R	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0012N1207								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088	MODIFICATION - ELEVATOR CONTROL SYSTEM - INTRODUCTION OF ZINC-ONLY COATED CONTROL CABLES, SERVICE BULLETIN								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1305								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1307								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1301								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART D	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1359								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART E	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1313								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-088 PART F	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1315								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART G	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1309								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART H	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1365								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART I	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1341 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART J	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1341 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART K	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1317 (RHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART L	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1317 (LHS)								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART M	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1349								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 27 - FLIGHT CONTROLS									
SB 700-27-088 PART N	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1347								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART O	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1319								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART P	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1343								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART Q	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1331								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART R	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1333								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART S	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1329								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART T	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1327								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-27-088 PART U	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1303								Bulletin ATA:27
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
SB 700-27-088 PART V	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1311								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-088 PART W	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1353								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-088 PART X	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INTRODUCTION OF ZINC-ONLY CABLE GC413-0013N1357								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-089	MODIFICATION - SLAT/FLAP CONTROL SYSTEM - INTRODUCTION OF AN IMPROVED SLAT FLAP RESOLVER PART NUMBER GT415-5300-5, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-089 PART A	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE FLAP RESOLVER								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-27-089 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SLAT RESOLVER								Bulletin	ATA:27
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-029	MODIFICATION - LEADING EDGE SLAT SYSTEM - REPLACEMENT OF THE SLAT NO. 4 OUTBOARD END SEAL RETAINER FOR BETTER SUPPORT, SERVICE BULLETIN								Bulletin	ATA:27
	MOS/MSC	N/A								
	HRS									
	AFL									
TCCA CF-2008-31	ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS								AD	ATA:27
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
TCCA CF-2008-31 PARA (A1)	INSPECTION/LUBRICATION ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS								AD	ATA:27
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
TCCA CF-2008-31 PARA (A2)	REPEAT ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS INSPECTION/LUBRICATION								AD	ATA:27
	DAYS/MSC	-	19-Dec-09						5167 d	
	HRS		0						4101.3	
	AFL		0						1225	
TCCA CF-2008-31 PARA (A3)	REPEAT ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS INSPECTION/LUBRICATION								AD	ATA:27
	DAYS/MSC	-	19-Dec-09						5167 d	
	HRS		0						4101.3	
	AFL		0						1225	
TCCA CF-2008-31 PARA (A4)	COMPLETE ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS A DISASSEMBLY WITH INSPECTION AND LUBRICATION								AD	ATA:27
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
TCCA CF-2008-31 PARA (B)	INSPECTION/LUBRICATION ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS								AD	ATA:27
	DAYS/MSC	-	19-Dec-09						5167 d	
	HRS		0						4101.3	
	AFL		0						1225	
TCCA CF-2008-31 PARA (D)	REPORT FINDINGS ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS								AD	ATA:27
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
TCCA CF-2015-06 R01	FLIGHT CONTROLS - IMPROPERLY FORMULATED TASK IN THE AIRCRAFT MAINTENANCE MANUAL FOR THE FLIGHT CONTROL UNIT BACK -UP MODULE								AD	ATA:27
	MOS/MSC	-	19-Dec-17						73.7	
	HRS		2670.5						1430.8	
	AFL		875						350	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 27 - FLIGHT CONTROLS										
TCCA CF-2015-06 R01	NO. 1 FLIGHT CONTROL UNIT (FCU) BACK-UP MODULE OPERATIONAL CHECK								AD	ATA:27
	MOS/MSC	-	19-Dec-17						73.7	
	HRS		2670.5						1430.8	
	AFL		875						350	
TCCA CF-2015-06 R01	NO. 2 FLIGHT CONTROL UNIT (FCU) BACK-UP MODULE OPERATIONAL CHECK								AD	ATA:27
	MOS/MSC	-	19-Dec-17						73.7	
	HRS		2670.5						1430.8	
	AFL		875						350	
TCCA CF-2016-06 R01	FLIGHT CONTROLS - AILERON & RUDDER CONTROL SYSTEM - CABLE TENSION RELAXATION								AD	ATA:27
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
TCCA CF-2016-06 R01 PART (I)	ACCOMPLISH TIME LIMITS / MAINTENANCE CHECKS (TLMC) - MANUAL CHANGE								AD	ATA:27
	MOS/MSC	-								
	DAYS/MSC	/ -	27-Jul-16						2755 d	
	HRS		2078.9						2022.4	
	AFL		719						506	
TCCA CF-2016-06 R01 PART (II)	ACCOMPLISH INSPECTION OF THE AILERON AND RUDDER CONTROL CABLE TENSION								AD	ATA:27
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
ATA 28 - FUEL										
28-10-00-201[S]	DETAILED INSPECTION OF THE VENT TUBING VAPOR-BARRIER COATING								Service	ATA:28
	MOS	180 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 28.005	AFL		1069						156	
				PROC. REF: AMM 28 10 00 220 801						PKG:52
28-10-00-202[S]	DETAILED INSPECTION OF THE CENTER-TANK VAPOR-BARRIER COATING								Service	ATA:28
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 28.010	AFL		1069						156	
				PROC. REF: AMM 28 10 00 220 802						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-11-00-201[S]	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL SURFACES								Service	ATA:28
	MOS		06-Dec-23						2.2	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 28.015	AFL		1223						2	
				PROC. REF: AMM 28 11 00 210 802						PKG:4
28-11-00-202[S]	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL COMPONENTS								Service	ATA:28
	MOS		06-Dec-23						2.2	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 28.020	AFL		1223						2	
				PROC. REF: AMM 28 11 00 210 803						PKG:4
28-11-01-900-801-01	LH LOWER PANEL, WING ACCESS DOOR								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 11 01 000 801, AMM 28 11 01 400 801						
28-11-01-900-801-02	RH LOWER PANEL, WING ACCESS DOOR								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 11 01 000 801, AMM 28 11 01 400 801						
28-11-05-201[S]	DETAILED INSPECTION OF THE WATER DRAIN VALVES								Service	ATA:28
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 28.025	AFL		1069						156	
				PROC. REF: AMM 28 11 05 220 801						PKG:34
28-11-05-900-801-01	LH WATER DRAIN (BL42.0 FSTA 640.4) VALVE								Component	ATA:28
PN:GP422-1107-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1987	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801						
28-11-05-900-801-02	LH WATER DRAIN (WS52.5 LWR STR #10 - #11) VALVE								Component	ATA:28
PN:GP422-1107-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1961	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-11-05-900-801-03	RH WATER DRAIN (BL42.0 FSTA 634.00) VALVE								Component ATA:28
PN:GP422-1107-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1966	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801					
28-11-05-900-801-04	RH WATER DRAIN (WS52.5 LWR STR #10- #11) VALVE								Component ATA:28
PN:GP422-1107-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1959	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801					
28-11-09-900-801-01	LH WING TANK PRESSURE RELIEF VALVE								Component ATA:28
PN:GP422-1109-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1143	HRS		0	TSN 0					4101.3
WC#: 28.090	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801					
28-11-09-900-801-02	RH WING TANK PRESSURE RELIEF VALVE								Component ATA:28
PN:GP422-1109-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1144	HRS		0	TSN 0					4101.3
WC#: 28.090	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801					
28-11-09-900-801-03	CENTER TANK PRESSURE RELIEF VALVE								Component ATA:28
PN:GP422-1109-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0066	HRS		0	TSN 0					4101.3
WC#: 28.095	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801					
28-11-25-900-801-01	LEFT GRAVITY FILL CAP								Component ATA:28
PN:GP425-1104-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1262	HRS		0	TSN 0					4101.3
WC#: 28.100	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801					
28-11-25-900-801-02	RIGHT FORWARD GRAVITY FILL CAP								Component ATA:28
PN:GP425-1104-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1263	HRS		0	TSN 0					4101.3
WC#: 28.100	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-11-25-900-801-03	RIGHT AFT GRAVITY FILL CAP								Component	ATA:28
PN:GP425-1104-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1265	HRS		0	TSN 0					4101.3	
WC#: 28.100	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801						
28-11-29-900-801-01	LH WING TANK GRAVITY FILL ADAPTER								Component	ATA:28
PN:GP425-1105-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0874	HRS		0	TSN 0					4101.3	
WC#: 28.105	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-11-29-900-801-02	CENTER TANK GRAVITY FILL ADAPTER								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.105	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-11-29-900-801-03	RH WING TANK GRAVITY FILL ADAPTER								Component	ATA:28
PN:GP425-1105-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0876	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-12-00-201[S]	GENERAL VISUAL INSPECTION OF THE AFT FUEL-TANK DRAIN-MAST								Service	ATA:28
	MOS		28-Nov-23						2.5	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 28.030	AFL		1223						2	
				PROC. REF: AMM 28 12 00 210 801						PKG:4
28-12-00-202[S]	FUNCTIONAL TEST OF THE AFT FUEL-TANK COMPARTMENT								Service	ATA:28
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 28.035	AFL		1069						156	
				PROC. REF: AMM 28 12 00 720 801						PKG:38
28-12-05-900-801-01	AFT DRAIN TANK VALVE								Component	ATA:28
PN:GP422-1102-1	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7	
SN:0818	HRS		3474.7	TSN 0					626.6	
WC#: 28.110	AFL		1069	TSN 0					156	
				PROC. REF: AMM 28 12 05 000 801, AMM 28 12 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-12-09-900-801-01	AFT TANK PRESSURE RELIEF VALVE								Component	ATA:28
PN:GP422-1105-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0299	HRS		0	TSN 0					4101.3	
WC#: 28.115	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 12 09 000 801, AMM 28 12 09 400 801						
28-12-13-900-801-01	LH FLEXIBLE, AUXILIARY TANK FUEL CELL								Component	ATA:28
PN:GD421-0101-9	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7	
SN:T010445	HRS		3474.7	TSN 0					626.6	
WC#: 28.125	AFL		1069	TSN 0					156	
				PROC. REF: AMM 28 12 13 000 801, AMM 28 12 13 400 801						
28-12-13-900-801-02	RH FLEXIBLE, AUXILIARY TANK FUEL CELL								Component	ATA:28
PN:GD421-0101-8	MOS/MSC	O/C	19-Mar-21	TSN 135, TSR 2					34.7	
SN:114322	HRS		3474.7	TSN 3474.7, TSR 0					626.6	
WC#: 28.125	AFL		1069	TSN 1069, TSR 0					156	
				PROC. REF: AMM 28 12 13 000 801, AMM 28 12 13 400 801						
28-13-00-201[S]	FUNCTIONAL TEST OF THE FUEL VENT TUBING								Service	ATA:28
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 28.040	AFL		1069						156	
				PROC. REF: AMM 28 13 00 720 801						PKG:38
28-13-00-202[S]	OPERATIONAL TEST OF THE VENT SYSTEM								Service	ATA:28
	MOS		22-Nov-23						2.6	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 28.045	AFL		1223						2	
				PROC. REF: AMM 28 13 00 710 801						PKG:4
28-13-05-900-801-01	LH SURGE BOX								Component	ATA:28
PN:GC426-0101-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:5396	HRS		0	TSN 0					4101.3	
WC#: 28.130	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-13-05-900-801-02	RH SURGE BOX								Component	ATA:28
PN:GC426-0101-8	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:GSC0158-09	HRS		0	TSN 0					4101.3	
WC#: 28.130	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-20-01-900-801-01	FUEL CONTROL PANEL								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.150	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 20 01 000 801, AMM 28 20 01 400 801						
28-21-00-201 S	FUNCTIONAL TEST OF THE FUEL-FEED TUBING SHROUDS								Service	ATA:28
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 28.050	AFL		1069						156	
				PROC. REF: AMM 28 21 00 720 801						PKG:38
28-21-00-202 S	VISUAL CHECK OF THE SHROUD DRAINS								Service	ATA:28
	MOS		28-Nov-23						2.5	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 28.055	AFL		1223						2	
				PROC. REF: AMM 28 21 00 210 801						PKG:4
28-21-01-900-801-01	LEFT FORWARD AC BOOST PUMP CARTRIDGE								Component	ATA:28
PN:GP422-1401-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:10BE152	HRS		0	TSN 0					4101.3	
WC#: 28.155	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801						
28-21-01-900-801-02	RIGHT FORWARD AC BOOST PUMP CARTRIDGE								Component	ATA:28
PN:GP422-1401-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:10BE153	HRS		0	TSN 0					4101.3	
WC#: 28.155	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801						
28-21-01-900-801-03	LEFT AFT AC BOOST PUMP CARTRIDGE								Component	ATA:28
PN:GP422-1401-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:10BE150	HRS		0	TSN 0					4101.3	
WC#: 28.160	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801						
28-21-01-900-801-04	RIGHT AFT AC BOOST PUMP CARTRIDGE								Component	ATA:28
PN:GP422-1401-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:8BE123	HRS		0	TSN 0					4101.3	
WC#: 28.160	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-21-05-900-801-01	LEFT FORWARD AC BOOST PUMP CANISTER								Component ATA:28
PN:GP422-1401-17	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:10BE152	HRS		0	TSN 0					4101.3
WC#: 28.165	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801					
28-21-05-900-801-02	LEFT AFT AC BOOST PUMP CANISTER								Component ATA:28
PN:GP422-1401-17	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:10BE150	HRS		0	TSN 0					4101.3
WC#: 28.170	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801					
28-21-05-900-801-03	RIGHT FORWARD AC BOOST PUMP CANNISTER								Component ATA:28
PN:GP422-1401-17	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:10BE153	HRS		0	TSN 0					4101.3
WC#: 28.165	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801					
28-21-05-900-801-04	RIGHT AFT AC BOOST PUMP CANNISTER								Component ATA:28
PN:GP422-1401-17	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:8BE123	HRS		0	TSN 0					4101.3
WC#: 28.170	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801					
28-21-09-900-801-01	LOB PRESSURE SWITCH								Component ATA:28
PN:GP422-1306-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1272	HRS		0	TSN 0					4101.3
WC#: 28.175	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801					
28-21-09-900-801-02	LIB PRESSURE SWITCH								Component ATA:28
PN:GP422-1306-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2673	HRS		0	TSN 0					4101.3
WC#: 28.180	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801					
28-21-09-900-801-03	RIB PRESSURE SWITCH								Component ATA:28
PN:GP422-1306-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2678	HRS		0	TSN 0					4101.3
WC#: 28.180	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-21-09-900-801-04	ROB PRESSURE SWITCH								Component	ATA:28
PN:GP422-1306-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2677	HRS		0	TSN 0					4101.3	
WC#: 28.175	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801						
28-21-13-900-801-01	LH DC AUXILIARY PUMP ASSY								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.185	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 13 000 801, AMM 28 21 13 400 801						
28-21-13-900-801-02	RH DC AUXILIARY PUMP ASSY								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.185	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 13 000 801, AMM 28 21 13 400 801						
28-21-25-900-801-01	LH EJECTOR VENT SCAVENGE PUMP								Component	ATA:28
PN:GP422-1408-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0797	HRS		0	TSN 0					4101.3	
WC#: 28.190	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 25 000 801, AMM 28 21 25 400 801						
28-21-25-900-801-02	RH EJECTOR VENT SCAVENGE PUMP								Component	ATA:28
PN:GP422-1408-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0794	HRS		0	TSN 0					4101.3	
WC#: 28.190	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 25 000 801, AMM 28 21 25 400 801						
28-21-29-201 S	OPERATIONAL (INTERNAL LEAK) TEST OF THE ENGINE FEED SHUTOFF-VALVES								Service	ATA:28
	MOS		11-Jul-18						67	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 28.060	AFL		921						304	
				PROC. REF: AMM 28 21 29 710 802						PKG:8
28-21-29-900-801-01	LEFT ENGINE FEED SHUTOFF VALVE								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.200	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-21-29-900-801-02	RIGHT ENGINE FEED SHUTOFF VALVE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.200	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801					
28-21-33-900-801-01	LH ENGINE FEED SOV ACTUATOR								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.195	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 33 000 801, AMM 28 21 33 400 801					
28-21-33-900-801-02	RH ENGINE FEED SOV ACTUATOR								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.195	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 33 000 801, AMM 28 21 33 400 801					
28-21-37-900-801-01	APU BODY VALVE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.205	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 37 000 801, AMM 28 21 37 400 801					
28-21-41-900-801-01	APU SHUT-OFF VALVE ACTUATOR								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.140	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 41 000 801, AMM 28 21 41 400 801					
28-21-45-900-801-01	LH SHUTOFF CROSSFEED VALVE								Component ATA:28
PN:GP422-1412-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1164	HRS		0	TSN 0					4101.3
WC#: 28.210	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 21 45 000 801, AMM 28 21 45 400 801					
28-21-45-900-801-02	RH SHUTOFF CROSSFEED VALVE								Component ATA:28
PN:GP422-1412-15	MOS/MSC	O/C	01-Feb-16	TSR 0					96.3
SN:AA410540	HRS		1928.5	TSR 0					2172.8
WC#: 28.210	AFL		681	TSR 0					544
				PROC. REF: AMM 28 21 45 000 801, AMM 28 21 45 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-21-53-900-801-01	LH CHECK FEED VALVE								Component	ATA:28
PN:GP422-1410-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1750	HRS		0	TSN 0					4101.3	
WC#: 28.215	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 53 000 801, AMM 28 21 53 400 801						
28-21-53-900-801-02	RH CHECK FEED VALVE								Component	ATA:28
PN:GP422-1410-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1760	HRS		0	TSN 0					4101.3	
WC#: 28.215	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 53 000 801, AMM 28 21 53 400 801						
28-21-57-900-801-01	LEFT CHECK FEED VALVE								Component	ATA:28
PN:GP422-1410-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1748	HRS		0	TSN 0					4101.3	
WC#: 28.220	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 57 000 801, AMM 28 21 57 400 801						
28-21-57-900-801-02	RIGHT CHECK FEED VALVE								Component	ATA:28
PN:GP422-1410-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1749	HRS		0	TSN 0					4101.3	
WC#: 28.220	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 57 000 801, AMM 28 21 57 400 801						
28-21-61-900-801-01	LH CHECK DC AUX PUMP VALVE								Component	ATA:28
PN:GP422-1305-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1039	HRS		0	TSN 0					4101.3	
WC#: 28.225	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 61 000 801, AMM 28 21 61 400 801						
28-21-61-900-801-02	RH CHECK DC AUX PUMP VALVE								Component	ATA:28
PN:GP422-1305-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1040	HRS		0	TSN 0					4101.3	
WC#: 28.225	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 21 61 000 801, AMM 28 21 61 400 801						
28-22-00-201	OPERATIONAL TEST OF THE AFT-TANK MANUAL-TRANSFER SYSTEM								Service	ATA:28
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 28.065	AFL		690						535	
				PROC. REF: AMM 28 22 00 710 803						PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-22-00-202	OPERATIONAL TEST OF THE WING TO WING MANUAL-TRANSFER SYSTEM								Service	ATA:28
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 28.070	AFL		690						535	
				PROC. REF: AMM 28 22 00 710 801						PKG:8
28-22-01-900-801-01	LH SHUTOFF WING TRANSFER VALVE								Component	ATA:28
PN:GP422-1304-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0824	HRS		0	TSN 0					4101.3	
WC#: 28.230	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 22 01 000 801, AMM 28 22 01 400 801						
28-22-01-900-801-02	RH SHUTOFF WING TRANSFER VALVE								Component	ATA:28
PN:GP422-1304-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0823	HRS		0	TSN 0					4101.3	
WC#: 28.230	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 22 01 000 801, AMM 28 22 01 400 801						
28-22-05-900-801-01	WING TRANSFER SHUT-OFF VALVE ACTUATOR								Component	ATA:28
PN:GP422-1412-4	MOS/MSC	O/C	28-Mar-13	TSO 0					130.5	
SN:T20422	HRS		896.8	TSO 0					3204.5	
	AFL		345	TSO 0					880	
				PROC. REF: AMM 28 22 05 000 801, AMM 28 22 05 400 801						
28-22-09-900-801-01	LH CENTER TRANSFER PUMP CARTRIDGE								Component	ATA:28
PN:GP422-1307-13	MOS/MSC	O/C	24-Jul-14	TSN 5					114.6	
SN:12BJ243	HRS		1391.1	TSN 0					2710.2	
WC#: 28.235	AFL		537	TSN 0					688	
				PROC. REF: AMM 28 22 09 000 801, AMM 28 22 09 400 801						
28-22-09-900-801-02	RH CENTER TRANSFER PUMP CARTRIDGE								Component	ATA:28
PN:GP422-1307-13	MOS/MSC	O/C	24-Jul-14	TSN 5					114.6	
SN:12BJ245	HRS		1391.1	TSN 0					2710.2	
WC#: 28.235	AFL		537	TSN 0					688	
				PROC. REF: AMM 28 22 09 000 801, AMM 28 22 09 400 801						
28-22-13-900-801-01	LH CENTER TRANSFER PUMP ASSEMBLY								Component	ATA:28
PN:GP422-1307-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-22-13-900-801-02	RH CENTER TRANSFER PUMP ASSEMBLY								Component ATA:28
PN:GP422-1307-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-22-13-900-802-01	LH CENTER TRANSFER PUMP CANISTER								Component ATA:28
PN:GP422-1307-15	MOS/MSC	O/C	24-Jul-14	TSN 5					114.6
SN:12BJ243	HRS		1391.1	TSN 0					2710.2
	AFL		537	TSN 0					688
				PROC. REF: AMM 28 22 13 000 801, AMM 28 22 13 400 801					
28-22-13-900-802-02	RH CENTER TRANSFER PUMP CANISTER								Component ATA:28
PN:GP422-1307-15	MOS/MSC	O/C	24-Jul-14	TSN 5					114.6
SN:12BJ245	HRS		1391.1	TSN 0					2710.2
	AFL		537	TSN 0					688
				PROC. REF: AMM 28 22 13 000 801, AMM 28 22 13 400 801					
28-22-17-900-801-01	LH CENTER TRANSFER - DC AUX PRESSURE SWITCH								Component ATA:28
PN:GP422-1306-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2347	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 22 17 000 801, AMM 28 22 17 400 801					
28-22-17-900-801-02	RH CENTER TRANSFER - DC AUX PRESSURE SWITCH								Component ATA:28
PN:GP422-1306-5	MOS/MSC	O/C	12-Jul-16						91
SN:2804	HRS		2078.9						2022.4
	AFL		719						506
				PROC. REF: AMM 28 22 17 000 801, AMM 28 22 17 400 801					
28-22-17-900-802-01	LH AC CENTER PRESSURE SWITCH								Component ATA:28
PN:GP422-1306-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2020	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-22-17-900-802-02	RH AC CENTER PRESSURE SWITCH								Component ATA:28
PN:GP422-1306-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2299	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-22-21-900-801-01	LH CHECK CENTER TANK TRANSFER VALVE								Component ATA:28
PN:GP422-1405-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3591	HRS		0	TSN 0					4101.3
WC#: 28.240	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 22 21 000 801, AMM 28 22 21 400 801					
28-22-21-900-801-02	RH CHECK CENTER TANK TRANSFER VALVE								Component ATA:28
PN:GP422-1405-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:3592	HRS		0	TSN 0					4101.3
WC#: 28.240	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 22 21 000 801, AMM 28 22 21 400 801					
28-22-25-900-801-01	LH AFT TANK TRANSFER PUMP ASSEMBLY								Component ATA:28
PN:GP422-1302-15	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:4BE41	HRS		0	TSN 0					4101.3
WC#: 28.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 22 25 000 801, AMM 28 22 25 400 801					
28-22-25-900-801-02	RH AFT TANK TRANSFER PUMP ASSEMBLY								Component ATA:28
PN:GP422-1302-17	MOS/MSC	O/C	27-Jul-16						90.5
SN:11BF46	HRS		2078.9						2022.4
WC#: 28.120	AFL		719						506
				PROC. REF: AMM 28 22 25 000 801, AMM 28 22 25 400 801					
28-22-37-900-801-01	AFT SHUT-OFF VALVE ACTUATOR								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.145	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 22 37 000 801, AMM 28 22 37 400 801					
28-22-37-900-801-02	LH AFT TANK TRANSFER VALVE ACTUATOR								Component ATA:28
PN:GP422-1404-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-22-37-900-801-03	RH AFT TANK TRANSFER VALVE ACTUATOR								Component ATA:28
PN:GP422-1404-3	MOS/MSC	O/C	19-Mar-16						94.7
SN:T58544	HRS		1978.6						2122.7
	AFL		690						535
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-22-41-900-801-01	LOB FUEL CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.245	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-22-41-900-801-02	LIB FUEL CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.250	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-22-41-900-801-03	RIB FUEL CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.250	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-22-41-900-801-04	ROB FUEL CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.245	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-23-01-900-801-01	EXTERNAL REFUEL/DEFUEL PANEL								Component ATA:28
PN:GP541-1102-1	MOS/MSC	O/C	23-Apr-18	TSR 0					69.6
SN:1442	HRS		2798.5	TSR 0					1302.8
WC#: 28.255	AFL		902	TSR 0					323
				PROC. REF: AMM 28 23 01 000 801, AMM 28 23 01 400 801					
28-23-05-900-801-02	RH REFUEL ADAPTOR CAP								Component ATA:28
PN:GP425-1102-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:31601	HRS		0	TSN 0					4101.3
WC#: 28.260	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 05 000 801, AMM 28 23 05 400 801					
28-23-05-900-802-01	REFUEL/DE-FUEL ADAPTOR								Component ATA:28
PN:GP516-1102-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:02064	HRS		0	TSN 0					4101.3
WC#: 28.265	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 05 000 801, AMM 28 23 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-23-13-900-801-01	LEFT TANK MANIFOLD REFUEL/DEFUEL CONTROL								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.270	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801					
28-23-13-900-801-02	CENTER TANK MANIFOLD REFUEL/DEFUEL CONTROL								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.270	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801					
28-23-13-900-801-03	RIGHT TANK MANIFOLD REFUEL/DEFUEL CONTROL								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.270	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801					
28-23-17-900-801-01	LH CHECK REFUEL VALVE								Component ATA:28
PN:GP422-1111-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0776	HRS		0	TSN 0					4101.3
WC#: 28.275	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 17 000 801, AMM 28 23 17 400 801					
28-23-17-900-801-02	RH CHECK REFUEL VALVE								Component ATA:28
PN:GP422-1111-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0788	HRS		0	TSN 0					4101.3
WC#: 28.275	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 17 000 801, AMM 28 23 17 400 801					
28-23-21-900-801-01	CHECK REFUEL/DEFUEL VALVE								Component ATA:28
PN:GP422-1108-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0382	HRS		0	TSN 0					4101.3
WC#: 28.280	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 21 000 801, AMM 28 23 21 400 801					
28-23-25-900-801-01	LH SHUTOFF DEFUEL VALVE								Component ATA:28
PN:GP422-1412-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:AA191763	HRS		0	TSN 0					4101.3
WC#: 28.285	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 23 25 000 801, AMM 28 23 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-23-25-900-801-02	RH SHUTOFF DEFUEL VALVE								Component	ATA:28
PN:GP422-1412-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:AA196289	HRS		0	TSN 0					4101.3	
WC#: 28.285	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 23 25 000 801, AMM 28 23 25 400 801						
28-23-29-900-801-01	LH SHUT-OFF VALVE ACTUATOR								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.135	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 23 29 000 801, AMM 28 23 29 400 801						
28-23-29-900-801-02	RH SHUT-OFF VALVE ACTUATOR								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.135	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 23 29 000 801, AMM 28 23 29 400 801						
28-23-33-900-801-01	AFT TANK REFUEL SHUTOFF VALVE								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 28.290	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 23 33 000 801, AMM 28 23 33 400 801						
28-24-00-201[S]	OPERATIONAL TEST OF THE FUEL RETURN TO TANK (FRTT) CHECK VALVES, POST SB 700-28-034 AND A/C 9111 AND SUBS								Service	ATA:28
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 28.075	AFL		1069						156	
				PROC. REF: AMM 28 26 00 710 802						PKG:38
28-27-05-900-801-01	LH EJECTOR PUMP VALVE								Component	ATA:28
PN:GP422-1415-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3092	HRS		0	TSN 0					4101.3	
WC#: 28.295	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 27 05 000 801, AMM 28 27 05 400 801						
28-27-05-900-801-02	RH EJECTOR PUMP VALVE								Component	ATA:28
PN:GP422-1415-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3079	HRS		0	TSN 0					4101.3	
WC#: 28.295	AFL		0	TSN 0					1225	
				PROC. REF: AMM 28 27 05 000 801, AMM 28 27 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-27-09-900-801-01	LH CENTER TRANSFERT PUMP - DC AUX PUMP VALVE CHECK								Component	ATA:28
PN:GP422-1405-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3593	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-27-09-900-801-02	RH CENTER TRANSFERT PUMP - DC AUX PUMP VALVE CHECK								Component	ATA:28
PN:GP422-1405-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3594	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-41-00-101	FUNCTIONAL TEST OF THE TEMPERATURE SENSORS								Service	ATA:28
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
WC#: 28.080	AFL		1069						156	
				PROC. REF: AMM 28 41 25 720 801						PKG:38
28-41-01-900-801-01	RIGHT MAIN AVIONIC BAY FMQG COMPUTER								Component	ATA:28
PN:GP546-1501-13	MOS/MSC	O/C	08-Sep-15						101.1	
SN:0388	HRS		1771.8	TSR 0					2329.5	
WC#: 28.300	AFL		649	TSR 0					576	
				PROC. REF: AMM 28 41 01 000 801, AMM 28 41 01 400 801						
28-41-05-900-801-02	RH (L 25.35 IN) FUEL PROBE								Component	ATA:28
PN:GP422-1514-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0847	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-41-05-900-801-03	LH BL4.75 UPPER STR #18 - #19 FUEL W/COMP (L36.71 IN) PROBE								Component	ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-41-05-900-801-04	RH BL4.75 UPPER STR #18 - #19 FUEL W/COMP (L36.71 IN) PROBE								Component	ATA:28
PN:GP422-1514-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0402	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-41-09-900-801-01	LH (L 36.17 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0845	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-02	RH (L 36.17 IN) FUEL PROBE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-03	LH (L 35.88 IN) FUEL PROBE								Component ATA:28
PN:GP422-1514-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0842	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-04	RH (L 35.88 IN) FUEL PROBE								Component ATA:28
PN:GP422-1514-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0415	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-05	LH (L 27.81 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0821	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-06	RH (L 27.81 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0797	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-07	LH (L 17.51 IN) FUEL PROBE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-41-09-900-801-08	RH (L 17.51 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0839	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-09	LH (L 28.85 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0802	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-10	RH (L 28.85 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0808	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-11	LH (L 30.77 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0807	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-12	RH (L 30.77 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0805	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-13	LH (L 20.16 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0782	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-14	RH (L 20.16 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0788	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-41-09-900-801-15	LH (L 18.38 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-6	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0801	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-16	RH (L 18.38 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-6	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0794	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-17	LH (L 17.51 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0807	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-18	RH (L 17.51 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0812	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-19	LH (L 14.65 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-8	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0816	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-20	RH (L 14.65 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-8	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0817	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-21	LH (L 9.63 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0794	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-41-09-900-801-22	RH (L 9.63 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0792	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-23	LH (L 9.33 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-10	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0841	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-24	RH (L 9.33 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-10	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0807	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-25	LH (L 8.98 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0865	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-26	RH (L 8.98 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0857	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-27	LH (L 8.12 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-12	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0782	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-28	RH (L 8.12 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-12	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0788	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-41-09-900-801-29	LH (L 6.53 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0792	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-30	RH (L 6.53 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0787	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-31	LH (L 7.61 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0820	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-32	RH (L 7.61 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0843	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-33	LH (L 21.67 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-15	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0769	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-09-900-801-34	RH (L 21.67 IN) FUEL PROBE								Component ATA:28
PN:GP422-1501-15	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0770	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-17-900-801-01	LH (WS415.4 LWR STR#10-#11) FUEL HIGH LEVEL SENSOR								Component ATA:28
PN:GP422-1505-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1682	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
28-41-17-900-801-02	LH (WS66.00 LWR STR#16-#17) FUEL HIGH LEVEL SENSOR								Component ATA:28
PN:GP422-1505-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1680	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-17-900-801-03	RH (WS415.4 LWR STR#10-#11) FUEL HIGH LEVEL SENSOR								Component ATA:28
PN:GP422-1505-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1653	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-17-900-801-04	RH (WS66.00 LWR STR#16-#17) FUEL HIGH LEVEL SENSOR								Component ATA:28
PN:GP422-1505-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1668	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-21-900-801-01	DENSIOMETER ENCLOSURE								Component ATA:28
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 28.305	AFL		0	TSN 0					1225
				PROC. REF: AMM 28 41 21 000 801, AMM 28 41 21 400 801					
28-41-21-900-802-01	FUEL DENSIOMETER								Component ATA:28
PN:GP422-1512-1	MOS/MSC	O/C	26-Apr-12	TSR 0					141.5
SN:0331	HRS		443.4	TSR 0					3657.9
WC#: 28.310	AFL		160	TSR 0					1065
				PROC. REF: AMM 28 41 21 000 801, AMM 28 41 21 400 801					
28-41-25-900-801-01	LH (WS66.00 LWR STR#7-#8) FUEL TEMP SENSOR								Component ATA:28
PN:GP422-1508-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:02287	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
28-41-25-900-801-02	LH (CANT RIB LWR STR#8-#9) FUEL TEMP SENSOR								Component ATA:28
PN:GP422-1508-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:02297	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
28-41-25-900-801-03	RH (WS108.5 LWR STR#7-#8) FUEL TEMP SENSOR								Component	ATA:28
PN:GP422-1508-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:02328	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-41-25-900-801-04	RH (WS199.0 LWR STR#7-#8) FUEL TEMP SENSOR								Component	ATA:28
PN:GP422-1508-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:02299	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
28-41-25-900-801-05	RH (WS66.00 LWR STR#7-#8) FUEL TEMP SENSOR								Component	ATA:28
PN:GP422-1508-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:02298	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
282300-701 U	REFUEL/DEFUEL PANEL								Component	ATA:28
PN:GP541-1102-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1562	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
ASB A700-28-031	MODIFICATION - FUEL FEED SYSTEM - REPLACEMENT OF THE EXISTING APU FUEL FEED LINE FITTING WITH A SHROUDED ONE, ALERT SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-28-031 REV 01	MODIFICATION - FUEL FEED SYSTEM - REPLACEMENT OF THE EXISTING APU FUEL FEED LINE FITTING WITH A SHROUDED ONE, ALERT SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2021-10-22	FUEL - REFUEL DEFUEL TUBE - MISLOCATED BRACKET ASSEMBLY								AD	ATA:28
	MOS/MSC	-	17-Jan-22						24.8	
	HRS		3689.6						411.7	
	AFL		1117						108	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
SB 700-28-001	MODIFICATION - DISTRIBUTION - PIPING PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-28-001 REV 01 PART (A)	MODIFICATION - DISTRIBUTION - PIPING PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-28-001 REV 01 PART (B)	MODIFICATION - DISTRIBUTION - PIPING PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-28-002	MODIFICATION - REFUEL/DEFUEL SYSTEM - ADDITION OF REFUEL/DEFUEL CONTROL PANEL IN FLIGHT COMPARTMENT, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-28-002 REV 01	MODIFICATION - REFUEL/DEFUEL SYSTEM - ADDITION OF REFUEL/DEFUEL CONTROL PANEL IN FLIGHT COMPARTMENT. (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-28-002 REV 02	MODIFICATION - REFUEL/DEFUEL SYSTEM - ADDITION OF REFUEL/DEFUEL CONTROL PANEL IN FLIGHT COMPARTMENT, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
SB 700-28-020	MODIFICATION - VENT SYSTEM - INSTALLATION OF COVERS OVER FUEL VENT LINES, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
SB 700-28-020 REV 01	MODIFICATION - VENT SYSTEM - INSTALLATION OF COVERS OVER FUEL VENT LINES, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-021	MODIFICATION - VENT SYSTEM - CABIN CROSSOVER LINES REWORKED FOR SUFFICIENT CLEARANCE, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-021 REV 01	MODIFICATION - VENT SYSTEM - CABIN CROSSOVER LINES REWORKED FOR SUFFICIENT CLEARANCE, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-021 REV 02	REWORK - VENT SYSTEM - CABIN CROSSOVER LINES REWORKED FOR SUFFICIENT CLEARANCE, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-021 REV 03	REWORK - VENT SYSTEM - CABIN CROSSOVER LINES REWORKED FOR SUFFICIENT CLEARANCE, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-026	MODIFICATION - REFUEL/DEFUEL SYSTEM - REPLACEMENT OF THE REFUEL/DEFUEL TUBE WITH A SHORTER ONE TO ELIMINATE STRESS PROBLEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-026 REV 01	MODIFICATION - REFUEL/DEFUEL SYSTEM - REPLACEMENT OF THE REFUEL/DEFUEL TUBE WITH A SHORTER ONE TO ELIMINATE STRESS PROBLEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
SB 700-28-026 REV 02	MODIFICATION - REFUEL/DEFUEL SYSTEM - REPLACEMENT OF THE REFUEL/DEFUEL TUBE WITH A SHORTER ONE TO ELIMINATE STRESS PROBLEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-027	SPECIAL CHECK/REWORK - FUEL FEED AND TRANSFER SYSTEMS - POSSIBLE DAMAGE OF FUEL PUMP WIRING IN CONDUITS, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-028	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - INTRODUCTION OF NEW COMPUTER PART NUMBER GP546-1501-3, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-029	MODIFICATION - FUEL FEED SYSTEM - SCAVENGE SYSTEM INSTALLATION TO REDUCE UNUSABLE FUEL QUANTITY, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-029 REV 01	MODIFICATION - FUEL FEED SYSTEM - SCAVENGE SYSTEM INSTALLATION TO REDUCE UNUSABLE FUEL QUANTITY, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-032	MODIFICATION - DISTRIBUTION - WIRING PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-032 REV 01	MODIFICATION - DISTRIBUTION - WIRING PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
SB 700-28-032 REV 02	MODIFICATION - DISTRIBUTION - WIRING PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-033	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - FMQGS COMPUTER CHANGE TO PART NO. GP546-1501-5, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-034	MODIFICATION - DISTRIBUTION - REPLACEMENT OF THE FUEL CONTROL PANEL / ACTIVATION OF THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-035	MODIFICATION - DISTRIBUTION - INSTALLATION OF FUEL RE-CIRCULATION AND SCAVENGE SYSTEMS FOR AIRCRAFT '9003' ONLY, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-036	CANCELLED PRIOR TO ISSUE, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-039	MODIFICATION - DISTRIBUTION - PERMANENT WIRING CONFIGURATION FOR THE FUEL RE-CIRCULATION SYSTEM FOLLOWING POWER SOURCE CHANGE, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-040	ACTIVATION OF FWD FUEL TANK, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
SB 700-28-041	MODIFICATION - FUEL FEED SYSTEM - TEMPORARY DE-ACTIVATION OF THE FUEL SCAVENGE SYSTEM, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-042	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-042 REV 01	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-042 REV 02 PART (A)	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-042 REV 02 PART (B)	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-042 REV 02 PART (C)	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-043	MODIFICATION - FUEL FEED SYSTEM - INTRODUCTION OF INTEGRAL FUEL TANK COATING BETWEEN THE DC FUEL PUMP AND MATING FLANGE (A/C 9002 TO 9124), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
SB 700-28-043 REV 01	MODIFICATION - FUEL FEED SYSTEM - INTRODUCTION OF INTEGRAL FUEL TANK COATING BETWEEN THE DC FUEL PUMP AND MATING FLANGE, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-28-044	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTER TO PART NO. GP546-1501-8, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-045	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTER TO PART NO. GP546-1501-9 (A/C 9003, 9096, 9115 TO 9132), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-046	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - SEGREGATION OF PINS AT LTP1 TO PREVENT EXCESS EICAS ERROR MESSAGES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-28-046 REV 01	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - SEGREGATION OF PINS AT LTP1 TO PREVENT EXCESS EICAS ERROR MESSAGES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-046 REV 02	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - SEGREGATION OF PINS AT LTP1 TO PREVENT EXCESS EICAS ERROR MESSAGES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-047	MODIFICATION - REFUEL/DEFUEL SYSTEM - NEW TUBE INSTALLATION TO REDUCE REFUELING TIME (A/C 9002, 9004 TO 9095, 9097 TO 9158), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 28 - FUEL									
SB 700-28-047 REV 01	MODIFICATION - REFUEL/DEFUEL SYSTEM - NEW TUBE INSTALLATION TO REDUCE REFUELING TIME, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-28-048	MODIFICATION - DISTRIBUTION - CHANGE OF PLACARDS ON THE FUEL CONTROL PANEL FOR AUTOMATIC FUEL RE-CIRCULATION SYSTEM (A/C 9159 TO 9219), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-28-049	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTER TO PART NO. GP546-1501-11 (A/C 9003, 9096, 9115 TO 9126, AND 9128 TO 9301, AND A/C 9002, 9004 TO 9095 AND 9097 TO 9114 WITH A FMQGC -9 INSTALLED), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-28-049 REV 01	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTER TO PART NO. GP546-1501-11 OR GP546-1501-13, SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-28-050	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTER TO PART NO. GP546-1501-10 (A/C 9002, 9004 TO 9095 AND 9097 TO 9114), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-28-051 PART (A)	SPECIAL CHECK/MODIFICATION/REWORK - FUEL FEED SYSTEM - INSPECT FUEL TUBE, PART NO. GD428-1003 FOR FOULING ON BRACKET AND TRIM BRACKET TO PROVIDE LARGER CLEARANCE (A/C 9002 TO 9266), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-28-051 PART (B)	SPECIAL CHECK/MODIFICATION/REWORK - FUEL FEED SYSTEM - INSPECT FUEL TUBE, PART NO. GD428-1003 FOR FOULING ON BRACKET AND TRIM BRACKET TO PROVIDE LARGER CLEARANCE (A/C 9002 TO 9266), SERVICE BULLETIN								Bulletin ATA:28
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 28 - FUEL										
SB 700-28-051 PART (C)	SPECIAL CHECK/MODIFICATION/REWORK - FUEL FEED SYSTEM - INSPECT FUEL TUBE, PART NO. GD428-1003 FOR FOULING ON BRACKET AND TRIM BRACKET TO PROVIDE LARGER CLEARANCE (A/C 9002 TO 9266), SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-28-052	MODIFICATION - AFT FUEL TANK - TRIM PULL TAB NEXT TO RELIEF VALVE, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-28-053	MODIFICATION - FUEL TRANSFER SYSTEM - DESIGN IMPROVEMENT TO THE CENTER TRANSFER PUMP, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-	25-Jul-14						114.5	
	HRS		1391.1						2710.2	
	AFL		537						688	
SB 700-28-054	SPECIAL CHECK/MODIFICATION - FUEL FEED SYSTEM - CHECK THE FUEL FEED LINE OF THE LEFT-HAND ENGINE FOR CHAFING, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-	29-Jul-11						150.4	
	HRS		68.1						4033.2	
	AFL		38						1187	
SB 700-28-054 PART (A)	INSPECTION SPECIAL CHECK/MODIFICATION - FUEL FEED SYSTEM - CHECK THE FUEL FEED LINE OF THE LEFT-HAND ENGINE FOR CHAFING, SERVICE BULLETIN								Bulletin	ATA:28
	MOS/MSC	-	29-Jul-11						150.4	
	HRS		68.1						4033.2	
	AFL		38						1187	
SB 700-28-054 PART (B)	REPLACEMENT SPECIAL CHECK/MODIFICATION - FUEL FEED SYSTEM - CHECK THE FUEL FEED LINE OF THE LEFT-HAND ENGINE FOR CHAFING, SERVICE BULLETIN OF THE FUEL FEED LINE								Bulletin	ATA:28
	MOS/MSC	-	22-Aug-11						149.6	
	HRS									
	AFL									
ATA 29 - HYDRAULIC POWER										
29-12-00-201[S]	VISUAL CHECK OF THE NO. 1 AND NO. 2 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS								Service	ATA:29
	MOS		28-Nov-23						2.5	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 29.005	AFL		1223						2	
				PROC. REF: AMM 29 12 00 210 802						PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
29-12-01-900-801-01	NO. 1 ENGINE DRIVEN HYDRAULIC PUMP								Component ATA:29
PN:GX472-0010-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:K0819	HRS		0	TSN 0					4101.3
WC#: 29.035	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 01 000 801, AMM 29 12 01 400 801					
29-12-01-900-801-02	NO. 2 ENGINE DRIVEN HYDRAULIC PUMP								Component ATA:29
PN:GX472-0010-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:K0805	HRS		0	TSN 0					4101.3
WC#: 29.035	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 01 000 801, AMM 29 12 01 400 801					
29-12-05-900-801-01	1B AC MOTOR PUMP								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.040	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801					
29-12-05-900-801-02	2B AC MOTOR PUMP								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.045	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801					
29-12-09-900-801-01	NO. 1 MANIFOLD FILTER								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.085	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 09 000 801, AMM 29 12 09 400 801					
29-12-09-900-801-02	NO. 2 MANIFOLD FILTER								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.085	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 09 000 801, AMM 29 12 09 400 801					
29-12-25-900-801-01	NO. 1 HYDRAULIC RESERVOIR								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.060	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 25 000 801, AMM 29 12 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 29 - HYDRAULIC POWER										
29-12-25-900-801-02	NO. 2 HYDRAULIC RESERVOIR								Component	ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 29.060	AFL		0	TSN 0					1225	
				PROC. REF: AMM 29 12 25 000 801, AMM 29 12 25 400 801						
29-12-33-101	OPERATIONAL TEST OF THE FIREWALL HYDRAULIC SHUTOFF-VALVES								Service	ATA:29
	MOS		19-Mar-21					23-Sep-2025	34.7	
	HRS	1500	3474.7		4974.7		873.4		626.6	
WC#: 29.010	AFL		1069						156	
				PROC. REF: AMM 29 12 33 710 801						PKG:5
29-12-33-900-801-01	NO. 1 S/O FIREWALL VALVE								Component	ATA:29
PN:GX473-0010-5	MOS/MSC	O/C	27-Dec-13	TSN 0					121.5	
SN:TA4123	HRS		1176.4	TSN 0					2924.9	
WC#: 29.065	AFL		464	TSN 0					761	
				PROC. REF: AMM 29 12 33 000 801, AMM 29 12 33 400 801						
29-12-33-900-801-02	NO. 2 S/O FIREWALL VALVE								Component	ATA:29
PN:GX473-0010-5	MOS/MSC	O/C	19-Jul-14	TSN 0					114.7	
SN:TA4786	HRS		1387.1	TSN 0					2714.2	
WC#: 29.065	AFL		533	TSN 0					692	
				PROC. REF: AMM 29 12 33 000 801, AMM 29 12 33 400 801						
29-12-33-900-802-01	NO. 1 HYDRAULIC FIREWALL SHUTOFF ACTUATOR ASSEMBLY								Component	ATA:29
PN:GX473-0126-1	MOS/MSC	O/C	09-Jan-20	TSR 2					49.1	
SN:TA5343	HRS		3338.3	TSR 0					763	
	AFL		1038	TSR 0					187	
				PROC. REF: AMM 29 12 33 000 802, AMM 29 12 33 400 802						
29-12-33-900-802-02	NO. 2 HYDRAULIC FIREWALL SHUTOFF ACTUATOR ASSEMBLY								Component	ATA:29
PN:GX473-0126-1	MOS/MSC	O/C	05-Feb-20	TSR 0					48.2	
SN:TA5744	HRS		3362.2	TSR 0					739.1	
	AFL		1043	TSR 0					182	
				PROC. REF: AMM 29 12 33 000 802, AMM 29 12 33 400 802						
29-12-37-900-801-01	LH PRIORITY VALVE								Component	ATA:29
PN:GX473-0060-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:PN0849	HRS		0	TSN 0					4101.3	
WC#: 29.070	AFL		0	TSN 0					1225	
				PROC. REF: AMM 29 12 37 000 801, AMM 29 12 37 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
29-12-37-900-801-02	RH PRIORITY VALVE								Component ATA:29
PN:GX473-0060-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:PN0850	HRS		0	TSN 0					4101.3
WC#: 29.070	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 37 000 801, AMM 29 12 37 400 801					
29-12-41-900-801-01	NO. 1 HEAT EXCHANGER								Component ATA:29
PN:GX474-0010-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:4299	HRS		0	TSN 0					4101.3
WC#: 29.105	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 41 000 801, AMM 29 12 41 400 801					
29-12-41-900-801-02	NO. 2 HEAT EXCHANGER								Component ATA:29
PN:GX474-0010-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:4298	HRS		0	TSN 0					4101.3
WC#: 29.105	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 41 000 801, AMM 29 12 41 400 801					
29-12-45-900-801-01	NO. 1 HEAT EXCHANGER BYPASS VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.075	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801					
29-12-45-900-801-02	NO. 2 HEAT EXCHANGER BYPASS VALVE								Component ATA:29
PN:GX473-0105-7	MOS/MSC	O/C	02-Mar-15	TSR 6					107.3
SN:PN4174	HRS		1589.8	TSR 0					2511.5
WC#: 29.075	AFL		590	TSR 0					635
				PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801					
29-12-61-900-801-01	LH CHECK VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.080	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801					
29-12-61-900-801-02	RH CHECK VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.080	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 29 - HYDRAULIC POWER										
29-12-61-900-801-03	CENTER CHECK VALVE								Component	ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 29.080	AFL		0	TSN 0					1225	
				PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801						
29-13-00-101	OPERATIONAL (INTERNAL LEAK) TEST OF THE NO. 3 HYDRAULIC SYSTEM								Service	ATA:29
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500 (+50/-50)	3474.7	Adj 50	5024.7	5074.7	923.4 (+50)		626.6	
WC#: 29.015	AFL		1069						156	
				PROC. REF: AMM 29 13 00 790 802						PKG:5
29-13-00-201 S	VISUAL CHECK OF THE NO. 3 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS								Service	ATA:29
	MOS		28-Nov-23						2.5	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 29.020	AFL		1223						2	
				PROC. REF: AMM 29 13 00 210 802						PKG:4
29-13-01-900-801-01	3A AC MOTOR PUMP								Component	ATA:29
PN:4211605	MOS/MSC	O/C	06-May-22	TSR 0					21.2	
SN:3287	HRS		3754.2	TSR 0					347.1	
WC#: 29.050	AFL		1133	TSR 0					92	
				PROC. REF: AMM 29 13 01 000 801, AMM 29 13 01 400 801						
29-13-01-900-801-02	3B AC MOTOR PUMP								Component	ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 29.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 29 13 01 000 801, AMM 29 13 01 400 801						
29-13-05-900-801-01	NO. 3 MANIFOLD FILTER								Component	ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 29.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 29 13 05 000 801, AMM 29 13 05 400 801						
29-13-21-201 S	FUNCTIONAL TEST OF THE NO. 3 HYDRAULIC SYSTEM ACCUMULATOR								Service	ATA:29
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 29.025	AFL		1223						2	
				PROC. REF: AMM 29 13 21 720 801						PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
29-13-21-900-801-01	NO. 3 SYSTEM HYDRAULIC ACCUMULATOR								Component ATA:29
PN:GX473-0100-7	MOS/MSC	O/C	22-Jul-15	TSN 0					102.6
SN:60190-3373	HRS		1712.9	TSN 0					2388.4
WC#: 29.090	AFL		624	TSN 0					601
				PROC. REF: AMM 29 13 21 000 801, AMM 29 13 21 400 801					
29-13-29-900-801-01	NO. 3 HYDRAULIC RESERVOIR								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.095	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 13 29 000 801, AMM 29 13 29 400 801					
29-13-33-900-801-01	RELIEF/BLEED VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.100	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 13 33 000 801, AMM 29 13 33 400 801					
29-13-37-900-801-01	NO. 3 HEAT EXCHANGER								Component ATA:29
PN:GX474-0010-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:4297	HRS		0	TSN 0					4101.3
WC#: 29.105	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 13 37 000 801, AMM 29 13 37 400 801					
29-13-41-900-801-01	NO. 3 HEAT EXCHANGER BYPASS VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.075	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 13 41 000 801, AMM 29 13 41 400 801					
29-13-49-900-801-01	NO. 1 CHECK IN LINE VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.110	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
29-13-57-900-801-01	MANIFOLD VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.115	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 13 57 000 801, AMM 29 13 57 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
29-14-00-201	FUNCTIONAL TEST OF THE RAM AIR TURBINE (RAT) HYDRAULIC FLUID-HEATING SYSTEM								Service ATA:29
	MOS		19-Mar-16					26-Sep-2025	94.7
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3
WC#: 29.030	AFL		690						535
				PROC. REF: AMM 29 14 00 720 801					PKG:8
29-14-01-900-801-01	NO. 1 CHECK RESTRICTOR VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801					
29-14-01-900-801-02	NO. 2 CHECK RESTRICTOR VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801					
29-14-01-900-801-03	NO. 3 CHECK RESTRICTOR VALVE								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801					
29-31-01-900-801-01	NO. 1 PRESSURE TRANSDUCER								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.125	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801					
29-31-01-900-801-02	NO. 2 PRESSURE TRANSDUCER								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.125	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801					
29-31-01-900-801-03	NO. 3 PRESSURE TRANSDUCER								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.125	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
29-31-05-900-801-01	1A PRESSURE SWITCH								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.130	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801					
29-31-05-900-801-02	1B PRESSURE SWITCH								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.130	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801					
29-31-05-900-801-03	2A PRESSURE SWITCH								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.135	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801					
29-31-05-900-801-04	2B PRESSURE SWITCH								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.135	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801					
29-31-05-900-801-05	NO. 3A PRESSURE SWITCH								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.140	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801					
29-31-05-900-801-06	NO. 3B PRESSURE SWITCH								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.140	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801					
29-33-01-900-801-01	NO. 1 TEMPERATURE TRANSDUCER								Component ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 29.145	AFL		0	TSN 0					1225
				PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 29 - HYDRAULIC POWER										
29-33-01-900-801-02	NO. 2 TEMPERATURE TRANSDUCER								Component	ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 29.145	AFL		0	TSN 0					1225	
				PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801						
29-33-01-900-801-03	NO. 3 TEMPERATURE TRANSDUCER								Component	ATA:29
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 29.145	AFL		0	TSN 0					1225	
				PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801						
ASB A700-29-016	SPECIAL CHECK/REWORK - NO. 3 HYDRAULIC SYSTEM - POSSIBLE CONTAMINATION CAUSED BY RAM AIR TURBINE (RAT) PIVOT SHAFT, ALERT SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2011-01-10	HYDRAULIC SYSTEM LINES - RELOCATE THE NO. 2 AND NO. 3 HYDRAULIC SYSTEM LINES IN THE WING AUXILIARY SPAR AREA ON THE LEFT SIDE OF THE AIRCRAFT, AND MODIFY THE LEFT WING RIB AND LEFT AND RIGHT DEBRIS SHIELDS								AD	ATA:29
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
MODSUM IS700-29-000 REV B1	SPOILER HYDRAULIC SYSTEM INSTALLATION, MODIFICATION SUMMARY								Bulletin	ATA:29
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-29-013	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - HYDRAULIC TUBE GM478-1442-9 REPLACEMENT, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-29-014	MODIFICATION - QUICK DISCONNECTS - ADD P-CLAMPS TO HYDRAULIC TUBES GM478-4300 AND GM478-4330 (CENTER WING AT FS573.70), SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
SB 700-29-015	MODIFICATION - HYDRAULIC SYSTEMS NO. 1 AND NO. 3 - REPLACE FLOW-DIRECTION IDENTIFICATION TAPE ON HYDRAULIC LINES (A/C 9022, 9039, 9044 AND 9057), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-29-017	SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS - INSPECTION OF ALL HYDRAULIC FILTER ELEMENT PART NUMBERS, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-29-018 PART (A)	SPECIAL CHECK/MODIFICATION - NO. 1 HYDRAULIC SYSTEM TUBES - INTERFERENCE BETWEEN TWO HYDRAULIC TUBES (A/C 9002 TO 9126 AND 9128 TO 9171), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-29-018 PART (B)	SPECIAL CHECK/MODIFICATION - NO. 1 HYDRAULIC SYSTEM TUBES - INTERFERENCE BETWEEN TWO HYDRAULIC TUBES (A/C 9002 TO 9126 AND 9128 TO 9171), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-29-019	MODIFICATION - NO. 2 AND 3 HYDRAULIC SYSTEMS - REPLACE FAULTY PRIORITY VALVE PART NO. GX473-0060-1 (A/C 9145 TO 9148, 9150, 9151, 9153, 9162, 9163 AND 9165), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-29-020 PART (A)	SPECIAL CHECK/REWORK - NO. 3 HYDRAULIC SYSTEM - CHECK FAILREAD SUPPORT BRACKETS FOR CORRECT INSTALLATION AND REWORK HYDRAULIC TUBES IF DAMAGED (A/C 9002 TO 9126 AND 9128 TO 9215), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-29-020 PART (B)	SPECIAL CHECK/REWORK - NO. 3 HYDRAULIC SYSTEM - CHECK FAILREAD SUPPORT BRACKETS FOR CORRECT INSTALLATION AND REWORK HYDRAULIC TUBES IF DAMAGED (A/C 9002 TO 9126 AND 9128 TO 9215), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
SB 700-29-021	MODIFICATION - NO. 2 & NO. 3 HYDRAULIC SYSTEMS - RELOCATION OF HYDRAULIC LINES IN THE WING AUXILIARY SPAR, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-29-021 REV 01	MODIFICATION - NO. 2 & NO. 3 HYDRAULIC SYSTEMS - RELOCATION OF HYDRAULIC LINES IN THE WING AUXILIARY SPAR, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-022	MODIFICATION - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS - REPLACEMENT OF HEAT-EXCHANGER BYPASS-VALVES WITH NON EPDM RUBBER, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-023	MODIFICATION - QUICK DISCONNECTS - RELOCATE AND REPLACE HYDRAULIC HOSE IN BOTH PYLONS, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-024	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE BRACKET IN AFT EQUIPMENT BAY (SUPERSEDED BY SB 700-29-031 REV 04), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	27-May-11						152.5
	HRS		31.1						4070.2
	AFL		11						1214
SB 700-29-025	SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 185BL, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	26-Apr-12						141.5
	HRS		443.4						3657.9
	AFL		160						1065
SB 700-29-025 PART (A)	INSPECTION SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 185BL, SERVICE BULLETIN OF HYDRAULIC TUBES								Bulletin ATA:29
	MOS/MSC	-	26-Apr-12						141.5
	HRS		443.4						3657.9
	AFL		160						1065

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
SB 700-29-025 PART (B)	ADJUSTMENT SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 185BL, SERVICE BULLETIN OF HYDRAULIC TUBES LOCATION								Bulletin ATA:29
	MOS/MSC	-	26-Apr-12						141.5
	HRS		443.4						3657.9
	AFL		160						1065
SB 700-29-026	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF EDP V-BAND COUPLING CLAMP, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	03-Nov-11						147.3
	HRS		227.8						3873.5
	AFL		100						1125
SB 700-29-026 PART (A)	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF EDP V-BAND COUPLING CLAMP, SERVICE BULLETIN INSPECTION								Bulletin ATA:29
	MOS/MSC	-	03-Nov-11						147.3
	HRS		227.8						3873.5
	AFL		100						1125
SB 700-29-026 PART (B)	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF EDP V-BAND COUPLING CLAMP, SERVICE BULLETIN EDP V-BAND COUPLING CLAMP REPLACEMENT								Bulletin ATA:29
	MOS/MSC	-	03-Nov-11						147.3
	HRS		227.8						3873.5
	AFL		100						1125
SB 700-29-027	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - HYDRAULIC FIREWALL SHUT-OFF VALVES (HFSOV) INTRODUCTION OF IMPROVED ACTUATOR AS A SEPARATE LRU PART NO. 975237-501 (GX473-0126-1), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	27-Dec-13						121.5
	HRS		1176.4						2924.9
	AFL		464						761
SB 700-29-028	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-028 PART (A)	MODIFICATION MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN - MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO.								Bulletin ATA:29
	MOS		EFF					03-Oct-2035	
	HRS								
	AFL	T:3500	EFF		4021 *		2796		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 29 - HYDRAULIC POWER										
SB 700-29-028 PART (B)	MODIFICATION MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN - REMOVAL - INSTALLATION OF NEW ACCUMULATOR (FOR ALL ACCUMULATORS, PART NO. 900094 -5 NOT LISTED IN PART A AND WITHOUT "E" OR "ENA" SUFFIX)								Bulletin	ATA:29
	MOS		EFF					03-Oct-2035		
	HRS									
	AFL	T:3500	EFF		4021 *		2796			
SB 700-29-030	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - REPLACEMENT OF RAT ACCUMULATOR, PART NO. GX473-0100-5 WITH RAT ACCUMULATOR, PART NO. GX473-0100-7, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-	22-Jul-15						102.6	
	HRS		1712.9						2388.4	
	AFL		624						601	
SB 700-29-031	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-	11-Jul-17						79	
	HRS		2473.8						1627.5	
	AFL		817						408	
SB 700-29-031 REV 01	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-29-031 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION APPLICABLE TO AIRCRAFT ON WHICH BASIC ISSUE OF THIS SERVICE BULLETIN IS NOT INCORPORATED								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-29-031 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN RETROACTIVE ACTION OF THIS SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-29-031 REV 02	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
SB 700-29-031 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION APPLICABLE TO AIRCRAFT ON WHICH BASIC ISSUE OF THIS SERVICE BULLETIN IS NOT INCORPORATED								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-031 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN RETROACTIVE ACTION OF THIS SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-031 REV 03	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-29-031 REV 03 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION APPLICABLE TO AIRCRAFT ON WHICH BASIC ISSUE OF THIS SERVICE BULLETIN IS NOT INCORPORATED								Bulletin ATA:29
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-29-031 REV 03 PART B	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN RETROACTIVE ACTION OF THIS SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-29-031 REV 04	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-031 REV 04 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION APPLICABLE TO AIRCRAFT ON WHICH BASIC ISSUE OF THIS SERVICE BULLETIN IS NOT INCORPORATED								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 29 - HYDRAULIC POWER									
SB 700-29-031 REV 04 PART B	ACCOMPLISH, SERVICE BULLETIN RETROACTIVE ACTION OF THIS SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-031 REV 04 PART C	ACCOMPLISH, SERVICE BULLETIN INSPECTION IN PYLON								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-032	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE (SUPERSEDED BY 700-29-032 REV 01), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-032 REV 01	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE (SUPERSEDED BY 700-29-032 REV 02), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-29-032 REV 02	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE (SUPERSEDED BY 700-29-032 REV 03), SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-29-032 REV 03	MODIFICATION - NO. 2 HYDRAULIC SYSTEM - ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	AFL								
SB BR700-29-900512	NO. 1 ENGINE - HYDRAULIC POWER - LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING, SERVICE BULLETIN								Bulletin ATA:29
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 29 - HYDRAULIC POWER										
SB BR700-29-900512	NO. 2 ENGINE - HYDRAULIC POWER - LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-29-900512 R01	NO. 1 ENGINE - HYDRAULIC POWER - LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING - NON-MODIFICATION, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-29-900512 R01	NO. 2 ENGINE - HYDRAULIC POWER - LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING - NON-MODIFICATION, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	-								
	HRS									
	ENC									
TCCA CF-2010-10	HYDRAULIC SYSTEMS NUMBER 2 AND 3: DAMAGE CAUSED BY MAIN LANDING GEAR TIRE FAILURE								AD	ATA:29
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
ATA 30 - ICE AND RAIN PROTECTION										
30-11-01-900-801-01	LH MODULATING VALVE								Component	ATA:30
PN:GG436-4001-13	MOS/MSC	O/C	03-Aug-17						78.3	
SN:00493	HRS		2500.6						1600.7	
WC#: 30.025	AFL		835						390	
				PROC. REF: AMM 30 11 01 000 801, AMM 30 11 01 400 801						
30-11-01-900-801-02	RH MODULATING VALVE								Component	ATA:30
PN:GG436-4001-13	MOS/MSC	O/C	06-Aug-14						114.2	
SN:00831	HRS		1391.1						2710.2	
WC#: 30.025	AFL		537						688	
				PROC. REF: AMM 30 11 01 000 801, AMM 30 11 01 400 801						
30-11-05-900-801-01	LEFT SLAT NO. 4 TEMPERATURE SENSOR								Component	ATA:30
PN:GG436-4078-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1369	HRS		0	TSN 0					4101.3	
WC#: 30.030	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 30 - ICE AND RAIN PROTECTION										
30-11-05-900-801-02	RIGHT SLAT NO. 4 TEMPERATURE SENSOR								Component	ATA:30
PN:GG436-4078-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1374	HRS		0	TSN 0					4101.3	
WC#: 30.030	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801						
30-11-05-900-801-03	LH WAI TEMPERATURE SENSOR								Component	ATA:30
PN:GG436-4003-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1863	HRS		0	TSN 0					4101.3	
WC#: 30.035	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801						
30-11-05-900-801-04	RH WAI TEMPERATURE SENSOR								Component	ATA:30
PN:GG436-4003-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1884	HRS		0	TSN 0					4101.3	
WC#: 30.035	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801						
30-11-09-202[S]	OPERATIONAL TEST OF THE WING XBLEED SYSTEM								Service	ATA:30
	MOS		19-Mar-21						34.7	
	HRS	2000 (+50/-50)	3474.7						626.6	
WC#: 30.005	AFL		1069						156	
				PROC. REF: AMM 30 11 00 710 802						PKG:6
30-11-09-900-801-01	WAI ISOLATION VALVE								Component	ATA:30
PN:GG436-4004-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:01116	HRS		0	TSN 0					4101.3	
WC#: 30.040	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 11 09 000 801, AMM 30 11 09 400 801						
30-12-05-101	DISCARD THE LH SLAT NO. 1 WING ANTI-ICING TELESCOPIC-DUCT (LH), PARTNO. GG468-4022-3 (S/N 0001, 0002, 0023, 0029, 0044,0045, 0048 AND 0056)								Service	ATA:30
PN:GG468-4022-3	MOS/MSC	N/A	20-Dec-09						169.7	
SN:0424	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: AMM 30 12 05 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 30 - ICE AND RAIN PROTECTION									
30-12-05-102	DISCARD THE LH SLAT NO. 1 WING ANTI-ICING TELESCOPIC-DUCT (LH), PARTNO. GG468-4022-3 (SERIAL NUMBERS NOT COVERED BY TASK30-12-05-101*)								Service ATA:30
PN:GG468-4022-3	MOS		20-Dec-09					12-Apr-2044	169.7
SN:0424	HRS	15000	0		15000 (M)		10898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 30 12 05 961 801					
30-12-05-103	DISCARD THE NO. 1 WING ANTI-ICING TELESCOPIC-DUCT (RH), PARTNO. GG468-4022-4 (S/N 0001, 0002, 0003, 0031, 0038,0047, 0049, 0056, 0057, 0058 AND 0061)								Service ATA:30
PN:GG468-4022-4	MOS/MSC	N/A	20-Dec-09						169.7
SN:0332	HRS		0						4101.3
	AFL		0						1225
				PROC. REF: AMM 30 12 05 961 801					
30-12-05-104	DISCARD THE NO. 1 WING ANTI-ICING TELESCOPIC-DUCT (RH), PARTNO. GG468-4022-4 (SERIAL NUMBERS NOT COVERED BY TASK30-12-05-103*)								Service ATA:30
PN:GG468-4022-4	MOS		20-Dec-09					12-Apr-2044	169.7
SN:0332	HRS	15000	0		15000		10898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 30 12 05 961 801					
30-12-05-900-801-01	LH SLAT NO. 1 TELESCOPIC, A/I SUPPLY LH DUCT								Component ATA:30
PN:GG468-4022-3	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:0424	HRS		0	TSN 0					4101.3
WC#: 30.045	AFL		0	TSN 0					1225
				PROC. REF: AMM 30 12 05 000 801, AMM 30 12 05 400 801					
30-12-05-900-801-02	RH SLAT NO. 1 TELESCOPIC, A/I SUPPLY RH DUCT								Component ATA:30
PN:GG468-4022-4	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:0332	HRS		0	TSN 0					4101.3
WC#: 30.045	AFL		0	TSN 0					1225
				PROC. REF: AMM 30 12 05 000 801, AMM 30 12 05 400 801					
30-12-09-900-801-01	NO. 1 COUPLING COVER								Component ATA:30
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 30.050	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 30 - ICE AND RAIN PROTECTION									
30-12-09-900-801-02	NO. 2 COUPLING COVER								Component ATA:30
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 30.055	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
30-12-09-900-801-03	NO. 3 COUPLING COVER								Component ATA:30
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 30.060	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
30-12-09-900-801-04	NO. 4 COUPLING COVER								Component ATA:30
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 30.065	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
30-12-09-900-801-05	NO. 5 COUPLING COVER								Component ATA:30
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 30.070	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
30-12-09-900-801-06	ANTI-ICE SUPPLY CENTER WING TO FUSE FAIRING DUCT								Component ATA:30
PN:GG468-4033-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0329	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
30-12-13-101	DISCARD THE LH WING ANTI-ICING FLEXIBLE-JOINTS, PART NO.GG468-4025-1								Service ATA:30
PN:GG468-4025-1	MOS		20-Dec-09					12-Apr-2044	169.7
SN:0991	HRS	15000	0		15000		10898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 30 12 13 961 801					
30-12-13-101	DISCARD THE RH WING ANTI-ICING FLEXIBLE-JOINTS, PART NO.GG468-4025-1								Service ATA:30
PN:GG468-4025-1	MOS		20-Dec-09					12-Apr-2044	169.7
SN:1002	HRS	15000	0		15000		10898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 30 12 13 961 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 30 - ICE AND RAIN PROTECTION										
30-12-13-900-801-01	LH FLEXIBLE JOINT								Component	ATA:30
PN:GG468-4025-1	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:0991	HRS		0	TSN 0					4101.3	
WC#: 30.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 12 13 000 801, AMM 30 12 13 400 801						
30-12-13-900-801-02	RH FLEXIBLE JOINT								Component	ATA:30
PN:GG468-4025-1	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:1002	HRS		0	TSN 0					4101.3	
WC#: 30.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 12 13 000 801, AMM 30 12 13 400 801						
30-21-01-900-801-01	LH ENGINE NOSE COWL ANTI-ICE VALVE								Component	ATA:30
PN:510-0020-7	MOS/MSC	O/C	01-Feb-18						72.3	
SN:D1761B	HRS		2704.8						1396.5	
WC#: 30.080	AFL		883						342	
				PROC. REF: AMM 30 21 01 000 801, AMM 30 21 01 400 801						
30-21-01-900-801-02	RH ENGINE NOSE COWL ANTI-ICE VALVE								Component	ATA:30
PN:510-0020-7	MOS/MSC	O/C	12-Jul-18						67	
SN:D0806B	HRS		2892.3						1209	
WC#: 30.080	AFL		921						304	
				PROC. REF: AMM 30 21 01 000 801, AMM 30 21 01 400 801						
30-21-05-201	GENERAL VISUAL INSPECTION OF THE COWL ANTI-ICING-VALVE DUCTS								Service	ATA:30
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 30.010	AFL		690						535	
				PROC. REF: AMM 30 21 05 210 802						PKG:8
30-31-01-900-801-01	NO. 1 HEATER/BRAKE TEMPERATURE MONITOR								Component	ATA:30
PN:GH569-0017-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:987	HRS		0	TSN 0					4101.3	
WC#: 30.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 31 01 000 801, AMM 30 31 01 400 801						
30-31-01-900-801-02	NO. 2 HEATER/BRAKE TEMPERATURE MONITOR								Component	ATA:30
PN:GH569-0017-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0986	HRS		0	TSN 0					4101.3	
WC#: 30.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 31 01 000 801, AMM 30 31 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 30 - ICE AND RAIN PROTECTION										
30-41-00-202	FUNCTIONAL TEST OF THE WINDSHIELD RAIN-REPELLANT LAYER								Service	ATA:30
	MOS	12 (+10%/-10%)	28-Nov-23	Adj 1	31-Dec-24	03-Feb-25	324 d (+34)	31-Dec-2024	2.5	
	HRS	750 (+50/-50)	4099.1	Adj 50	4899.1	4949.1	797.8 (+50)		2.2	
WC#: 30.015	AFL		1223						2	
				PROC. REF: AMM 30 40 00 720 801						
30-41-00-301	DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL								Service	ATA:30
	MOS	15 (+3m/-3m)	28-Nov-23	Adj 3	31-May-25	31-Aug-25	475 d (+92)	31-May-2025	2.5	
	HRS	750 (+50/-50)	4099.1	Adj 50	4899.1	4949.1	797.8 (+50)		2.2	
	AFL		1223						2	
				PROC. REF: AMM 56 10 01 220 801						PKG:31
30-41-01-900-801-01	LH WINDSHIELD TEMPERATURE CONTROLLER								Component	ATA:30
PN:GC584-1001-4	MOS/MSC	O/C	17-Jun-11						151.8	
SN:993	HRS		43.3						4058	
WC#: 30.090	AFL		15						1210	
				PROC. REF: AMM 30 41 01 000 801, AMM 30 41 01 400 801						
30-41-01-900-801-02	RH WINDSHIELD TEMPERATURE CONTROLLER								Component	ATA:30
PN:GC584-1001-4	MOS/MSC	O/C	17-Jun-11						151.8	
SN:994	HRS		43.3						4058	
WC#: 30.090	AFL		15						1210	
				PROC. REF: AMM 30 41 01 000 801, AMM 30 41 01 400 801						
30-81-01-201[S]	OPERATIONAL TEST OF THE ICE DETECTORS								Service	ATA:30
	MOS		19-Mar-21						34.7	
	HRS	1500 (+50/-50)	3474.7						626.6	
WC#: 30.020	AFL		1069						156	
				PROC. REF: AMM 30 81 01 710 801						PKG:5
30-81-01-900-801-01	LH ICE DETECTOR								Component	ATA:30
PN:GG436-4006-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:20592	HRS		0	TSN 0					4101.3	
WC#: 30.095	AFL		0	TSN 0					1225	
				PROC. REF: AMM 30 81 01 000 801, AMM 30 81 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 30 - ICE AND RAIN PROTECTION										
30-81-01-900-801-02	RH ICE DETECTOR								Component	ATA:30
PN:GG436-4006-9	MOS/MSC	O/C	10-Aug-16	TSR 0					90	
SN:21464	HRS		2096	TSR 0					2005.3	
WC#: 30.095	AFL		727	TSR 0					498	
				PROC. REF: AMM 30 81 01 000 801, AMM 30 81 01 400 801						
FAA 2014-03-05	ICE AND RAIN PROTECTION - MODIFY THE AIR DATA PROBES AND SENSORS (SUPERSEDED BY FAA AD 2014-26-09)								AD	ATA:30
	MOS/MSC	-	18-Mar-14						118.8	
	HRS		1278.5						2822.8	
	AFL		496						729	
FAA 2014-26-09	ICE AND RAIN PROTECTION - MODIFY THE AIR DATA PROBES AND SENSORS								AD	ATA:30
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
FAA 2014-26-09 PARA (G)	MODIFY THE AIR DATA PROBES AND SENSORS (RETAINED MODIFICATION)								AD	ATA:30
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
FAA 2014-26-09 PARA (H)	MODIFY THE AIR DATA PROBES AND SENSORS (NEW MODIFICATION)								AD	ATA:30
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
SB 700-30-015	MODIFICATION - ANTI-ICING SYSTEM - DUCT SUPPORTS AT FS708.00 TO GIVE ADDED CLEARANCE TO THE BELLY FAIRING, SERVICE BULLETIN								Bulletin	ATA:30
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-30-016	MODIFICATION - AIR DATA PROBES AND SENSORS - HEATER/BRAKE TEMPERATURE MONITORING UNITS (HBMU) SOFTWARE UPGRADE (A/C 9005 TO 9024 AND 9026 TO 9045), SERVICE BULLETIN								Bulletin	ATA:30
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 30 - ICE AND RAIN PROTECTION									
SB 700-30-018	SPECIAL CHECK/MODIFICATION - WING ANTI-ICING SYSTEM - BOROSCOPIC INSPECTION OF LEADING EDGE SLAT TELESCOPIC WIRING ASSEMBLIES FOR POSSIBLE DAMAGE (SUPERSEDED BY SB 700-30-020), SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	N/R							
	HRS								
	AFL								
SB 700-30-020	MODIFICATION - WING ANTI-ICING SYSTEM - INTRODUCTION OF IMPROVED TELESCOPIC WIRING FOR THE LEADING EDGE AND SLAT (A/C 9002, 9004, TO 9126, AND 9128 TO 9160), SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-30-021	MODIFICATION – AIR DATA PROBES AND SENSORS – RECONFIGURATION OF RELAY TO HMBU TO REMOVE NUMBER 2 PITOT HEAT NUISANCE, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-30-021 REV 01	MODIFICATION - AIR DATA PROBES AND SENSORS - RECONFIGURATION OF RELAY TO HMBU TO REMOVE NUMBER 2 PITOT HEAT NUISANCE, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-	18-Mar-14						118.8
	HRS		1278.5						2822.8
	AFL		496						729
SB 700-30-022	SPECIAL CHECK/REWORK - WING ANTI-ICE (WAI) SYSTEM - CHECK SLAT-TO-SLAT DISTANCE AND SHIMS AT WAI FLEXIBLE JOINTS (EFFECTIVITY 9169 TO 9194), SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-30-023	MODIFICATION – WING ANTI-ICING SYSTEM – INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-30-023 PART (A)	MODIFICATION MODIFICATION – WING ANTI-ICING SYSTEM – INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR, SERVICE BULLETIN - LEFT WING								Bulletin ATA:30
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 30 - ICE AND RAIN PROTECTION									
SB 700-30-023 PART (B)	MODIFICATION MODIFICATION – WING ANTI-ICING SYSTEM – INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR, SERVICE BULLETIN - RIGHT WING								Bulletin ATA:30
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-30-023 REV 01	MODIFICATION - WING ANTI-ICING SYSTEM - INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-30-023 REV 01 PART (A)	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - LEFT WING								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-30-023 REV 01 PART (B)	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - RIGHT WING								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-30-024	SPECIAL CHECK/MODIFICATION - WINDSHIELD AND SIDE WINDOW ANTI-ICING SYSTEM - CHECK THE HEATER BRAIDED WIRE CONNECTION OF THE WINDSHIELD (A/C 9002 TO 9257), SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-30-025	SPECIAL CHECK/REWORK - WING ANTI-ICING (WAI) SYSTEM - INSPECT WAI DUCT BELLOWS FOR CHAFING WITH ELEVATOR CABLE (A/C 9002 TO 9126, 9128 TO 9235 AND 9237 TO 9244), SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-30-026	MODIFICATION - ANTI-ICING SYSTEM - PART NO. CHANGE OF THE WING ANTI-ICE VALVE (WAIV) TO GG436-4001-13, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-	06-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 30 - ICE AND RAIN PROTECTION									
SB BR700-30-101826	NO. 1 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE (EFF. EBU S/N E005 TO E560), SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-30-101826	NO. 2 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE (EFF. EBU S/N E005 TO E560), SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-30-101826 R01	NO. 1 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-30-101826 R01	NO. 2 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-30-101826 R02	NO. 1 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-30-101826 R02	NO. 2 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN								Bulletin ATA:30
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 30 - ICE AND RAIN PROTECTION										
VSB 789714-30-002[U]	WINDSHIELD TEMPERATURE CONTROLLER (WTC), VENDOR SERVICE BULLETIN								Bulletin	ATA:30
	MOS/MSC	-	17-Jun-11						151.8	
	HRS		43.3						4058	
	AFL		15						1210	
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-21-01-900-801-01	LH DIGITAL CLOCK								Component	ATA:31
PN:APE4190-030	MOS/MSC	O/C	29-Mar-12						142.4	
SN:586	HRS		427.7						3673.6	
WC#: 31.035	AFL		152						1073	
				PROC. REF: AMM 31 21 01 000 801, AMM 31 21 01 400 801						
31-21-01-900-801-02	RH DIGITAL CLOCK								Component	ATA:31
PN:APE4190-030	MOS/MSC	O/C	29-Mar-12	TSR 0					142.4	
SN:274	HRS		427.7	TSR 0					3673.6	
WC#: 31.035	AFL		152	TSR 0					1073	
				PROC. REF: AMM 31 21 01 000 801, AMM 31 21 01 400 801						
31-31-00-201[S]	OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (CONTROL COLUMN AND RUDDER PEDAL PARAMETERS) (A/C 9002, 9025 AND 9066 TO 9089 POST SB 700-31-014 AND A/C 9003, 9090 AND SUBS)								Service	ATA:31
	MOS									
	HRS	4500 (+50/-50)	0						4101.3	
WC#: 31.005	AFL									
				PROC. REF: AMM 31 31 00 710 802						PKG:10
31-31-00-203	FUNCTIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) FORCE SENSORS (POST SB 700-31-020)								Service	ATA:31
	MOS/MSC	N/A								
	HRS									
	AFL									
				PROC. REF: AMM 31 31 00 720 801						
31-31-01-900-801-01	(FDR) FLIGHT DATA RECORDER								Component	ATA:31
PN:980-4700-041	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:SSFDR-17525	HRS		0	TSN 0					4101.3	
WC#: 31.040	AFL		0	TSN 0					1225	
				PROC. REF: AMM 31 31 01 000 801, AMM 31 31 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-31-05-900-801-01	ACCELEROMETER								Component	ATA:31
PN:971-4193-001	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:12626	HRS		0	TSN 0					4101.3	
WC#: 31.045	AFL		0	TSN 0					1225	
			PROC. REF: AMM 31 31 05 000 801, AMM 31 31 05 400 801							
31-31-09-201	OPERATIONAL TEST FDR (ULB) UNDERWATER LOCATOR BEACON (31-31-09-201)								Service	ATA:31
PN:DK120/90	MOS	30 (+3m/-3m)	30-Dec-22	Adj 3	30-Sep-25	31-Dec-25	597 d (+92)	30-Sep-2025	13.4	
SN:AT115214	HRS		3913.7						187.6	
	AFL		1171						54	
			PROC. REF: AMM 31 31 09 710 802							PKG:32
31-31-09-202	DISCARD FDR (ULB) UNDERWATER LOCATOR BEACON BATTERY (31-31-09-202)								Service	ATA:31
PN:DK120/90	MOS/MSC	DUE	12-Jul-18		01-Jul-25 (M)		506 d	01-Jul-2025	67	
SN:AT115214	HRS		2892.3						1209	
WC#: 31.050	AFL		921						304	
			PROC. REF: AMM 31 31 09 961 801							
31-31-09-900-801-01	FDR (ULB) UNDERWATER LOCATOR BEACON								Component	ATA:31
PN:DK120/90	MOS/MSC	O/C	12-Jul-18	TSN 2					67	
SN:AT115214	HRS		2892.3	TSN 0					1209	
WC#: 31.050	AFL		921	TSN 0					304	
			PROC. REF: AMM 31 31 09 000 801, AMM 31 31 09 400 801							
31-33-00-301	DOWNLOAD OF THE QUICK ACCESS RECORDER (POST SB 700-31-026)								Service	ATA:31
	MOS/MSC	N/A	20-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
			PROC. REF: AMM 31 33 00 970 801							
31-41-00-301[S]	DISCARD NO. 1 IAC BATTERY								Service	ATA:31
PN:7014664-902	MOS	15 (+3m/-3m)	14-Dec-23						1.9	
SN:NA	HRS		4099.1						2.2	
	AFL		1223						2	
			PROC. REF: AMM 31 41 01 961 801							PKG:31
31-41-00-301[S]	DISCARD NO. 2 IAC BATTERY								Service	ATA:31
PN:7014664-902	MOS	15 (+3m/-3m)	14-Dec-23						1.9	
SN:NA	HRS		4099.1						2.2	
	AFL		1223						2	
			PROC. REF: AMM 31 41 01 961 801							PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-41-00-301[S]	DISCARD NO. 3 IAC BATTERY								Service	ATA:31
PN:7014664-902	MOS	15 (+3m/-3m)	14-Dec-23						1.9	
SN:NA	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 31 41 01 961 801						PKG:31
31-41-01-900-801-01	NO.1 INTEGRATED AVIONICS COMPUTER								Component	ATA:31
PN:7017300-61014	MOS/MSC	O/C	21-Jun-21						31.7	
SN:090111839	HRS		3606						495.3	
WC#: 31.055	AFL		1100						125	
				PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801						
31-41-01-900-801-02	NO.2 INTEGRATED AVIONICS COMPUTER								Component	ATA:31
PN:7017300-61014	MOS/MSC	O/C	30-Dec-22						13.4	
SN:01040851	HRS		3913.7						187.6	
WC#: 31.055	AFL		1171						54	
				PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801						
31-41-01-900-801-03	NO.3 INTEGRATED AVIONICS COMPUTER								Component	ATA:31
PN:7017300-61014	MOS/MSC	O/C	24-Jan-23	TSR 0					12.6	
SN:07073658	HRS		3915.7	TSR 0					185.6	
WC#: 31.055	AFL			TSR 0						
				PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801						
31-41-01-900-802-01	NO. 1 IAC BATTERY								Component	ATA:31
PN:7014664-902	MOS/MSC	H/T	14-Dec-23	TSN 12					1.9	
SN:NA	HRS		4099.1	TSN 185.4					2.2	
	AFL		1223	TSN 52					2	
				PROC. REF: GENERIC NO REF						
31-41-01-900-802-02	NO. 2 IAC BATTERY								Component	ATA:31
PN:7014664-902	MOS/MSC	H/T	14-Dec-23	TSN 12					1.9	
SN:NA	HRS		4099.1	TSN 185.4					2.2	
	AFL		1223	TSN 52					2	
				PROC. REF: GENERIC NO REF						
31-41-01-900-802-03	NO. 3 IAC BATTERY								Component	ATA:31
PN:7014664-902	MOS/MSC	H/T	14-Dec-23	TSN 12					1.9	
SN:NA	HRS		4099.1	TSN 185.4					2.2	
	AFL		1223	TSN 52					2	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-41-05-900-801-01	NO. 1 CONFIGURATION IAC MODULE								Component ATA:31
PN:7014940-902	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:09047983	HRS		0	TSN 0					4101.3
WC#: 31.060	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801					
31-41-05-900-801-02	NO. 2 CONFIGURATION IAC MODULE								Component ATA:31
PN:7014940-902	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:09047972	HRS		0	TSN 0					4101.3
WC#: 31.060	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801					
31-41-05-900-801-03	NO. 3 CONFIGURATION IAC MODULE								Component ATA:31
PN:7014940-902	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:09047982	HRS		0	TSN 0					4101.3
WC#: 31.060	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801					
31-42-01-900-801-01	NO. 1 DATA ACQUISITION (DAU) UNIT								Component ATA:31
PN:10604303M09	MOS/MSC	O/C	27-Jul-16						90.5
SN:01121059	HRS		2078.9						2022.4
WC#: 31.065	AFL		719						506
				PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801					
31-42-01-900-801-02	NO. 2 DATA ACQUISITION (DAU) UNIT								Component ATA:31
PN:10604B03M09	MOS/MSC	O/C	21-Jun-21	TSN 138					31.7
SN:09092104	HRS		3606	TSN 3606, TSR 3606					495.3
WC#: 31.065	AFL		1100	TSN 1100, TSR 1100					125
				PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801					
31-42-01-900-801-03	NO. 3 DATA ACQUISITION (DAU) UNIT								Component ATA:31
PN:10604B03M09	MOS/MSC	O/C	29-Oct-15	TSN 70					99.4
SN:09092105	HRS		1817.7	TSN 1817.7, TSR 1817.7					2283.6
WC#: 31.065	AFL		660	TSN 660, TSR 660					565
				PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-42-01-900-801-04	NO. 4 DATA ACQUISITION (DAU) UNIT								Component	ATA:31
PN:10604B03M09	MOS/MSC	O/C	21-Jun-21	TSN 138					31.7	
SN:09092103	HRS		3606	TSN 3606					495.3	
WC#: 31.065	AFL		1100	TSN 1100					125	
				PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801						
31-43-01-900-801-01	FWD POWER LAMP DRIVER								Component	ATA:31
PN:LT45D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2353	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
31-43-01-900-801-02	AFT POWER LAMP DRIVER								Component	ATA:31
PN:LT45D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2389	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
31-43-01-900-801-03	R/H POWER LAMP DRIVER								Component	ATA:31
PN:LT45D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:2341	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
31-44-01-900-801-01	LH ISOLATION COUPLER								Component	ATA:31
PN:5008500-002	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:14913	HRS		0	TSN 0					4101.3	
WC#: 31.070	AFL		0	TSN 0					1225	
				PROC. REF: AMM 31 44 01 000 801, AMM 31 44 01 400 801						
31-44-01-900-801-02	RH ISOLATION COUPLER								Component	ATA:31
PN:5008500-002	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:15099	HRS		0	TSN 0					4101.3	
WC#: 31.070	AFL		0	TSN 0					1225	
				PROC. REF: AMM 31 44 01 000 801, AMM 31 44 01 400 801						
31-61-00-201[S]	OPERATIONAL TEST OF THE EICAS DISPLAY REVERSION								Service	ATA:31
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 31.015	AFL		1171						54	
				PROC. REF: AMM 31 61 00 710 803						PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-61-00-202[S]	OPERATIONAL TEST OF THE PRIMARY FLIGHT DISPLAY REVERSION								Service	ATA:31
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 31.020	AFL		1171						54	
				PROC. REF: AMM 31 61 00 710 802						PKG:32
31-61-00-203[S]	OPERATIONAL TEST OF THE IRS REVERSION								Service	ATA:31
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 31.025	AFL		1171						54	
				PROC. REF: AMM 31 61 00 710 805						PKG:32
31-61-00-204[S]	OPERATIONAL TEST OF THE ADC REVERSION								Service	ATA:31
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 31.030	AFL		1171						54	
				PROC. REF: AMM 31 61 00 710 806						PKG:32
31-61-01-900-801-01	PILOT PFD DISPLAY UNIT								Component	ATA:31
PN:7014300-901	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0905J160	HRS		0	TSN 0					4101.3	
WC#: 31.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801						
31-61-01-900-801-02	PILOT MFD DISPLAY UNIT								Component	ATA:31
PN:7014300-901	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0905J161	HRS		0	TSN 0					4101.3	
WC#: 31.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801						
31-61-01-900-801-03	PILOT EICAS DISPLAY UNIT								Component	ATA:31
PN:7014300-901	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0905J162	HRS		0	TSN 0					4101.3	
WC#: 31.075	AFL		0	TSN 0					1225	
				PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801						
31-61-01-900-801-04	COPILOT EICAS DISPLAY UNIT								Component	ATA:31
PN:7014300-901	MOS/MSC	O/C	06-Jun-22	TSN 150					20.2	
SN:0905J165	HRS		3781.1	TSN 3781.1					320.2	
WC#: 31.080	AFL		1141	TSN 1141					84	
				PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
31-61-01-900-801-05	COPILOT MFD DISPLAY UNIT								Component ATA:31
PN:7014300-901	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0905J164	HRS		0	TSN 0					4101.3
WC#: 31.080	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801					
31-61-01-900-801-06	COPILOT PFD DISPLAY UNIT								Component ATA:31
PN:7014300-901	MOS/MSC	O/C	06-Jun-22	TSR 100					20.2
SN:0703G211	HRS		3781.1	TSR 3781.1					320.2
WC#: 31.080	AFL		1141	TSR 1141					84
				PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801					
31-61-05-900-801-01	LH PANEL- PFD CONTROLLER CONTROL								Component ATA:31
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 31.085	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 61 05 000 801, AMM 31 61 05 400 801					
31-61-05-900-801-02	RH PANEL- PFD CONTROLLER CONTROL								Component ATA:31
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 31.085	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 61 05 000 801, AMM 31 61 05 400 801					
31-61-09-900-801-01	LH MFD CONTROLLER								Component ATA:31
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 31.090	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 61 09 000 801, AMM 31 61 09 400 801					
31-61-09-900-801-02	RH MFD CONTROLLER								Component ATA:31
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 31.090	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 61 09 000 801, AMM 31 61 09 400 801					
31-61-13-900-801-01	EICAS (EC-900) CONTROLLER								Component ATA:31
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 31.095	AFL		0	TSN 0					1225
				PROC. REF: AMM 31 61 13 000 801, AMM 31 61 13 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-61-17-900-801-01	PANEL - REVERSION CONTROLLER CONTROL								Component	ATA:31
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 31.100	AFL		0	TSN 0					1225	
				PROC. REF: AMM 31 61 17 000 801, AMM 31 61 17 400 801						
ASB A700-31-029 PART (A)	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1(A/C 9002 TO 9126, 9128 TO 9151 AND 9153 TO 9999), ALERT SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-31-029 PART (B)	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1 (A/C 9002 TO 9137, 9139 TO 9150 AND 9153 TO 9999), ALERT SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-31-029 REV 01 PART (A)	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1(9002 TO 9126, 9128 TO 9151 AND 9153 TO 9173), ALERT SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-31-029 REV 01 PART (B)	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1(9002 TO 9137, 9139 TO 9150, 9153 TO 9173), ALERT SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS								AD	ATA:31
	MOS/MSC	-	17-Jan-22						24.8	
	HRS		3689.6						411.7	
	AFL		1117						108	
Category: APPLIANCE										
FAA 2023-10-02	INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION								AD	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE- 2023 - SATISFIED BY FAA 2021-23-12)								AD	ATA:31
	MOS/MSC	-	01-Jun-23						8.3	
	HRS		3974.2						127.1	
	AFL		1183						42	
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)								AD	ATA:31
	MOS/MSC	-	29-Jun-23						7.4	
	HRS		4002.9						98.4	
	AFL		1192						33	
SB 700-31-009	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - INTRODUCTION OF NEW UNITS FOR FULL FUNCTIONALITY CERTIFICATION, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-31-010	MODIFICATION - INDICATING/RECORDING SYSTEM - DATA ACQUISITION UNITS (DAU) - REPLACEMENT FOR FULL FUNCTIONALITY CERTIFICATION, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-31-012	MODIFICATION - CLOCK SYSTEM - INTRODUCTION OF TWO DIGITAL CLOCKS USING GPS INPUT FOR TIME SETTING, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-31-012 REV 01	MODIFICATION - CLOCK SYSTEM - INTRODUCTION OF TWO DIGITAL CLOCKS USING GPS INPUT FOR TIME SETTING, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-31-013	MODIFICATION - IAC/DAU - SOFTWARE UPDATE FOR POST FULL FUNCTIONALITY CERTIFICATION, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
SB 700-31-014	MODIFICATION) FLIGHT DATA RECORDING-SYSTEM) INSTALLATION OF ROTARY VARIABLE DIFFERENTIAL TRANSFORMERS (RVDT) TO RECORD THE CONTROL COLUMNS AND RUDDER PEDALS POSITIONS, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-014 REV 01	MODIFICATION) FLIGHT DATA RECORDING-SYSTEM) INSTALLATION OF ROTARY VARIABLE DIFFERENTIAL TRANSFORMERS (RVDT) TO RECORD THE CONTROL COLUMNS AND RUDDER PEDALS POSITIONS (SERIAL NO. 9002, 9025, 9066 TO 9089), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-015	SPECIAL CHECK/MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) - POSSIBLE CRACKS ON MOUNTING TRAY, MODEL NO. MT-854, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-016	MODIFICATION - DATA ACQUISITION SYSTEM - DATA ACQUISITION UNIT (DAU) SOFTWARE UPGRADE TO P/N 10604B03M09 (EFFECTIVITY 9002 TO 9106 AND 9108 TO 9117), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-017	MODIFICATION - CENTRAL WARNING SYSTEM - INSTALLATION OF AUDIO PANELS WITH LOWER AURAL WARNING AUDIO SETTINGS, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-018	MODIFICATION - INTEGRATED AVIONICS COMPUTERS (IAC) - AVIONICS 2001 BATCH 1 IAC UPGRADE, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-018 REV 01	MODIFICATION - INTEGRATED AVIONICS COMPUTERS (IAC) - AVIONICS 2001 BATCH 1 IAC UPGRADE, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
SB 700-31-019 PART (A)	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - PROVISIONS FOR THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-019 PART (B)	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - PROVISIONS FOR THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-020 PART (A)	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9107 AND 9119 TO 9147) (SUPERSEDED BY 700-31-020 REV 01), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-020 PART (B)	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9119 TO 9999) (SUPERSEDED BY 700-31-020 REV 01), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-020 REV 01 PART (A)	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9107 AND 9119 TO 9147) (SUPERSEDED BY 700-31-020 REV 02), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-31-020 REV 01 PART (B)	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9119 TO 9999) (SUPERSEDED BY 700-31-020 REV 02), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
SB 700-31-020 REV 02	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-020 REV 02 PART (A)	MODIFICATION MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN - REPLACEMENT OF THE FDR AND THE DAU 1, 2, 3 AND 4								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-020 REV 02 PART (B)	MODIFICATION MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN - INSTALLATION OF THE FTUS AND ACTIVATION OF THE CFMS								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-020 REV 03	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-020 REV 03 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF THE FDR AND THE DAU 1, 2, 3 AND 4								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-020 REV 03 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INSTALLATION OF THE FTUS AND ACTIVATION OF THE CFMS								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-021	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 2 IAC UPGRADE (A/C 9002 TO 9153), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
SB 700-31-021 REV 01	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 2 IAC UPGRADE (A/C 9002 TO 9153), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-022	MODIFICATION - DATA ACQUISITION SYSTEM - DATA ACQUISITION UNIT (DAU) UPGRADE TO PART NO. 10604B03M09. EFFECTIVITY S/N 9118 TO 9126 AND 9128 TO 9158, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-023	MODIFICATION - WARNING/CAUTION CONTROL SYSTEM - REDUCTION OF AURAL WARINING OUTPUTS (9002 TO 9208), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-31-024	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - RETERMINATE EGPWS STRAPPING TO GIVE PRIORITY TO IACS "MINIMUMS, MINIMUMS" AURAL CALLOUT, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-025	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 2+ IAC UPGRADE (A/C 9002 TO 9174), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-025 REV 01	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 2+ IAC UPGRADE (A/C 9002 TO 9174), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-026	MODIFICATION - FLIGHT DATA RECORDING-SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER (SUPERSEDED BY 700-31-026 REV 01), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
SB 700-31-026 REV 01	MODIFICATION - FLIGHT DATA RECORDING-SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER (SUPERSEDED BY 700-31-026 REV 02), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-31-026 REV 02	MODIFICATION - FLIGHT DATA RECORDING-SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER (ON HOLD), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-31-027	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - DISPLAY OF METRIC UNITS INSTEAD OF IMPERIAL UNITS, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-027 REV 01	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - DISPLAY OF METRIC UNITS INSTEAD OF IMPERIAL UNITS, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-028	MODIFICATION - INTEGRATED AVIONIC COMPUTER (IAC) SYSTEM - EXAMINE IACS FOR POSSIBLE DEFECTIVE SRAM DEVICES, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-31-030	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-030 REV 01	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
SB 700-31-030 REV 02	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-	06-Aug-14						114.2	
	HRS		1391.1						2710.2	
	AFL		537						688	
SB 700-31-030 REV 03	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-31-030 REV 04	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-31-030 REV 05	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-31-031	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - IAC -009 SOFTWARE UPGRADE (A/C 9128 TO 9174 POST SB 700-31-025 AND 9175 TO 9244), SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-31-034	MODIFICATION - CENTRAL PROCESSING SYSTEM - BATCH 3.3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-	16-Aug-16						89.8	
	HRS		2096						2005.3	
	AFL		727						498	
SB 700-31-034 REV 01	MODIFICATION - CENTRAL PROCESSING SYSTEM - BATCH 3.3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-31-034 REV 02	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.3 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
SB 700-31-038 REV 01	MODIFICATION - ELECTRONIC FLIGHT-INSTRUMENT SYSTEM (EFIS) - INSTALLATION OF SYNTHETIC VISION WITH THE PRIMUS ELITE DU-875AF, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN SVS UPGRADE FOR AIRCRAFT WITH MFD DATA LOADER (BAS67010045-1)								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN SVS UPGRADE FOR AIRCRAFT WITH DL-1000 DATA LOADER (BAS67010045-2)								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN SVS FULL INSTALLATION FOR AIRCRAFT WITH DU-870 INSTALLED								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 02	MODIFICATION - ELECTRONIC FLIGHT-INSTRUMENT SYSTEM (EFIS) - INSTALLATION OF SYNTHETIC VISION WITH THE PRIMUS ELITE DU-875AF, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN SVS UPGRADE FOR AIRCRAFT WITH MFD DATA LOADER (BAS67010045-1)								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN SVS UPGRADE FOR AIRCRAFT WITH DL-1000 DATA LOADER (BAS67010045-2)								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 31 - INDICATING/RECORDING SYSTEMS									
SB 700-31-038 REV 02 PART C	ACCOMPLISH, SERVICE BULLETIN SVS FULL INSTALLATION FOR AIRCRAFT WITH DU-870 INSTALLED								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 03	MODIFICATION - ELECTRONIC FLIGHT-INSTRUMENT SYSTEM (EFIS) - INSTALLATION OF SYNTHETIC VISION WITH THE PRIMUS ELITE DU-875AF (LEARJET INC. STC), SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 03 PART A	ACCOMPLISH, SERVICE BULLETIN SVS UPGRADE FOR AIRCRAFT WITH MFD DATA LOADER (BAS67010045-1)								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 03 PART B	ACCOMPLISH, SERVICE BULLETIN SVS UPGRADE FOR AIRCRAFT WITH DL-1000 DATA LOADER (BAS67010045-2)								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-038 REV 03 PART C	ACCOMPLISH, SERVICE BULLETIN SVS FULL INSTALLATION FOR AIRCRAFT WITH DU-870 INSTALLED								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-31-039	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-31-039 REV 01	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin ATA:31
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 31 - INDICATING/RECORDING SYSTEMS										
SB 700-31-039 REV 02	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-31-039 REV 03	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE (BOMBARDIER INC. STC), SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-31-039 REV 04	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE (LEARJET INC. STC), SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-31-040	MODIFICATION - FLIGHT DATA RECORDING SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER, SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-								
	HRS									
	AFL									
VSB 980-4700-31-22[U]	HONEYWELL - INDICATING/RECORDING SYSTEMS - SOLID STATE FLIGHT DATA RECORDER (SSFDR) - MODIFICATION (MOD) 20 TO THE SSFDR PN 980-4700-001, -003, -009, -011, -017-019, -025, -027, -033, -034, -035, -041 AND -042, VENDOR SERVICE BULLETIN								Bulletin	ATA:31
	MOS/MSC	-	12-Jul-18						67	
	HRS		2892.3						1209	
	AFL		921						304	
ATA 32 - LANDING GEAR										
32-10-00-201[S]	RESTORATION LH MLG ASSEMBLY GEAR								Service	ATA:32
PN:GW318-1001-5	MOS	240 (+3m/-3m)	30-Jun-11						151.4	
SN:09MDT0701	HRS									
WC#: 32.280	AFL									
				PROC. REF: AMM 32 11 00 615 801						PKG:56
32-10-00-201[S]	RESTORATION RH MLG ASSEMBLY GEAR								Service	ATA:32
PN:GW318-1001-6	MOS	240 (+3m/-3m)	30-Jun-11						151.4	
SN:09MDT0700	HRS									
WC#: 32.285	AFL									
				PROC. REF: AMM 32 11 00 615 801						PKG:56

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-10-00-202 S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PIN								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.005	AFL		1069						156	
				PROC. REF: AMM 32 10 00 220 802						PKG:38
32-10-00-203 S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.010	AFL		1069						156	
				PROC. REF: AMM 32 10 00 220 803						PKG:38
32-10-00-204 S	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK-STRUT ASSEMBLY (INTERNAL)								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.015	AFL									
				PROC. REF: AMM 32 11 01 280 801						PKG:56
32-10-00-206 S	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PINS								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.020	AFL									
				PROC. REF: AMM 32 10 00 280 802						PKG:56
32-10-00-207 S	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.025	AFL									
				PROC. REF: AMM 32 10 00 280 803						PKG:56
32-10-00-208 S	DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.030	AFL		1069						156	
				PROC. REF: AMM 32 10 00 220 805						PKG:38
32-10-00-209 S	SPECIAL DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.035	AFL									
				PROC. REF: AMM 32 10 00 280 804						PKG:56

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-10-00-210[S]	DETAILED INSPECTION OF THE SHOCK STRUT ASSEMBLY (INTERNAL)								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.040	AFL		1069						156	
				PROC. REF: AMM 32 11 01 220 804						PKG:38
32-10-00-211[S]	DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.045	AFL		1069						156	
				PROC. REF: AMM 32 11 17 220 801						PKG:38
32-10-00-212[S]	SPECIAL DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.050	AFL									
				PROC. REF: AMM 32 11 17 280 801						PKG:56
32-10-00-213[S]	DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.055	AFL		1069						156	
				PROC. REF: AMM 32 32 01 220 801						PKG:38
32-10-00-214[S]	SPECIAL DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.060	AFL									
				PROC. REF: AMM 32 32 01 280 801						PKG:56
32-11-00-201[S]	LUBRICATION OF THE MAIN LANDING GEAR (MLG) AND COMPONENTS								Service	ATA:32
	MOS		28-Nov-23						2.5	
	HRS	250 (+10%/-10%)	4099.1						2.2	
WC#: 32.065	AFL		1223						2	
				PROC. REF: AMM 12 22 00 640 802						PKG:63
32-11-00-900-801-01	LH MLG PINTLE PIN								Component	ATA:32
PN:21112-101	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:08EXC1727	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.270	AFL		1069	TSN 1069					156	
				PROC. REF: AMM 32 11 00 000 801, AMM 32 11 00 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-11-00-900-801-02	RH MLG PINTLE PIN								Component	ATA:32
PN:21112-102	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:08EXC1740	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.270	AFL		1069	TSN 1069					156	
				PROC. REF: AMM 32 11 00 000 801, AMM 32 11 00 400 801						
32-11-00-900-801-03	LH CROSS PINTLE PIN								Component	ATA:32
PN:21116-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:08EXC0894	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.275	AFL		1069	TSN 1069					156	
				PROC. REF: AMM 32 11 00 000 801, AMM 32 11 00 400 801						
32-11-00-900-801-04	RH CROSS PINTLE PIN								Component	ATA:32
PN:21116-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:08EXC0892	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.275	AFL		1069	TSN 1069					156	
				PROC. REF: AMM 32 11 00 000 801, AMM 32 11 00 400 801						
32-11-00-900-803-01	LH MLG ASSEMBLY GEAR								Component	ATA:32
PN:GW318-1001-5	MOS/MSC	O/C	19-Mar-21	TSN 135, TSR 1					34.7	
SN:09MDT0701	HRS		3474.7	TSN 3474.7, TSR 0					626.6	
WC#: 32.280	AFL		1069	TSN 1069, TSR 0					156	
				PROC. REF: CMM 32-10-11, AMM 32 11 00 000 801, AMM 32 11 00 400 801						
32-11-00-900-803-02	RH MLG ASSEMBLY GEAR								Component	ATA:32
PN:GW318-1001-6	MOS/MSC	O/C	19-Mar-21	TSN 135, TSR 1					34.7	
SN:09MDT0700	HRS		3474.7	TSN 3474.7, TSR 0					626.6	
WC#: 32.285	AFL		1069	TSN 1069, TSR 0					156	
				PROC. REF: CMM 32-10-11, AMM 32 11 00 000 801, AMM 32 11 00 400 801						
32-11-01-101	DISCARD THE LH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21115								Service	ATA:32
PN:21194-1	MOS/MSC	N/A	20-Dec-09						169.7	
SN:08EXC1001	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: GENERIC NO REF						
32-11-01-101	DISCARD THE RH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21115								Service	ATA:32
PN:21194-1	MOS/MSC	N/A	20-Dec-09						169.7	
SN:08EXC0999	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-11-01-102	DISCARD THE LH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/MAIN FITTING PIN, PART NO. 21260 AND 21274-1								Service ATA:32
PN:21274-1	MOS		20-Dec-09					20-Jun-2081	169.7
SN:07CPS0695	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 01 961 802					
32-11-01-102	DISCARD THE RH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/MAIN FITTING PIN, PART NO. 21260 AND 21274-1								Service ATA:32
PN:21274-1	MOS		20-Dec-09					20-Jun-2081	169.7
SN:07CPS0705	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 01 961 802					
32-11-01-103	DISCARD THE LH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER, PART NO. 21206 AND 21209								Service ATA:32
PN:PN	MOS		20-Dec-09					20-Jun-2081	169.7
SN:UNKNOWN	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 01 961 803					
32-11-01-103	DISCARD THE RH MAIN LANDING GEAR (MLG) SHOCK STRUTCYLINDER, PART NO. 21206 AND 21209								Service ATA:32
PN:PN	MOS		20-Dec-09					20-Jun-2081	169.7
SN:UNKNOWN	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 01 961 803					
32-11-01-104	DISCARD THE LH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON,PART NO. 21216 AND 21218								Service ATA:32
PN:21218-5	MOS		20-Dec-09					20-Jun-2081	169.7
SN:08GGC00146	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 01 961 804					
32-11-01-104	DISCARD THE RH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON,PART NO. 21216 AND 21218								Service ATA:32
PN:21218-5	MOS		20-Dec-09					20-Jun-2081	169.7
SN:08GGC00147	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 01 961 804					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-11-01-105	DISCARD THE LH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21194-1								Service	ATA:32
PN:21194-1	MOS		20-Dec-09					22-Oct-2064	169.7	
SN:08EXC1001	HRS		0						4101.3	
	AFL	10999	0		10999		9774		1225	
				PROC. REF: AMM 32 11 01 961 801						
32-11-01-105	DISCARD THE RH MAIN LANDING GEAR (MLG) CONNECTING SHOCKSTRUT/TRAILING ARM PIN, PART NO. 21194-1								Service	ATA:32
PN:21194-1	MOS		20-Dec-09					22-Oct-2064	169.7	
SN:08EXC0999	HRS		0						4101.3	
	AFL	10999	0		10999		9774		1225	
				PROC. REF: AMM 32 11 01 961 801						
32-11-01-201 S	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT EXTENSION								Service	ATA:32
	MOS		28-Nov-23						2.5	
	HRS	500 (+50/-50)	4099.1						2.2	
WC#: 32.070	AFL		1223						2	
				PROC. REF: AMM 32 11 01 220 801						PKG:2
32-11-01-900-801-01	LEFT HAND MLG SHOCK STRUT ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.295	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-11-01-900-801-02	RIGHT HAND MLG SHOCK STRUT ASSEMBLY								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.295	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-11-01-900-802-01	LH MLG SHOCK STRUT								Component	ATA:32
PN:21200-113	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09MDT0939	HRS		0	TSN 0					4101.3	
WC#: 32.290	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801						
32-11-01-900-802-02	RH MLG SHOCK STRUT								Component	ATA:32
PN:21200-113	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09MDT0940	HRS		0	TSN 0					4101.3	
WC#: 32.290	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-11-01-900-803-01	LH MLG TRAILING ARM / SHOCK STRUT PIN								Component ATA:32
PN:21194-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08EXC1001	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.300	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-01-900-803-02	RH MLG TRAILING ARM / SHOCK STRUT PIN								Component ATA:32
PN:21194-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08EXC0999	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.300	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801					
32-11-01-900-804-01	LH MLG UPPER PIN								Component ATA:32
PN:21274-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:07CPS0695	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.305	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801					
32-11-01-900-804-02	RH MLG UPPER PIN								Component ATA:32
PN:21274-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:07CPS0705	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.305	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801					
32-11-01-900-805-01	LH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON								Component ATA:32
PN:21218-5	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08GGC00146	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-01-900-805-02	RH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON								Component ATA:32
PN:21218-5	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08GGC00147	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-01-900-806-01	LH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER								Component ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-11-01-900-806-02	RH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER								Component	ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-11-01-900-807-01	LH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON ASSY								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-11-01-900-807-02	RH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON ASSY								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-11-01-900-808-01	LH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER ASSY								Component	ATA:32
PN:21208-109	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7	
SN:19VAC0044	HRS		3474.7	TSN 0					626.6	
	AFL		1069	TSN 0					156	
				PROC. REF: GENERIC NO REF						
32-11-01-900-808-02	RH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER ASSY								Component	ATA:32
PN:21208-109	MOS/MSC	O/C	19-Mar-21	TSN 135					34.7	
SN:08GGC00148	HRS		3474.7	TSN 3474.7					626.6	
	AFL		1069	TSN 1069					156	
				PROC. REF: GENERIC NO REF						
32-11-09-101	DISCARD THE LEFT HAND MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE,PART NO. 21410								Service	ATA:32
PN:21410-105	MOS		20-Dec-09					20-Jun-2081	169.7	
SN:H0719	HRS		0						4101.3	
	AFL	15000	0		15000		13775		1225	
				PROC. REF: AMM 32 11 09 961 801						
32-11-09-101	DISCARD THE RIGHT HAND MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE,PART NO. 21410								Service	ATA:32
PN:21410-105	MOS		20-Dec-09					20-Jun-2081	169.7	
SN:H0715	HRS		0						4101.3	
	AFL	15000	0		15000		13775		1225	
				PROC. REF: AMM 32 11 09 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-11-09-102	DISCARD THE LH MAIN LANDING GEAR (MLG) PIVOT PIN, PART NO.21114								Service ATA:32
PN:21114-1	MOS		20-Dec-09					20-Jun-2081	169.7
SN:08EXC1716	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 09 961 802					
32-11-09-102	DISCARD THE RH MAIN LANDING GEAR (MLG) PIVOT PIN, PART NO.21114								Service ATA:32
PN:21114-1	MOS		20-Dec-09					20-Jun-2081	169.7
SN:08EXC1698	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 09 961 802					
32-11-09-900-801-01	LEFT HAND MLG TRAILING ARM ASSEMBLY								Component ATA:32
PN:21410-105	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:H0719	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.310	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801					
32-11-09-900-801-02	RIGHT HAND MLG TRAILING ARM ASSEMBLY								Component ATA:32
PN:21410-105	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:H0715	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.310	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801					
32-11-09-900-801-03	LH MLG HINGE PIN								Component ATA:32
PN:21114-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08EXC1716	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.315	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801					
32-11-09-900-801-04	RH MLG HINGE PIN								Component ATA:32
PN:21114-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08EXC1698	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.315	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801					
32-11-13-900-801-01	LOB MLG HARNESS ASSY								Component ATA:32
PN:21802-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:395	HRS		0	TSN 0					4101.3
WC#: 32.320	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-11-13-900-801-02	LIB MLG HARNESS ASSY								Component ATA:32
PN:21801-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:390	HRS		0	TSN 0					4101.3
WC#: 32.320	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801					
32-11-13-900-801-03	RIB MLG HARNESS ASSY								Component ATA:32
PN:21803-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:401	HRS		0	TSN 0					4101.3
WC#: 32.325	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801					
32-11-13-900-801-04	ROB MLG HARNESS ASSY								Component ATA:32
PN:21804-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:391	HRS		0	TSN 0					4101.3
WC#: 32.325	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801					
32-11-17-101	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE-STAYLOWER-PIN, PART NO. 21113								Service ATA:32
PN:21113-1	MOS		20-Dec-09					06-Jul-2065	169.7
SN:08EXC1727	HRS		0						4101.3
	AFL	11168	0		11168		9943		1225
				PROC. REF: AMM 32 11 17 961 801					
32-11-17-101	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE-STAYLOWER-PIN, PART NO. 21113								Service ATA:32
PN:21113-1	MOS		19-Mar-21					10-Jun-2060	34.7
SN:DCL-032	HRS		3474.7						626.6
	AFL	11168	1069	TAC 2287	9950		8725		156
				PROC. REF: AMM 32 11 17 961 801					
32-11-17-102	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE RODEND, PART NO. 21510								Service ATA:32
PN:21510-3	MOS		20-Dec-09					02-Mar-2055	169.7
SN:09-05	HRS		0						4101.3
	AFL	8683	0		8683		7458		1225
				PROC. REF: AMM 32 11 17 961 802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-11-17-102	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE RODEND, PART NO. 21510								Service ATA:32
PN:21510-3	MOS		20-Dec-09					02-Mar-2055	169.7
SN:09-10	HRS		0						4101.3
	AFL	8683	0		8683		7458		1225
				PROC. REF: AMM 32 11 17 961 802					
32-11-17-103	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON,PART NO. 21512								Service ATA:32
PN:21512-1	MOS		20-Dec-09					02-Mar-2055	169.7
SN:817	HRS		0						4101.3
	AFL	8683	0		8683		7458		1225
				PROC. REF: AMM 32 11 17 961 803					
32-11-17-103	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON,PART NO. 21512								Service ATA:32
PN:21512-1	MOS		20-Dec-09					02-Mar-2055	169.7
SN:820	HRS		0						4101.3
	AFL	8683	0		8683		7458		1225
				PROC. REF: AMM 32 11 17 961 803					
32-11-17-104	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER,PART NO. 21521								Service ATA:32
PN:21521-2	MOS		20-Dec-09					02-Mar-2055	169.7
SN:DAY1060	HRS		0						4101.3
	AFL	8683	0		8683		7458		1225
				PROC. REF: AMM 32 11 17 961 804					
32-11-17-104	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER,PART NO. 21521								Service ATA:32
PN:21521-2	MOS		20-Dec-09					02-Mar-2055	169.7
SN:DAY1068	HRS		0						4101.3
	AFL	8683	0		8683		7458		1225
				PROC. REF: AMM 32 11 17 961 804					
32-11-17-106	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE-STAY UPPER-PIN, PART NO. GM227-1725								Service ATA:32
PN:PN	MOS		20-Dec-09	TAC 0				09-Feb-2123	169.7
SN:UNKNOWN	HRS		0	TAC 0					4101.3
	AFL	25000	0	TAC 0	25000		23775		1225
				PROC. REF: AMM 32 11 17 961 805					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-11-17-106	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE-STAY UPPER-PIN, PART NO. GM227-1725								Service ATA:32
PN:PN	MOS		20-Dec-09	TAC 0				09-Feb-2123	169.7
SN:UNKNOWN	HRS		0	TAC 0					4101.3
	AFL	25000	0	TAC 0	25000		23775		1225
				PROC. REF: AMM 32 11 17 961 805					
32-11-17-900-801-01	LH MAIN LANDING GEAR (MLG) SIDE BRACE ROD END								Component ATA:32
PN:21510-3	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:09-05	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-17-900-801-02	RH MAIN LANDING GEAR (MLG) SIDE BRACE ROD END								Component ATA:32
PN:21510-3	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:09-10	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-17-900-801-03	LH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON								Component ATA:32
PN:21512-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:817	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-17-900-801-04	RH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON								Component ATA:32
PN:21512-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:820	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-17-900-801-05	LH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER								Component ATA:32
PN:21521-2	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:DAY1060	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-11-17-900-801-06	RH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER								Component ATA:32
PN:21521-2	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:DAY1068	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-11-17-900-802-01	LH MLG SIDE BRACE ACTUATOR								Component ATA:32
PN:21501-107	MOS/MSC	O/C	21-Jun-21	TSR 0					31.7
SN:00783	HRS		3606	TSR 0					495.3
WC#: 32.330	AFL		1100	TSN 1100, TSR 0					125
				PROC. REF: CMM 32-30-23, AMM 32 11 17 000 801, AMM 32 11 17 400 801					
32-11-17-900-802-02	RH MLG SIDE BRACE ACTUATOR								Component ATA:32
PN:21500-107	MOS/MSC	O/C	19-Mar-21	TSN 135					34.7
SN:00786	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.330	AFL		1069	TSN 1069					156
				PROC. REF: CMM 32-30-23, AMM 32 11 17 000 801, AMM 32 11 17 400 801					
32-11-17-900-805-01	LH MLG SIDE-STAY UPPER PIN ASSY								Component ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-11-17-900-805-02	RH MLG SIDE-STAY UPPER PIN ASSY								Component ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-11-29-101	DISCARD THE LEFT HAND MAIN LANDING GEAR (MLG) MAIN FITTING, PARTNO. 21310								Service ATA:32
PN:21310-105	MOS		20-Dec-09					20-Jun-2081	169.7
SN:08WHM0481	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 29 961 801					
32-11-29-101	DISCARD THE RIGHT HAND MAIN LANDING GEAR (MLG) MAIN FITTING, PARTNO. 21310								Service ATA:32
PN:21310-106	MOS		20-Dec-09					20-Jun-2081	169.7
SN:08WHM0518	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 11 29 961 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-11-29-102	DISCARD THE LH MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO.21112								Service	ATA:32
PN:21112-101	MOS		20-Dec-09					10-Dec-2065	169.7	
SN:08EXC1727	HRS		0						4101.3	
	AFL	11271	0		11271		10046		1225	
				PROC. REF: AMM 32 11 29 961 802						
32-11-29-102	DISCARD THE RH MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO.21112								Service	ATA:32
PN:21112-102	MOS		20-Dec-09					10-Dec-2065	169.7	
SN:08EXC1740	HRS		0						4101.3	
	AFL	11271	0		11271		10046		1225	
				PROC. REF: AMM 32 11 29 961 802						
32-11-29-103	DISCARD THE LH MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN,PART NO. 21116-1								Service	ATA:32
PN:21116-1	MOS		20-Dec-09					20-Jun-2081	169.7	
SN:08EXC0894	HRS		0						4101.3	
	AFL	15000	0		15000		13775		1225	
				PROC. REF: AMM 32 11 29 961 803						
32-11-29-103	DISCARD THE RH MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN, PART NO. 21116-1								Service	ATA:32
PN:21116-1	MOS		20-Dec-09					20-Jun-2081	169.7	
SN:08EXC0892	HRS		0						4101.3	
	AFL	15000	0		15000		13775		1225	
				PROC. REF: AMM 32 11 29 961 803						
32-11-29-900-801-01	NOSE LANDING GEAR MAIN FITTING								Component	ATA:32
PN:1286-0101	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:420	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.390	AFL		1069	TSN 1069					156	
				PROC. REF: GENERIC NO REF						
32-12-00-201[S]	LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOORS								Service	ATA:32
	MOS		28-Nov-23						2.5	
	HRS	250 (+10%/-10%)	4099.1						2.2	
WC#: 32.075	AFL		1223						2	
				PROC. REF: AMM 12 22 00 640 819						PKG:63

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-12-00-202[S]	LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOOR ACTUATOR								Service	ATA:32
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 32.080	AFL		1171						54	
				PROC. REF: AMM 12 22 00 640 834						PKG:32
32-12-01-900-801-01	LH OUTBOARD MLG DOOR								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 12 01 000 801, AMM 32 12 01 400 801						
32-12-01-900-801-02	RH OUTBOARD MLG DOOR								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 12 01 000 801, AMM 32 12 01 400 801						
32-12-05-900-801-01	LH INBOARD MLG DOOR								Component	ATA:32
PN:GS328-0001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:12094	HRS		0	TSN 0					4101.3	
WC#: 32.335	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 12 05 000 801, AMM 32 12 05 400 801						
32-12-05-900-801-02	RH INBOARD MLG DOOR								Component	ATA:32
PN:GS328-0001-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:12094	HRS		0	TSN 0					4101.3	
WC#: 32.335	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 12 05 000 801, AMM 32 12 05 400 801						
32-12-09-900-801-01	LEFT HAND MLG MAIN FITTING								Component	ATA:32
PN:21310-105	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:08WHM0481	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.340	AFL		1069	TSN 1069					156	
				PROC. REF: AMM 32 12 09 000 801, AMM 32 12 09 400 801						
32-12-09-900-801-02	RIGHT HAND MLG MAIN FITTING								Component	ATA:32
PN:21310-106	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:08WHM0518	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.340	AFL		1069	TSN 1069					156	
				PROC. REF: AMM 32 12 09 000 801, AMM 32 12 09 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-20-00-201[S]	RESTORATION NLG ASSY GEAR								Service	ATA:32
PN:GW318-2000-1	MOS	240 (+3m/-3m)	30-Jun-11						151.4	
SN:09MDT0483	HRS									
WC#: 32.355	AFL									
				PROC. REF: AMM 32 21 00 615 801						PKG:56
32-20-00-204[S]	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.085	AFL		1069						156	
				PROC. REF: AMM 32 21 00 220 801						PKG:38
32-20-00-205[S]	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.090	AFL									
				PROC. REF: AMM 32 21 00 280 801						PKG:56
32-20-00-206[S]	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.095	AFL		1069						156	
				PROC. REF: AMM 32 21 00 220 802						PKG:38
32-20-00-207[S]	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.100	AFL									
				PROC. REF: AMM 32 21 00 280 802						PKG:56
32-20-00-208[S]	DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.105	AFL		1069						156	
				PROC. REF: AMM 32 21 00 220 803						PKG:38
32-20-00-209[S]	SPECIAL DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.110	AFL									
				PROC. REF: AMM 32 21 00 280 803						PKG:56

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-20-00-210[S]	DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.115	AFL		1069						156	
				PROC. REF: AMM 32 33 01 220 801						PKG:38
32-20-00-211[S]	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)								Service	ATA:32
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 32.120	AFL									
				PROC. REF: AMM 32 33 01 280 801						PKG:56
32-21-00-201[S]	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND COMPONENTS								Service	ATA:32
	MOS		28-Nov-23						2.5	
	HRS	250 (+10%/-10%)	4099.1						2.2	
WC#: 32.125	AFL		1223						2	
				PROC. REF: AMM 12 22 00 640 801						PKG:63
32-21-00-900-801-01	NLG PINTLE PIN								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.385	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 21 00 000 801, AMM 32 21 00 400 801						
32-21-00-900-801-02	NLG PINTLE PIN								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-21-00-900-802-01	NLG ASSY GEAR								Component	ATA:32
PN:GW318-2000-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09MDT0483	HRS		0	TSN 0					4101.3	
WC#: 32.355	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 21 00 000 801, AMM 32 21 00 400 801						
32-21-01-101	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT AXLE, PART NO. 1286-0201/-0203/-0204								Service	ATA:32
PN:1286-0203	MOS		20-Dec-09					20-Jun-2081	169.7	
SN:1232243/005	HRS		0						4101.3	
	AFL	15000	0		15000		13775		1225	
				PROC. REF: AMM 32 21 17 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-21-01-102	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT PISTON(SLIDING TUBE), PART NO. 1286-0001 AND 1286-0077								Service ATA:32
PN:1286-0077	MOS		20-Dec-09					20-Jun-2081	169.7
SN:1276905/004	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 21 01 961 803					
32-21-01-103	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT MAIN FITTING, PART NO. 1286-0101/-0109								Service ATA:32
PN:1286-0101	MOS		20-Dec-09					15-Jan-2066	169.7
SN:420	HRS		0						4101.3
	AFL	11295	0		11295		10070		1225
				PROC. REF: AMM 32 21 01 961 802					
32-21-01-107	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT RETRACTION ACTUATOR BOLT, PART NO. 1285-0007/-0041								Service ATA:32
PN:PN	MOS		20-Dec-09	TAC 0				20-Jun-2081	169.7
SN:UNKNOWN	HRS		0	TAC 0					4101.3
	AFL	15000	0	TAC 0	15000		13775		1225
				PROC. REF: AMM 32 33 01 961 802					
32-21-01-108	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT LH STEERING ACTUATOR BOLT, PART NO. 1285-0010								Service ATA:32
	MOS		20-Dec-09					20-Jun-2081	169.7
	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 51 21 961 801					
32-21-01-108	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT RH STEERING ACTUATOR BOLT, PART NO. 1285-0010								Service ATA:32
	MOS		20-Dec-09					20-Jun-2081	169.7
	HRS		0						4101.3
	AFL	15000	0		15000		13775		1225
				PROC. REF: AMM 32 51 21 961 801					
32-21-01-201[S]	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) SHOCK STRUT EXTENSION								Service ATA:32
	MOS		28-Nov-23						2.5
	HRS	500 (+50/-50)	4099.1						2.2
WC#: 32.130	AFL		1223						2
				PROC. REF: AMM 32 21 01 220 801					PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-21-01-900-801-01	NOSE LANDING GEAR (NLG) SHOCK STRUT (SLIDING TUBE) PISTON								Component ATA:32
PN:1286-0077	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:1276905/004	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-21-01-900-804-01	NLG SHOCK STRUT								Component ATA:32
PN:22175-109	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:83380988	HRS		0	TSN 0					4101.3
WC#: 32.365	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-21-01, AMM 32 21 01 000 801, AMM 32 21 01 400 801					
32-21-03-900-801-01	NOSE LANDING GEAR STRUT								Component ATA:32
PN:1286A0000-02	MOS/MSC	O/C	19-Mar-21	TSN 135, TSR 3					34.7
SN:00529	HRS		3474.7	TSN 3474.7, TSR 0					626.6
WC#: 32.360	AFL		1069	TSN 1069, TSR 0					156
				PROC. REF: AMM 32 21 03 000 801, AMM 32 21 03 400 801					
32-21-05-101	DISCARD THE NOSE LANDING GEAR (NLG) UPPER DRAG BRACE,PART NO. 22511								Service ATA:32
PN:22511-1	MOS		20-Dec-09					24-Mar-2071	169.7
SN:08ALT0069	HRS		0						4101.3
	AFL	12540	0		12540		11315		1225
				PROC. REF: AMM 32 21 05 961 805					
32-21-05-102	DISCARD THE NOSE LANDING GEAR (NLG) LOWER DRAG BRACE,PART NO. 22516								Service ATA:32
PN:22516-3	MOS		20-Dec-09					23-Dec-2066	169.7
SN:08ALT0074	HRS		0						4101.3
	AFL	11520	0		11520		10295		1225
				PROC. REF: AMM 32 21 05 961 802					
32-21-05-105	DISCARD THE NOSE LANDING GEAR (NLG) DRAG BRACE APEXPIN, PART NO. 22530								Service ATA:32
PN:22530-1	MOS		20-Dec-09					09-Aug-2065	169.7
SN:08EXC0411	HRS		0						4101.3
	AFL	11190	0		11190		9965		1225
				PROC. REF: AMM 32 21 05 961 803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-21-05-106	DISCARD THE LH NOSE LANDING GEAR (NLG) DRAG BRACETRUNNION PIN, PART NO. 22534								Service ATA:32
PN:22534-1	MOS		20-Dec-09					23-Sep-2065	169.7
SN:09CPS0964	HRS		0						4101.3
	AFL	11220	0		11220		9995		1225
				PROC. REF: AMM 32 21 05 961 804					
32-21-05-106	DISCARD THE RH NOSE LANDING GEAR (NLG) DRAG BRACETRUNNION PIN, PART NO. 22534								Service ATA:32
PN:22534-1	MOS		20-Dec-09					23-Sep-2065	169.7
SN:09CPS0965	HRS		0						4101.3
	AFL	11220	0		11220		9995		1225
				PROC. REF: AMM 32 21 05 961 804					
32-21-05-107	DISCARD THE NOSE LANDING GEAR (NLG) DRAG BRACE FORWARD STABILIZER LINK, PART NO. 22580								Service ATA:32
PN:PN	MOS		20-Dec-09	TAC 0				02-Mar-2067	169.7
SN:UNKNOWN	HRS		0	TAC 0					4101.3
	AFL	11565	0	TAC 0	11565		10340		1225
				PROC. REF: AMM 32 21 05 961 806					
32-21-05-108	DISCARD THE NOSE LANDING GEAR (NLG) DRAG BRACE AFT STABILIZER LINK, PART NO. 22585								Service ATA:32
PN:PN	MOS		20-Dec-09	TAC 0				01-Dec-2066	169.7
SN:UNKNOWN	HRS		0	TAC 0					4101.3
	AFL	11505	0	TAC 0	11505		10280		1225
				PROC. REF: AMM 32 21 05 961 807					
32-21-05-900-801-01	NLG DRAG BRACE								Component ATA:32
PN:22500-105	MOS/MSC	O/C	19-Mar-21	TSR 3					34.7
SN:09MDT0490	HRS		3474.7	TSN 3474.7, TSR 0					626.6
WC#: 32.350	AFL		1069	TSN 1069, TSR 0					156
				PROC. REF: GENERIC NO REF					
32-21-05-900-801-03	NLG APEX DRAG BRACE PIN								Component ATA:32
PN:22530-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08EXC0411	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.725	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-21-05-900-802-01	NLG UPPER DRAG BRACE								Component ATA:32
PN:22511-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08ALT0069	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: CMM 32-70-07, AMM 32 21 05 000 801, AMM 32 21 05 400 801					
32-21-05-900-803-01	NLG LOWER DRAG BRACE								Component ATA:32
PN:22516-3	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08ALT0074	HRS		3474.7	TSN 3474.7					626.6
	AFL		1069	TSN 1069					156
				PROC. REF: CMM 32-70-07					
32-21-05-900-806-01	DOWNLOCK NLG ACTUATOR								Component ATA:32
PN:22570-101	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:09CPS0968	HRS		0	TSN 0					4101.3
WC#: 32.365	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 21 05 000 801, AMM 32 21 05 400 801					
32-21-05-900-807-01	NOSE LANDING GEAR (NLG) DRAG BRACE FORWARD STABILIZER LINK								Component ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-21-05-900-807-02	NOSE LANDING GEAR (NLG) DRAG BRACE AFT STABILIZER LINK								Component ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-21-07-900-801-01	LH NLG TRUNNION PIN								Component ATA:32
PN:22534-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:09CPS0964	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.375	AFL		1069	TSN 1069					156
				PROC. REF: GENERIC NO REF					
32-21-07-900-801-02	RH NLG TRUNNION PIN								Component ATA:32
PN:22534-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:09CPS0965	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.375	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 21 07 000 801, AMM 32 21 07 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-21-07-900-801-03	NLG LOWER PIN								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.380	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 21 07 000 801, AMM 32 21 07 400 801						
32-21-09-900-801-01	LH NLG HARNESS								Component	ATA:32
PN:22800-105	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09CPS0964	HRS		0	TSN 0					4101.3	
WC#: 32.395	AFL		0	TSN 0					1225	
				PROC. REF: CMM 32-60-04, AMM 32 21 09 000 801, AMM 32 21 09 400 801						
32-21-09-900-801-02	RH NLG HARNESS								Component	ATA:32
PN:22801-107	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09MDT0730	HRS		0	TSN 0					4101.3	
WC#: 32.395	AFL		0	TSN 0					1225	
				PROC. REF: CMM 32-60-04, AMM 32 21 09 000 801, AMM 32 21 09 400 801						
32-21-17-900-801-01	NOSE LANDING GEAR AXLE								Component	ATA:32
PN:1286-0203	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7	
SN:1232243/005	HRS		3474.7	TSN 3474.7					626.6	
WC#: 32.345	AFL		1069	TSN 1069					156	
				PROC. REF: GENERIC NO REF						
32-22-00-101	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR FORWARD DOORS								Service	ATA:32
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 32.135	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-32-20-001, NDT MT-32-20-001						PKG:76
32-22-00-201[S]	LUBRICATION OF THE NOSE LANDING GEAR (NLG) DOORS								Service	ATA:32
	MOS		28-Nov-23						2.5	
	HRS	250 (+10%/-10%)	4099.1						2.2	
WC#: 32.140	AFL		1223						2	
				PROC. REF: AMM 12 22 00 640 803						PKG:63
32-22-00-202[S]	DETAILED INSPECTION OF THE NOSE-GEAR-DOOR HINGES AND ACTUATOR ATTACHMENT FITTING								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.145	AFL		1069						156	
				PROC. REF: AMM 32 22 01 220 801						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-22-05-900-801-01	NLG AFT DOOR ASSY								Component	ATA:32
PN:GS328-0005-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B370	HRS		0	TSN 0					4101.3	
WC#: 32.400	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 22 05 000 801, AMM 32 22 05 400 801						
32-22-17-900-801-01	LH NLG FWD DOOR ASSY								Component	ATA:32
PN:GS328-0003-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B382	HRS		0	TSN 0					4101.3	
WC#: 32.405	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 22 17 000 801, AMM 32 22 17 400 801						
32-22-17-900-801-02	RH NLG FWD DOOR ASSY								Component	ATA:32
PN:GS328-0004-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B376	HRS		0	TSN 0					4101.3	
WC#: 32.405	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 22 17 000 801, AMM 32 22 17 400 801						
32-31-01-900-801-01	LANDING GEAR CONTROL PANEL								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.415	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 31 01 000 801, AMM 32 31 01 400 801						
32-31-05-900-801-01	LANDING GEAR CONTROL HANDLE								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.410	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 31 05 000 801, AMM 32 31 05 400 801						
32-31-09-101	VISUAL CHECK OF THE LANDING-GEAR ELECTRONIC CONTROL UNIT (LG ECU)								Service	ATA:32
	MOS		06-Jul-18					09-Jul-2027	67.2	
	HRS	3000 (+50/-50)	2892.3	Adj 50	5942.3	5992.3	1841 (+50)		1209	
WC#: 32.150	AFL		921						304	
				PROC. REF: AMM 32 31 09 210 801						PKG:8
32-31-09-900-801-01	LANDING GEAR ECU								Component	ATA:32
PN:GW415-5100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E488	HRS		0	TSN 0					4101.3	
WC#: 32.420	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 31 09 000 801, AMM 32 31 09 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-31-13-900-801-01	NO. 2 SYSTEM L/G CONTROL SELECTOR VALVE								Component ATA:32
PN:GW415-6025-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:NGL/2185/09	HRS		0	TSN 0					4101.3
WC#: 32.425	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 31 13 000 801, AMM 32 31 13 400 801					
32-31-15-900-801-01	NO. 3 SYSTEM L/G CONTROL SELECTOR VALVE								Component ATA:32
PN:GW415-6025-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:NGL/2189/09	HRS		0	TSN 0					4101.3
WC#: 32.425	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 31 15 000 801, AMM 32 31 15 400 801					
32-31-17-900-801-01	L/G DOOR CONTROL SELECTOR VALVE								Component ATA:32
PN:GW415-6025-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:NGL/2188/09	HRS		0	TSN 0					4101.3
WC#: 32.425	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 31 17 000 801, AMM 32 31 17 400 801					
32-31-21-900-801-01	CHECK, SIDE BRACE CONTROL VALVE								Component ATA:32
PN:GW415-6075-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:NGL/1337/07	HRS		0	TSN 0					4101.3
WC#: 32.430	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 31 21 000 801, AMM 32 31 21 400 801					
32-32-01-105	DISCARD THE LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATORASSEMBLY, PART NO. 21600								Service ATA:32
PN:GW412-1000-1	MOS		20-Dec-09					09-Feb-2123	169.7
SN:09MDT0789	HRS		0						4101.3
	AFL	25000	0		25000		23775		1225
				PROC. REF: AMM 32 32 01 961 801					
32-32-01-105	DISCARD THE RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATORASSEMBLY, PART NO. 21600								Service ATA:32
PN:GW412-1000-2	MOS		20-Dec-09					09-Feb-2123	169.7
SN:09MDT0778	HRS		0						4101.3
	AFL	25000	0		25000		23775		1225
				PROC. REF: AMM 32 32 01 961 801					
32-32-01-900-801-01	LH MLG RETRACTION ACTUATOR								Component ATA:32
PN:GW412-1000-1	MOS/MSC	H/T	19-Mar-21	TSN 135, TSR 3					34.7
SN:09MDT0789	HRS		3474.7	TSN 3474.7, TSR 0					626.6
WC#: 32.435	AFL		1069	TSN 1069, TSR 0					156
				PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-32-01-900-801-02	RH MLG RETRACTION ACTUATOR								Component ATA:32
PN:GW412-1000-2	MOS/MSC	H/T	19-Mar-21	TSN 135, TSR 3					34.7
SN:09MDT0778	HRS		3474.7	TSN 3474.7, TSR 0					626.6
WC#: 32.435	AFL		1069	TSN 1069, TSR 0					156
				PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801					
32-32-01-900-801-03	LH MLG SIDE STAY (LOWER) PIN								Component ATA:32
PN:21113-1	MOS/MSC	H/T	19-Mar-21	TSN 135					34.7
SN:08EXC1727	HRS		3474.7	TSN 3474.7					626.6
WC#: 32.440	AFL		1069	TSN 1069					156
				PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801					
32-32-01-900-801-04	RH MLG SIDE STAY (LOWER) PIN								Component ATA:32
PN:21113-1	MOS/MSC	H/T	19-Mar-21						34.7
SN:DCL-032	HRS		3474.7						626.6
WC#: 32.440	AFL		1069	TSN 2287					156
				PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801					
32-32-01-900-803-01	LH MLG RETRACTION ACTUATOR PIN								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.450	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801					
32-32-01-900-803-02	RH MLG RETRACTION ACTUATOR PIN								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.450	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801					
32-32-01-900-804-01	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR CYLINDER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-27					
32-32-01-900-804-02	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR CYLINDER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-27					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-32-01-900-805-01	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-32-01-900-805-02	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-32-01-900-806-01	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ROD END								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-32-01-900-806-02	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ROD END								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-32-01-900-807-01	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR GLAND NUT								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-32-01-900-807-02	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR GLAND NUT								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-32-05-107	DISCARD THE LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY,PART NO. 21900								Service	ATA:32
PN:GW415-0001-3	MOS		20-Dec-09					09-Feb-2123	169.7	
SN:09SM00018	HRS		0						4101.3	
	AFL	25000	0		25000		23775		1225	
				PROC. REF: AMM 32 32 05 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-32-05-107	DISCARD THE RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY,PART NO. 21900								Service ATA:32
PN:GW415-0001-4	MOS		20-Dec-09					09-Feb-2123	169.7
SN:09SM00014	HRS		0						4101.3
	AFL	25000	0		25000		23775		1225
				PROC. REF: AMM 32 32 05 961 801					
32-32-05-900-801-01	LH MLG UPLOCK								Component ATA:32
PN:GW415-0001-3	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:09SM00018	HRS		0	TSN 0					4101.3
WC#: 32.455	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-24, AMM 32 32 05 000 801, AMM 32 32 05 400 801					
32-32-05-900-801-02	RH MLG UPLOCK								Component ATA:32
PN:GW415-0001-4	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:09SM00014	HRS		0	TSN 0					4101.3
WC#: 32.455	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-24, AMM 32 32 05 000 801, AMM 32 32 05 400 801					
32-32-05-900-802-01	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY SIDE PLATE								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-802-02	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY SIDE PLATE								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-803-01	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LATCH								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-803-02	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LATCH								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-32-05-900-804-01	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LOCK LEVER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-804-02	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LOCK LEVER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-805-01	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-805-02	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-806-01	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-806-02	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-05-900-807-01	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-32-05-900-807-02	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-32-09-900-801-01	LH MLG DOOR INBOARD ACTUATOR								Component ATA:32
PN:GW412-2000-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:09MDT0667	HRS		0	TSN 0					4101.3
WC#: 32.460	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-32, AMM 32 32 09 000 801, AMM 32 32 09 400 801					
32-32-09-900-801-02	RH MLG DOOR INBOARD ACTUATOR								Component ATA:32
PN:GW412-2000-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:09MDT0640	HRS		0	TSN 0					4101.3
WC#: 32.460	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-32, AMM 32 32 09 000 801, AMM 32 32 09 400 801					
32-32-13-101	DISCARD THE LH MAIN-GEAR DOOR UPLOCK, PART NO. GW415-2200-5/6								Service ATA:32
PN:GW415-2200-5	MOS		20-Dec-09					13-Jan-2045	169.7
SN:09SM00019	HRS		0						4101.3
	AFL	6250	0		6250		5025		1225
				PROC. REF: AMM 32 32 13 961 801					
32-32-13-101	DISCARD THE RH MAIN-GEAR DOOR UPLOCK, PART NO.GW415-2200-5/6								Service ATA:32
PN:GW415-2200-6	MOS		20-Dec-09					13-Jan-2045	169.7
SN:09SM00010	HRS		0						4101.3
	AFL	6250	0		6250		5025		1225
				PROC. REF: AMM 32 32 13 961 801					
32-32-13-900-801-01	LH MLG DOOR INBOARD UPLOCK								Component ATA:32
PN:GW415-2200-5	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:09SM00019	HRS		0	TSN 0					4101.3
WC#: 32.465	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-28, AMM 32 32 13 000 801, AMM 32 32 13 400 801					
32-32-13-900-801-02	RH MLG DOOR INBOARD UPLOCK								Component ATA:32
PN:GW415-2200-6	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:09SM00010	HRS		0	TSN 0					4101.3
WC#: 32.465	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-28, AMM 32 32 13 000 801, AMM 32 32 13 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-33-01-105	DISCARD THE NOSE LANDING GEAR (NLG) RETRACTION ACTUATORASSEMBLY, PART NO. 22400-101/-103								Service ATA:32
PN:GW412-1050-3	MOS		20-Dec-09					16-Apr-2102	169.7
SN:09MDT0328	HRS		0						4101.3
	AFL	20000	0		20000		18775		1225
				PROC. REF: AMM 32 33 01 961 801					
32-33-01-111	RESTORATION OF THE NOSE LANDING GEAR (NLG) SHOCK-STRUT ASSEMBLY TO RETRACTION-ACTUATOR MAIN-FITTING JOINT (POST SB 700-32-035 PART C)								Service ATA:32
	MOS/MSC	N/A	20-Dec-09						169.7
	HRS		0						4101.3
	AFL		0						1225
				PROC. REF: AMM 32 21 01 610 801					
32-33-01-112	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) SHOCK-STRUT ASSEMBLY TO RETRACTION-ACTUATOR MAIN-FITTING JOINT (POST SB 700-32-035 PART C)								Service ATA:32
	MOS/MSC	N/A	20-Dec-09						169.7
	HRS		0						4101.3
	AFL		0						1225
				PROC. REF: AMM 32 21 00 220 804					
32-33-01-900-801-01	NLG RETRACTION ACTUATOR								Component ATA:32
PN:GW412-1050-3	MOS/MSC	H/T	19-Mar-21	TSN 135, TSR 3					34.7
SN:09MDT0328	HRS		3474.7	TSN 3474.7, TSR 0					626.6
WC#: 32.480	AFL		1069	TSN 1069, TSR 0					156
				PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801					
32-33-01-900-802-01	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR CYLINDER								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-30-25					
32-33-01-900-803-01	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR PISTON								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-33-01-900-804-01	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR GLAND NUT								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-33-01-900-805-01	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR ROD END								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-33-01-900-811-01	NOSE LANDING GEAR (NLG) SHOCK STRUT RETRACTION ACTUATOR BOLT								Component	ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-33-05-106	DISCARD THE NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY,PART NO. 22600-101/-103								Service	ATA:32
PN:PN	MOS		20-Dec-09					09-Feb-2123	169.7	
SN:UNKNOWN	HRS		0						4101.3	
	AFL	25000	0		25000		23775		1225	
				PROC. REF: AMM 32 33 05 961 801						
32-33-05-900-801-01	NLG UPLOCK								Component	ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.485	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801						
32-33-05-900-803-01	NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY HOOK								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-33-05-900-804-01	NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY LOCK LEVER								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-33-05-900-805-01	NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY STOP PIN								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-33-09-900-801-01	NLG FWD DOOR ACTUATOR								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.490	AFL		0	TSN 0					1225	
				PROC. REF: CMM 32-30-30, AMM 32 33 09 000 801, AMM 32 33 09 400 801						
32-33-09-900-802-01	NOSE LANDING GEAR (NLG) UPLOCK ACTUATOR CYLINDER								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-33-09-900-803-01	NOSE LANDING GEAR (NLG) UPLOCK ACTUATOR PISTON								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-33-13-101	DISCARD THE NOSE-GEAR FORWARD-DOOR UPLOCK, PART NO.GW415-2300-1								Service	ATA:32
PN:PN	MOS		20-Dec-09					17-Nov-2030	169.7	
SN:UNKNOWN	HRS		0						4101.3	
	AFL	2850	0		2850		1625		1225	
				PROC. REF: AMM 32 33 13 961 801						
32-33-13-900-801-01	NLG FORWARD DOOR UPLOCK								Component	ATA:32
PN:PN	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.495	AFL		0	TSN 0					1225	
				PROC. REF: CMM 32-30-31, AMM 32 33 13 000 802, AMM 32 33 13 400 802						
32-34-00-101	FUNCTIONAL TEST OF THE LANDING-GEAR EMERGENCY EXTENSION								Service	ATA:32
	MOS		19-Mar-21					27-Oct-2025	34.7	
	HRS	1500	3474.7		5024.7 (M)		923.4		626.6	
	AFL		1069						156	
				PROC. REF: AMM 32 34 00 720 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-34-00-201	FUNCTIONAL TEST OF THE LANDING-GEAR EMERGENCY EXTENSION								Service	ATA:32
	MOS		19-Mar-21					23-Sep-2025	34.7	
	HRS	1500 (+50/-50)	3474.7		4974.7	5024.7	873.4 (+50)		626.6	
WC#: 32.155	AFL		1069						156	
				PROC. REF: AMM 32 34 00 720 801						PKG:5
32-34-00-202 S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE NOSE LANDING-GEAR WHEEL-WELL, FS202.75 TO FS280.00								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.160	AFL	450 (+50/-50)	996						229	
				PROC. REF: AMM 32 34 00 220 801						PKG:58
32-34-00-203 S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE FORWARD AVIONICS COMPARTMENT, FS202.75 TO FS280.00								Service	ATA:32
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.165	AFL		1069						156	
				PROC. REF: AMM 32 34 00 220 802						PKG:34
32-34-00-204 S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MAIN AVIONICS COMPARTMENT, FS280.00 TO FS557.00								Service	ATA:32
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.170	AFL		1069						156	
				PROC. REF: AMM 32 34 00 220 803						PKG:34
32-34-00-205 S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MID-LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.175	AFL		1069						156	
				PROC. REF: AMM 32 34 00 220 804						PKG:38
32-34-00-206 S	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY EXTENSION CONTROL PATH IN THE MAIN LANDING-GEAR WHEEL-WELL, FS719.30 TO FS781.00								Service	ATA:32
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 32.180	AFL		1069						156	
				PROC. REF: AMM 32 34 00 220 805						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-34-01-900-801-01	MANUAL RELEASE HANDLE								Component ATA:32
PN:GW415-7100-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0402	HRS		0	TSN 0					4101.3
WC#: 32.515	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 34 01 000 801, AMM 32 34 01 400 801					
32-34-03-900-801-01	NLG DOOR QUADRANT								Component ATA:32
PN:GW413-1000-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:DCL-374	HRS		0	TSN 0					4101.3
WC#: 32.500	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-34-03-900-801-02	MANUAL RELEASE QUADRANT								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.520	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-34-03-900-802-01	NOSE LANDING GEAR QUADRANT								Component ATA:32
PN:GW413-2000-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:DCL-380	HRS		0	TSN 0					4101.3
WC#: 32.510	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 34 01 000 801, AMM 32 34 01 400 801					
32-34-03-900-803-01	MLG QUADRANT								Component ATA:32
PN:GW413-7000-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:DCL380	HRS		0	TSN 0					4101.3
WC#: 32.505	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 34 01 000 801, AMM 32 34 01 400 801					
32-34-05-900-801-01	LH SHUTOFF VALVE								Component ATA:32
PN:GW415-6175-3	MOS/MSC	O/C	22-Dec-23						1.6
SN:503T	HRS		4099.1						2.2
WC#: 32.620	AFL		1223						2
				PROC. REF: AMM 32 34 05 000 801, AMM 32 34 05 400 801					
32-34-05-900-801-02	RH SHUTOFF VALVE								Component ATA:32
PN:GW415-6175-3	MOS/MSC	O/C	22-Dec-23						1.6
SN:2185T	HRS		4099.1						2.2
WC#: 32.620	AFL		1223						2
				PROC. REF: AMM 32 34 05 000 801, AMM 32 34 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-34-05-900-802-01	HYD S/O DUMP MANUAL RELEASE VALVE								Component	ATA:32
PN:GW415-6101-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09MDT0497	HRS		0	TSN 0					4101.3	
WC#: 32.525	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 34 05 000 801, AMM 32 34 05 400 801						
32-34-05-900-802-02	HYDRAULIC DUMP VALVE								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.530	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-34-09-900-801-01	MAIN LANDING GEAR MRS ALTERNATE POWER VALVE								Component	ATA:32
PN:GW415-6051-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09MDT0499	HRS		0	TSN 0					4101.3	
WC#: 32.475	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 34 09 000 801, AMM 32 34 09 400 801						
32-34-09-900-801-02	ALTERNATE POWER VALVE								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.535	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 34 09 000 801, AMM 32 34 09 400 801						
32-40-00-201[S]	FUNCTIONAL TEST OF THE BRAKE ACCUMULATORS								Service	ATA:32
	MOS		27-Nov-23						2.5	
	HRS	500 (+50/-50)	4099.1						2.2	
WC#: 32.185	AFL		1223						2	
				PROC. REF: AMM 32 40 00 720 801						PKG:2
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 1 ASSY MLG WHEEL NO.1 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:1909	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 280 801						
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 2 ASSY MLG WHEEL NO.2 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:1935	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 280 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 3 ASSY MLG WHEEL NO.3 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:0439	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 280 801						
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 4 ASSY MLG WHEEL NO.4 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:1452	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 280 801						
32-41-01-202	DETAILED INSPECTION NO. 1 ASSY MLG WHEEL NO.1 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:1909	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 220 801						
32-41-01-202	DETAILED INSPECTION NO. 2 ASSY MLG WHEEL NO.2 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:1935	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 220 801						
32-41-01-202	DETAILED INSPECTION NO. 3 ASSY MLG WHEEL NO.3 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:0439	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 220 801						
32-41-01-202	DETAILED INSPECTION NO. 4 ASSY MLG WHEEL NO.4 MLG WHEEL ASSY								Service	ATA:32
PN:3-1599	MOS/MSC	T/C	12-Jan-24						1	
SN:1452	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 41 01 220 801						
32-41-01-900-801-01	NO. 1 ASSY MLG WHEEL								Component	ATA:32
PN:3-1599	MOS/MSC	O/C	12-Jan-24	TSO 0					1	
SN:1909	HRS		4100.9	TSO 0					.4	
WC#: 32.540	AFL		1224	TSO 0					1	
				PROC. REF: CMM 32-48-22, CMM 32-48-30						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-41-01-900-801-02	NO. 2 ASSY MLG WHEEL								Component ATA:32
PN:3-1599	MOS/MSC	O/C	12-Jan-24	TSO 0					1
SN:1935	HRS		4100.9	TSO 0					.4
WC#: 32.545	AFL		1224	TSO 0					1
				PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801					
32-41-01-900-801-03	NO. 3 ASSY MLG WHEEL								Component ATA:32
PN:3-1599	MOS/MSC	O/C	12-Jan-24	TSO 0					1
SN:0439	HRS		4100.9	TSO 0					.4
WC#: 32.550	AFL		1224	TSO 0					1
				PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801					
32-41-01-900-801-04	NO. 4 ASSY MLG WHEEL								Component ATA:32
PN:3-1599	MOS/MSC	O/C	12-Jan-24	TSO 0					1
SN:1452	HRS		4100.9	TSO 0					.4
WC#: 32.555	AFL		1224	TSO 0					1
				PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801					
32-41-01-900-802-01	NO. 1 MLG TIRE								Component ATA:32
PN:382K02-1	MOS/MSC	O/C	12-Jan-24	TSN 0					1
SN:22750083	HRS		4100.9	TSN 0					.4
WC#: 32.540	AFL		1224	TSN 0					1
				PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801					
32-41-01-900-802-02	NO. 2 MLG TIRE								Component ATA:32
PN:382K02-1	MOS/MSC	O/C	12-Jan-24	TSN 0					1
SN:23391064	HRS		4100.9	TSN 0					.4
WC#: 32.545	AFL		1224	TSN 0					1
				PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801					
32-41-01-900-802-03	NO. 3 MLG TIRE								Component ATA:32
PN:382K02-1	MOS/MSC	O/C	12-Jan-24	TSN 0					1
SN:23231071	HRS		4100.9	TSN 0					.4
WC#: 32.550	AFL		1224	TSN 0					1
				PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-41-01-900-802-04	NO. 4 MLG TIRE								Component	ATA:32
PN:382K02-1	MOS/MSC	O/C	12-Jan-24	TSN 0					1	
SN:22901063	HRS		4100.9	TSN 0					.4	
WC#: 32.555	AFL		1224	TSN 0					1	
				PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801						
32-42-01-201	SPECIAL DETAILED INSPECTION LH ASSY NLG WHEEL LH NLG WHEEL ASSY								Service	ATA:32
PN:3-1560	MOS/MSC	T/C	12-Jan-24						1	
SN:0221	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 42 01 280 801						
32-42-01-201	SPECIAL DETAILED INSPECTION RH ASSY NLG WHEEL RH NLG WHEEL ASSY								Service	ATA:32
PN:3-1560	MOS/MSC	T/C	12-Jan-24						1	
SN:1352	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 42 01 280 801						
32-42-01-202	DETAILED INSPECTION LH ASSY NLG WHEEL LH NLG WHEEL ASSY								Service	ATA:32
PN:3-1560	MOS/MSC	T/C	12-Jan-24						1	
SN:0221	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 42 01 220 801						
32-42-01-202	DETAILED INSPECTION RH ASSY NLG WHEEL RH NLG WHEEL ASSY								Service	ATA:32
PN:3-1560	MOS/MSC	T/C	12-Jan-24						1	
SN:1352	HRS		4100.9						.4	
	AFL		1224						1	
				PROC. REF: AMM 32 42 01 220 801						
32-42-01-900-801-01	LH ASSY NLG WHEEL								Component	ATA:32
PN:3-1560	MOS/MSC	O/C	12-Jan-24	TSO 0					1	
SN:0221	HRS		4100.9	TSO 0					.4	
WC#: 32.560	AFL		1224	TSO 0					1	
				PROC. REF: CMM 32-48-23, AMM 32 42 01 000 801, AMM 32 42 01 400 801						
32-42-01-900-801-02	RH ASSY NLG WHEEL								Component	ATA:32
PN:3-1560	MOS/MSC	O/C	12-Jan-24	TSO 0					1	
SN:1352	HRS		4100.9	TSO 0					.4	
WC#: 32.565	AFL		1224	TSO 0					1	
				PROC. REF: CMM 32-48-23, AMM 32 42 01 000 801, AMM 32 42 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-42-01-900-802-01	LH NLG TIRE								Component	ATA:32
PN:217K22-1	MOS/MSC	O/C	12-Jan-24	TSN 0					1	
SN:30090477	HRS		4100.9	TSN 0					.4	
WC#: 32.560	AFL		1224	TSN 0					1	
				PROC. REF: AMM 32 42 01 000 801, AMM 32 42 01 400 801						
32-42-01-900-802-02	RH NLG TIRE								Component	ATA:32
PN:217K22-1	MOS/MSC	O/C	12-Jan-24						1	
SN:30090471	HRS		4100.9						.4	
WC#: 32.565	AFL		1224						1	
				PROC. REF: AMM 32 42 01 000 801, AMM 32 42 01 400 801						
32-43-00-201	DETAILED INSPECTION OF THE BRAKE WEAR INDICATORS								Service	ATA:32
	MOS/MSC	O/C	17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.200	AFL		996						229	
				PROC. REF: AMM 32 43 00 220 801						
32-43-00-900-801-01	AUTOBRAKE SWITCH								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.645	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 47 000 801, AMM 32 43 47 400 801						
32-43-01-900-801-01	BRAKE CONTROL UNIT								Component	ATA:32
PN:GW415-7125-5	MOS/MSC	O/C	28-Apr-13	TSR 0					129.5	
SN:271	HRS		945.7	TSR 0					3155.6	
WC#: 32.570	AFL		365	TSR 0					860	
				PROC. REF: AMM 32 43 01 000 801, AMM 32 43 01 400 801						
32-43-05-900-801-01	LEFT NO.1 POSITION BRAKE PEDAL TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.575	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801						
32-43-05-900-801-02	LEFT NO.2 POSITION BRAKE PEDAL TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.575	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-43-05-900-801-03	RIGHT NO. 1 POSITION BRAKE PEDAL TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.580	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801						
32-43-05-900-801-04	RIGHT NO. 2 POSITION BRAKE PEDAL TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.580	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801						
32-43-07-201[S]	VISUAL CHECK OF THE BRAKE-PEDAL RETURN SPRING								Service	ATA:32
	MOS		28-Nov-23						2.5	
	HRS	500 (+50/-50)	4099.1						2.2	
WC#: 32.205	AFL		1223						2	
				PROC. REF: AMM 32 43 07 210 801						PKG:2
32-43-09-900-801-01	LEFT FORWARD BRAKE CONTROL VALVE								Component	ATA:32
PN:GW415-6150-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1530	HRS		0	TSN 0					4101.3	
WC#: 32.585	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801						
32-43-09-900-801-02	RIGHT FORWARD BRAKE CONTROL VALVE								Component	ATA:32
PN:GW415-6150-1	MOS/MSC	O/C	21-Dec-23						1.7	
SN:4577	HRS		4099.1	TSN 0					2.2	
WC#: 32.585	AFL		1223	TSN 0					2	
				PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801						
32-43-09-900-801-03	LEFT AFT BRAKE CONTROL VALVE								Component	ATA:32
PN:GW415-6150-1	MOS/MSC	O/C	21-Dec-23	TSN 0					1.7	
SN:4576	HRS		4099.1	TSN 0					2.2	
WC#: 32.590	AFL		1223	TSN 0					2	
				PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801						
32-43-09-900-801-04	RIGHT AFT BRAKE CONTROL VALVE								Component	ATA:32
PN:GW415-6150-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1733	HRS		0	TSN 0					4101.3	
WC#: 32.590	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-43-13-201 S	FUNCTIONAL TEST OF THE BRAKE DISK FOR DRIVE SLOT ENLARGEMENT								Service	ATA:32
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
				PROC. REF: AMM 32 43 13 720 801						PKG:32
32-43-13-301	RESTORATION (REPLATING) OF THE BRAKE ASSEMBLY - TORQUE TUBE								Service	ATA:32
	MOS	60 (+3m/-3m)	20-Dec-09		19-May-26	19-Aug-26	828 d (+92)	19-May-2026	169.7	
	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: AMM 32 43 13 840 801						PKG:34
32-43-13-900-801-01	NO. 1 MLG BRAKE								Component	ATA:32
PN:GW313-2001-3	MOS/MSC	O/C	31-May-19	TSO 0					56.4	
SN:2074	HRS		3134	TSO 0					967.3	
WC#: 32.595	AFL		982	TSO 0					243	
				PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801						
32-43-13-900-801-02	NO. 2 MLG BRAKE								Component	ATA:32
PN:GW313-2001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1629	HRS		0	TSN 0					4101.3	
WC#: 32.595	AFL		0	TSN 0					1225	
				PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801						
32-43-13-900-801-03	NO. 3 MLG BRAKE								Component	ATA:32
PN:GW313-2001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1618	HRS		0	TSN 0					4101.3	
WC#: 32.595	AFL		0	TSN 0					1225	
				PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801						
32-43-13-900-801-04	NO. 4 MLG BRAKE								Component	ATA:32
PN:GW313-2001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1621	HRS		0	TSN 0					4101.3	
WC#: 32.595	AFL		0	TSN 0					1225	
				PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801						
32-43-17-900-801-01	LEFT FORWARD BRAKE PRESSURE TRANSDUCER								Component	ATA:32
PN:GW415-1350-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:7649-9-9	HRS		0	TSN 0					4101.3	
WC#: 32.600	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-43-17-900-801-02	RIGHT FORWARD BRAKE PRESSURE TRANSDUCER								Component ATA:32
PN:GW415-1350-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:7649-9-7	HRS		0	TSN 0					4101.3
WC#: 32.600	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801					
32-43-17-900-801-03	LEFT AFT BRAKE PRESSURE TRANSDUCER								Component ATA:32
PN:GW415-1350-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:7649-9-11	HRS		0	TSN 0					4101.3
WC#: 32.605	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801					
32-43-17-900-801-04	RIGHT AFT BRAKE PRESSURE TRANSDUCER								Component ATA:32
PN:GW415-1350-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:7649-9-13	HRS		0	TSN 0					4101.3
WC#: 32.605	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801					
32-43-21-900-801-01	LOB SHUTTLE VALVE								Component ATA:32
PN:GW415-6200-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1615	HRS		0	TSN 0					4101.3
WC#: 32.610	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801					
32-43-21-900-801-02	LIB SHUTTLE VALVE								Component ATA:32
PN:GW415-6200-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1616	HRS		0	TSN 0					4101.3
WC#: 32.610	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801					
32-43-21-900-801-03	RIB SHUTTLE VALVE								Component ATA:32
PN:GW415-6200-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1605	HRS		0	TSN 0					4101.3
WC#: 32.615	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801					
32-43-21-900-801-04	ROB SHUTTLE VALVE								Component ATA:32
PN:GW415-6200-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1601	HRS		0	TSN 0					4101.3
WC#: 32.615	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-43-25-101	OPERATIONAL TEST OF THE BRAKE SHUTOFF VALVE								Service	ATA:32
	MOS		27-Nov-23					12-Jan-2025	2.5	
	HRS	500	4099.1		4599.1		497.8		2.2	
	AFL		1223						2	
				PROC. REF: AMM 32 43 25 710 801						
32-43-25-201 S	OPERATIONAL TEST OF THE BRAKE SHUTOFF VALVE								Service	ATA:32
	MOS		27-Nov-23						2.5	
	HRS	500 (+50/-50)	4099.1						2.2	
WC#: 32.210	AFL		1223						2	
				PROC. REF: AMM 32 43 25 710 801						PKG:2
32-43-29-900-801-01	CHECK, BRAKE CONTROL VALVE								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.470	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 29 000 801, AMM 32 43 29 400 801						
32-43-29-900-801-02	NO. 2 SYS PRESSURE CHECK, BRAKE CONTROL VALVE								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.625	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 43 29 000 801, AMM 32 43 29 400 801						
32-43-33-900-801-01	NO. 1 HYDRAULIC FUSE VALVE								Component	ATA:32
PN:GW415-1300-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1492	HRS		0	TSN 0					4101.3	
WC#: 32.630	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-43-33-900-801-02	NO. 2 HYDRAULIC FUSE VALVE								Component	ATA:32
PN:GW415-1300-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1488	HRS		0	TSN 0					4101.3	
WC#: 32.630	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
32-43-33-900-801-03	NO. 3 HYDRAULIC FUSE VALVE								Component	ATA:32
PN:GW415-1300-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1639	HRS		0	TSN 0					4101.3	
WC#: 32.630	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-43-33-900-801-04	NO. 4 HYDRAULIC FUSE VALVE								Component ATA:32
PN:GW415-1300-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1493	HRS		0	TSN 0					4101.3
WC#: 32.630	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-43-37-101	DISCARD THE NO. 2 BRAKE ACCUMULATOR, PART NO. GW415-1250-1								Service ATA:32
PN:GW415-1250-1	MOS		19-Mar-16					09-Mar-2053	94.7
SN:60185-2031NAE	HRS		1978.6	TAC 3216.1					2122.7
	AFL	8366	690	TAC 848	8208		6983		535
				PROC. REF: AMM 32 43 37 961 801					
32-43-37-900-801-05	NO. 2 BRAKE ACCUMULATOR								Component ATA:32
PN:GW415-1250-1	MOS/MSC	H/T	19-Mar-16	TSO 1					94.7
SN:60185-2031NAE	HRS		1978.6	TSN 3216.1, TSO 0					2122.7
WC#: 32.635	AFL		690	TSN 848, TSO 0					535
				PROC. REF: AMM 32 43 37 000 801, AMM 32 43 37 400 801					
32-43-41-900-801-01	PRESSURE GAUGE AND CHARGING VALVE								Component ATA:32
PN:GW415-1260-1	MOS/MSC	O/C	15-Dec-23	TSN 1					1.9
SN:23F1268	HRS		4099.1	TSN 0					2.2
WC#: 32.640	AFL		1223	TSN 0					2
				PROC. REF: AMM 32 43 41 000 801, AMM 32 43 41 400 801					
32-43-45-900-801-01	GROUND LIFT/AUTO BRAKE CONTROL PANEL								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.650	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 45 000 801, AMM 32 43 45 400 801					
32-43-49-900-801-01	NO.2 HYDRAULIC SYSTEM PRESSURE SWITCH								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.655	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 49 000 801, AMM 32 43 49 400 801					
32-43-51-900-801-01	NO.3 HYDRAULIC SYSTEM PRESSURE SWITCH								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.655	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 43 51 000 801, AMM 32 43 51 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-43-53-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WHEEL SPEED TRANSDUCERS CONNECTORS								Service	ATA:32
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 32 43 53 210 802						PKG:38
32-43-53-900-801-01	NO. 1 MLG WHEEL SPEED TRANSDUCER								Component	ATA:32
PN:GW415-1050-9	MOS/MSC	O/C	22-Jul-15	TSN 0					102.6	
SN:3451	HRS		1712.9	TSN 0					2388.4	
WC#: 32.660	AFL		624	TSN 0					601	
				PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801						
32-43-53-900-801-02	NO. 2 MLG WHEEL SPEED TRANSDUCER								Component	ATA:32
PN:GW415-1050-9	MOS/MSC	O/C	22-Jul-15	TSN 0					102.6	
SN:3561	HRS		1712.9	TSN 0					2388.4	
WC#: 32.660	AFL		624	TSN 0					601	
				PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801						
32-43-53-900-801-03	NO. 3 MLG WHEEL SPEED TRANSDUCER								Component	ATA:32
PN:GW415-1050-9	MOS/MSC	O/C	22-Jul-15	TSN 0					102.6	
SN:3567	HRS		1712.9	TSN 0					2388.4	
WC#: 32.660	AFL		624	TSN 0					601	
				PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801						
32-43-53-900-801-04	NO. 4 MLG WHEEL SPEED TRANSDUCER								Component	ATA:32
PN:GW415-1050-9	MOS/MSC	O/C	22-Jul-15	TSN 0					102.6	
SN:3572	HRS		1712.9	TSN 0					2388.4	
WC#: 32.660	AFL		624	TSN 0					601	
				PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801						
32-44-01-900-801-01	PARKING BRAKE VALVE								Component	ATA:32
PN:GW415-6225-5	MOS/MSC	O/C	19-Sep-23	TSR 0					4.7	
SN:167	HRS		4035.7	TSR 0					65.6	
WC#: 32.665	AFL		1204	TSR 0					21	
				PROC. REF: AMM 32 44 01 000 801, AMM 32 44 01 400 801						
32-44-05-101	DISCARD THE NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-1/-3								Service	ATA:32
PN:GW415-1200-3	MOS		11-Aug-15					10-Aug-2038	102	
SN:60188-0055	HRS		1727.1	TAC 4832					2374.2	
	AFL	5816	632	TAC 1742	4706		3481		593	
				PROC. REF: AMM 32 44 05 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-44-05-900-801-01	NO. 3 BRAKE ACCUMULATOR								Component ATA:32
PN:GW415-1200-3	MOS/MSC	H/T	11-Aug-15						102
SN:60188-0055	HRS		1727.1	TSN 4832					2374.2
WC#: 32.670	AFL		632	TSN 1742					593
				PROC. REF: AMM 32 44 05 000 801, AMM 32 44 05 400 801					
32-44-09-900-801-01	PARKING BRAKE HANDLE								Component ATA:32
PN:24700-107	MOS/MSC	O/C	27-Jul-16	TSN 23					90.5
SN:J34399-4	HRS		2078.9	TSN 0					2022.4
WC#: 32.675	AFL		719	TSN 0					506
				PROC. REF: AMM 32 44 09 000 801, AMM 32 44 09 400 801					
32-51-01-900-801-01	STEERING CONTROL UNIT								Component ATA:32
PN:GW415-8100-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:09-401	HRS		0	TSN 0					4101.3
WC#: 32.680	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 01 000 801, AMM 32 51 01 400 801					
32-51-05-900-801-01	STEERING CONTROL HANDWHEEL								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.690	AFL		0	TSN 0					1225
				PROC. REF: CMM 32-50-18, AMM 32 51 05 000 801, AMM 32 51 05 400 801					
32-51-09-900-801-01	LH RUDDER CONTROL RVDT								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.695	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 09 000 801, AMM 32 51 09 400 801					
32-51-09-900-801-02	RH RUDDER CONTROL RVDT								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.695	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 09 000 801, AMM 32 51 09 400 801					
32-51-13-900-801-01	STEERING SOLENOID VALVE								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.700	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 13 000 801, AMM 32 51 13 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
32-51-17-900-801-01	NOSE STEERING MANIFOLD								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.705	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 17 000 801, AMM 32 51 17 400 801					
32-51-21-900-801-01	NOSE LANDING GEAR (NLG) SHOCK STRUT STEERING ACTUATOR BOLT								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
32-51-21-900-802-01	LH SWIVEL, STEERING ACTUATOR MANIFOLD								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.710	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801					
32-51-21-900-802-02	RH SWIVEL, STEERING ACTUATOR MANIFOLD								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.710	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801					
32-51-21-900-803-01	LH STEERING ACTUATOR								Component ATA:32
PN:1287A0000-02	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:02146	HRS		0	TSN 0					4101.3
WC#: 32.715	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801					
32-51-21-900-803-02	RH STEERING ACTUATOR								Component ATA:32
PN:1288A0000-02	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:02143	HRS		0	TSN 0					4101.3
WC#: 32.715	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801					
32-51-29-900-801-01	PRESSURE STEERING CONTROL SWITCH								Component ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 32.685	AFL		0	TSN 0					1225
				PROC. REF: AMM 32 51 29 000 801, AMM 32 51 29 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-51-33-900-801-01	HYDRAULIC COMPENSATOR								Component	ATA:32
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 32.720	AFL		0	TSN 0					1225	
				PROC. REF: AMM 32 51 33 000 801, AMM 32 51 33 400 801						
32-60-00-201 S	VISUAL CHECK OF THE LANDING GEAR POSITION AND WARNING SYSTEM								Service	ATA:32
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 32.215	AFL		1223						2	
				PROC. REF: AMM 32 60 00 210 801						PKG:4
32-ZL-00-201 S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR (NLG) ASSEMBLY								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.220	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 20 00 210 801						PKG:58
32-ZL-00-202 S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - LH								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.225	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 10 00 210 801						PKG:58
32-ZL-00-203 S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - RH								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.230	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 10 00 210 801						PKG:58
32-ZL-00-204 S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - LH								Service	ATA:32
	MOS		27-Jul-16						90.5	
	HRS		2078.9						2022.4	
WC#: 32.235	AFL	900 (+50/-50)	719						506	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 20 00 210 802						PKG:60
32-ZL-00-205 S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - RH								Service	ATA:32
	MOS		27-Jul-16						90.5	
	HRS		2078.9						2022.4	
WC#: 32.240	AFL	900 (+50/-50)	719						506	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 20 00 210 802						PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
32-ZL-00-206 S	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - AFT								Service	ATA:32
	MOS		27-Jul-16						90.5	
	HRS		2078.9						2022.4	
WC#: 32.245	AFL	900 (+50/-50)	719						506	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 20 00 210 802						PKG:60
32-ZL-00-207 S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - LH								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.250	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 12 05 210 801						PKG:58
32-ZL-00-208 S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - RH								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.255	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 12 05 210 801						PKG:58
32-ZL-00-209 S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - LH								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.260	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 12 01 210 801						PKG:58
32-ZL-00-210 S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - RH								Service	ATA:32
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 32.265	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 32 12 01 210 801						PKG:58
321206-701 U	LH MLG DOOR CLOSED PROXIMITY SENSOR								Component	ATA:32
PN:GW415-3000-1	MOS/MSC	O/C	27-Jul-16						90.5	
SN:30010	HRS		2078.9						2022.4	
	AFL		719						506	
321206-702 U	RH MLG DOOR CLOSED PROXIMITY SENSOR								Component	ATA:32
PN:GW415-3000-1	MOS/MSC	O/C	27-Jul-16						90.5	
SN:30011	HRS		2078.9						2022.4	
	AFL		719						506	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
ASB A700-32-009	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF BRAKE CONTROL UNIT TO PREVENT POSSIBLE UNCOMMANDED BRAKING, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-011 PART (A)	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAR EMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-011 PART (B)	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAR EMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-011 PART (C)	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAR EMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-011 REV 01 PART (A)	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAR EMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-011 REV 01 PART (B)	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAR EMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
ASB A700-32-011 REV 01 PART (C)	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAR EMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-012 PART (A)	SPECIAL CHECK/REWORK - NOSE LANDING GEAR - EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-012 PART (B)	SPECIAL CHECK/REWORK - NOSE LANDING GEAR - EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-012 PART (C)	SPECIAL CHECK/REWORK - NOSE LANDING GEAR - EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-012 REV 01 PART (A)	SPECIAL CHECK/REWORK - NOSE LANDING GEAR - EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-012 REV 01 PART (B)	SPECIAL CHECK/REWORK - NOSE LANDING GEAR - EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
ASB A700-32-012 REV 01 PART (C)	SPECIAL CHECK/REWORK - NOSE LANDING GEAR - EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
ASB A700-32-017	SPECIAL CHECK/REWORK - BRAKE CONTROL SYSTEM - REPLACEMENT OF BRAKE CONTROL UNITS (BCU) WITH SPECIFIC SERIAL NUMBER (A/C 9138, 9145 TO 9147, 9150, 9151 AND 9159), ALERT SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-32-019 PART (A)	SPECIAL CHECK/REWORK - NOSE WHEELS AND TIRES - INSPECT AND REPLACE DEFECTIVE NOSE LANDING GEAR (NLG) TIRES (A/C 9002 TO 9126 AND 9128 TO 9175), ALERT SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-32-019 PART (B)	SPECIAL CHECK/REWORK - NOSE WHEELS AND TIRES - INSPECT AND REPLACE DEFECTIVE NOSE LANDING GEAR (NLG) TIRES (A/C 9002 TO 9126 AND 9128 TO 9175), ALERT SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2006-18-08	APPLIANCE AD - GOODYEAR AVIATION TIRES - PART NUMBER 217K22-1 - INSPECTION TO DETERMINE SERIAL NUMBER (S/N), AND REPLACEMENT								AD	ATA:32
	DAYS/MSC	-	19-Dec-09						5167 d	
	HRS		0						4101.3	
	AFL		0						1225	
Category: APPLIANCE										
FAA 2012-17-01[U]	GOODYEAR AVIATION TIRES: TO PREVENT MLG TIRE FAILURE DURING TAKEOFF AND LANDING								AD	ATA:32
	MOS/MSC	-	26-Dec-14						109.5	
	HRS		1518.9						2582.4	
	AFL		566						659	
FAA 2019-03-22[S]	LANDING GEAR - SAFETY DEVICE MODIFICATION AT NOSE GEAR RETRACTION ACTUATOR TO MAIN FITTING JOINT								AD	ATA:32
	MOS/MSC	-	17-Jul-19						54.8	
	HRS		3188.8						912.5	
	AFL		996						229	
FAA 2019-03-22 PARA (G)	REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE AND ACCOMPLISH THE TASKS SPECIFIED IN AWL								AD	ATA:32
	DAYS/MSC	-	17-Jul-19						1670 d	
	HRS		3188.8						912.5	
	AFL		996						229	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
FAA 2019-03-22 PARA (H) (1)	PERFORM A GVI FOR DAMAGE OF THE COTTER PIN RETAINING THE BOLT THAT SECURES THE NLG RETRACTION ACTUATOR TO THE NLG STRUT, AND A GVI OF THE MODIFICATION NUMBER SHOWN ON THE IDENTIFICATION PLATE FOR THE NLG STRUT, AND, IF APPLICABLE, MARK THE CORRECT MODIFICATION NUMBER ON THE IDENTIFICATION PLATE OF THE NLG STRUT AND PERFORM THE MODIFICATION OF THE NLG RETRACTION ACTUATOR HARDWARE (IF DAMAGE TO THE COTTER PIN IS PRESENT)								AD	ATA:32
	MOS/MSC	-	17-Jul-19						54.8	
	HRS		3188.8						912.5	
	AFL		996						229	
FAA 2020-03-21	LANDING GEAR - TRAILING ARM ASSEMBLY AXLE BORE CORROSION								AD	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-03-21 PARA (H) LH	INSPECT THE LEFT HAND MLG TRAILING ARM ASSEMBLIES TO DETERMINE IF AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED								AD	ATA:32
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-03-21 PARA (H) RH	INSPECT THE RIGHT HAND MLG TRAILING ARM ASSEMBLIES TO DETERMINE IF AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED								AD	ATA:32
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-03-21 PARA (I) &(J) LH	ACCOMPLISH A DETAILED INSPECTION FOR SURFACE FINISH DISCREPANCIES ON THE INNER DIAMETER OF THE AFFECTED MLG TRAILING ARM ASSEMBLY AXLE BORE (IF, DURING THE INSPECTION OR REVIEW REQUIRED BY PARA (H), IT IS DETERMINED THAT AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED) AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS								AD	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-03-21 PARA (I) &(J) RH	ACCOMPLISH A DETAILED INSPECTION FOR SURFACE FINISH DISCREPANCIES ON THE INNER DIAMETER OF THE AFFECTED MLG TRAILING ARM ASSEMBLY AXLE BORE (IF, DURING THE INSPECTION OR REVIEW REQUIRED BY PARA (H), IT IS DETERMINED THAT AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED) AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS								AD	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
FAA 2020-03-21 PARA (K)	REPLACE THE PRIMER AND PAINT AND APPLY THE CORROSION PREVENTIVE COMPOUND ON THE INNER DIAMETER OF THE AXLE BORE ON ALL AFFECTED MLG TRAILING ARM ASSEMBLIES								AD	ATA:32
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-03-21 PARA (M)	SUBMIT A REPORT TO BOMBARDIER OF POSITIVE FINDINGS OF THE INSPECTIONS REQUIRED BY PARAGRAPHS (I) AND (J) OF THIS AD								AD	ATA:32
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2023-24-08	NOSE WHEEL STEERING SELECTOR VALVE (SSV) REPLACEMENT								AD	ATA:32
	MOS	T:66	EBT		06-Aug-29 *		NEW REQMT	06-Aug-2029		
	HRS	T:3200	EBT		7358.2 *					
	AFL									
MODSUM IS700-32-0001U REV A	INSTALL - MLG DOOR, OUTBOARD, HINGE PIN REPLACEMENT, MODIFICATION SUMMARY								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
MODSUM IS700-32-0001U REV B	INSTL-MLG DOOR, OUTBOARD, HINGE PIN REPLACEMENT, MODIFICATION SUMMARY								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
MODSUM IS700-32-0002U REV A	KIT - INTRO OF ADDITIONAL HYDRAULIC LINE SUPPORT - MLG BAY (EFFECTIVITY 9002-9999), MODIFICATION SUMMARY								Bulletin	ATA:32
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-32-006	MODIFICATION - LANDING GEAR EMERGENCY EXTENSION - INSTALLATION OF A NEW SUPPORT PLATE ON THE SHUTOFF AND DUMP VALVE ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-007	MODIFICATION - NOSE GEAR EXTENSION AND RETRACTION - DOOR UPLOCK FITTING REPLACEMENT (A/C 9002 TO 9085, 9091 TO 9093), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-007 REV 01	MODIFICATION - NOSE GEAR EXTENSION AND RETRACTION - DOOR UPLOCK FITTING REPLACEMENT (A/C 9002 TO 9085, 9091 TO 9093), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-007 REV 02	MODIFICATION - NOSE GEAR EXTENSION AND RETRACTION - DOOR UPLOCK FITTING REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-008	SPECIAL CHECK/MODIFICATION - NOSE-GEAR DOOR SYSTEM - FORWARD DOOR SPRING, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-010	REWORK - MAIN LANDING GEAR (MLG) - SERIALIZATION OF MLG SIDE STAY PIN (A/C 9002 TO 9173), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-010 REV 01	REWORK - MAIN LANDING GEAR (MLG) - SERIALIZATION OF MLG SIDE STAY PIN (A/C 9002 TO 9173), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-013	SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR - INSTALLATION OF NINE-PIECE RETAINING RING ON NOSE LANDING GEAR SHOCK STRUT, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-014	MODIFICATION/REWORK - MAIN LANDING GEAR (MLG) - TO PREVENT INGRESS OF MOISTURE TO THE MLG SIDE BRACE INDICATOR HOUSING, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-015	SPECIAL CHECK/REWORK - BRAKE CONTROL SYSTEM - CHECK TORQUE AND SAFETY HYDRAULIC LINES WITH SUPPORT HARDWARE, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-015 REV 01	SPECIAL CHECK/REWORK - BRAKE CONTROL SYSTEM - CHECK TORQUE AND SAFETY HYDRAULIC LINES WITH SUPPORT HARDWARE, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-016	MODIFICATION - BRAKE CONTROL SYSTEM - PART NO. CHANGE OF THE BRAKE CONTROL UNIT TO GW415-7125-5, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-018	MODIFICATION - GENERAL - PREVENT INGRESS OF FOREIGN OBJECT DAMAGE (FOD) IN THE MAIN LANDING GEAR (MLG) WHEEL WELL (9002 TO 9126 AND 9128 TO 9999)., SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-32-021	SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES SYSTEM - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND (A/C 9173, 9175, 9177, 9179, 9181, 9183, 9184, 9185, 9193, 9194, 9199, 9220, 9230, 9234, 9235, 9236, 9238, 9240, 9242, 9247, 9250, 9252, 9256, 9258, 9262, 9264, 9268, 9270, 9272, 9274 TO 9286, 9290 TO 9297, 9300 TO 9304, 9306 AND 9309), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-021 REV 01	SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES SYSTEM - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND (A/C 9002 TO 9302), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-021 REV 02	SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-021 REV 03	ICA - SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-022	MODIFICATION - MAIN GEAR DOOR SYSTEM - INSTALLATION OF IMPROVED MLG DOOR SURROUND FAIRING CLIP (EFFECTIVITY 9002 TO 9272), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-32-023	MODIFICATION - NOSE-GEAR DOOR SYSTEM - IMPROVED INSTALLATION OF THE NLG DOOR PROXIMITY SWITCH TARGET, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-32-024 PART (A)	MODIFICATION - MAIN LANDING GEAR (MLG) - REPLACE SUSPECT SHOCK STRUT PINS (A/C 9002 TO 9009, 9016, 9019, 9020, 9024, 9060, 9062 AND 9104), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-024 PART (B)	MODIFICATION - MAIN LANDING GEAR (MLG) - REPLACE SUSPECT SHOCK STRUT PINS (A/C 9002 TO 9009, 9016, 9019, 9020, 9024, 9060, 9062 AND 9104), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-32-027	SPECIAL CHECK/MODIFICATION - LANDING-GEAR CONTROL SYSTEM - REPLACEMENT OF LANDING-GEAR SELECTOR-VALVE, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	10-Apr-12						142
	HRS		431.8						3669.5
	AFL		154						1071

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-028	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER - HARNESS, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-028 REV 01	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER- HARNESS, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	22-Jul-15						102.6
	HRS		1712.9						2388.4
	AFL		624						601
SB 700-32-028 REV 02	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER- HARNESS, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-029	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-32-029 PART (A)	INSPECTION MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-32-029 PART (B)	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN MODIFICATION								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-32-030	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-030 PART (A)	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN MODIFICATION - MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO.								Bulletin ATA:32
	MOS		EFF					05-Nov-2035	
	HRS								
	AFL	T:3500	EFF		4043 *		2818		
SB 700-32-030 PART (B)	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN MODIFICATION - REMOVAL - INSTALLATION OF NEW ACCUMULATOR								Bulletin ATA:32
	MOS		EFF					05-Nov-2035	
	HRS								
	AFL	T:3500	EFF		4043 *		2818		
SB 700-32-031	SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM -POSSIBILITY OF UNEXPECTED BRAKE RELEASING AT LOW TAXI SPEED, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-031 PART (A)	INSPECTION SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM -POSSIBILITY OF UNEXPECTED BRAKE RELEASING AT LOW TAXI SPEED, SERVICE BULLETIN OF THE WHEEL SPEED TRANSDUCERS								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-031 PART (B)	REPLACEMENT SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM -POSSIBILITY OF UNEXPECTED BRAKE RELEASING AT LOW TAXI SPEED, SERVICE BULLETIN OF THE WHEEL SPEED TRANSDUCERS								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-032	ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-032 PART (A)	INSPECTION ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-032 PART (B)	REMOVE ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN AND REPLACE THE BCU								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-033	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-1 WITH NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-3, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	11-Aug-15						102
	HRS		1727.1						2374.2
	AFL		632						593
SB 700-32-034	MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF WHEEL SPEED TRANSDUCER PART NO 140-209-4 (GW415-1050-9), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	22-Jul-15						102.6
	HRS		1712.9						2388.4
	AFL		624						601
SB 700-32-034 REV 01	SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF IMPROVED WHEEL SPEED TRANSDUCERS, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-034 REV 01 PART (A)	INSPECTION SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF IMPROVED WHEEL SPEED TRANSDUCERS, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-034 REV 01 PART (B)	MODIFICATION SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF IMPROVED WHEEL SPEED TRANSDUCERS, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-034 REV 02	MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF WHEEL SPEEDTRANSDUCER PART NO 140-209-4 (GW415-1050-9), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-034 REV 02 PART (A)	ACCOMPLISH MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF WHEEL SPEEDTRANSDUCER PART NO 140-209-4 (GW415 -1050-9), SERVICE BULLETIN INSPECTION								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-034 REV 02 PART (B)	ACCOMPLISH MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF WHEEL SPEEDTRANSDUCER PART NO 140-209-4 (GW415 -1050-9), SERVICE BULLETIN MODIFICATION								Bulletin ATA:32
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-32-035	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	20-Aug-15						101.7
	HRS		1731.4						2369.9
	AFL		635						590
SB 700-32-035 PART (A)	VISUAL INSPECTION ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT								Bulletin ATA:32
	MOS/MSC	-	20-Aug-15						101.7
	HRS		1731.4						2369.9
	AFL		635						590
SB 700-32-035 PART (B)	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK								Bulletin ATA:32
	MOS/MSC	-	20-Aug-15						101.7
	HRS		1731.4						2369.9
	AFL		635						590
SB 700-32-035 PART (C)	INSTALLATION ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT								Bulletin ATA:32
	MOS/MSC	-	20-Aug-15						101.7
	HRS		1731.4						2369.9
	AFL		635						590

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-035 REV 01	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	05-Oct-15						100.2
	HRS		1796.5						2304.8
	AFL		657						568
SB 700-32-035 REV 01 PART (A)	VISUAL INSPECTION ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT								Bulletin ATA:32
	MOS/MSC	-	05-Oct-15						100.2
	HRS		1796.5						2304.8
	AFL		657						568
SB 700-32-035 REV 01 PART (B)	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK								Bulletin ATA:32
	MOS/MSC	-	05-Oct-15						100.2
	HRS		1796.5						2304.8
	AFL		657						568
SB 700-32-035 REV 01 PART (C)	INSTALLATION ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT								Bulletin ATA:32
	MOS/MSC	-	05-Oct-15						100.2
	HRS		1796.5						2304.8
	AFL		657						568
SB 700-32-035 REV 02	SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-035 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN VISUAL INSPECTION OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-035 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-035 REV 02 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN INSTALLATION OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-037	MODIFICATION - PARKING BRAKE SYSTEM - REPLACEMENT OF THE PARK BRAKE HANDLE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-32-037 PART (A)	ACCOMPLISH MODIFICATION - PARKING BRAKE SYSTEM - REPLACEMENT OF THE PARK BRAKE HANDLE ASSEMBLY, SERVICE BULLETIN VISUAL INSPECTION OF THE EMERGENCY/PARKING BRAKE HANDLE ASSEMBLY								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-32-037 PART (B)	REPLACEMENT MODIFICATION - PARKING BRAKE SYSTEM - REPLACEMENT OF THE PARK BRAKE HANDLE ASSEMBLY, SERVICE BULLETIN OF THE EMERGENCY/PARKING BREAK HANDLE ASSEMBLY								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-32-038	REPAIR - NOSE WHEEL STEERING CONTROL SYSTEM - NOSEWHEEL-STEERING CONTROL SYSTEM - REPAIR OF STEERING CYLINDER LVDT CONDUIT, PART NO. 9070A0036-01, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-32-038 REV 01	REPAIR - NOSE WHEEL STEERING CONTROL SYSTEM - NOSEWHEEL-STEERING CONTROL SYSTEM - REPAIR OF STEERING CYLINDER LVDT CONDUIT, PART NO. 9070A0036-01, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 32 - LANDING GEAR									
SB 700-32-039	SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-039 REV 01), SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-039 PART A	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-039 REV 01), SERVICE BULLETIN INSPECTION OF PART NUMBER AND SERIAL NUMBER								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-039 PART B	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-039 REV 01), SERVICE BULLETIN FIRST INSPECTION								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-039 PART C	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-039 REV 01), SERVICE BULLETIN SECOND INSPECTION								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-039 PART D	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-039 REV 01), SERVICE BULLETIN PRIMER AND PAINT REPLACEMENT								Bulletin ATA:32
	MOS/MSC	-	17-Jul-19						54.8
	HRS		3188.8						912.5
	AFL		996						229
SB 700-32-039 REV 01	SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-32-039 REV 01 PART A	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN INSPECTION OF PART NUMBER AND SERIAL NUMBER								Bulletin ATA:32
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
SB 700-32-039 REV 01 PART B	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN FIRST INSPECTION								Bulletin	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-32-039 REV 01 PART C	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN SECOND INSPECTION								Bulletin	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-32-039 REV 01 PART D	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN PRIMER AND PAINT REPLACEMENT								Bulletin	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-32-040	MODIFICATION - BRAKE CONTROL SYSTEM - LH AND RH ASSEMBLY REPLACEMENT OF THE SWIVEL JOINT ASSEMBLIES, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-32-040 REV 01	MODIFICATION - BRAKE CONTROL SYSTEM - LH AND RH ASSEMBLY REPLACEMENT OF THE SWIVEL JOINT ASSEMBLIES, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-32-041	MODIFICATION - NOSE LANDING GEAR (NLG) - LOWER DRAG BRACE GROUND LOCK PIN ERROR PROOFING, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-32-041 REV 01	MODIFICATION - NOSE LANDING GEAR (NLG) - LOWER DRAG BRACE GROUND LOCK PIN ERROR PROOFING, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
SB 700-32-042	MODIFICATION - MLG - MAIN LANDING GEAR ASSEMBLY IMPROVED RESISTANCE TO WATER INGRESS, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-32-042 REV 01	MODIFICATION - MLG - MAIN LANDING GEAR ASSEMBLY IMPROVED RESISTANCE TO WATER INGRESS, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-32-043	SPECIAL CHECK - BRAKE CONTROL SYSTEM - DETERMINATION OF HYDRAULIC SYSTEM NO. 2 AND NO. 3 BRAKE ACCUMULATOR CYCLES (PART NO. GW415-1250 AND GW415-1200), SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-	10-Nov-21						27	
	HRS		3663.4						437.9	
	AFL		1113						112	
SB 700-32-043 REV 01	SPECIAL CHECK - BRAKE CONTROL SYSTEM - DETERMINATION OF HYDRAULIC SYSTEM NO. 2 AND NO. 3 BRAKE ACCUMULATOR CYCLES (PART NO. GW415-1250 AND GW415-1200), SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-32-043 REV 02	SPECIAL CHECK - BRAKE CONTROL SYSTEM - DETERMINATION OF HYDRAULIC SYSTEM NO. 2 AND NO. 3 BRAKE ACCUMULATOR CYCLES (PART NO. GW415-1250 AND GW415-1200), SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-32-044	MODIFICATION - NOSEWHEEL-STEERING CONTROL SYSTEM - REPLACEMENT OF THE STEERING SOLENOID VALVE, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-32-044 REV 01	MODIFICATION - NOSEWHEEL-STEERING CONTROL SYSTEM - REPLACEMENT OF THE STEERING SOLENOID VALVE, SERVICE BULLETIN								Bulletin	ATA:32
	MOS	T:60	EFF		24-Nov-27 *		1382 d	24-Nov-2027		
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 32 - LANDING GEAR										
SB 700-32-045	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF BRAKE CONTROL UNIT (BCU), SERVICE BULLETIN								Bulletin	ATA:32
	MOS	T:48	EFF		25-May-26 *		834 d	25-May-2026		
	HRS									
	AFL									
SB 700-32-046	MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF RESTRICTOR ON THE CYLINDER PORT OF BRAKE SHUT-OFF VALVE (BSOV), SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
SB M-DT 700-32-022 U	MESSIER-DOWTY-NOSE LANDING GEAR WHEEL ASSEMBLY REPLACE GREASE SEAL WITH A NEW GREASE SEAL AND WATER SHIELD, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB M-DT SB700-32-032 U REV 01	MESSIER-DOWTY - BD700-1A10, BD700-1A11 - NLG SHOCK STRUT ASSEMBLY REMOVAL OF A SECTION OF THE SHRINKABLE TUBING, SERVICE BULLETIN								Bulletin	ATA:32
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	
ATA 33 - LIGHTS										
33-00-00-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING TIP LIGHTS AND COMPONENTS CONNECTORS AND GROUND STUDS								Service	ATA:33
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 33 00 00 210 801						PKG:38
33-11-01-900-801-01	LEFT 7.5A CONVERTER								Component	ATA:33
PN:GC531-0001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1117	HRS		0	TSN 0					4101.3	
WC#: 33.025	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
33-11-01-900-801-02	RIGHT FORWARD 7.5A CONVERTER								Component ATA:33
PN:GC531-0001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1224	HRS		0	TSN 0					4101.3
WC#: 33.030	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
33-11-01-900-801-03	RIGHT AFT 7.5A CONVERTER								Component ATA:33
PN:GC531-0001-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1221	HRS		0	TSN 0					4101.3
WC#: 33.035	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
33-11-01-900-802-01	LH 15A DC/DC CONVERTER								Component ATA:33
PN:GC531-0002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0771	HRS		0	TSN 0					4101.3
WC#: 33.040	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802					
33-11-01-900-802-02	RH 15A DC/DC CONVERTER								Component ATA:33
PN:GC531-0002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0779	HRS		0	TSN 0					4101.3
WC#: 33.040	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802					
33-11-01-900-803-01	LH 0.1A DC/AC INVERTER								Component ATA:33
PN:GC531-0003-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0766	HRS		0	TSN 0					4101.3
WC#: 33.045	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802					
33-11-01-900-803-02	RH 0.1A DC/AC INVERTER								Component ATA:33
PN:GC531-0003-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0843	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802					
33-11-01-900-803-03	LH 0.5A DC/AC INVERTER								Component ATA:33
PN:GC531-0004-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0811	HRS		0	TSN 0					4101.3
WC#: 33.050	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 33 - LIGHTS										
33-11-01-900-803-04	RH 0.5A DC/AC INVERTER								Component	ATA:33
PN:GC531-0004-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0817	HRS		0	TSN 0					4101.3	
WC#: 33.050	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802						
33-13-05-900-801-01	LH MAP READING LIGHT								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 13 05 000 801, AMM 33 13 05 400 801						
33-13-05-900-801-02	RH MAP READING LIGHT								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.055	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 13 05 000 801, AMM 33 13 05 400 801						
33-24-50-601 U S	OPERATIONAL TEST OF THE ORDINANCE SIGNS								Service	ATA:33
	MOS	15	22-Nov-23						2.6	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
33-31-01-900-801-01	UPPER TAIL NAVIGATION LIGHT ASSEMBLY								Component	ATA:33
PN:2LA006419-22	MOS/MSC	O/C	19-Mar-16	TSN 14					94.7	
SN:2990021	HRS		1978.6	TSN 0					2122.7	
WC#: 33.060	AFL		690	TSN 0					535	
				PROC. REF: AMM 33 31 01 000 801, AMM 33 31 01 400 801						
33-31-09-900-801-01	APU COMPARTMENT LIGHT								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.065	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 31 09 000 801, AMM 33 31 09 400 801						
33-31-13-900-801-01	NO. 1 MAIN LIGHT								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.070	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 31 13 000 801, AMM 33 31 13 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
33-31-13-900-801-02	NO. 2 MAIN LIGHT								Component ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 33.070	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 31 13 000 801, AMM 33 31 13 400 801					
33-31-13-900-801-03	NO. 3 MAIN LIGHT								Component ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 33.070	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 31 13 000 801, AMM 33 31 13 400 801					
33-31-13-900-801-04[U]	AFT EQUIPMENT BAY SERVICE LIGHT ASSEMBLY								Component ATA:33
PN:2LA002607-22	MOS/MSC	O/C	12-Jan-24	TSN 0					1
SN:5727697	HRS		4100.9	TSN 0					.4
	AFL		1224	TSN 0					1
33-31-17-900-801-01	LH FS381 AUTO SHUT-OFF BOX								Component ATA:33
PN:GE534-0001-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1513575	HRS		0	TSN 0					4101.3
WC#: 33.075	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801					
33-31-17-900-801-02	LH FS909 AUTO SHUT-OFF BOX								Component ATA:33
PN:GE534-0001-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1499826	HRS		0	TSN 0					4101.3
WC#: 33.080	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801					
33-31-17-900-801-03	RH DVC AUTO SHUT-OFF LIGHT								Component ATA:33
PN:GE534-0001-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1505827	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
33-40-01-900-801-01	EXTERNAL LIGHTS CONTROL PANEL								Component ATA:33
PN:BI7003430004-003	MOS/MSC	O/C	14-Feb-11						155.9
SN:221798	HRS		7.4						4093.9
	AFL		4						1221
				PROC. REF: AMM 33 40 01 000 801, AMM 33 40 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 33 - LIGHTS										
33-41-01-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING LANDING AND TAXI LIGHTS CONNECTORS								Service	ATA:33
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 33 41 01 210 801						PKG:38
33-41-01-900-801-01	LH LANDING LIGHT LENS								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801						
33-41-01-900-801-02	RH LANDING LIGHT LENS								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.085	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801						
33-41-01-900-802-01	LH WING LANDING/TAXI LIGHT								Component	ATA:33
PN:1X4455178-50	MOS/MSC	O/C	27-Jul-16	TSN 0					90.5	
SN:3394815	HRS		2078.9	TSN 0					2022.4	
WC#: 33.090	AFL		719	TSN 0					506	
				PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801						
33-41-01-900-802-02	RH WING LANDING/TAXI LIGHT								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.090	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801						
33-41-03-900-801-01	PULSE CONTROL UNIT								Component	ATA:33
PN:1152B	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:QR00451	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 41 03 000 801, AMM 33 41 03 400 801						
33-41-05-900-801-01	LH NLG LIGHT								Component	ATA:33
PN:2LA409800-05	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1384	HRS		0	TSN 0					4101.3	
WC#: 33.095	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 41 05 000 801, AMM 33 41 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
33-41-05-900-801-02	RH NLG LIGHT								Component ATA:33
PN:2LA409800-05	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1352	HRS		0	TSN 0					4101.3
WC#: 33.095	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 41 05 000 801, AMM 33 41 05 400 801					
33-42-01-900-801-01	LH WING NAVIGATION (RED) LIGHT								Component ATA:33
PN:2LA007181-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1509249	HRS		0	TSN 0					4101.3
WC#: 33.105	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 42 01 000 801, AMM 33 42 01 400 801					
33-42-01-900-801-02	RH WING NAVIGATION (GREEN) LIGHT								Component ATA:33
PN:2LA007182-22	MOS/MSC	O/C	16-Feb-22	TSN 5					23.8
SN:5278959	HRS		3721.3	TSN 0					380
WC#: 33.100	AFL		1124	TSN 0					101
				PROC. REF: AMM 33 42 01 000 801, AMM 33 42 01 400 801					
33-42-09-900-801-01	NOSE GEAR BAY/TAIL LIGHT								Component ATA:33
PN:2LA006419-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1495601	HRS		0	TSN 0					4101.3
WC#: 33.110	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 42 09 000 801, AMM 33 42 09 400 801					
33-42-13-900-801-01	FAILURE IND (MID CENTER FUSE) BOX								Component ATA:33
PN:8ES007656-22	MOS/MSC	O/C	21-Jun-11						151.7
SN:1752254	HRS		43.3						4058
WC#: 33.115	AFL		15						1210
				PROC. REF: AMM 33 42 13 000 801, AMM 33 42 13 400 801					
33-43-01-900-801-01	LH STROBE WING LIGHT								Component ATA:33
PN:2LA006178-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1480220	HRS		0	TSN 0					4101.3
WC#: 33.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801					
33-43-01-900-801-02	RH STROBE WING LIGHT								Component ATA:33
PN:2LA006178-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1499088	HRS		0	TSN 0					4101.3
WC#: 33.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 33 - LIGHTS										
33-43-01-900-801-03	STROBE WING LIGHT								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 33.125	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801						
33-43-05-900-801-01	STROBE (TAIL) LIGHT								Component	ATA:33
PN:2LA006181-22	MOS/MSC	O/C	23-Feb-12	TSN 0					143.6	
SN:1043	HRS		398.6	TSN 0					3702.7	
WC#: 33.130	AFL		144	TSN 0					1081	
				PROC. REF: AMM 33 43 05 000 801, AMM 33 43 05 400 801						
33-43-09-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE LOWER STROBE/ANTICOLLISION LIGHT CONNECTOR								Service	ATA:33
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 33 43 09 210 801						PKG:38
33-43-09-900-801-01	UPPER STROBE, ANTICOLLISION FUSELAGE LIGHT								Component	ATA:33
PN:2LA003849-22	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7	
SN:4901882	HRS		3474.7	TSN 0					626.6	
WC#: 33.135	AFL		1069	TSN 0					156	
				PROC. REF: AMM 33 43 09 000 801, AMM 33 43 09 400 801						
33-43-09-900-801-02	LOWER STROBE, ANTICOLLISION FUSELAGE LIGHT								Component	ATA:33
PN:2LA003849-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1520252	HRS		0	TSN 0					4101.3	
WC#: 33.135	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 43 09 000 801, AMM 33 43 09 400 801						
33-44-01-900-801-01	LH WING/TAIL STROBE LIGHT POWER SUPPLY								Component	ATA:33
PN:8ES007046-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1517352	HRS		0	TSN 0					4101.3	
WC#: 33.140	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 44 01 000 801, AMM 33 44 01 400 801						
33-44-01-900-801-02	RH WING/TAIL STROBE LIGHT POWER SUPPLY								Component	ATA:33
PN:8ES007046-22	MOS/MSC	O/C	04-Apr-13	TSN 0					130.2	
SN:2275175	HRS		902.7	TSN 0					3198.6	
WC#: 33.140	AFL		347	TSN 0					878	
				PROC. REF: AMM 33 44 01 000 801, AMM 33 44 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
33-44-01-900-801-03	TAIL WING/TAIL STROBE LIGHT POWER SUPPLY								Component ATA:33
PN:8ES456038-03	MOS/MSC	O/C	23-Feb-12	TSN 0					143.6
SN:2113461	HRS		398.6	TSN 0					3702.7
WC#: 33.145	AFL		144	TSN 0					1081
				PROC. REF: AMM 33 44 01 000 801, AMM 33 44 01 400 801					
33-44-05-900-801-01	UPPER STROBE/ANTICOLLISION LIGHT POWER SUPPLY								Component ATA:33
PN:8ES006794-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1530169	HRS		0	TSN 0					4101.3
WC#: 33.150	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 44 05 000 801, AMM 33 44 05 400 801					
33-44-05-900-801-02	LOWER STROBE/ANTICOLLISION LIGHT POWER SUPPLY								Component ATA:33
PN:8ES006794-22	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1530168	HRS		0	TSN 0					4101.3
WC#: 33.150	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 44 05 000 801, AMM 33 44 05 400 801					
33-45-01-900-801-01	LH SCANLITE WING								Component ATA:33
PN:2LA455189-50	MOS/MSC	O/C	27-Jul-16	TSN 7					90.5
SN:3528783	HRS		2078.9	TSN 0					2022.4
WC#: 33.155	AFL		719	TSN 0					506
				PROC. REF: AMM 33 45 01 000 801, AMM 33 45 01 400 801					
33-45-01-900-801-02	RH SCANLITE WING								Component ATA:33
PN:2LA455189-50	MOS/MSC	O/C	27-Jul-16	TSN 1					90.5
SN:3088118	HRS		2078.9	TSN 0					2022.4
WC#: 33.155	AFL		719	TSN 0					506
				PROC. REF: AMM 33 45 01 000 801, AMM 33 45 01 400 801					
33-46-01-900-801-01	LH LOGO LIGHT								Component ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 33.160	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 46 01 000 801, AMM 33 46 01 400 801					
33-46-01-900-801-02	RH LOGO LIGHT								Component ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 33.160	AFL		0	TSN 0					1225
				PROC. REF: AMM 33 46 01 000 801, AMM 33 46 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 33 - LIGHTS										
33-50-00-201[S]	FUNCTIONAL TEST OF THE EMERGENCY LIGHTS POWER-SUPPLIES								Service	ATA:33
	MOS	15 (+3m/-3m)	28-Nov-23						2.5	
	HRS		4099.1						2.2	
WC#: 33.015	AFL		1223						2	
				PROC. REF: AMM 33 51 09 720 801						PKG:31
33-50-00-202[S]	OPERATIONAL TEST OF THE EMERGENCY LIGHTS								Service	ATA:33
	MOS		22-Nov-23						2.6	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 33.020	AFL		1223						2	
				PROC. REF: AMM 33 51 00 710 801						PKG:4
33-51-01-900-801-01	LH PASSENGER DOOR LIGHT								Component	ATA:33
PN:GE535-0001-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1508354	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 51 01 000 801, AMM 33 51 01 400 801						
33-51-05-900-801-01	RH OVER WING L/E EMERGENCY EXIT LIGHT								Component	ATA:33
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 33 51 05 000 801, AMM 33 51 05 400 801						
33-51-05-900-801-02	FS797-813 EMERGENCY LIGHT								Component	ATA:33
PN:GE535-0001-5	MOS/MSC	O/C	22-Jul-15	TSN 0					102.6	
SN:3105580	HRS		1712.9	TSN 0					2388.4	
	AFL		624	TSN 0					601	
				PROC. REF: GENERIC NO REF						
33-51-09-900-801-01	NO.1 EMERGENCY LIGHTING POWER SUPPLY								Component	ATA:33
PN:8ES409800-00	MOS/MSC	O/C	21-Jan-22	TSN 145					24.7	
SN:004444	HRS		3689.6	TSN 3689.6					411.7	
	AFL		1117	TSN 1117					108	
				PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
33-51-09-900-801-02	NO.2 EMERGENCY LIGHTING POWER SUPPLY								Component ATA:33
PN:8ES409800-00	MOS/MSC	O/C	29-Aug-23	TSN 0					5.4
SN:5938977	HRS		4030.9	TSN 0					70.4
	AFL		1200	TSN 0					25
				PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801					
33-51-09-900-801-03	NO.3 EMERGENCY LIGHTING POWER SUPPLY								Component ATA:33
PN:8ES409800-00	MOS/MSC	O/C	21-Jan-22						24.7
SN:004260	HRS		3689.6						411.7
	AFL		1117						108
				PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801					
33-51-09-900-801-04	NO.4 EMERGENCY LIGHTING POWER SUPPLY								Component ATA:33
PN:8ES409800-00	MOS/MSC	O/C	21-Jan-22	TSR 0					24.7
SN:004263	HRS		3689.6	TSR 0					411.7
	AFL		1117	TSR 0					108
				PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801					
33-51-50-601 U S	OPERATIONAL TEST OF THE CABIN EMERGENCY LIGHTING SYSTEM								Service ATA:33
	MOS	15	22-Nov-23						2.6
	HRS		4099.1						2.2
	AFL		1223						2
									PKG:31
330000-701 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653187	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-702 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653188	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-703 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653189	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330000-704 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653190	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-705 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653191	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-706 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653192	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-707 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653193	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-708 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653194	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-709 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653195	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-710 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653196	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-711 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653197	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330000-712 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653198	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-713 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1653199	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330000-714 U	LONG MIRROR LIGHT								Component ATA:33
PN:2LA455090-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1666340	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330003-701 U	MIRROR LIGHT POWER SUPPLY								Component ATA:33
PN:5XA455614-11	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1677437	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330003-702 U	MIRROR LIGHT POWER SUPPLY								Component ATA:33
PN:5XA455614-11	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1677440	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330004-701 U	EXIT SIGN ASSEMBLY								Component ATA:33
PN:2LA455093-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1646619	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330005-701 U	GALLEY WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1564964	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330005-702 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640117	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330005-703 U	GALLEY WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640119	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330005-704 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640127	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-701 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640131	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-702 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640120	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-703 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640121	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-704 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640122	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-705 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	22-Oct-12	TSN 0					135.6
SN:2219465	HRS		648.9	TSN 0					3452.4
	AFL		248	TSN 0					977
330006-706 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1688840	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330006-707 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640125	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-708 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640126	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-709 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640128	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-710 U	WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640129	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330006-711 U	GALLEY WASH LIGHT POWER SUPPLY								Component ATA:33
PN:8ES455827-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1640130	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330007-701 U	DOME LIGHT								Component ATA:33
PN:2LA455608-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1655615	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330007-702 U	DOME LIGHT								Component ATA:33
PN:2LA455608-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1655616	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330007-703 U	DOME LIGHT								Component ATA:33
PN:2LA455608-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1655617	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330008-701 U	CARGO COMPARTMENT DOME LIGHT								Component ATA:33
PN:2LA455637-80	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1645023	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330008-702 U	CARGO COMPARTMENT DOME LIGHT								Component ATA:33
PN:2LA455637-80	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1645026	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330013-701 U	WASH 18.78” LIGHT								Component ATA:33
PN:2LA455826-03	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661288	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330013-702 U	WASH 18.78” LIGHT								Component ATA:33
PN:2LA455826-03	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661289	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330013-703 U	WASH 18.78” LIGHT								Component ATA:33
PN:2LA455826-03	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661290	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330013-704 U	WASH 18.78” LIGHT								Component ATA:33
PN:2LA455826-03	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661291	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330014-701 U	WASH 25.91” LIGHT								Component ATA:33
PN:2LA455826-06	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661295	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330014-702 U	WASH 25.91” LIGHT								Component ATA:33
PN:2LA455826-06	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661296	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330015-701 U	WASH 28.52” LIGHT								Component ATA:33
PN:2LA455826-07	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1701899	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330015-702 U	WASH 28.52” LIGHT								Component ATA:33
PN:2LA455826-07	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661298	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330016-710 U	WASH 30.39” LIGHT								Component ATA:33
PN:2LA455826-08	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1701901	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330017-701 U	WASH 33.01 LIGHT								Component ATA:33
PN:2LA455826-09	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661304	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330017-702 U	WASH 33.01 LIGHT								Component ATA:33
PN:2LA455826-09	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661305	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330017-703 U	WASH 33.01 LIGHT								Component ATA:33
PN:2LA455826-09	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661306	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330017-704 U	WASH 33.01 LIGHT								Component ATA:33
PN:2LA455826-09	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661307	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-701 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661308	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330018-702 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661309	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-703 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661310	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-704 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661311	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-705 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661312	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-706 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661313	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-707 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661314	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-708 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661315	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-709 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661316	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330018-710 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661317	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-711 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661318	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-712 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661319	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-713 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661320	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-714 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661321	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-715 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661322	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-716 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661323	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-717 U	WASH 34.92” LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661324	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330018-718 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661325	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-719 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661326	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-720 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661327	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-721 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661328	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-722 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661329	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-723 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1528142	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330018-724 U	WASH 34.92" LIGHT								Component ATA:33
PN:2LA455826-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1721081	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330025-701 U	WARDROBE (LH ENTRANCE ENCLOSURE) ASSEMBLY								Component ATA:33
PN:2LA455829-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1647661	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
330025-702 U	WARDROBE LIGHT ASSEMBLY								Component ATA:33
PN:2LA455829-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1647666	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330025-703 U	WARDROBE LIGHT ASSEMBLY								Component ATA:33
PN:2LA455829-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1647667	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330026-701 U	SHORT MIRROR LIGHT								Component ATA:33
PN:2LA455090-40	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1597394	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330029-701 U	DIRECTOR SYSTEM INT LIGHTING UNIT								Component ATA:33
PN:8ES455611-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1631176	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330031-701 U	ANNUNCIATOR LUMINESCENT FACE PLATE								Component ATA:33
PN:7003000003-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:34082	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330031-702 U	LUMINESCENT PANEL								Component ATA:33
PN:7003000003-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:34722	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
330032-701 U	CABIN POWER OUTLET LUMINESCENT FACE PLATE								Component ATA:33
PN:7003110021-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:34083	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
335109-701 U	NO. 1 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK								Component ATA:33
PN:8ES360000-00	MOS/MSC	O/C	20-Jul-20	TSN 0					42.7
SN:18081	HRS		3416.1	TSN 0					685.2
	AFL		1057	TSN 0					168

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
335109-702 U	NO. 2 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK								Component ATA:33
PN:8ES360000-00	MOS/MSC	O/C	22-Oct-18	TSN 0					63.6
SN:15259	HRS		2978.9	TSN 0					1122.4
	AFL		946	TSN 0					279
335109-703 U	NO. 3 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK								Component ATA:33
PN:8ES360000-00	MOS/MSC	O/C	10-Aug-23	TSN 6					6
SN:22285	HRS		4009.8	TSN 0					91.5
	AFL		1193	TSN 0					32
335109-704 U	NO. 4 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK								Component ATA:33
PN:8ES360000-00	MOS/MSC	O/C	02-Feb-16	TSN 0					96.3
SN:8616	HRS		1928.5	TSN 0					2172.8
	AFL		681	TSN 0					544
339000-701 U	READING, LED (F.S. 596.55 LHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643814	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-702 U	READING, LED (F.S. 535.45 LHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643815	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-703 U	READING, LED (F.S. 500 LHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643816	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-704 U	READING, LED (F.S. 430.00 LHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643817	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-705 U	READING, LED (F.S. 429.00 RHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643818	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
339000-706 U	READING, LED (F.S. 500.00 RHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643819	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-707 U	READING, LED (F.S. 535.55 RHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643820	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-708 U	READING, LED (F.S. 596.55 RHS) LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643821	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-709 U	READING, LED LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643822	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-710 U	READING, LED LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643823	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-711 U	READING, LED LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643824	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-712 U	READING, LED LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643825	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-713 U	READING, LED LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643826	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
339000-714 U	READING, LED LIGHT								Component ATA:33
PN:2LA455089-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643827	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-715 U	READING, LED LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643802	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-716 U	READING, LED LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643803	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-717 U	READING, LED (F.S. 566.00 LHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643804	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-718 U	READING, LED (F.S. 566.00 LHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643805	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-719 U	READING, LED (F.S. 469.45 LHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643806	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-720 U	READING, LED (F.S. 469.45 LHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643807	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-721 U	READING, LED (F.S. 469.45 RHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643808	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
339000-722 U	READING, LED (F.S. 469.45 RHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643809	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-723 U	READING, LED (F.S. 566.00 RHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643810	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-724 U	READING, LED (F.S. 566.00 RHS) LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643811	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-725 U	READING, LED LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643812	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339000-726 U	READING, LED LIGHT								Component ATA:33
PN:2LA455092-31	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1643813	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339002-701 U	WASH 21.42" LIGHT								Component ATA:33
PN:2LA455826-04	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661292	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339002-702 U	WASH 21.42" LIGHT								Component ATA:33
PN:2LA455826-04	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661293	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339002-703 U	WASH 23.31" LIGHT								Component ATA:33
PN:2LA455826-05	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661294	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
339002-704 U	WASH 30.39" LIGHT								Component ATA:33
PN:2LA455826-08	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661299	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339002-705 U	WASH 30.39" LIGHT								Component ATA:33
PN:2LA455826-08	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661301	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339002-706 U	WASH 30.39" LIGHT								Component ATA:33
PN:2LA455826-08	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661302	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-701 U	WASH 28.52" LIGHT								Component ATA:33
PN:2LA455905-07	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1701900	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-702 U	WASH 28.52" LIGHT								Component ATA:33
PN:2LA455905-07	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661330	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-703 U	WASH 28.52" LIGHT								Component ATA:33
PN:2LA455905-07	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661331	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-704 U	WASH 28.52" LIGHT								Component ATA:33
PN:2LA455905-07	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661297	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-705 U	WASH 30.39" LIGHT								Component ATA:33
PN:2LA455905-08	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661300	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 33 - LIGHTS									
339003-706 U	WASH 30.39" LIGHT								Component ATA:33
PN:2LA455905-09	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661303	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-707 U	WASH 40.12” LIGHT								Component ATA:33
PN:2LA455905-12	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661332	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-708 U	WASH 40.12” LIGHT								Component ATA:33
PN:2LA455905-12	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661333	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-709 U	WASH 40.12” LIGHT								Component ATA:33
PN:2LA455905-12	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661334	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339003-710 U	WASH 40.12” LIGHT								Component ATA:33
PN:2LA455905-12	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1661335	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339034-701 U	DOME LIGHT								Component ATA:33
PN:2LA455601-25	MOS/MSC	O/C	19-May-11						152.7
SN:1726997	HRS		30	TSN 0					4071.3
	AFL		10	TSN 0					1215
339070-701 U	GOOSE-NECK READING LIGHT								Component ATA:33
PN:0320-0158-7880	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5001	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
339070-702 U	GOOSE-NECK READING LIGHT								Component ATA:33
PN:0320-0158-7880	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:5002	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 33 - LIGHTS										
339075-701 U	GOOSE-NECK PLUG-IN UNIT								Component	ATA:33
PN:0280-2022-7830	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1009001	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
ASB A700-33-022	MODIFICATION - EMERGENCY LIGHTING - CHANGE OF BOLTS ON THE EXTERIOR EMERGENCY LIGHTS (A/C S/N 9165 TO 9180), ALERT SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2021-03-17 S	LIGHTS - EMERGENCY LIGHT BATTERY PACK CORROSION								AD	ATA:33
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2021-03-17 PARA (G)	INSPECT THE ELB TO DETERMINE THE LAST REPLACEMENT DATE OR THE MANUFACTURING DATE, AS APPLICABLE, REPLACE THE ELB (IF, ANY DATE IS FOUND TO BE 4 YEARS OR OLDER)								AD	ATA:33
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2021-03-17 PARA (H)	REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE								AD	ATA:33
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2021-03-17 PARA (J) S	COMPLIANCE WITH RESTORATION TASK FOR AIRPLANES ON WHICH THE MISIDENTIFIED TASK WAS ACCOMPLISHED								AD	ATA:33
	MOS/MSC	DUE	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-33-001	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-33-001 REV 01	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 33 - LIGHTS										
SB 700-33-001 REV 02	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-33-001 REV 03	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS (A/C 9002 TO 9398), SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
SB 700-33-010	MODIFICATION - SERVICE COMPARTMENT LIGHTING - RELOCATION OF AVIONICS BAY LIGHT SWITCHES TO ELIMINATE FOULING CONDITION, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-33-011	MODIFICATION - LANDING AND TAXI LIGHTING - REPLACEMENT OF LANDING/TAXI LIGHT LENS RETAINERS ON EXISTING FRAME, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-33-011 REV 01	MODIFICATION - LANDING AND TAXI LIGHTING - REPLACEMENT OF LANDING/TAXI LIGHT LENS RETAINERS ON EXISTING FRAME, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-33-014	MODIFICATION - LANDING AND TAXI LIGHTING - ADDITION OF MISSING BACKSHELLS AT CONNECTORS DS30P1 AND DS31P1, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-33-019	MODIFICATION - LOGO LIGHTING - WIRING CHANGES AND SHIELDING PROVISIONS FOR BUILD 4.0 ELECTRICAL SYSTEM, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 33 - LIGHTS										
SB 700-33-023	MODIFICATION - NAVIGATION LIGHTING - REPLACEMENT OF THE HALOGEN NAVIGATION LIGHTS WITH LED UNITS, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-33-024	SPECIAL CHECK/MODIFICATION - INTERNAL AND EXTERNAL EMERGENCY LIGHTING - STLMC DISCARD TASK, SERVICE BULLETIN								Bulletin	ATA:33
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-33-024 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION TASK								Bulletin	ATA:33
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-33-024 PART B	ACCOMPLISH, SERVICE BULLETIN TECH PUBS MODIFICATION								Bulletin	ATA:33
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
ATA 34 - NAVIGATION										
34-00-00-CUS-9024[U]	UPDATE EGPWS - TERRAIN DATA BASE TO THE LATEST VERSION.								Service	ATA:34
	MOS	15	22-Nov-23		28-Feb-25		383 d	28-Feb-2025	2.6	
	HRS		4099.1						2.2	
	AFL		1223						2	
34-11-00-101	FUNCTIONAL TEST OF THE AIR DATA COMPUTER, (RVSM QUALIFIED A/C)								Service	ATA:34
	MOS	24 (+3m/-3m)	14-Dec-23	Adj 3	31-Mar-26	14-Jun-26	779 d (+75)	31-Mar-2026	1.9	
	HRS		4099.1						2.2	
WC#: 34.005	AFL		1223						2	
			PROC. REF: AMM 34 11 00 720 801							
34-11-00-202	FUNCTIONAL TEST OF THE PITOT-STATIC SYSTEMS								Service	ATA:34
	MOS	24 (+3m/-3m)	14-Dec-23	Adj 24d	31-Jan-26	07-Apr-26	720 d (+66)	31-Jan-2026	1.9	
	HRS		4099.1						2.2	
WC#: 34.010	AFL		1223						2	
			PROC. REF: AMM 34 11 00 720 802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
34-11-01-201	DETAILED INSPECTION OF THE PITOT-STATIC PROBES								Service	ATA:34
	MOS	24 (+3m/-3m)	14-Dec-23	Adj 3	31-Mar-26	14-Jun-26	779 d (+75)	31-Mar-2026	1.9	
	HRS		4099.1						2.2	
WC#: 34.015	AFL		1223						2	
				PROC. REF: AMM 34 11 01 220 801						
34-11-01-900-801-01	NO. 1 PITOT STATIC PROBE								Component	ATA:34
PN:0856TT1	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:260110	HRS		0	TSN 0					4101.3	
WC#: 34.035	AFL		0	TSN 0					1225	
				PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801						
34-11-01-900-801-02	NO. 2 PITOT STATIC PROBE								Component	ATA:34
PN:0856TT4	MOS/MSC	H/T	14-Feb-11	TSN 0					155.9	
SN:265869	HRS		7.4	TSN 0					4093.9	
WC#: 34.035	AFL		4	TSN 0					1221	
				PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801						
34-11-01-900-801-03	NO. 3 PITOT STATIC PROBE								Component	ATA:34
PN:0856TT3	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:261360	HRS		0	TSN 0					4101.3	
WC#: 34.035	AFL		0	TSN 0					1225	
				PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801						
34-11-01-900-801-04	STANDBY PITOT STATIC PROBE								Component	ATA:34
PN:0856TT2	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7	
SN:260537	HRS		0	TSN 0					4101.3	
WC#: 34.035	AFL		0	TSN 0					1225	
				PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801						
34-11-03-201[S]	SERVICING OF THE VISUAL DRAINS								Service	ATA:34
	MOS	15 (+3m/-3m)	14-Dec-23						1.9	
	HRS		4099.1						2.2	
WC#: 34.020	AFL		1223						2	
				PROC. REF: AMM 34 11 03 616 801						PKG:31
34-11-05-900-801-01	TOTAL TEMPERATURE SENSOR								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 34.040	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 11 05 000 801, AMM 34 11 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
34-11-09-900-801-01	NO. 1 MICRO AIR DATA COMPUTER								Component ATA:34
PN:7030700-70708	MOS/MSC	O/C	09-Jan-20	TSN 121					49.1
SN:09082312	HRS		3338.3	TSN 3338.3					763
WC#: 34.045	AFL		1038	TSN 1038					187
				PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801					
34-11-09-900-801-02	NO. 2 MICRO AIR DATA COMPUTER								Component ATA:34
PN:7030700-70708	MOS/MSC	O/C	09-Jan-20						49.1
SN:06081125	HRS		3338.3						763
WC#: 34.045	AFL		1038						187
				PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801					
34-11-09-900-801-03	NO. 3 MICRO AIR DATA COMPUTER								Component ATA:34
PN:7030700-70708	MOS/MSC	O/C	09-Jan-20						49.1
SN:10112687	HRS		3338.3						763
WC#: 34.045	AFL		1038						187
				PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801					
34-11-CA-200	RECERTIFY NO. 1 MICRO AIR DATA COMPUTER PER 14 CFR 91.411								Service ATA:34
PN:7030700-70708	MOS	24	14-Dec-23		31-Dec-25		689 d	31-Dec-2025	1.9
SN:09082312	HRS		4099.1						2.2
	AFL		1223						2
				PROC. REF: GENERIC NO REF					
34-11-CA-200	RECERTIFY NO. 2 MICRO AIR DATA COMPUTER PER 14 CFR 91.411								Service ATA:34
PN:7030700-70708	MOS	24	14-Dec-23		31-Dec-25		689 d	31-Dec-2025	1.9
SN:06081125	HRS		4099.1						2.2
	AFL		1223						2
				PROC. REF: GENERIC NO REF					
34-11-CA-200	RECERTIFY NO. 3 MICRO AIR DATA COMPUTER PER 14 CFR 91.411								Service ATA:34
PN:7030700-70708	MOS	24	14-Dec-23		31-Dec-25		689 d	31-Dec-2025	1.9
SN:10112687	HRS		4099.1						2.2
	AFL		1223						2
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
34-12-01-201	FUNCTIONAL TEST OF THE STANDBY AIRSPEED/ALTIMETER INDICATOR (A/C 9002 TO 9157)								Service	ATA:34
	MOS/MSC	N/A	30-Jun-11						151.4	
	HRS		0						4101.3	
WC#: 34.025	AFL		0						1225	
				PROC. REF: GENERIC NO REF						
34-12-03-900-801-01	INTEGRATED STANDBY INDICATOR								Component	ATA:34
PN:C16786KA01	MOS/MSC	O/C	11-Jul-22	TSN 9					19	
SN:C16786036035	HRS		3802.1						299.2	
WC#: 34.050	AFL		1144						81	
				PROC. REF: GENERIC NO REF						
34-12-CA-200	RECERTIFY INTEGRATED STANDBY INDICATOR PER 14 CFR 91.411								Service	ATA:34
PN:C16786KA01	MOS	24	14-Dec-23		31-Dec-25		689 d	31-Dec-2025	1.9	
SN:C16786036035	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: GENERIC NO REF						
34-13-00-101	DISCARD OF THE NO. 1 PITOT-STATIC PROBES, (RVSM QUALIFIEDA/C)								Service	ATA:34
PN:0856TT1	MOS		20-Dec-09					15-Apr-2034	169.7	
SN:260110	HRS	9600	0		9600		5498.7		4101.3	
	AFL		0						1225	
				PROC. REF: AMM 34 11 01 961 801						
34-13-00-101	DISCARD THE NO. 2 PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FORRVSM OPERATORS ONLY)								Service	ATA:34
PN:0856TT4	MOS		14-Feb-11					20-Apr-2034	155.9	
SN:265869	HRS	9600	7.4		9607.4		5506.1		4093.9	
	AFL		4						1221	
				PROC. REF: AMM 34 11 01 961 801						
34-13-00-101	DISCARD THE NO. 3 PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FORRVSM OPERATORS ONLY)								Service	ATA:34
PN:0856TT3	MOS		20-Dec-09					15-Apr-2034	169.7	
SN:261360	HRS	9600	0		9600		5498.7		4101.3	
	AFL		0						1225	
				PROC. REF: AMM 34 11 01 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
34-13-00-101	DISCARD THE PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FORRVSM OPERATORS ONLY)								Service	ATA:34
PN:0856TT2	MOS		20-Dec-09					15-Apr-2034	169.7	
SN:260537	HRS	9600	0		9600		5498.7		4101.3	
	AFL		0						1225	
				PROC. REF: AMM 34 11 01 961 801						
34-13-00-201	FUNCTIONAL TEST OF THE INTEGRATED ELECTRONIC STANDBY INSTRUMENT (A/C 9158 AND SUBS)								Service	ATA:34
	MOS	24 (+3m/-3m)	14-Dec-23	Adj 25d	31-Jan-26	08-Apr-26	720 d (+67)	31-Jan-2026	1.9	
	HRS		4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 34 12 03 720 801						
34-21-01-900-801-01	STANDBY ATTITUDE HORIZON INDICATOR								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 34.055	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
34-22-01-900-801-01	STANDBY COMPASS								Component	ATA:34
PN:WL1001KCA1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:BC5090109	HRS		0	TSN 0					4101.3	
WC#: 34.060	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 22 01 000 801, AMM 34 22 01 400 801						
34-32-00-201[S]	DETAILED INSPECTION OF THE ELECTRO-OPTICAL UNIT HYGROMETER SENSOR (IF HUDS INSTALLED)								Service	ATA:34
	MOS		05-Dec-23						2.2	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 34.030	AFL		1223						2	
				PROC. REF: AMM 34 32 13 220 801						PKG:4
34-33-03-900-801-01	EVS SYSTEM - INFRARED (ISU) SENSOR UNIT								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 33 03 000 801, AMM 34 33 03 400 801						
34-33-06-900-802-01	EVS SYSTEM - INFRARED WINDOW								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 33 06 000 802, AMM 34 33 06 400 802						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
34-33-09-900-801-01	EVS SYSTEM - HEATER (EVSHC) CONTROLLER								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 33 09 000 801, AMM 34 33 09 400 801					
34-41-01-900-801-01	NOSE RADOME RECEIVER/TRANSMITTER ANTENNA								Component ATA:34
PN:7021450-801	MOS/MSC	O/C	28-Feb-14	TSR 0					119.5
SN:05035496	HRS		1256.8	TSR 0					2844.5
WC#: 34.065	AFL		487	TSR 0					738
				PROC. REF: AMM 34 41 01 000 801, AMM 34 41 01 400 801					
34-41-05-900-801-01	LH WEATHER RADAR CONTROLLER								Component ATA:34
PN:7008471-415	MOS/MSC	O/C	17-May-11	TSR 0					152.8
SN:0903B169	HRS		28.5	TSR 0					4072.8
WC#: 34.070	AFL		9	TSR 0					1216
				PROC. REF: AMM 34 41 05 000 801, AMM 34 41 05 400 801					
34-41-05-900-801-02	RH WEATHER RADAR CONTROLLER								Component ATA:34
PN:7008471-417	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0901B069	HRS		0	TSN 0					4101.3
WC#: 34.070	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 41 05 000 801, AMM 34 41 05 400 801					
34-42-01-900-801-01	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER								Component ATA:34
PN:965-0976-040-206-206	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:EMK5-29840	HRS		0	TSN 0					4101.3
WC#: 34.075	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 42 01 000 801, AMM 34 42 01 400 801					
34-43-01-900-801-01	TCAS PROCESSOR								Component ATA:34
PN:7517900-10020	MOS/MSC	O/C	06-Aug-14	TSN 56					114.2
SN:20010766	HRS		1391.1	TSN 1391.1					2710.2
WC#: 34.080	AFL		537	TSN 537					688
				PROC. REF: AMM 34 43 01 000 801, AMM 34 43 01 400 801					
34-43-05-900-801-01	TCAS LOWER TCAS ANTENNA								Component ATA:34
PN:S65-5366-10L	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7
SN:185-16906	HRS		3474.7	TSN 0					626.6
WC#: 34.085	AFL		1069	TSN 0					156
				PROC. REF: AMM 34 43 05 000 801, AMM 34 43 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
34-43-09-900-801-01	UPPER DIRECTIONAL TCAS ANTENNA								Component	ATA:34
PN:7514081-914	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:ANE32606	HRS		0	TSN 0					4101.3	
WC#: 34.090	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 43 09 000 801, AMM 34 43 09 400 801						
34-44-01-900-801-01	NO. 1 RADIO ALTIMETER RECEIVER								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 34.095	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 44 01 000 801, AMM 34 44 01 400 801						
34-44-01-900-801-02	NO. 2 RADIO ALTIMETER RECEIVER								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 34.095	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 44 01 000 801, AMM 34 44 01 400 801						
34-44-05-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE RADIO ALTIMETER ANTENNAS CONNECTORS								Service	ATA:34
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-26	19-Sep-26	870 d (+81)	30-Jun-2026	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 34 44 05 210 801						PKG:34
34-44-05-900-801-01	TRANSCEIVER NO. 1 RADIO ALTIMETER ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 34.100	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801						
34-44-05-900-801-02	TRANSCEIVER NO. 2 RADIO ALTIMETER ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 34.100	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801						
34-44-05-900-801-03	RECEIVER NO. 1 RADIO ALTIMETER ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 34.105	AFL		0	TSN 0					1225	
				PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
34-44-05-900-801-04	RECEIVER NO. 2 RADIO ALTIMETER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.105	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801					
34-45-01-900-801-01	NO. 1 IRU								Component ATA:34
PN:HG2001GD03	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:56023491	HRS		0	TSN 0					4101.3
WC#: 34.110	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801					
34-45-01-900-801-02	NO. 2 IRU								Component ATA:34
PN:HG2001GD03	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:56023554	HRS		0	TSN 0					4101.3
WC#: 34.110	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801					
34-45-01-900-801-03	NO. 3 IRU								Component ATA:34
PN:HG2001GD03	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:56023580	HRS		0	TSN 0					4101.3
WC#: 34.110	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801					
34-45-05-900-801-01	MSU TRIPLEX MODE SELECT CONTROL PANEL								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.115	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 45 05 000 801, AMM 34 45 05 400 801					
34-46-01-900-801-01	CONTROL DISPLAY (IRS) UNIT								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 46 01 000 801, AMM 34 46 01 400 801					
34-47-01-900-801-01	LIGHTNING SENSOR SYSTEM LP-860 PROCESSOR								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.125	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 47 01 000 801, AMM 34 47 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
34-47-05-900-801-01	LIGHTNING SENSOR SYSTEM ANTENNA								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.130	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 47 05 000 801, AMM 34 47 05 400 801					
34-47-06-900-801-01	(AT-850) ANTENNA								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.135	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
34-51-01-900-801-01	NO. 1 RECEIVER NAVIGATION UNIT								Component ATA:34
PN:7510100-631	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0904C167	HRS		0	TSN 0					4101.3
WC#: 34.140	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 51 01 000 801, AMM 34 51 01 400 801					
34-51-01-900-801-02	NO. 2 RECEIVER NAVIGATION UNIT								Component ATA:34
PN:7510100-631	MOS/MSC	O/C	18-Jul-17	TSR 0					78.8
SN:0804B633	HRS		2477.5	TSR 0					1623.8
WC#: 34.140	AFL		818	TSR 0					407
				PROC. REF: AMM 34 51 01 000 801, AMM 34 51 01 400 801					
34-51-05-900-801-01	LH VOR/ILS (WHITE) ANTENNA								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.145	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 51 05 000 801, AMM 34 51 05 400 801					
34-51-05-900-801-02	RH VOR/ILS (WHITE) ANTENNA								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.145	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 51 05 000 801, AMM 34 51 05 400 801					
34-51-09-900-801-01	VOR/LOC PHASING COUPLER								Component ATA:34
PN:SSPD113-38	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:666-2172	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
34-51-17-900-801-01	GLIDE SLOPE ANTENNA								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.150	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 51 17 000 801, AMM 34 51 17 400 801					
34-51-21-900-801-01	GLIDESLOPE ANTENNA DIPLEXER								Component ATA:34
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.155	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 51 21 000 801, AMM 34 51 21 400 801					
34-51-25-900-801-01	BOTTOM MARKER BEACON ANTENNA								Component ATA:34
PN:S35-1000-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:102-8070	HRS		0	TSN 0					4101.3
WC#: 34.160	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 51 25 000 801, AMM 34 51 25 400 801					
34-52-01-900-801-01	NO. 1 ADF (AT-860) ANTENNA								Component ATA:34
PN:7510300-901	MOS/MSC	O/C	21-Jan-22	TSN 0					24.7
SN:2003S197	HRS		3689.6	TSN 0					411.7
WC#: 34.165	AFL		1117	TSN 0					108
				PROC. REF: AMM 34 52 01 000 801, AMM 34 52 01 400 801					
34-52-01-900-801-02	NO. 2 ADF (AT-860) ANTENNA								Component ATA:34
PN:7510300-901	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 34.165	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 52 01 000 801, AMM 34 52 01 400 801					
34-53-01-900-801-01	NO.1 LOWER DME ANTENNA								Component ATA:34
PN:S65-5366-10L	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7
SN:185-16907	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: AMM 34 53 01 000 801, AMM 34 53 01 400 801					
34-53-01-900-801-02	NO.2 LOWER DME ANTENNA								Component ATA:34
PN:S65-5366-10L	MOS/MSC	O/C	27-Jul-16						90.5
SN:13553	HRS		2078.9						2022.4
	AFL		719						506
				PROC. REF: AMM 34 53 01 000 801, AMM 34 53 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
34-54-01-900-801-01	NO.1 UPPER ATC ANTENNA								Component ATA:34
PN:S65-5366-10L	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:9435	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801					
34-54-01-900-801-02	NO.2 UPPER ATC ANTENNA								Component ATA:34
PN:S65-5366-10L	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:9436	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801					
34-54-01-900-801-03	NO.1 LOWER ATC ANTENNA								Component ATA:34
PN:S65-5366-10L	MOS/MSC	O/C	27-Jul-16						90.5
SN:13554	HRS		2078.9						2022.4
	AFL		719						506
				PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801					
34-54-01-900-801-04	NO.2 LOWER ATC ANTENNA								Component ATA:34
PN:S65-5366-10L	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7
SN:185-16905	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801					
34-55-01-900-801-01	NO. 1 GLOBAL POSITIONING SENSOR UNIT								Component ATA:34
PN:HG2021GD04	MOS/MSC	O/C	05-Aug-14						114.2
SN:1096	HRS		1391.1						2710.2
WC#: 34.170	AFL		537						688
				PROC. REF: AMM 34 55 01 000 801, AMM 34 55 01 400 801					
34-55-01-900-801-02	NO. 2 GLOBAL POSITIONING SENSOR UNIT								Component ATA:34
PN:HG2021GD04	MOS/MSC	O/C	05-Aug-14						114.2
SN:1601	HRS		1391.1						2710.2
WC#: 34.170	AFL		537						688
				PROC. REF: AMM 34 55 01 000 801, AMM 34 55 01 400 801					
34-55-05-900-801-01	LH GPS ANTENNA								Component ATA:34
PN:26002806-401	MOS/MSC	O/C	05-Aug-14	TSN 1					114.2
SN:773-2347	HRS		1391.1	TSN 0					2710.2
WC#: 34.175	AFL		537	TSN 0					688
				PROC. REF: AMM 34 55 05 000 801, AMM 34 55 05 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
34-55-05-900-801-02	RH GPS ANTENNA								Component ATA:34
PN:26002806-401	MOS/MSC	O/C	05-Aug-14	TSN 1					114.2
SN:773-2867	HRS		1391.1	TSN 0					2710.2
WC#: 34.175	AFL		537	TSN 0					688
				PROC. REF: AMM 34 55 05 000 801, AMM 34 55 05 400 801					
34-61-01-900-801-01	NO. 1 FMS CDU UNIT								Component ATA:34
PN:2888-09-1	MOS/MSC	O/C	22-Apr-21						33.6
SN:C343323	HRS		3533.7						567.6
WC#: 34.180	AFL		1082						143
				PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801					
34-61-01-900-801-02	NO. 2 FMS CDU UNIT								Component ATA:34
PN:2888-09-1	MOS/MSC	O/C	22-Apr-21	TSN 136					33.6
SN:C432812	HRS		3533.7	TSN 3533.7					567.6
WC#: 34.180	AFL		1082	TSN 1082					143
				PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801					
34-61-01-900-801-03	NO. 3 FMS CDU UNIT								Component ATA:34
PN:2888-09-1	MOS/MSC	O/C	22-Apr-21	TSR 56					33.6
SN:C441183	HRS		3533.7	TSR 1437.7					567.6
	AFL		1082	TSR 355					143
				PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801					
34-62-01-900-801-01	FMS DATA LOADER								Component ATA:34
PN:G7226-01	MOS/MSC	O/C	26-Jul-16						90.5
SN:1871	HRS		2078.9						2022.4
WC#: 34.185	AFL		719						506
				PROC. REF: AMM 34 62 01 000 801, AMM 34 62 01 400 801					
340000-701 U	MOUNTING TRAY OVERHEAD ASSEMBLY								Component ATA:34
PN:GT547-0002-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:422	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
343200-701 U	OPTICAL PROJECTOR UNIT								Component ATA:34
PN:GT546-0003-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:551	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
343201-701 U	OPTICAL COMBINER UNIT								Component ATA:34
PN:GT546-0004-5	MOS/MSC	O/C	19-Mar-21	TSR 5					34.7
SN:085	HRS		3474.7	TSR 0					626.6
	AFL		1069	TSR 0					156
343202-701 U	EVS FOR HUFDS COMPUTER								Component ATA:34
PN:GT546-0001-7	MOS/MSC	O/C	20-Feb-18	TSR 0					71.7
SN:611	HRS		2738.7	TSR 0					1362.6
	AFL		888	TSR 0					337
343203-701 U	EVS HEATED FAIRING								Component ATA:34
PN:GC214-0166-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:0225	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
343204-701 U	EVS HEATED CONTROLLER								Component ATA:34
PN:GC584-1002-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:733623IN00336	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
343300-701 U	INFRARED WINDOW								Component ATA:34
PN:GT546-1001-1	MOS/MSC	O/C	02-Feb-17						84.3
SN:14510570	HRS		2298.8						1802.5
	AFL		777						448
343301-701 U	SENSOR, INFRARED ISU UNIT								Component ATA:34
PN:GT546-1000-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:09141422	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
343303-701 U	AC IDENTIFICATION (AIT) TAG								Component ATA:34
PN:GT546-1003-1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:09210839	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
347201-701 U	PROCESSOR LIGHTNING SENSOR (LP860) UNIT								Component ATA:34
PN:7011822-904	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:10072314	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
347202-701 U	SENSOR, ANTENNA LIGHTNING UNIT								Component	ATA:34
PN:7014062-901	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:10061585	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
ASB A700-34-001	SPECIAL CHECK/MODIFICATION - ON-BOARD DATA-LOADER SYSTEM - VERIFICATION AND/OR INSTALLATION OF LATEST AIRCRAFT DATABASE VERSION (GEX003V2 OR LATER), ALERT SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-34-029	SPECIAL CHECK - VHF NAVIGATION SYSTEM - POTENTIAL MISLEADING GLIDE SLOPE DATA FROM NV-850 NAV RECEIVER MODULE A2, ALERT SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2003-04-06	APPLIANCE AD - INSPECTION TO DETERMINE P/N INTEGRATED NAVIGATION UNIT								AD	ATA:34
	MOS/MSC	N/A								
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2006-22-05	APPLIANCE AD - AIRCRAFT EQUIPPED WITH HONEYWELL PRIMUS II RNZ-850()/-851() INTEGRATED NAVIGATION UNITS								AD	ATA:34
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
Category: APPLIANCE										
FAA 2010-07-02	APPLIANCE AD - HONEYWELL - PRIMUS II RNZ-850( )/-851( ) INTEGRATED NAVIGATION UNITS - INSPECTION TO DETERMINE P/N - MOD LEVEL - TO ENSURE ACCURATE LOCALIZER & GLIDESLOPE DEVIATION INDICATIONS								AD	ATA:34
	MOS/MSC	-	08-May-15						105.1	
	HRS		1661.7						2439.6	
	AFL		607						618	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
FAA 2010-07-02 PARA (H) (AMOC)	REVISE THE LIMITATIONS SECTION OF THE AFM TO INCLUDE "FLIGHT LIMITATIONS"								AD	ATA:34
	MOS/MSC	-	08-May-15						105.1	
	HRS		1661.7						2439.6	
	AFL		607						618	
Category: APPLIANCE										
FAA 2010-07-02 PARA (L) (AMOC)	INSPECTION TO DETERMINE MOD LEVEL TO ENSURE THAT THE NRM IS AT MOD T CONFIGURATION								AD	ATA:34
	MOS/MSC	-	08-May-15						105.1	
	HRS		1661.7						2439.6	
	AFL		607						618	
Category: APPLIANCE										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION & SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS								AD	ATA:34
	MOS/MSC	-	06-Aug-14						114.2	
	HRS		1391.1						2710.2	
	AFL		537						688	
Category: APPLIANCE										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION								AD	ATA:34
	MOS/MSC	-	30-Oct-14						111.4	
	HRS		1448.1						2653.2	
	AFL		555						670	
Category: APPLIANCE										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS								AD	ATA:34
	MOS/MSC	-	04-Aug-15						102.2	
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2016-10-06	NAVIGATION - GENERAL VISUAL INSPECTION OF THE NETWORK INTERFACE INSTALLATION BETWEEN THE IMS AND CES TO DETERMINE IF PINS ARE PRESENT AT POSITIONS 25, 27, 48, 50 AND DISCONNECT THE INSTALLATION IF ANY PINS ARE PRESENT								AD	ATA:34
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
FAA 2017-11-11	APPLIANCE AD - NAVWORX, INC, AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS - REMOVE, DISABLE, OR REVISE SOFTWARE TO BROADCAST A SIL OF 0								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILANCE SYSTEM PROCESSING UNITS								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-03-04 PARA (G)	DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED								AD	ATA:34
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-03-04 PARA (H) (1)	REPLACE AFFECTED PITOT PROBES								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-03-04 PARA (H) (2)	DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
FAA 2019-01-02	APPLIANCE AD - NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCASET (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-01-02 PARA (G) (1)	DISABLE THE AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN FUNCTION IN EACH UNIT								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-01-02 PARA (G) (2)	REVISE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT IN ACCORDANCE WITH PARAGRAPH 5.2.C OF SB2018-01								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-07-10	APPLIANCE AD - NAVIGATION - LITEF ATTITUDE HEADING AND REFERENCE SYSTEM (AHRS) - REMOVAL								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-07-10 PARA (F) (1)	REMOVE THE AHRS UNIT FROM SERVICE								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-07-10 PARA (F) (2)	REMOVAL FROM SERVICE OF P/N 145130-7100 TERMINATES THE REQUIREMENTS OF AD 2010-26-09 (75 FR 81424, DECEMBER 28, 2010)								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
FAA 2019-07-10 PARA (F) (3)	DO NOT INSTALL AN AHRS UNIT P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, OR 145130-7100 ON ANY AIRCRAFT								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-12-09	APPLIANCE AD - NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)								AD	ATA:34
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-13-03[S]	APPLIANCE AD - TRIG AVIONICS LTD. - NAVIGATION - TRANSPONDERS INSTALLATION - INSPECTION / MODIFICATION								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-13-03 PARA (G)	INSPECT THE TRANSPONDER INSTALLATION TO DETERMINE IF THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK								AD	ATA:34
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2019-13-03 PARA (I[S])	DO NOT INSTALL AN AFFECTED TRANSPONDER ON ANY AIRCRAFT, UNLESS THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT -FACING AVIONICS RACK AS DEFINED IN THIS AD								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
FAA 2020-16-08	APPLIANCE AD - ASPEN AVIONICS, INC. - EFD1000 FLIGHT DISPLAY SYSTEMS - AIRPLANE FLIGHT MANUAL - REVISION								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2020-18-51	APPLIANCE AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2020-18-51-E	APPLIANCE/EMERGENCY AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT								AD	ATA:34
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE, EMERGENCY										
FAA 2022-13-05	NAVIGATION - AIRCRAFT FLIGHT MANUAL - REVISE								AD	ATA:34
	DAYS/MSC	-	04-Aug-22						556 d	
	HRS		3808.4						292.9	
	AFL		1146						79	
FAA 2023-03-06	NAVIGATION - AIRPLANE FLIGHT MANUAL (AFM) LIMITATIONS AND MASTER MINIMUM EQUIPMENT LIST (MMEL) ITEM PROHIBITION IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE								AD	ATA:34
	MOS/MSC	-	07-Mar-23						11.1	
	HRS		3954.3						147	
	AFL		1179						46	
FAA 2023-03-06 PARA (G)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 1 TO PARA (G)								AD	ATA:34
	DAYS/MSC	-	07-Mar-23						341 d	
	HRS		3954.3						147	
	AFL		1179						46	
FAA 2023-03-06 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 2 TO PARA (H) OF THIS AD								AD	ATA:34
	DAYS/MSC	-	07-Mar-23						341 d	
	HRS		3954.3						147	
	AFL		1179						46	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 34 - NAVIGATION										
FAA 2023-13-15	MINIMUM EQUIPMENT LIST (MEL) ITEM PROHIBITION IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE								AD	ATA:34
	MOS/MSC	-	27-Jul-23						6.5	
	HRS									
	AFL		1192						33	
MODSUM IS700-34-0009U REV A	NAVIGATION - EGPWS - CONFIGURATION STRAPPING FOR ALTERNATE MOD 6 AURAL ALTITUDE CALLOUTS, MODIFICATION SUMMARY								Bulletin	ATA:34
	MOS/MSC	T:A/R								
	HRS									
	AFL									
MODSUM IS700-34-0013U REV A	NAVIGATION, AIR DATA SYSTEM, PITOT TUBE ASSY, RHS, IDENTIFICATION CORRECTION IF INCORRECTLY IDENTIFIED, MODIFICATION SUMMARY								Bulletin	ATA:34
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-34-002	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-34-002 REV 01	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-34-002 REV 02	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-34-002 REV 03	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION (A/C EFFECTIVITY : S/N 9002 TO 9139), SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-34-002 REV 04	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION (A/C 9002 TO 9139), SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-002 REV 05	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION (A/C 9002 TO 9139), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-003	MODIFICATION - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-004	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-004 REV 01	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-004 REV 02	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-004 REV 03	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-004 REV 04	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-004 REV 05	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3) (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-004 REV 05 RETRO	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3) (A/C 9002 TO 9999) - RETROACTIVE ACTION, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-004 REV 06 S	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3) (A/C 9002 TO 9269) (ON HOLD), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-34-005	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - ADDITION OF A SECOND GPS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-005 REV 01	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - ADDITION OF A SECOND GPS (A/C 9002 TO 9139), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-013	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM - CHANGE 7 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-013 REV 01	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM - CHANGE 7 SOFTWARE UPGRADE, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-014 PART (A)	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-014 PART (B)	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-014 PART (C)	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-014 REV 01 PART (A)	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-34-014 REV 01 PART (B)	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-34-014 REV 01 PART (C)	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-34-015	MODIFICATION - NAVIGATION - TRAFFIC/COLLISION AVOIDANCE SYSTEM (TCAS) UNIT WIRING CHANGES, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-016	MODIFICATION - NAVIGATION - FLIGHT MANAGEMENT SYSTEM CONTROL AND DISPLAY UNITS (FMS CDU) DIMMING WIRING CHANGES, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-016 REV 01	MODIFICATION - NAVIGATION - FLIGHT MANAGEMENT SYSTEM CONTROL AND DISPLAY UNITS (FMS CDU) DIMMING WIRING CHANGES, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-017	MODIFICATION - INERTIAL REFERENCE SYSTEM (IRS) - INTRODUCTION OF "LASER REF IV", SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-019	SPECIAL CHECK/REWORK - AIR DATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-019 REV 01	SPECIAL CHECK/REWORK - AIR DATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-019 REV 02	SPECIAL CHECK/REWORK - AIR DATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-019 REV 03	SPECIAL CHECK/REWORK - AIR DATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-020	MODIFICATION - AIR DATA SYSTEM - REPLACEMENT OF MICRO AIR-DATA COMPUTER, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-020 REV 01	MODIFICATION - AIR DATA SYSTEM - REPLACEMENT OF MICRO AIR-DATA COMPUTER, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-021	MODIFICATION - GENERAL - REPLACEMENT OF SOME 90 DEGREE ANTENNA CONNECTORS TO MAKE TEH SERVICING OF EXTERNAL ANTENNAS EASIER AND FASTER, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-022	MODIFICATION - STANDBY ARTIFICIAL-HORIZON SYSTEM - CHANGE POWER SOURCE TO 28 V DC DIRECT FROM AVIONICS BATTERY BUS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-023	MODIFICATION - RADIO ALTIMETER SYSTEM - RADIO ALTIMETER ANTENNA CORROSION PROTECTION, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-025	MODIFICATION - NAVIGATION - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-03-1), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-025 REV 01	MODIFICATION - NAVIGATION - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-03-1), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-025 REV 02	MODIFICATION - NAVIGATION - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-03-1 OR 2888-09-1) (A/C 9002, 9004 TO 9124), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-027	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - NEW MODE 'S' TRANSPONDER TO MEET EUROCONTROL ELEMENTARY SURVEILLANCE REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-027 REV 01	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - NEW MODE 'S' TRANSPONDER TO MEET EUROCONTROL ELEMENTARY SURVEILLANCE REQUIREMENTS (A/C 9002 TO 9126 AND 9128 TO 9139), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-027 REV 02	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - NEW MODE 'S' TRANSPONDER TO MEET EUROCONTROL ELEMENTARY SURVEILLANCE REQUIREMENTS (A/C 9002 TO 9126 AND 9128 TO 9139), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-028	SPECIAL CHECK/REWORK - STANDBY ARTIFICIAL-HORIZON SYSTEM - IDENTIFY AND REPLACE DEFECTIVE STBY ADI (CB-18) CIRCUIT BREAKER ON THE STBY ADI CB/RELAY PANEL, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-030	MODIFICATION - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR LSS (A/C 9140 TO 9999), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-030 REV 01	MODIFICATION - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR LSS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-34-031	MODIFICATION - VHF NAVIGATION SYSTEM - REPLACEMENT OF THE RNZ-851 NAVIGATION RECEIVER UNITS TO ELIMINATE ERRONEOUS GLIDE SLOPE INDICATION ON INSTRUMENT LANDING SYSTEM (ILS) APPROACH, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-032	MODIFICATION - HEAD UP DISPLAY (HUD) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISION FOR HUD (A/C 9141 TO 9148), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-34-032 REV 1[U]	MODIFICATION - PROVISIONS - HEAD UP DISPLAY (HUD) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR HUD, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-032 REV 2[U]	MODIFICATION - HEAD UP DISPLAY (HUD) SYSTEM-INSTALLATION ON AIRCRAFT WITH PROVISION FOR HUD, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-34-033	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-033 REV 01	MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF THE ENHANCED VISION SYSTEM (A/C 9159 TO 9999), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-34-033 REV 2[U]	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS)., SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-34-035	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - CHANGE TCAS CLIMB INHIBIT ALTITUDE TO OPTIMUM ALTITUDE - EFFECTIVITY 9002 TO 9158, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-036	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - REPLACEMENT OF SUNVISOR STOWAGE BRACKET (A/C 9002 TO 9139 AND 9141 TO 9165), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-037	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS) - EFFECTIVITY 9002 TO 9158, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-037 REV 01	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS) - EFFECTIVITY 9002 TO 9158, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-037 REV 02	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-038	MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF THE EVS PROVISIONS - EFFECTIVITY 9002 TO 9148, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-039	MODIFICATION - ATC TRANSPONDER SYSTEM - MODE "S" TRANSPONDER TO MEET EUROCONTROL ENHANCED SURVEILLANCE REQUIREMENTS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-039 REV 01	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - MODE "S" TRANSPONDER TO MEET EUROCONTROL ENHANCED SURVEILLANCE REQUIREMENTS (A/C 9002 TO 9189), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-34-041	MODFICATION - GENERAL - ELECTRONIC FLIGHT BAG (EFB) AND COCKPIT TOUCH SCREENS PROVISION INSTALLATION, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-34-042	MODIFICATION - PROVISIONS - GENERAL - INSTALLATION OF THE DIGITAL TAPPING EQUIPMENT (DTE), THE RIGHT HAND SIDE USB PORT AND CONNECTOR ASSEMBLY FOR ELECTRONIC FLIGHT BAG (EFB) INSTALLATION, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-043	MODIFICATION - PROVISIONS - GENERAL - INSTALLATION OF THE DIGGITAL TAPPING EQUIPMENT (DTE), THE LEFT HAND SIDE USB PORT AND CONNECTOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-34-044	SPECIAL CHECK/REWORK - FLIGHT MANAGEMENT SYSTEM - ENSURE THE CORRECT AIRCRAFT DATABASE IS INSTALLED ON THE FMS (A/C 9002 TO 9126, 9128 TO 9180), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-046	MODIFICATION - AIR-DATA COMPUTER SYSTEM - INTRODUCTION OF NEW AMADC FOR TAT SPLIT (A/C 9002 TO 9205), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-046 REV 01	MODIFICATION - AIR-DATA COMPUTER SYSTEM - INTRODUCTION OF NEW AMADC FOR TAT SPLIT (A/C 9002 TO 9204), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-047	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-09-1), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-048	MODIFICATION - WEATHER RADAR SYSTEM - CAP AND STOW TWO CAIMS WIRES TO PREVENT GROUND CLUTTER ON MULTI-FUNCTION DISPLAY (MFD) (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-048 REV 01	MODIFICATION - WEATHER RADAR SYSTEM - CAP AND STOW TWO CAIMS WIRES TO PREVENT GROUND CLUTTER ON MULTI-FUNCTION DISPLAY (MFD), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-050	MODIFICATION - HEAD-UP-DISPLAY SYSTEM - INTRODUCTION OF NEW HEAD-UP FLIGHT-DISPLAY COMPUTER (HFDC) TO SUPPORT BATCH 3, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-050 REV 01	MODIFICATION - HEAD-UP-DISPLAY SYSTEM - INTRODUCTION OF NEW HEAD-UP FLIGHT-DISPLAY COMPUTER (HFDC) TO SUPPORT BATCH 3, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	05-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-34-051	MODIFICATION - GENERAL - INSTALLATION OF NEW PILOTVIEW™ CLASS 2 ELECTRONIC FLIGHT BAG (EFB) (A/C 9167, 9171, 9173, 9175, 9177, 9181, 9183, 9193, 9194, 9196, 9197, 9200, 9202, 9208, 9210, 9213, 9215, 9223, AND 9225 POST SB'S 700-34-041, 700-34-042, AND 700-34-043), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-052	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - REMOVAL OF ATTENUATOR WHEN FMS CDU -820 PART NO. 2888-03-1 IS REPLACED WITH PART NO. 2888-09-1 IN THE NO.2 POSITION AND EVS IS INSTALLED (A/C 9002 TO 9199), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-34-053	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-053 REV 01	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	05-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-34-053 REV 02	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-053 REV 03	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-053 REV 04	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-054	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF SBAS WITH LPV APPROACH CAPABILITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-054 REV 01	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF SBAS WITH LPV APPROACH CAPABILITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	05-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-34-054 REV 02	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF SBAS WITH LPV APPROACH CAPABILITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-054 REV 03	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF SBAS WITH LPV APPROACH CAPABILITY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-058	MODIFICATION - HEAD-UP-DISPLAY (HUD) SYSTEM - REPLACEMENT OF FAN ON HFDC TRAY, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-059	MODIFICATION - WEATHER RADAR SYSTEM - CONNECT TWO CAIMS WIRES AND PERFORM SOFTWARE UPLOAD TO PREVENT WEATHER RADAR TILT DROOPING, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-34-059 REV 01	MODIFICATION - WEATHER RADAR SYSTEM - CONNECT TWO CAIMS WIRES AND PERFORM SOFTWARE UPLOAD TO PREVENT WEATHER RADAR TILT DROOPING, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-34-061	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION OF LABELS ON THE HUD OPTICAL COMBINER UNIT (COU), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	19-Jul-12						138.7
	HRS		561.2						3540.1
	AFL		212						1013
SB 700-34-062	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT) (SUPERSEDED BY 700-34-062 REV 01), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-062 REV 01	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT) (SUPERSEDED BY 700-34-062 REV 02), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-062 REV 02	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT) (SUPERSEDED BY 700-34-062 REV 03), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	05-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-34-062 REV 03	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT) (SUPERSEDED BY 700-34-062 REV 04), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-062 REV 04	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-062 REV 05	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT), SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-063	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION OF NEW RECEIVER/TRANSMITTER UNIT WITH SOFTWARE VERSION 7.0 UPGRADE, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-34-064	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION OF NEW RECEIVER/TRANSMITTER UNIT WITH SOFTWARE VERSION 7.1 UPGRADE, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	06-Aug-14						114.2
	HRS		1391.1						2710.2
	AFL		537						688
SB 700-34-066	SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-34-066 PART (A)	ACCOMPLISH, SERVICE BULLETIN AN INSPECTION ON THE STANDBY COMPASS AND LEAD ASSEMBLY								Bulletin ATA:34
	DAYS/MSC	-	27-Jul-16						2755 d
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-34-066 PART (B)	ACCOMPLISH, SERVICE BULLETIN A VISUAL CHECK OF THE “Y” SOCKET END OF THE WIRE AND ACCOMPLISH INSULATION RESISTANCE TEST								Bulletin ATA:34
	DAYS/MSC	-	27-Jul-16						2755 d
	HRS		2078.9						2022.4
	AFL		719						506

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 34 - NAVIGATION									
SB 700-34-066 PART (C)	ACCOMPLISH, SERVICE BULLETIN REMOVAL / INSTALLATION OF THE NEW LEAD ASSEMBLY								Bulletin ATA:34
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-34-067	MODIFICATION - NAVIGATION - INTRODUCTION OF BANDPASS FILTER TO THE RADIO ALTIMETER TO PREVENT INTERFERENCE FROM 5G MOBILE NETWORKS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-	14-Dec-23						1.9
	HRS		4099.1						2.2
	AFL		1223						2
SB 700-34-067 REV 01	MODIFICATION - NAVIGATION - INTRODUCTION OF BANDPASS FILTER TO THE RADIO ALTIMETER TO PREVENT INTERFERENCE FROM 5G MOBILE NETWORKS, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	-							
	HRS								
	AFL								
SB 700D34-040 REV 1[U]	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALL THE HUD TRAY AND PERFORM BORESIGHTING, SERVICE BULLETIN								Bulletin ATA:34
	MOS/MSC	A/R	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
ATA 35 - OXYGEN									
35-10-05-201	RESTORATION LH FULL FACE CREW OXYGEN MASK								Service ATA:35
PN:MF10-08-01	MOS	75	16-Nov-20		28-Feb-27		1113 d	28-Feb-2027	38.8
SN:SE55112I	HRS								
WC#: 35.035	AFL								
			PROC. REF: AMM 35 11 05 615 801						
35-10-05-201	RESTORATION RH FULL FACE CREW OXYGEN MASK								Service ATA:35
PN:MF10-08-01	MOS	75	21-Dec-22		31-Mar-29		1875 d	31-Mar-2029	13.7
SN:1075221	HRS								
WC#: 35.040	AFL								
			PROC. REF: AMM 35 11 05 615 801						
35-11-01-201	DISCARD OF THE LEFT INBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:GC481-0090-5	MOS	180	01-Oct-22		31-Oct-37		5011 d	31-Oct-2037	16.3
SN:C23031036	HRS								
	AFL								
			PROC. REF: AMM 35 11 01 960 802						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 35 - OXYGEN									
35-11-01-201	DISCARD OF THE LEFT OUTBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:GC481-0090-5	MOS	180	01-Oct-22		31-Oct-37		5011 d	31-Oct-2037	16.3
SN:C22120605	HRS								
	AFL								
				PROC. REF: AMM 35 11 01 960 802					
35-11-01-201	DISCARD OF THE RIGHT INBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:GC481-0090-5	MOS	180	01-Oct-22		31-Oct-37		5011 d	31-Oct-2037	16.3
SN:C23031035	HRS								
	AFL								
				PROC. REF: AMM 35 11 01 960 802					
35-11-01-201	DISCARD OF THE RIGHT OUTBOARD OXYGEN STORAGE CYLINDER								Service ATA:35
PN:GC481-0090-5	MOS	180	01-Apr-23		30-Apr-38		5192 d	30-Apr-2038	10.3
SN:C23061357	HRS								
	AFL								
				PROC. REF: AMM 35 11 01 960 802					
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE LEFT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service ATA:35
PN:GC481-0090-5	MOS	60	01-Oct-22		31-Oct-27		1358 d	31-Oct-2027	16.3
SN:C23031036	HRS								
WC#: 35.025	AFL								
				PROC. REF: AMM 35 11 01 720 801					
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE LEFT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service ATA:35
PN:GC481-0090-5	MOS	60	01-Oct-22		31-Oct-27		1358 d	31-Oct-2027	16.3
SN:C22120605	HRS								
WC#: 35.015	AFL								
				PROC. REF: AMM 35 11 01 720 801					
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE RIGHT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service ATA:35
PN:GC481-0090-5	MOS	60	01-Oct-22		31-Oct-27		1358 d	31-Oct-2027	16.3
SN:C23031035	HRS								
WC#: 35.030	AFL								
				PROC. REF: AMM 35 11 01 720 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE RIGHT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Service	ATA:35
PN:GC481-0090-5	MOS	60	01-Oct-22		31-Oct-27		1358 d	31-Oct-2027	16.3	
SN:C23061357	HRS									
WC#: 35.020	AFL									
				PROC. REF: AMM 35 11 01 720 801						
35-11-01-900-801-01	LEFT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component	ATA:35
PN:GC481-0090-5	MOS/MSC	H/T	29-Dec-23	TSN 14					1.4	
SN:C22120605	HRS		4099.1	TSN 0					2.2	
WC#: 35.015	AFL		1223	TSN 0					2	
				PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801						
35-11-01-900-801-02	RIGHT OUTBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component	ATA:35
PN:GC481-0090-5	MOS/MSC	H/T	08-Dec-23	TSN 8					2.1	
SN:C23061357	HRS		4099.1	TSN 0					2.2	
WC#: 35.020	AFL		1223	TSN 0					2	
				PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801						
35-11-01-900-801-03	LEFT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component	ATA:35
PN:GC481-0090-5	MOS/MSC	H/T	29-Dec-23	TSN 14					1.4	
SN:C23031036	HRS		4099.1	TSN 0					2.2	
WC#: 35.025	AFL		1223	TSN 0					2	
				PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801						
35-11-01-900-801-04	RIGHT INBOARD OXYGEN CYLINDER & REGULATOR BOTTLE								Component	ATA:35
PN:GC481-0090-5	MOS/MSC	H/T	29-Dec-23	TSN 14					1.4	
SN:C23031035	HRS		4099.1	TSN 0					2.2	
WC#: 35.030	AFL		1223	TSN 0					2	
				PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801						
35-11-05-900-801-01	LH FULL FACE CREW OXYGEN MASK								Component	ATA:35
PN:MF10-08-01	MOS/MSC	O/C	19-Mar-21	TSO 4					34.7	
SN:SE55112I	HRS		3474.7	TSO 0					626.6	
WC#: 35.035	AFL		1069	TSO 0					156	
				PROC. REF: AMM 35 11 05 000 801, AMM 35 11 05 400 801						
35-11-05-900-801-02	RH FULL FACE CREW OXYGEN MASK								Component	ATA:35
PN:MF10-08-01	MOS/MSC	O/C	21-Dec-22	TSO 0					13.7	
SN:1075221	HRS		3913.7	TSO 0					187.6	
WC#: 35.040	AFL		1171	TSO 0					54	
				PROC. REF: AMM 35 11 05 000 801, AMM 35 11 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
35-11-09-900-801-01	LH STOWAGE BOX								Component	ATA:35
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 35.045	AFL		0	TSN 0					1225	
				PROC. REF: AMM 35 11 09 000 801, AMM 35 11 09 400 801						
35-11-09-900-801-02	RH STOWAGE BOX								Component	ATA:35
PN:MXP411-3	MOS/MSC	O/C	12-Jul-16						91	
SN:21909	HRS		2078.9						2022.4	
WC#: 35.045	AFL		719						506	
				PROC. REF: AMM 35 11 09 000 801, AMM 35 11 09 400 801						
35-11-50-601 U S	OPERATIONAL TEST OF CREW OXYGEN SYSTEM MODIFICATIONS MASKS								Service	ATA:35
	MOS	15	28-Nov-23						2.5	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
35-11-50-603 U S	DETAILED INSPECTION OF CREW PROTECTIVE BREATHING EQUIPMENT (PBE)								Service	ATA:35
	MOS	15	06-Dec-23						2.2	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
35-12-09-900-801-01	OXYGEN PRESSURE TRANSDUCER								Component	ATA:35
PN:GC481-0070-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:6807	HRS		0	TSN 0					4101.3	
WC#: 35.050	AFL		0	TSN 0					1225	
				PROC. REF: AMM 35 12 09 000 801, AMM 35 12 09 400 801						
35-20-05-900-801-01	S/O THERAPEUTIC OXYGEN VALVE								Component	ATA:35
PN:P21046	MOS/MSC	O/C	22-Dec-22	TSN 0					13.6	
SN:R22070116	HRS		3913.7	TSN 0					187.6	
WC#: 35.010	AFL		1171	TSN 0					54	
				PROC. REF: AMM 35 20 05 000 801, AMM 35 20 05 400 801						
35-21-01-201 S	FUNCTIONAL TEST OF THE PASSENGER OXYGEN CONTROL PANEL								Service	ATA:35
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 35.005	AFL		1171						54	
				PROC. REF: AMM 35 21 01 720 801						PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
35-21-01-900-801-01	PASSENGER OXYGEN CONTROL PANEL / ALTIMETRIC VALVE								Component	ATA:35
PN:RCA73-06 (604-44101-3)	MOS/MSC	O/C	08-Mar-13	TSN 104, TSO 9					131.1	
SN:304	HRS		850.3	TSO 0					3251	
WC#: 35.055	AFL		332	TSO 0					893	
				PROC. REF: AMM 35 21 01 000 801, AMM 35 21 01 400 801						
35-21-50-601 U S	OPERATIONAL TEST OF PASSENGER OXYGEN SYSTEM								Service	ATA:35
	MOS	15	28-Nov-23						2.5	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
35-21-50-602 U S	FUNCTIONAL TEST OF PASSENGER OXYGEN SYSTEM								Service	ATA:35
	MOS	30	30-Dec-22						13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
										PKG:32
350001-701 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1018	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
350001-702 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1019	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
350001-703 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1021	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
350001-704 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1022	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 35 - OXYGEN									
350001-705 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1023	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
350001-706 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1025	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
350001-707 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1026	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
350001-708 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1027	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
350001-709 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1028	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
350001-710 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1029	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
350001-711 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1048	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
350001-712 U	OXYGEN BOX ASSEMBLY								Component ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:1152	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
350001-713 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1153	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
350001-714 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:833-325-1	MOS/MSC	O/C	17-Jul-19	TSN 0					54.8	
SN:D19041498	HRS		3188.8	TSN 0					912.5	
	AFL		996	TSN 0					229	
350001-715 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1006	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1143	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
350001-716 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1004	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1155	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
350001-717 U	OXYGEN BOX ASSEMBLY								Component	ATA:35
PN:PA1005	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:1158	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
350002-701 U	STOWAGE BOX (LH ENTRANCE ENCLOSURE) ASSEMBLY								Component	ATA:35
PN:MXP411-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:SE39765	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
351103-701 U	PILOT (SWEEP-ON 2000) CREW OXYGEN MASK								Component	ATA:35
PN:174252-14	MOS/MSC	O/C	19-Mar-21	TSO 4					34.7	
SN:28469	HRS		3474.7	TSO 0					626.6	
	AFL		1069	TSO 0					156	
351103-701B U	RESTORATION PILOT (SWEEP-ON 2000) CREW OXYGEN MASK (35-11-50-602)								Service	ATA:35
PN:174252-14	MOS	75	17-Nov-20		28-Feb-27		1113 d	28-Feb-2027	38.8	
SN:28469	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
351103-702 U	COPILOT (SWEEP-ON 2000) CREW OXYGEN MASK								Component	ATA:35
PN:174252-14	MOS/MSC	O/C	19-Mar-21	TSO 4					34.7	
SN:21400	HRS		3474.7	TSO 0					626.6	
	AFL		1069	TSO 0					156	
351103-702B U	RESTORATION COPILOT (SWEEP-ON 2000) CREW OXYGEN MASK (35-11-50-602)								Service	ATA:35
PN:174252-14	MOS	75	17-Nov-20		28-Feb-27		1113 d	28-Feb-2027	38.8	
SN:21400	HRS									
	AFL									
351152-701 U	LH ENCLOSURE HALF FACE CREW OXYGEN MASK								Component	ATA:35
PN:MC20-004	MOS/MSC	O/C	21-Dec-22	TSO 0					13.7	
SN:141059	HRS		3913.7	TSO 0					187.6	
	AFL		1171	TSO 0					54	
351152-701B U	RESTORATION LH ENCLOSURE HALF FACE CREW OXYGEN MASK (35-11-50-602)								Service	ATA:35
PN:MC20-004	MOS	75	21-Dec-22		31-Mar-29		1875 d	31-Mar-2029	13.7	
SN:141059	HRS		3913.7						187.6	
	AFL		1171						54	
352101-002 U	RH ALTIMETRIC VALVE								Component	ATA:35
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 35.055	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
353110-701 U	CREW (AFT L/H WARDROBE) PROTECTIVE BREATHING EQUIPMENT PBE								Component	ATA:35
PN:MR-10037N	MOS/MSC	O/C	19-Mar-21	TSN 4					34.7	
SN:E2003361	HRS		3474.7	TSN 0					626.6	
	AFL		1069	TSN 0					156	
353110-701B U	RESTORE CREW (AFT L/H WARDROBE) PROTECTIVE BREATHING EQUIPMENT PBE (35-11-50-604)								Service	ATA:35
PN:MR-10037N	MOS/MSC	DUE	01-Nov-20		31-May-31 (M)		2666 d	31-May-2031	39.3	
SN:E2003361	HRS									
	AFL									
EASA 2010-0152 U	OXYGEN MASK REGULATOR - MODIFICATION								AD	ATA:35
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	AFL		4						1221	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
EASA 2011-0090[U]	OXYGEN MASK REGULATOR INFLATABLE HARNESS - INDENTIFICATION/REPLACEMENT								AD	ATA:35
	MOS/MSC	-	02-Jun-11						152.3	
	HRS		35.5						4065.8	
	AFL		13						1212	
EASA 2011-0090 R01	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS - IDENTIFICATION / REPLACEMENT								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
EASA 2011-0090 R01 PARA (1)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHT CREW OXYGEN MASK REGULATOR THAT IS INSTALLED IN THE AEROPLANE TO IDENTIFY THE P/N AND BATCH NUMBER OF THAT HARNESS AND REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS (IF THE P/N AND BATCH NUMBER)								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
EASA 2011-0090 R01 PARA (2)	OXYGEN MASK REGULATORS WITH A DATE OF MANUFACTURING (DMF) CODE OF NOVEMBER 2008 (112008 OR 11-08) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (012011 OR 01-11) OR LATER, ARE EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD, PROVIDED IT CAN BE DEMONSTRATED THAT THE INFLATABLE HARNESS HAS NOT BEEN REPLACED ON THOSE MASKS								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
EASA 2011-0090 R01 PARA (3)	DO NOT INSTALL A FLIGHT CREW OXYGEN MASK REGULATOR ON AN AEROPLANE								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
EASA 2011-0090 R01 PARA (4)	FOR BOMBARDIER AEROPLANES, THE INSTRUCTIONS OF INTERTECHNIQUE SB MXH-35-241 (OR A LATER REVISION) MUST BE USED TO COMPLY WITH THE REQUIREMENTS OF PARAGRAPH (1) AND (3) OF THIS AD								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
FAA 1994-06-04 U	EROS FULL FACE MASK								AD	ATA:35
	MOS/MSC	-	19-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
FAA 2011-01-09	APPLIANCE AD - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) PART NUMBER 119003-11 INSTALLED ON VARIOUS TRANSPORT AIRPLANES								AD	ATA:35
	DAYS/MSC	-	14-Feb-11						4745 d	
	HRS		7.4						4093.9	
	AFL		4						1221	
Category: APPLIANCE										
FAA 2011-04-09 U	DEACTIVATION OF CHEMICAL OXYGEN GENERATORS INSTALLED IN A LAVATORY.								AD	ATA:35
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
FAA 2011-14-08	APPLIANCE AD - INSPECTION/RECORDS CHECK TO DETERMINE THE MANUFACTURER AND PART NUMBER OF THE OXYGEN MASK ASSEMBLIES INSTALLED, AN INSPECTION TO DETERMINE THE MANUFACTURING DATE AND MODIFICATION STATUS IF CERTAIN OXYGEN MASK ASSEMBLIES ARE INSTALLED, AND CORRECTIVE ACTION FOR CERTAIN OXYGEN MASK ASSEMBLIES								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2011-14-08 PARA (G.1)	DO A RECORDS CHECK TO DETERMINE IF ANY OXYGEN MASK ASSEMBLY PART NUMBER								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2011-14-08 PARA (G.2)	INSPECT THE OXYGEN MASK ASSEMBLY TO DETERMINE IF THE IN-LINE FLOW INDICATOR MUST BE REPLACED (IF, AS A RESULT OF ANY OF THE RECORDS CHECKS/INSPECTIONS REQUIRED IN PARAGRAPH (G)(1) OF THIS AD, YOU DETERMINE THAT AN OXYGEN MASK ASSEMBLY PART NUMBER LISTED IN B/E AEROSPACE SB 174080-35-04 IS INSTALLED)								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
FAA 2011-14-08 PARA (H)	MODIFY THE OXYGEN MASK ASSEMBLY BY REPLACING THE IN-LINE FLOW INDICATOR (AFTER THE INSPECTION IN PARAGRAPH (G)(2) OF THIS AD AND IT WAS DETERMINED THE IN-LINE FLOW INDICATOR MUST BE REPLACED)								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2012-03-05	BOMBARDIER INC., AIRPLANES - DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA)								AD	ATA:35
	MOS/MSC	-	06-Jul-12						139.2	
	HRS		541.7						3559.6	
	AFL		200						1025	
FAA 2012-03-05 PARA (G)	INSPECTION BOMBARDIER INC., AIRPLANES - DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) OF OXYGEN PRESSURE REGULATORS								AD	ATA:35
	MOS/MSC	-	06-Jul-12						139.2	
	HRS		541.7						3559.6	
	AFL		200						1025	
FAA 2012-03-05 PARA (G) (1)	REPLACE BOMBARDIER INC., AIRPLANES - DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) THE AFFECTED OXYGEN CRA								AD	ATA:35
	MOS/MSC	-	06-Jul-12						139.2	
	HRS		541.7						3559.6	
	AFL		200						1025	
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES								AD	ATA:35
	MOS/MSC	-	21-Jul-15						102.7	
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-241, REVISION 3, DATED JUNE 23, 2011								AD	ATA:35
	MOS/MSC	-	21-Jul-15						102.7	
	HRS									
	AFL									
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES								AD	ATA:35
	MOS/MSC	-	21-Jul-15						102.7	
	HRS									
	AFL									
Category: APPLIANCE										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS								AD	ATA:35
	MOS/MSC	-	04-Jan-16						97.2	
	HRS		1899.5						2201.8	
	AFL		675						550	
Category: APPLIANCE										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER								AD	ATA:35
	MOS/MSC	-								
	DAYS/MSC	/ -	04-Jan-16						2960 d	
	HRS		1899.5						2201.8	
	AFL		675						550	
Category: APPLIANCE										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).								AD	ATA:35
	MOS/MSC	-								
	DAYS/MSC	/ -	04-Jan-16						2960 d	
	HRS		1899.5						2201.8	
	AFL		675						550	
Category: APPLIANCE										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1								AD	ATA:35
	MOS/MSC	-								
	DAYS/MSC	/ -	04-Jan-16						2960 d	
	HRS		1899.5						2201.8	
	AFL		675						550	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."								AD	ATA:35
	MOS/MSC	-								
	DAYS/MSC	/ -	04-Jan-16						2960 d	
	HRS		1899.5						2201.8	
	AFL		675						550	
Category: APPLIANCE										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT								AD	ATA:35
	MOS/MSC	-	04-Jan-16						97.2	
	HRS		1899.5						2201.8	
	AFL		675						550	
Category: APPLIANCE										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12								AD	ATA:35
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
Category: APPLIANCE										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12								AD	ATA:35
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
Category: APPLIANCE										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12								AD	ATA:35
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
Category: APPLIANCE										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12								AD	ATA:35
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
FAA 2016-15-06[S]	OXYGEN - REPLACEMENT OF FLEXIBLE RELIEF HOSES FOR THE CREW OXYGEN BOTTLES WITH NEW METAL DESIGN RELIEF HOSES								AD	ATA:35
	MOS/MSC	-	23-Aug-16						89.6	
	HRS		2104.2						1997.1	
	AFL		733						492	
FAA 2016-15-06 PARA (G)	INCORPORATE BOMBARDIER MODSUM R700T400542 BY REPLACING THE OXYGEN FLEXIBLE RELIEF HOSES FOR THE CREW OXYGEN BOTTLES WITH NEW METAL DESIGN HOSES								AD	ATA:35
	MOS/MSC	-	23-Aug-16						89.6	
	HRS		2104.2						1997.1	
	AFL		733						492	
FAA 2016-15-06 PARA (I[S])	PARTS INSTALLATION PROHIBITION: AS OF THE EFFECTIVE DATE OF THIS AD, NO PERSON MAY INSTALL ON ANY AIRPLANE OXYGEN HOSES IN THE LOW-PRESSURE/HIGH-PRESSURE DISCHARGE SYSTEM WITH PART NUMBERS LISTED IN THE "USED PART NO." COLUMN OF SECTION 3.A, "KIT," OF THE APPLICABLE SERVICE INFORMATION SPECIFIED IN PARA (G)(1) THROUGH (G)(4)								AD	ATA:35
	MOS/MSC	-	23-Aug-16						89.6	
	HRS		2104.2						1997.1	
	AFL		733						492	
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES								AD	ATA:35
	MOS/MSC	-	18-Oct-17						75.8	
	HRS		2584.6						1516.7	
	AFL		860						365	
Category: APPLIANCE										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED								AD	ATA:35
	MOS/MSC	-	18-Oct-17						75.8	
	HRS		2584.6						1516.7	
	AFL		860						365	
Category: APPLIANCE										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED								AD	ATA:35
	MOS/MSC	-	18-Oct-17						75.8	
	HRS		2584.6						1516.7	
	AFL		860						365	
Category: APPLIANCE										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.								AD	ATA:35
	MOS/MSC	-	18-Oct-17						75.8	
	HRS		2584.6						1516.7	
	AFL		860						365	
Category: APPLIANCE										
FAA 2018-21-14[S]	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2018-21-14 PARA (I[S])	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD								AD	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
FAA 2020-02-15	OXYGEN SYSTEM - INSUFFICIENT ACCESSIBILITY TO THE PORTABLE OXYGEN BOTTLE								AD	ATA:35
	MOS/MSC	-	13-May-20						44.9	
	HRS		3401.2						700.1	
	AFL		1052						173	
FAA 2022-12-01	OXYGEN - SUPPLY SYSTEM FLEXIBLE OXYGEN HOSE - INSPECTION AND REPLACEMENT								AD	ATA:35
	MOS/MSC	-	03-Jul-22						19.3	
	HRS		3790.6						310.7	
	AFL		1142						83	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
FAA 2022-12-01 PARA (G)	DO AN INSPECTION OF THE OXYGEN HOSE ASSEMBLY TO DETERMINE IF ANY HOSE HAVING A PART NUMBER (P/N) IN THE O2C20T1 SERIES IS INSTALLED; IF P/N 02C20T1 SERIES INSTALLED OR ANY TEST FAILS, BEFORE FURTHER FLIGHT, REPLACE ALL THE OXYGEN HOSES								AD	ATA:35
	MOS/MSC	-	03-Jul-22						19.3	
	HRS		3790.6						310.7	
	AFL		1142						83	
FAA 2022-12-01 PARA (I[S]) (1)	PERFORM OXYGEN SYSTEM TEST; REPLACE ALL P/N 02C20T1 SERIES HOSES BEFORE FURTHER FLIGHT AFTER ANY HOSE FAILS ANY TEST (OPTIONAL INTERIM TESTING FOR CERTAIN AIRCRAFT)								AD	ATA:35
	MOS/MSC	-	03-Jul-22						19.3	
	HRS		3790.6						310.7	
	AFL		1142						83	
FAA 2022-12-01 PARA (I[S]) (3)	REPLACE ALL P/N 02C20T1 HOSES (OPTIONAL INTERIM TESTING FOR CERTAIN AIRPLANES)								AD	ATA:35
	MOS/MSC	-	03-Jul-22						19.3	
	HRS		3790.6						310.7	
	AFL		1142						83	
FAA 2022-14-07	OXYGEN - PASSENGER OXYGEN BOXES NON-CONFORMITY								AD	ATA:35
	MOS/MSC	-	20-Dec-22						13.7	
	HRS		3913.7						187.6	
	AFL		1171						54	
SB 700-35-004	SPECIAL CHECK/MODIFICATION - LOW PRESSURE/HIGH PRESSURE DISCHARGE SYSTEM - REPLACEMENT OF FLEXIBLE HOSE INSTALLED ON RIGHT-OUTBOARD OXYGEN CYLINDER TO PREVENT POSSIBLE RUPTURE, SERVICE BULLETIN								Bulletin	ATA:35
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-35-005 PART (A)	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY, SERVICE BULLETIN								Bulletin	ATA:35
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-35-005 PART (B)	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY, SERVICE BULLETIN								Bulletin	ATA:35
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 35 - OXYGEN									
SB 700-35-005 REV 01 PART (A)	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY (A/C 9002 TO 9100 AND 9102 TO 9105), SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-35-005 REV 01 PART (B)	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY (A/C 9002 TO 9100 AND 9102 TO 9105), SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-35-006 PART (A)	POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF THE CREW OXYGEN SYSTEM HOSES - SPECIAL CHECK - VISUAL INSPECTION OF SUSPECT HOSES, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-35-006 PART (B)	POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF THE CREW OXYGEN SYSTEM HOSES - MODIFICATION - REPLACEMENT OF AFFECTED HOSES, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-35-007 PART (A)	SPECIAL CHECK - VISUAL INSPECTION OF SUSPECTED HOSES - OXYGEN SYSTEM - POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF STC INSTALLED OXYGEN SYSTEM HOSES - FOR A/C S/N 9002 TO 9126, 9128, 9129, 9133, 9134, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-35-007 PART (B)	MODIFICATION - REPLACEMENT OF AFFECTED HOSES - OXYGEN SYSTEM - POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF STC INSTALLED OXYGEN SYSTEM HOSES - FOR A/C S/N 9002 TO 9126, 9128, 9129, 9133, 9134, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 35 - OXYGEN									
SB 700-35-009	MODIFICATION - OXYGEN SUPPLY SYSTEM - INTRODUCTION OF NEW OXYGEN CYLINDER AND REGULATOR ASSEMBLY WITH AN IMPROVED HIGH-PRESSURE RELIEF DEVICE (EFFECTIVITY A/C 9002 TO 9174), SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-35-009 REV 01	MODIFICATION - OXYGEN SUPPLY SYSTEM - INTRODUCTION OF NEW OXYGEN CYLINDER AND REGULATOR ASSEMBLY WITH AN IMPROVED HIGH-PRESSURE RELIEF DEVICE (EFFECTIVITY A/C 9002 TO 9174), SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-35-011	SPECIAL CHECK/REWORK – OXYGEN SUPPLY SYSTEM – INSPECT SERIAL NO. OF OXYGEN CYLINDER AND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-35-011 PART (A)	INSPECTION SPECIAL CHECK/REWORK – OXYGEN SUPPLY SYSTEM – INSPECT SERIAL NO. OF OXYGEN CYLINDER AND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN OF SERIAL NUMBERS								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-35-011 PART (B)	REPLACEMENT SPECIAL CHECK/REWORK – OXYGEN SUPPLY SYSTEM – INSPECT SERIAL NO. OF OXYGEN CYLINDER AND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN OF THE OXYGEN STORAGE CYLINDER AND THE REGULATOR								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-35-011 REV 01	SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM - INSPECT SERIAL NO. OF OXYGEN CYLINDER AND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-35-011 REV 01 PART (A)	INSPECTION SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM - INSPECT SERIAL NO. OF OXYGEN CYLINDER AND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN OF SERIAL NUMBERS								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 35 - OXYGEN									
SB 700-35-011 REV 01 PART (B)	REPLACEMENT SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM - INSPECT SERIAL NO. OF OXYGEN CYLINDER AND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN OF THE OXYGEN STORAGE CYLINDER AND THE REGULATOR								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-35-012	SPECIAL CHECK/MODIFICATION - OXYGEN SUPPLY SYSTEM - INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT ON THE INFLATABLE HARNESS OF THE CREW OXYGEN MASK, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-35-012 REV 01	SPECIAL CHECK/MODIFICATION - OXYGEN SUPPLY SYSTEM - INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT ON THE INFLATABLE HARNESS OF THE CREW OXYGEN MASK, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-	EFF						
	HRS								
	AFL								
SB 700-35-013	ICA - MODIFICATION - OXYGEN CREW - REPLACEMENT OF FLEXIBLE RELIEF HOSES, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-	EFF						
	HRS								
	AFL								
SB 700-35-013 REV 01	ICA - MODIFICATION - OXYGEN CREW - REPLACEMENT OF FLEXIBLE RELIEF HOSES, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-35-014	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET (SUPERSEDED BY 700-35-014 REV 01), SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-	13-May-20						44.9
	HRS		3401.2						700.1
	AFL		1052						173
SB 700-35-014 REV 01	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET, SERVICE BULLETIN								Bulletin ATA:35
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
SB 700-35-015	MODIFICATION - OXYGEN SUPPLY SYSTEM - FLEXIBLE OXYGEN HOSE REPLACEMENT, SERVICE BULLETIN								Bulletin	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-35-015 PART A	ACCOMPLISH, SERVICE BULLETIN PART NUMBER INSPECTION ON EXISTING OXYGEN SYSTEM								Bulletin	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-35-015 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - FLEXIBLE OXYGEN HOSE REPLACEMENT								Bulletin	ATA:35
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-35-015 REV 01	MODIFICATION - OXYGEN SUPPLY SYSTEM - FLEXIBLE OXYGEN HOSE REPLACEMENT, SERVICE BULLETIN								Bulletin	ATA:35
	MOS/MSC	-	18-Mar-21						34.8	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-35-015 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN PART NUMBER INSPECTION ON EXISTING OXYGEN SYSTEM								Bulletin	ATA:35
	MOS/MSC	-	18-Mar-21						34.8	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-35-015 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - FLEXIBLE OXYGEN HOSE REPLACEMENT								Bulletin	ATA:35
	MOS/MSC	-	18-Mar-21						34.8	
	HRS		3474.7						626.6	
	AFL		1069						156	
TCCA CF-2011-10	OXYGEN SUPPLY SYSTEM – DEFORMATION OF THE PRESSURE REGULATOR ON THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY								AD	ATA:35
	DAYS/MSC	-	17-May-11						4653 d	
	HRS		28.5						4072.8	
	AFL		9						1216	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 35 - OXYGEN										
VSB 100009507-35-1 U	AVOX - REMOVAL FROM SERVICE OF ALL 898 SERIES CYLINDER AND REGULATOR ASSEMBLIES CRAS AND REGULATOR ASSEMBLIES IDENTIFIER BY PART NUMBER PNR AND SERIAL NUMBER SER, VENDOR SERVICE BULLETIN								Bulletin	ATA:35
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
VSB MXH-35-241 REV 2 U	OXYGEN - HARNESS ASSEMBLY - INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT, VENDOR SERVICE BULLETIN								Bulletin	ATA:35
	MOS/MSC	-	02-Jun-11						152.3	
	HRS		35.5						4065.8	
	AFL		13						1212	
ATA 36 - PNEUMATIC										
36-11-01-900-801-01	LH HIGH PRESSURE BLEED VALVE								Component	ATA:36
PN:GG436-1001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:00918	HRS		0	TSN 0					4101.3	
WC#: 36.005	AFL		0	TSN 0					1225	
				PROC. REF: AMM 36 11 01 000 801, AMM 36 11 01 400 801						
36-11-01-900-801-02	RH HIGH PRESSURE BLEED VALVE								Component	ATA:36
PN:GG436-1001-9	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:00892	HRS		0	TSN 0					4101.3	
WC#: 36.005	AFL		0	TSN 0					1225	
				PROC. REF: AMM 36 11 01 000 801, AMM 36 11 01 400 801						
36-11-05-900-801-01	LH CHECK INTERMEDIATE PRESSURE VALVE								Component	ATA:36
PN:GG436-1002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:00854	HRS		0	TSN 0					4101.3	
WC#: 36.010	AFL		0	TSN 0					1225	
				PROC. REF: AMM 36 11 05 000 801, AMM 36 11 05 400 801						
36-11-05-900-801-02	RH CHECK INTERMEDIATE PRESSURE VALVE								Component	ATA:36
PN:GG436-1002-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:00879	HRS		0	TSN 0					4101.3	
WC#: 36.010	AFL		0	TSN 0					1225	
				PROC. REF: AMM 36 11 05 000 801, AMM 36 11 05 400 801						
36-11-09-900-801-01	LH BLEED PRESS - REGULATING & S/O VALVE								Component	ATA:36
PN:GG436-1005-3	MOS/MSC	O/C	11-Jul-23	TSR 48					7	
SN:11221	HRS		4002.9	TSR 814.1					98.4	
WC#: 36.015	AFL		1192	TSR 196					33	
				PROC. REF: AMM 36 11 09 000 801, AMM 36 11 09 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
36-11-09-900-801-02	RH BLEED PRESS - REGULATING & S/O VALVE								Component ATA:36
PN:GG436-1055-3	MOS/MSC	O/C	12-Jul-23	TSR 0					7
SN:13605	HRS		4002.9	TSR 0					98.4
WC#: 36.015	AFL		1192	TSR 0					33
				PROC. REF: AMM 36 11 09 000 801, AMM 36 11 09 400 801					
36-11-13-900-801-01	LH PRECOOLER								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.020	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801					
36-11-13-900-801-02	RH PRECOOLER								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.020	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801					
36-11-13-900-802-01	LH PLENUM INLET								Component ATA:36
PN:GG468-4072-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0386	HRS		0	TSN 0					4101.3
WC#: 36.025	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801					
36-11-13-900-802-02	RH PLENUM INLET								Component ATA:36
PN:GG468-4072-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0326	HRS		0	TSN 0					4101.3
WC#: 36.025	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801					
36-11-17-900-801-01	LH FAN AIR VALVE								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.035	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 17 000 801, AMM 36 11 17 400 801					
36-11-17-900-801-02	RH FAN AIR VALVE								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.035	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 17 000 801, AMM 36 11 17 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
36-11-21-201	DISCARD OF THE LH PNEUMATIC TEMPERATURE THERMOSTAT (THC) FILTER								Service ATA:36
	MOS		19-Mar-21					12-Feb-2027	34.7
	HRS	2250	3474.7		5724.7		1623.4		626.6
	AFL		1069						156
				PROC. REF: AMM 36 11 21 961 801					PKG:6
36-11-21-201	DISCARD OF THE RH PNEUMATIC TEMPERATURE THERMOSTAT (THC) FILTER								Service ATA:36
	MOS		19-Mar-21					12-Feb-2027	34.7
	HRS	2250	3474.7		5724.7		1623.4		626.6
	AFL		1069						156
				PROC. REF: AMM 36 11 21 961 801					PKG:6
36-11-21-900-801-01	LH PNEUMATIC TEMP THERMOSTAT								Component ATA:36
PN:CG0752503458N02	MOS/MSC	O/C	19-Mar-16	TSN 1					94.7
SN:NA	HRS		1978.6	TSN 0					2122.7
WC#: 36.040	AFL		690	TSN 0					535
				PROC. REF: CMM 36-12-05, AMM 36 11 21 000 801, AMM 36 11 21 400 801					
36-11-21-900-801-02	RH PNEUMATIC TEMP THERMOSTAT								Component ATA:36
PN:CG0752503458N02	MOS/MSC	O/C	19-Mar-16	TSN 1					94.7
SN:N/A	HRS		1978.6	TSN 0					2122.7
WC#: 36.040	AFL		690	TSN 0					535
				PROC. REF: CMM 36-12-05, AMM 36 11 21 000 801, AMM 36 11 21 400 801					
36-11-25-900-801-01	LH BLEED PRESSURE TRANSDUCER								Component ATA:36
PN:GG436-1007-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2246	HRS		0	TSN 0					4101.3
WC#: 36.045	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 25 000 801, AMM 36 11 25 400 801					
36-11-25-900-801-02	RH BLEED PRESSURE TRANSDUCER								Component ATA:36
PN:GG436-1007-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2288	HRS		0	TSN 0					4101.3
WC#: 36.045	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 25 000 801, AMM 36 11 25 400 801					
36-11-29-900-801-01	LH BOOT								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.065	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
36-11-29-900-801-02	RH BOOT								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.065	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
36-11-29-900-802-01	CROSS BLEED VALVE								Component ATA:36
PN:GG436-1008-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:01096	HRS		0	TSN 0					4101.3
WC#: 36.070	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 29 000 801, AMM 36 11 29 400 801					
36-11-29-900-802-02	COUPLING COVER								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.075	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
36-11-33-900-801-01	LH BLEED MANAGEMENT (BMC) CONTROLLER								Component ATA:36
PN:GG546-1017-13	MOS/MSC	O/C	15-Jun-12						139.9
SN:00923	HRS		535.7						3565.6
WC#: 36.080	AFL		196						1029
				PROC. REF: AMM 36 11 33 000 801, AMM 36 11 33 400 801					
36-11-33-900-801-02	RH BLEED MANAGEMENT (BMC) CONTROLLER								Component ATA:36
PN:GG546-1017-13	MOS/MSC	O/C	15-Jun-12						139.9
SN:00922	HRS		535.7						3565.6
WC#: 36.080	AFL		196						1029
				PROC. REF: AMM 36 11 33 000 801, AMM 36 11 33 400 801					
36-11-37-900-801-01	LH IP PRESSURE TRANSDUCER								Component ATA:36
PN:GG436-1018-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1034	HRS		0	TSN 0					4101.3
WC#: 36.085	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 37 000 801, AMM 36 11 37 400 801					
36-11-37-900-801-02	RH IP PRESSURE TRANSDUCER								Component ATA:36
PN:GG436-1018-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1033	HRS		0	TSN 0					4101.3
WC#: 36.085	AFL		0	TSN 0					1225
				PROC. REF: AMM 36 11 37 000 801, AMM 36 11 37 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
36-11-41-900-801-01	HP GROUND CONNECTION								Component ATA:36
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 36.090	AFL		0	TSN 0					1225
			PROC. REF: AMM 36 11 41 000 801, AMM 36 11 41 400 801						
36-11-41-900-801-02	DUCT								Component ATA:36
PN:GG468-4066-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:0394	HRS		0	TSN 0					4101.3
WC#: 36.095	AFL		0	TSN 0					1225
			PROC. REF: GENERIC NO REF						
36-11-61-101	DISCARD APU CROSS BLEED VALVE UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-19	MOS		19-Mar-21					03-Oct-2037	34.7
SN:6826	HRS	8000	3474.7		11474.7		7373.4		626.6
	AFL		1069						156
			PROC. REF: AMM 36 11 61 961 801						
36-11-61-101	DISCARD L/H FLOW CONTROL VALVE UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4596	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
			PROC. REF: AMM 36 11 61 961 801						
36-11-61-101	DISCARD LEFT BLEED FILTER UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4511	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
			PROC. REF: AMM 36 11 61 961 801						
36-11-61-101	DISCARD LEFT HAND FAN AIR VALVE UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4164	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
			PROC. REF: AMM 36 11 61 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
36-11-61-101	DISCARD LEFT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-17	MOS		20-Dec-09					30-Apr-2031	169.7
SN:3385	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 36 11 61 961 801					
36-11-61-101	DISCARD LH FLOW SENSOR VENTURI UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4530	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 36 11 61 961 801					
36-11-61-101	DISCARD R/H FLOW CONTROL VALVE UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4536	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 36 11 61 961 801					
36-11-61-101	DISCARD RH FLOW SENSOR VENTURI UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4558	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 36 11 61 961 801					
36-11-61-101	DISCARD RIGHT BLEED FILTER UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4514	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 36 11 61 961 801					
36-11-61-101	DISCARD RIGHT CROSS BLEED VALVE UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-17	MOS		03-Nov-11					01-Oct-2031	147.3
SN:5793	HRS	8000	227.8		8227.8		4126.5		3873.5
	AFL		100						1125
				PROC. REF: AMM 36 11 61 961 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
36-11-61-101	DISCARD RIGHT HAND FAN AIR VALVE UROSEAL CONNECTOR								Service ATA:36
PN:GG468-4054-15	MOS		20-Dec-09					30-Apr-2031	169.7
SN:4259	HRS	8000	0		8000		3898.7		4101.3
	AFL		0						1225
				PROC. REF: AMM 36 11 61 961 801					
36-11-61-900-801-01	LH FLOW SENSOR VENTURI UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4530	HRS		0	TSN 0					4101.3
WC#: 21.115	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06					
36-11-61-900-801-02	RH FLOW SENSOR VENTURI UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4558	HRS		0	TSN 0					4101.3
WC#: 21.115	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06					
36-11-61-900-801-03	LEFT BLEED FILTER UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4511	HRS		0	TSN 0					4101.3
WC#: 21.120	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06					
36-11-61-900-801-04	RIGHT BLEED FILTER UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4514	HRS		0	TSN 0					4101.3
WC#: 21.120	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06					
36-11-61-900-801-05	L/H FLOW CONTROL VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4596	HRS		0	TSN 0					4101.3
WC#: 21.125	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06, AMM 21 51 25 000 801, AMM 21 51 25 400 801					
36-11-61-900-801-06	R/H FLOW CONTROL VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4536	HRS		0	TSN 0					4101.3
WC#: 21.125	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06, AMM 21 51 25 000 801, AMM 21 51 25 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
36-11-61-900-801-07	LEFT HAND FAN AIR VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4164	HRS		0	TSN 0					4101.3
WC#: 36.030	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06					
36-11-61-900-801-08	RIGHT HAND FAN AIR VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-15	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:4259	HRS		0	TSN 0					4101.3
WC#: 36.030	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06					
36-11-61-900-801-09	LEFT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-17	MOS/MSC	H/T	20-Dec-09	TSN 0					169.7
SN:3385	HRS		0	TSN 0					4101.3
WC#: 36.050	AFL		0	TSN 0					1225
				PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801					
36-11-61-900-801-10	RIGHT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-17	MOS/MSC	H/T	03-Nov-11	TSN 0					147.3
SN:5793	HRS		227.8	TSN 0					3873.5
WC#: 36.050	AFL		100	TSN 0					1125
				PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801					
36-11-61-900-801-11	APU CROSS BLEED VALVE UROSEAL CONNECTOR								Component ATA:36
PN:GG468-4054-19	MOS/MSC	H/T	19-Mar-21	TSN 0					34.7
SN:6826	HRS		3474.7	TSN 0					626.6
WC#: 36.055	AFL		1069	TSN 0					156
				PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801					
361203-702 U	#2 L/H WING SLAT LOOP "D"								Component ATA:36
PN:GG584-1033-7	MOS/MSC	O/C	10-Aug-16	TSN 0					90
SN:16745/72/2	HRS		2096	TSN 0					2005.3
	AFL		727	TSN 0					498
361204-701 U	LH WING BLEED LEAK DETECTION LOOP ELEMENT								Component ATA:36
PN:GG584-1033-7	MOS/MSC	O/C	19-Mar-16						94.7
SN:13762/52/1	HRS		1978.6	TSN 0					2122.7
	AFL		690	TSN 0					535

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 36 - PNEUMATIC										
FAA 2020-12-15[S]	PNEUMATIC - CABIN-PRESSURE CONTROL SYSTEM - MODIFICATION/INSPECTION								AD	ATA:36
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-12-15 PARA ([S])	MEASUREMENT OF THE TRUNNION NUT TORQUE OF THE V-BAND CLAMPS								AD	ATA:36
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-12-15 PARA ([S]) (1)	DO A GENERAL VISUAL INSPECTION FOR CRACKING AND DEFORMATION, FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNNION NUT TORQUE OF LESS THAN 80 LBF-IN; AND PERFORM CORRECTIVE ACTIONS								AD	ATA:36
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-12-15 PARA ([S]) (2)	DO A MAGNIFICATION INSPECTION FOR ANY CRACKING AND DEFORMATION OF THE SAFETY VALVE AND AIRPLANE BULKHEAD FLANGE AREA, FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF 80 LBF-IN OR HIGHER; PERFORM CORRECTIVE ACTIONS								AD	ATA:36
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-36-016	MODIFICATION - DISTRIBUTION - UROSEAL INSTALLATION BETWEEN DUCT ASSEMBLY AND PRECOOLER DOES NOT MATCH GAP REQUIREMENTS, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-36-016 REV 01	MODIFICATION - DISTRIBUTION - UROSEAL INSTALLATION BETWEEN DUCT ASSEMBLY AND PRECOOLER DOES NOT MATCH GAP REQUIREMENTS, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-36-017	MODIFICATION - BLEED AIR SYSTEM - INTRODUCTION OF NEW BLEED MANAGEMENT CONTROLLERS, PART NO. GG546-1017-11, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
SB 700-36-018	MODIFICATION - BLEED-AIR LEAK DETECTION SYSTEM - REPLACEMENT OF SUPPORT BRACKET FOR THE THERMAL ANTI-ICE (TAI) BLEED DETECTION WIRE, SERVICE BULLETIN								Bulletin ATA:36
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-36-021 REV 01	MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM - REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 01 PART (A)	REROUTE MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM - REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN THE TWO ELEMENTS OF THE BLEED-AIR LEAK-DETECTION SYSTEM								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 01 PART (B)	MODIFICATION MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM - REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN TO LEAK DETECTION ELEMENTS								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 01 PART (C)	RELOCATE MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM - REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN UPPER INSULATION VENT HOLE OF THE LEFT SIDE THREE-BRANCH DUCT								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 01 PART (D)	INSTALL MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM - REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN TWO BONDING JUMPERS								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 02	ICA - MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 36 - PNEUMATIC									
SB 700-36-021 REV 02 PART (A)	MODIFICATION ICA - MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN – TRIM AIR DUCT – BLEED LEAK-DETECTION ELEMENTS RELOCATION								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 02 PART (B)	MODIFICATION ICA - MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN – BLEED AIR DUCT – BLEED LEAK-DETECTION ELEMENTS RELOCATION								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 02 PART (C)	MODIFICATION ICA - MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN –THREE-BRANCH DUCT (LEFT SIDE) – RELOCATION OF INSULATION VENT HOLE								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-021 REV 02 PART (D)	MODIFICATION ICA - MODIFICATION - BLEED-AIR LEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN – INSTALLATION OF ADDITIONAL BONDING JUMPERS								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-023 PART (A)	SPECIAL CHECK/MODIFICATION - BLEED AIR SYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY (A/C 9002 TO 9126 AND 9128 TO 9234), SERVICE BULLETIN								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-023 PART (B)	SPECIAL CHECK/MODIFICATION - BLEED AIR SYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY (A/C 9002 TO 9126 AND 9128 TO 9220), SERVICE BULLETIN								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-36-023 REV 01	ICA - SPECIAL CHECK/MODIFICATION - BLEED AIR SYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY, SERVICE BULLETIN								Bulletin ATA:36
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 36 - PNEUMATIC										
SB 700-36-023 REV 01 PART (A)	SPECIAL CHECK ICA - SPECIAL CHECK/MODIFICATION - BLEED AIR SYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-36-023 REV 01 PART (B)	MODIFICATION ICA - SPECIAL CHECK/MODIFICATION - BLEED AIR SYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-36-024	MODIFICATION - BLEED AIR SYSTEM - UPGRADE BLEED MANAGEMENT CONTROLLERS (BMC) TO PART NO. GG546-1017-13, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-36-024 REV 01	MODIFICATION - BLEED AIR SYSTEM - UPGRADE BLEED MANAGEMENT CONTROLLERS (BMC) TO PART NO. GG546-1017-13, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	-	EFF							
	HRS									
	AFL									
SB 700-36-025	MODIFICATION - BLEED AIR SYSTEM - REPLACEMENT OF THE BLEED-PRESSURE REGULATING-AND-SHUTOFF VALVE (PRSOV), SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	-	17-Jul-19						54.8	
	HRS		3188.8						912.5	
	AFL		996						229	
SB 700-36-026	SPECIAL CHECK/REWORK - BLEED-AIR LEAK-DETECTION SYSTEM - SPECIAL CHECK ON THE KIDDE LEAK DETECTION LOOP ELEMENTS, SERVICE BULLETIN								Bulletin	ATA:36
	MOS/MSC	-	06-Dec-23						2.2	
	HRS		4099.1						2.2	
	AFL		1223						2	
ATA 38 - WATER/WASTE										
38-11-50-602 U S	OPERATIONAL TEST OF THE WATER SUPPLY SHUT-OFF CIRCUIT								Service	ATA:38
	MOS	15	05-Dec-23						2.2	
	HRS		4099.1						2.2	
	AFL		1223						2	

PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 38 - WATER/WASTE										
38-13-52-601 U S	DISCARD POTABLE WATER TREATMENT UNIT FILTER MODULE								Service	ATA:38
	MOS	15	06-Dec-23						2.2	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
38-31-50-601 U S	GENERAL VISUAL INSPECTION OF THE FORWARD TOILET INSTALLATION								Service	ATA:38
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
38-32-50-601 U S	GENERAL VISUAL INSPECTION OF THE AFT TOILET INSTALLATION								Service	ATA:38
	MOS	15	30-Nov-23						2.4	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
38-90-00-000-145 U	HEATED HOSE (UNDER BAGGAGE COMPARTMENT FLOOR)								Component	ATA:38
PN:4E4422-10	MOS/MSC	O/C	27-Apr-21	TSN 0					33.5	
SN:N2003002	HRS		3533.7	TSN 0					567.6	
	AFL		1082	TSN 0					143	
380000-706 U	HEATED 1/2 ID HOSE								Component	ATA:38
PN:4E4422-09	MOS/MSC	O/C	07-Nov-18						63.1	
SN:N173402	HRS		2995.9						1105.4	
	AFL		948						277	
380000-709 U	HEATED 1/2 ID HOSE								Component	ATA:38
PN:4E4422-15	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:N1015501	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
380000-715 U	HEATED 1/2 ID HOSE								Component	ATA:38
PN:4E4422-21	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:N1012702	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
380000-717 U	HEATED 1/2 ID HOSE								Component ATA:38
PN:4E4422-25	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1021801	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380000-721 U	HEATED HOSE								Component ATA:38
PN:4E4422-41	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1021801	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380000-722 U	HEATED 1/2 ID (F.STA 789.5, .L. 82.5) HOSE								Component ATA:38
PN:4E4422-25	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1014801	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380001-703 U	HEATER VALVE								Component ATA:38
PN:4E4372-8	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:0264	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380002-701 U	HEATED 3/4" HOSE								Component ATA:38
PN:4E4425-18	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1021801	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380002-702 U	AFT LAVATORY HEATED DRAIN FLEX 3/4 HOSE								Component ATA:38
PN:4E4376-3	MOS/MSC	O/C	12-Jul-18	TSN 4					67
SN:N1805201	HRS		2892.3	TSN 0					1209
	AFL		921	TSN 0					304
380002-716 U	HEATED 3/4 ID HOSE								Component ATA:38
PN:4E4425-08	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1015501	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380003-701 U	VENT VALVE								Component ATA:38
PN:4E3261-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:0988	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 38 - WATER/WASTE										
380003-702 U	VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0989	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
380003-703 U	VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0926	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
380003-704 U	VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0931	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
380003-705 U	VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0932	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
380003-706 U	VENT VALVE								Component	ATA:38
PN:4E3261-5	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:0933	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
380006-706 U	MOTORIZED WITH MANUAL OVERRIDE VALVE								Component	ATA:38
PN:4E4348-13	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:N0832202	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
380007-701 U	POTABLE WATER TREATMENT UNIT								Component	ATA:38
PN:09-130021-102	MOS/MSC	O/C	06-Jul-18						67.2	
SN:1-0983	HRS		2892.3						1209	
	AFL		923						302	
380007-701A U S	RESTORE POTABLE WATER TREATMENT UNIT (38-13-50-601)								Service	ATA:38
PN:09-130021-102	MOS		06-Jul-18						67.2	
SN:1-0983	HRS	3000	2892.3						1209	
	AFL		921						304	

PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
380012-701 U	MOTORIZED VALVE								Component ATA:38
PN:4E4348-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1018801	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380012-702 U	MOTORIZED VALVE								Component ATA:38
PN:4E4348-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1018802	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380012-703 U	MOTORIZED VALVE								Component ATA:38
PN:4E4348-7	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1018803	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
380027-701 U	HEATED WYE FITTING								Component ATA:38
PN:4E3389-19	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:0178	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381000-701 U	CONTROL EIB PWS (A750) FS440 LH UNIT								Component ATA:38
PN:5E2651-20	MOS/MSC	O/C	08-Mar-13						131.1
SN:U174	HRS		850.3						3251
	AFL		332						893
381001-701 U	CONTROL PANEL, BACKUP (EIB) UNIT								Component ATA:38
PN:4E4381-1	MOS/MSC	O/C	20-Jul-20	TSN 0					42.7
SN:UC208	HRS		3416.1	TSN 0					685.2
	AFL		1057	TSN 0					168
381002-701 U	#1 POTABLE WATER SYSTEM PUMP								Component ATA:38
PN:4E4360-1	MOS/MSC	O/C	09-Jun-23	TSN 0					8.1
SN:C2142	HRS		3978.4	TSN 0					122.9
	AFL		1187	TSN 0					38
381002-702 U	#2 POTABLE WATER SYSTEM PUMP								Component ATA:38
PN:4E4360-1	MOS/MSC	O/C							
SN:UNKNOWN	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
381100-701 U	TOILET (FWD LAVATORY) ASSEMBLY								Component ATA:38
PN:7900368	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:0019	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381101-701 U	WATER (FWD LAVATORY) HEATER								Component ATA:38
PN:4E4099-2	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1022304	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381200-701 U	WATER (GALLEY) HEATER								Component ATA:38
PN:4E4099-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1024306	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381300-701 U	TOILET (AFT LAVATORY) ASSEMBLY								Component ATA:38
PN:7900268	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:63-1438	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381301-701 U	WATER (AFT LAVATORY) HEATER								Component ATA:38
PN:4E4099-3	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1016802	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381302-701 U	HEATER INTERFACE (AFT LAVATORY) UNIT								Component ATA:38
PN:7800367	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:262	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381303-701 U	LOGIC CONTROL MODULE								Component ATA:38
PN:7700721	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:172	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
381304-701 U	VACUUM SWITCH								Component ATA:38
PN:7700750	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:276	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
381305-702 U	AFT LAVATORY RINSE VALVE								Component ATA:38
PN:7800001-008	MOS/MSC	O/C	21-Jul-15	TSN 0					102.7
SN:14050108	HRS		1712.9	TSN 0					2388.4
	AFL		624	TSN 0					601
384200-701 U	CHECK FLOAT VALVE								Component ATA:38
PN:4E4350-2	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:N1016902	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
387200-701 U	PUMP DIAPHRAGM 4GPM 115V UNIT								Component ATA:38
PN:75102-00	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:09L30010	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
389501-701 U	LOGIC CONTROL MODULE UNIT								Component ATA:38
PN:7700928	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:0130	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
MODSUM IS700-38-000 U REV A	INTRODUCTION OF VENT HOLE ON WASTE CAP ASSY P/N 2651-126C OR P/N 2651-126A, MODIFICATION SUMMARY								Bulletin ATA:38
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-38-002	SPECIAL CHECK/REWORK - MAGAIR VACUUM TOILET, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-003	SPECIAL CHECK/REWORK - POTABLE WATER SYSTEM OPERATION (AIR PRESSURIZED), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-004 PART (A)	SPECIAL CHECK/REWORK - POTABLE WATER SYSTEM - CHECK FOR CORROSION IN FORWARD AND/OR AFT WATER TANKS AND REPLACEMENT OF UNSERVICEABLE WATER TANK(S), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
SB 700-38-004 PART (B)	SPECIAL CHECK/REWORK - POTABLE WATER SYSTEM - CHECK FOR CORROSION IN FORWARD AND/OR AFT WATER TANKS AND REPLACEMENT OF UNSERVICEABLE WATER TANK(S), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-004 PART (C)	SPECIAL CHECK/REWORK - POTABLE WATER SYSTEM - CHECK FOR CORROSION IN FORWARD AND/OR AFT WATER TANKS AND REPLACEMENT OF UNSERVICEABLE WATER TANK(S), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-005 PART (A)	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF AFT LIQUID LEVEL SENSOR AND MODIFICATION OF AFT HEATED WASTE LINE AND AFT WASTE TANK VENTING SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-005 PART (B)	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF AFT LIQUID LEVEL SENSOR AND MODIFICATION OF AFT HEATED WASTE LINE AND AFT WASTE TANK VENTING SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-005 PART (C)	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF AFT LIQUID LEVEL SENSOR AND MODIFICATION OF AFT HEATED WASTE LINE AND AFT WASTE TANK VENTING SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-006 PART (A)	SPECIAL CHECK - CHECK FOR UNSERVICEABLE HYDRAFLOW HOSES., SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-006 PART (B)	MODIFICATION - INSTALLATION OF UPGRADED MAGAIR TOILET ASSEMBLY(S), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
SB 700-38-006 PART (C)	MODIFICATION - INSTALLATION OR REPLACEMENT OF HYDRAFLOW HOSE(S), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-007	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF INLET FITTING, FORWARD LIQUID LEVEL SENSOR (LLS) AND ADDITION OF WATER SEPARATOR TO THE VENT LINE ON THE FORWARD WASTE HOLDING TANK AND REACTIVATION OF FORWARD LLS (AS NECESSARY)., SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-008	MODIFICATION - FORWARD CANTED DRAIN MAST (A/C 9002, 9004 TO 9095, AND 9097 TO 9153), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-008 REV 01	MODIFICATION - WASTE DISPOSAL - INSTALLATION OF CANTED DRAIN MAST (A/C 9002, 9004 TO 9095, AND 9097 TO 9153), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-008 REV 02	MODIFICATION – WASTE DISPOSAL – INSTALLATION OF CANTED DRAIN MAST, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-013	MODIFICATION - POTABLE WATER SYSTEM - IMPROVEMENT OF THE WATER TANKS PURGE PERFORMANCE. (SEE SB OR NOTE ON WORKCARD FOR EFFECTIVITY)., SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-013 REV 01	MODIFICATION - POTABLE WATER SYSTEM - IMPROVEMENT OF THE WATER TANKS PURGE PERFORMANCE, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
SB 700-38-014	MODIFICATION - GENERAL - REWIRE TEMPERATURE SENSOR TO PREVENT FREEZING IN THE AFT WATER SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-015	MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-015 PART (A)	INSTALL MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN NEW FORWARD 13 GALLON PARKER AIR/FUEL WATER TANK, PART NO. 330-0039-02 (BOMBARDIER PART NO. BAS67038442-3),								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-015 PART (B)	INSTALL MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN NEW AFT 13 GALLON PARKER AIR/FUEL WATER TANK, PART NO. 330-0039-02 (BOMBARDIER PART NO. BAS67038442-3)								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-015 REV 01	MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-015 REV 01 PART (A)	REPLACEMENT MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN OF THE FORWARD WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-015 REV 01 PART (B)	REPLACEMENT MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN OF THE AFT WATER TANK(S)								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
SB 700-38-016	MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-016 PART (A)	REPLACEMENT MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN OF THE FORWARD WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-016 PART (B)	REPLACEMENT MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN OF THE AFT WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-018	WATER TANK PRESSURIZATION SYSTEM - RELOCATION OF THE PRESSURE SENSOR, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-019	MODIFICATION - WASTE DISPOSAL - REPLACE VACUUM HOSE WITH RIGID PIPE, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-38-020	REWORK - POTABLE WATER SYSTEM (PWS) - TERMINATE CES WIRING TO EIB (EFFECTIVITY: A/C 9167, 9171, 9181, 9185, 9187, 9193), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-38-022	MODIFICATION - POTABLE WATER SYSTEM (PWS) - REPLACE VENT VALVES THAT MAY CAUSE WATER LEAKS (A/C 9167, 9171 TO 9194 AND 9196 TO 9205), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
SB 700-38-023	MODIFICATION - POTABLE WATER SYSTEM (PWS) - REPLACE WATER TANK VENT VALVES THAT MAY CAUSE WATER LEAKS (A/C 9167, 9171 TO 9264), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-024	MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-024 PART (A)	ACCESS MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN THE FORWARD 13 GALLON SHAW AERO DEVICES WATER TANK(S)								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-024 PART (B)	ACCESS MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN THE AFT 13 GALLON SHAW AERO DEVICES WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-025 PART (A)	MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-025 PART (B)	MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-025 REV 01	MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
SB 700-38-025 REV 01 PART (A)	REPLACEMENT MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN OF THE FORWARD WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-025 REV 01 PART (B)	REPLACEMENT MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN OF THE AFT WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-026 PART (A)	MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-026 PART (B)	MODIFICATION - POTABLE WATER SYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-026 REV 01	MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-026 REV 01 PART (A)	REPLACEMENT MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN OF THE FORWARD WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-026 REV 01 PART (B)	REPLACEMENT MODIFICATION – POTABLE WATER SYSTEM – INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN OF THE AFT WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 38 - WATER/WASTE										
SB 700-38-027	MODIFICATION - WASTE DISPOSAL - SEALING THE MAGAIR TOILET BASE TO PREVENT STRUCTURAL DAMAGE, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-029	MODIFICATION - WASTE DISPOSAL - ADDITION OF A GALLEY DRAIN, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-030	MODIFICATION - WASTE DISPOSAL - RELOCATION OF CHILLER DRAIN LINES TO PREVENT FREEZING AND SUBSEQUENT WATER SPILLS, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-031 U	PROOF - WATER SYS - QUICK DISCONNECT FOR WATER TREATMENT UNIT, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-	18-Nov-11						146.8	
	HRS		257.4						3843.9	
	AFL		109						1116	
SB 700-38-032	MODIFICATION – POTABLE WATER SYSTEM – SECURE BLANKET HEATER TO WASTE WATER TEE-FITTING BELOW FLOOR, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-38-033	MODIFICATION - WASTE DISPOSAL - INTRODUCTION OF IMPROVED RINSE VALVE TO PREVENT RINSE VALVE LEAKAGE, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	T:A/R								
	HRS									
	AFL									
SB 700-38-033 REV 01	MODIFICATION - WASTE DISPOSAL - INTRODUCTION OF IMPROVED RINSE VALVE TO PREVENT RINSE VALVE LEAKAGE, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 38 - WATER/WASTE										
SB 700-38-034	MODIFICATION - POTABLE WATER SYSTEM - FWD LAV CLAMP RELOCATION, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-034 PART (A)	INSPECTION MODIFICATION - POTABLE WATER SYSTEM - FWD LAV CLAMP RELOCATION, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-034 PART (B)	MODIFICATION MODIFICATION - POTABLE WATER SYSTEM - FWD LAV CLAMP RELOCATION, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-035	MODIFICATION - WASTE DISPOSAL - ADDITION OF HEATER AND INSULATION BLANKET TO THE DELTA PRESSURE (DP) SENSOR OF THE WATER TANK ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-	08-Mar-13						131.1	
	HRS		850.3						3251	
	AFL		332						893	
SB 700-38-036	MODIFICATION - POTABLE WATER SYSTEM - INSTALLATION OF WATER TREATMENT UNIT BYPASS SWITCH, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-036 REV 01	MODIFICATION - POTABLE WATER SYSTEM - INSTALLATION OF WATER TREATMENT UNIT BYPASS SWITCH, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-38-037	MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 38 - WATER/WASTE									
SB 700-38-037 PART (A)	REPLACEMENT MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN OF THE FORWARD WATER TANK(S)								Bulletin ATA:38
	MOS/MSC	-	EFF						
	HRS								
	AFL		EFF						
SB 700-38-037 PART (B)	REPLACEMENT MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN OF THE AFT WATER TANK								Bulletin ATA:38
	MOS/MSC	-	EFF						
	HRS								
	AFL		EFF						
SB 700-38-037 REV 01	MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-037 REV 01 PART (A)	REPLACEMENT MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN OF FORWARD WATER TANK(S)								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-037 REV 01 PART (B)	REPLACEMENT MODIFICATION - POTABLE WATER SYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN OF AFT WATER TANK								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-039	WATER TREATMENT UNIT (WTU) - STLMC UPDATE FOR THE RESTORATION OF POTABLE WATER TREATMENT UNIT (WTU), SERVICE BULLETIN								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-38-039 PART A	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE STLMC TASK 38-13-50-601 WITH NEW STLMC TEMPORARY REVISIONS								Bulletin ATA:38
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 38 - WATER/WASTE										
SB 700-38-039 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF THE UV FILTER								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700D38-009 REV 03	MODIFICATION - PROVISIONS - GENERAL - ENVIROVAC WASTE SYSTEM KIT INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-								
	HRS									
	AFL									
SB 700D38-011 U	REWORK - PROVISIONS - GENERAL - REWORK INTERIOR FURNISHINGS AND STRUCTURAL PROVISIONS FOR THE WATER SYSTEM - KIT INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	A/R	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
VSB 7900268-38-02 U	INSTALLATION OF ENVIRO-CLEAN SYSTEM ON VACUUM TOILET ASSEMBLIES, VENDOR SERVICE BULLETIN								Bulletin	ATA:38
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
ATA 44 - CABIN SYSTEMS										
441001-701 U	TOUCHSCREEN 10.4" (TSE) MONITOR-								Component	ATA:44
PN:1308520-100	MOS/MSC	O/C	03-Aug-17	TSR 63					78.3	
SN:2DY2H	HRS		2500.6	TSR 1650.3					1600.7	
	AFL		835	TSR 503					390	
441001-702 U	TOUCHSCREEN 10.4" (TSE) MONITOR-								Component	ATA:44
PN:1308520-100	MOS/MSC	O/C	16-Jul-20						42.8	
SN:3JRGT	HRS		3416.1						685.2	
	AFL		1057						168	
441001-703 U	TOUCHSCREEN 10.4" (TSE) MONITOR-								Component	ATA:44
PN:1308520-100	MOS/MSC	O/C	03-Aug-17	TSN 74					78.3	
SN:3NKRT	HRS		2500.6	TSN 2453.2					1600.7	
	AFL		835	TSN 818					390	
441001-704 U	TOUCHSCREEN 10.4" (TSE) MONITOR-								Component	ATA:44
PN:1308520-100	MOS/MSC	O/C	18-Nov-11						146.8	
SN:3JRGT	HRS		257.4						3843.9	
	AFL		109						1116	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
441003-701 U	21.3" ETHERNET MONITOR-								Component ATA:44
PN:866-0022-003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:EM0024	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441003-702 U	21.3" ETHERNET MONITOR-								Component ATA:44
PN:866-0022-003	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:EM0028	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441003-703 U	21.3" ETHERNET MONITOR-								Component ATA:44
PN:866-0022-003	MOS/MSC	O/C	19-Mar-21	TSR 12					34.7
SN:EM0104	HRS		3474.7	TSR 0					626.6
	AFL		1069	TSR 0					156
441004-701 U	ETHERNET SWITCHING (MCE #1) EQUIPMENT								Component ATA:44
PN:822-1943-002	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3TW8W	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441004-702 U	ETHERNET SWITCHING (MCE #2) EQUIPMENT								Component ATA:44
PN:822-1943-002	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:25MCF	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441005-701 U	MOVING MAP EQUIPMENT, MME-6000 EQUIPMENT								Component ATA:44
PN:822-1881-101	MOS/MSC	O/C	14-Apr-13	TSO 0					129.9
SN:2NF9F	HRS		923.4	TSO 0					3177.9
	AFL		356	TSO 0					869
441006-701 U	PROCESSOR / MASS STORAGE EQUIP. (MCE #1) EQUIPMENT								Component ATA:44
PN:822-1880-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3TWBK	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441006-702 U	PROCESSOR / MASS STORAGE EQUIP. (MCE #2) EQUIPMENT								Component ATA:44
PN:822-1880-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3TWCH	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
441007-701 U	MCE #1 POWER SUPPLY								Component ATA:44
PN:822-1879-001	MOS/MSC	O/C	09-Jul-18	TSO 2					67.1
SN:4BBDL	HRS		2892.3	TSO 0					1209
	AFL		921	TSO 0					304
441007-702 U	MCE #2 POWER SUPPLY								Component ATA:44
PN:822-1879-001	MOS/MSC	O/C	09-Jul-18	TSO 2					67.1
SN:4L2NT	HRS		2892.3	TSO 0					1209
	AFL		921	TSO 0					304
441008-701 U	NO. 1 ZONE DISTRIBUTION EQUIPMENT								Component ATA:44
PN:1308523-101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3NL2P	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441008-702 U	NO. 2 ZONE DISTRIBUTION EQUIPMENT								Component ATA:44
PN:1308523-101	MOS/MSC	O/C	29-Jun-22	TSO 0					19.4
SN:42B4M	HRS		3790.6	TSO 0					310.7
	AFL		1142	TSO 0					83
441008-703 U	NO. 3 ZONE DISTRIBUTION EQUIPMENT								Component ATA:44
PN:1308523-101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3XBMW	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441008-704 U	NO. 4 ZONE DISTRIBUTION EQUIPMENT								Component ATA:44
PN:1308523-101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3NKYY	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441008-705 U	NO. 5 ZONE DISTRIBUTION EQUIPMENT								Component ATA:44
PN:1308523-101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3NL2T	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441009-701 U	NO.1 RELAY DRIVE (RDE) EQUIPMENT								Component ATA:44
PN:2052-1-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3RXPK	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
441009-702 U	NO.2 RELAY DRIVE (RDE) EQUIPMENT								Component ATA:44
PN:2052-1-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3RXPL	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441009-704 U	NO.4 RELAY DRIVE (RDE) EQUIPMENT								Component ATA:44
PN:2052-1-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3RXPT	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441009-705 U	NO.5 RELAY DRIVE (RDE) EQUIPMENT								Component ATA:44
PN:2052-1-10	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3JWBJ	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441010-701 U	MODULAR CABINET EQUIPMENT. (MCE #1) EQUIPMENT								Component ATA:44
PN:822-1877-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3TWFC	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441010-702 U	MODULAR CABINET EQUIPMENT. (MCE #2) EQUIPMENT								Component ATA:44
PN:822-1877-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3TWGL	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441011-701 U	COOLING - MCE #1 FAN								Component ATA:44
PN:822-1916-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3TWCD	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441011-702 U	COOLING - MCE #2 FAN								Component ATA:44
PN:822-1916-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3TWCF	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441012-701 U	10.4" MONITOR ARM PLUG								Component ATA:44
PN:200-97450-101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50344	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
441012-702 U	10.4" MONITOR ARM PLUG								Component ATA:44
PN:200-97450-101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50472	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441012-703 U	10.4" MONITOR ARM PLUG								Component ATA:44
PN:200-97450-101	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50583	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-701 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50729	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-702 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA51388	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-703 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50731	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-704 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50732	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-705 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50733	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-706 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50734	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
441013-707 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50735	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-708 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50736	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-709 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50739	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-710 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50741	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-711 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50742	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441013-712 U	SIDELEDGE PLUG-IN ARM BASE MONITOR-								Component ATA:44
PN:200-92797-102	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:MA50730	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441015-701 U	MULTI-MODE WIRELESS LAN UNIT, WLU2 ASSEMBLY								Component ATA:44
PN:822-2210-001	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:181L5G	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
441015-702 U	WIRELESS LAN UNIT								Component ATA:44
PN:822-2210-001	MOS/MSC	O/C	17-May-11						152.8
SN:18C49R	HRS		28.5	TSN 0					4072.8
	AFL		9	TSN 0					1216

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
442001-701 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703GL	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-702 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703GY	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-703 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703H8	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-704 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703JF	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-705 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703JN	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-706 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703JT	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-707 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703JW	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-708 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703K1	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
442001-709 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703K6	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-710 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703KD	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-711 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703LG	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-712 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703LS	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-713 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703LT	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-714 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC01703LW	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-715 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC0310486	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442001-716 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3CC03402FD	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
442001-717 U	CONTROL, WIRELESS (WPCU)/ LOOSE UNIT								Component ATA:44
PN:FA979AA	MOS/MSC	O/C	17-Jun-11						151.8
SN:3CC04804WC	HRS		43.3	TSN 0					4058
	AFL		15	TSN 0					1210
442002-701 U	VIDEO ENCODER (VEE) #1 EQUIPMENT								Component ATA:44
PN:1308525-100	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3X9WY	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442002-702 U	VIDEO ENCODER (VEE) #2 EQUIPMENT								Component ATA:44
PN:1308525-100	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3NL0G	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442002-703 U	VIDEO ENCODER (VEE) #3 EQUIPMENT								Component ATA:44
PN:1308525-100	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3XDOM	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442003-701 U	AUDIO AMPLIFIER								Component ATA:44
PN:3600-1-2	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:3RYFP	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
442005-701 U	ETHERNET PLAYER CD/DVD/MP3 #1 UNIT								Component ATA:44
PN:866-0025-001	MOS/MSC	O/C	17-Jul-19	TSR 0					54.8
SN:004998	HRS		3188.8	TSR 0					912.5
	AFL		996	TSR 0					229
442005-702 U	ETHERNET PLAYER CD/DVD/MP3 #2 UNIT								Component ATA:44
PN:866-0025-001	MOS/MSC	O/C	14-Dec-23						1.9
SN:004322	HRS		4099.1						2.2
	AFL		1223						2
442312-701 U	MONITOR FAN UNIT								Component ATA:44
PN:009-0287-110	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:00265	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 44 - CABIN SYSTEMS										
442312-702 U	MONITOR FAN UNIT								Component	ATA:44
PN:009-0287-110	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:00266	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016								AD	ATA:44
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
Category: APPLIANCE										
SB 700-44-003	MODIFICATION - CABIN SYSTEMS - WIRELESS PASSENGER CONTROL UNIT (WPCU) SMART DOCK INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-44-003 REV 01	MODIFICATION - CABIN SYSTEMS - WIRELESS PASSENGER CONTROL UNIT (WPCU) SMART DOCK INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-	EFF							
	HRS									
	AFL									
SB 700-44-004	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGER CONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION WITH THE POST SMART DOCK INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-44-004 REV 01	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGER CONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION WITH THE POST SMART DOCK INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-44-004 REV 02	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGER CONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION WITH THE POST SMART DOCK INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 44 - CABIN SYSTEMS									
SB 700-44-006	INSPECTION - CABIN ELECTRONICS SYSTEM - VARIABLE FREQUENCY CABLES, SAC HARNESSES, CMS EMI CONNECTORS, GFI OUTLETS AND QUADRAX CONNECTORS, SERVICE BULLETIN								Bulletin ATA:44
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-44-007	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGER CONTROL UNIT (WPCU) NEW IPOD TOUCH (5) INSTALLATION, SERVICE BULLETIN								Bulletin ATA:44
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-44-007 REV 01	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGER CONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION, SERVICE BULLETIN								Bulletin ATA:44
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-44-011	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM (SUPERSEDED BY 700-44-011 REV 01), SERVICE BULLETIN								Bulletin ATA:44
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-44-011 REV 01	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM (SUPERSEDED BY 700-44-011 REV 02), SERVICE BULLETIN								Bulletin ATA:44
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-44-011 REV 02	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA-BAND SATELLITE DATA SYSTEM (SUPERSEDED BY 700-44-011 REV 03), SERVICE BULLETIN								Bulletin ATA:44
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-44-011 REV 03	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA-BAND SATELLITE DATA SYSTEM, SERVICE BULLETIN								Bulletin ATA:44
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 44 - CABIN SYSTEMS										
SB 700-44-012	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-44-012 REV 01	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-44-012 REV 02	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-44-014	MODIFICATION - CABIN SYSTEMS - JETWAVE SYSTEMS - BLV7.1 SOFTWARE UPDATE, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-44-014 REV 01	MODIFICATION - CABIN SYSTEMS - JETWAVE SYSTEMS - BLV7.1 SOFTWARE UPDATE, SERVICE BULLETIN								Bulletin	ATA:44
	MOS/MSC	-								
	HRS									
	AFL									
ATA 45 - CENTRAL MAINT SYSTEM										
45-45-00-201[S]	VISUAL CHECK OF THE ENGINE MAINTENANCE ALERTS								Service	ATA:45
	MOS		30-Nov-23						2.4	
	HRS	500 (+50/-50)	4099.1						2.2	
	AFL		1223						2	
				PROC. REF: AMM 71 00 00 210 803						PKG:2
454501-701[U]	PORTABLE MAINTENANCE ACCESS TERMINAL - PMAT								Component	ATA:45
PN:7023300-801	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09100621	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 45 - CENTRAL MAINT SYSTEM										
454502-701 U	PMAT BATTERY								Component	ATA:45
PN:7039534-400	MOS/MSC	O/C	04-Oct-16	TSN 0					88.2	
SN:234	HRS		2154.6	TSN 0					1946.7	
	AFL		745	TSN 0					480	
SB 700-45-001	MODIFICATION - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS) - INSTALLATION OF THE CAIMS REPORT-TO-PRINTER SWITCH, SERVICE BULLETIN								Bulletin	ATA:45
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-45-001 REV 01	MODIFICATION - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS) - INSTALLATION OF THE CAIMS REPORT-TO-PRINTER SWITCH (A/C 9002 TO 9139), SERVICE BULLETIN								Bulletin	ATA:45
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-45-004	MODIFICATION - CENTRAL MAINTENANCE SYSTEM - PORTABLE MAINTENANCE ACCESS TERMINAL (PMAT) (AM-200) PART NUMBER CHANGE, SERVICE BULLETIN								Bulletin	ATA:45
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-45-006	MODIFICATION - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE SYSTEM (CAIMS) - INSTALL PORTABLE MAINTENANCE-ACCESS TERMINAL (PMAT) AND CABLE ASSEMBLY ON GREEN AIRCRAFT, SERVICE BULLETIN								Bulletin	ATA:45
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-45-008	MODIFICATION - CENTRAL AIRCRAFT INFORMATION MAINTENACE SYSTEM (CAIMS) - INTRODUCTION OF CAIMS VERSION 7.1 TO SUPPORT POST FULL FUNCTIONALITY CERTIFICATION (PFF), SERVICE BULLETIN								Bulletin	ATA:45
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-45-009	MODIFICATION - CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) - INTRODUCTION OF PORTABLE MAINTENANCE ACCESS TERMINAL (PMAT) SOFTWARE VERSION 7.3 - FOR A/C S/N 9002 TO 9165, SERVICE BULLETIN								Bulletin	ATA:45
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 45 - CENTRAL MAINT SYSTEM									
SB 700-45-010	MODIFICATION - CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) - INTRODUCTION OF PMAT -801 (A/C 9002 TO 9205), SERVICE BULLETIN								Bulletin ATA:45
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-45-010 REV 01	MODIFICATION – CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS) – INTRODUCTION OF PMAT -801, SERVICE BULLETIN								Bulletin ATA:45
	MOS/MSC	-							
	HRS								
	AFL								
ATA 46 - INFORMATION SYSTEMS									
461013-701 U	LH GDC 64 TABLET TO AIRCRAFT INTERFACE UNIT (TAIU)								Component ATA:46
PN:1104-4000-01	MOS/MSC	O/C	05-Jul-21	TSN 0					31.2
SN:21907	HRS		3609	TSN 0					492.3
	AFL		1101	TSN 0					124
461013-702 U	RH GDC 64 TABLET TO AIRCRAFT INTERFACE UNIT (TAIU)								Component ATA:46
PN:1104-4000-01	MOS/MSC	O/C	05-Jul-21	TSN 0					31.2
SN:21908	HRS		3609	TSN 0					492.3
	AFL		1101	TSN 0					124
462001-701 U	LH EDU, FLIGHT BAG - UNIT								Component ATA:46
PN:245-604128-000	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:2011	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
462001-702 U	RH EDU, FLIGHT BAG - UNIT								Component ATA:46
PN:245-604128-000	MOS/MSC	O/C	09-Jun-11						152.1
SN:2176	HRS		41	TSN 0					4060.3
	AFL		14	TSN 0					1211
SB 700-46-001	MODIFICATION - ELECTRONIC FLIGHT BAG (EFB) SYSTEM - CMC ELECTRONIC FLIGHT BAG (EFB) UPGRADE, SERVICE BULLETIN								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 46 - INFORMATION SYSTEMS									
SB 700-46-001 REV 01	MODIFICATION - ELECTRONIC FLIGHT BAG (EFB) SYSTEM - CMC ELECTRONIC FLIGHT BAG (EFB) UPGRADE, SERVICE BULLETIN								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-46-001 REV 01 PART (A)	ACCOMPLISH, SERVICE BULLETIN EFB REMOVAL								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-46-001 REV 01 PART (B)	ACCOMPLISH, SERVICE BULLETIN EFB INSTALLATION								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-46-001 REV 02	MODIFICATION - ELECTRONIC FLIGHT BAG (EFB) SYSTEM - CMC ELECTRONIC FLIGHT BAG (EFB) UPGRADE, SERVICE BULLETIN								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-46-001 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN EFB REMOVAL								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-46-001 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN EFB INSTALLATION								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-46-005	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM, SERVICE BULLETIN								Bulletin ATA:46
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 46 - INFORMATION SYSTEMS										
SB 700-46-005 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - AHMS STRUCTURAL AND WIRE PROVISIONS								Bulletin	ATA:46
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-46-005 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - CABIN ROUTER OPTION PROVISIONS								Bulletin	ATA:46
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-46-005 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - AVHMS COMPLETIONS								Bulletin	ATA:46
	MOS/MSC	-								
	HRS									
	AFL									
ATA 49 - AIRBORNE AUXILIARY POWER										
49-11-00-201[S]	VISUAL CHECK OF THE SUPPORT MOUNTINGS								Service	ATA:49
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 49.005	AFL		1171						54	
				PROC. REF: AMM 49 11 00 210 801						PKG:32
49-11-01-201[S]	VISUAL CHECK OF THE MOUNTING STRUTS								Service	ATA:49
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 49.010	AFL		1171						54	
				PROC. REF: AMM 49 11 01 210 801						PKG:32
49-14-05-101	DISCARD THE APU DOOR LINEAR ACTUATOR, PART NO. 8653M9								Service	ATA:49
PN:8653M12	MOS/MSC	N/A	20-Dec-09						169.7	
SN:UNKNOWN	HRS		0						4101.3	
	AFL		0						1225	
				PROC. REF: AMM 49 14 05 961 801						
49-14-05-900-801-01	LINEAR ACTUATOR								Component	ATA:49
PN:8653M12	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 49.040	AFL		0	TSN 0					1225	
				PROC. REF: AMM 49 14 05 000 801, AMM 49 14 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 49 - AIRBORNE AUXILIARY POWER										
49-15-00-201[S]	GENERAL VISUAL INSPECTION OF THE OIL COOLER-DUCT AND BOOT ASSEMBLY								Service	ATA:49
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 49.015	AFL		1171						54	
				PROC. REF: AMM 49 15 00 210 801						PKG:32
49-15-09-201[S]	GENERAL VISUAL INSPECTION OF THE INLET DUCT AND BOOT ASSEMBLY								Service	ATA:49
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 49.020	AFL		1171						54	
				PROC. REF: AMM 49 15 00 210 802						PKG:32
49-18-00-201[S]	APU - GENERAL VISUAL INSPECTION OF THE APU DRAIN LINES								Service	ATA:49
	MOS		17-Jul-19						54.8	
	HRS	1000 (+50/-50)	2481.88						169.12	
	APUS		2157						191	
				PROC. REF: AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49-18-00, AMM 49 18 00 210 801, AMM 49-18-00						PKG:1000
49-21-00-301	APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (PRE SB RE220-49-7813)								Service	ATA:49
	MOS/MSC	-	20-Dec-09						169.7	
	HRS		0						2651	
	APUS		0						2348	
				PROC. REF: AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49-21-00						
49-21-00-302	APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (POST SB RE220-49-7813 AND APU S/N P-286 AND SUBS)								Service	ATA:49
	MOS		17-Jul-19					16-Aug-2027	54.8	
	HRS	2000 (+50/-50)	2481.88	Adj -481.88	4000	4050	1349 (+50)		169.12	
	APUS		2157						191	
				PROC. REF: AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49-21-00						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
49-30-00-204[S]	APU - GENERAL VISUAL INSPECTION OF THE APU FUEL-SYSTEM COMPONENTS								Service ATA:49
	MOS								
	HRS	1000 (+50/-50)							
	APUS								
				PROC. REF: AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49-30-00, AMM 49 30 00 210 804, AMM 49-30-00					PKG:1000
49-42-00-301[S]	APU - CLEANING OF THE STARTER MOTOR OF BRUSH DUST MATERIAL								Service ATA:49
	MOS		19-Mar-21						34.7
	HRS	750 (+50/-50)	2651						0
	APUS		2348						0
				PROC. REF: AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49-42-01, AMM 49 42 01 110 801, AMM 49-42-01					PKG:750
49-42-01-201[S]	APU - DETAILED INSPECTION OF THE STARTER MOTOR								Service ATA:49
	MOS		17-Jul-19						54.8
	HRS	1000 (+50/-50)	2481.88						169.12
	APUS		2157						191
				PROC. REF: AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49-42-01, AMM 49 42 01 220 801, AMM 49-42-01					PKG:1000
49-52-00-301	APU - CLEANING OF THE LOAD-CONTROL-VALVE INLET FILTER (LOAD CONTROL VALVE P/N 3291210-3)								Service ATA:49
	MOS/MSC	N/A							
	HRS		EFF						
	APUS								
				PROC. REF: AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49-52-05, AMM 49 52 05 160 801, AMM 49-52-05					
49-61-01-900-801-01	FADEC CONTROLLER								Component ATA:49
PN:2118990-3	MOS/MSC	O/C	18-Sep-15	TSR 0					100.8
SN:64-K0106	HRS		1775.8						2325.5
WC#: 49.045	AFL		650						575
				PROC. REF: AMM 49 61 01 000 801, AMM 49 61 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
49-62-00-201	APU - OPERATIONAL TEST OF THE APU EMERGENCY SHUTDOWN (APU SHUTDOWN SWITCH AND AFT SERVICE CONTROL PANEL APU SHUT-OFF SWITCH)								Service ATA:49
	MOS		22-Aug-18					03-Dec-2028	65.6
	HRS	2250 (+50/-50)	2240	Adj 10	4500	4550	1849 (+50)		411
	APUS								
			PROC. REF: AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49-62-00, AMM 49 62 00 710 802, AMM 49-62-00						
49-70-00-201 S	VISUAL CHECK OF THE APU INDICATING SYSTEM								Service ATA:49
	MOS		30-Nov-23						2.4
	HRS	1000 (+50/-50)	4099.1						2.2
WC#: 49.025	AFL		1223						2
			PROC. REF: AMM 49 70 00 210 801						PKG:4
49-80-04-900-801-01	APU EXHAUST DUCT ASSY (LOWER) INSULATION								Component ATA:49
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 49.050	AFL		0	TSN 0					1225
			PROC. REF: GENERIC NO REF						
49-80-05-201 S	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT								Service ATA:49
	MOS	30 (+3m/-3m)	30-Dec-22						13.4
	HRS		3913.7						187.6
WC#: 49.030	AFL		1171						54
			PROC. REF: AMM 49 80 05 210 801						PKG:32
49-80-05-900-801-01	THERMAL BLANKET								Component ATA:49
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 49.055	AFL		0	TSN 0					1225
			PROC. REF: GENERIC NO REF						
49-80-05-900-802-01	EXHAUST TAILPIPE DUCT								Component ATA:49
PN:GA453-0010-1001	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 49.060	AFL		0	TSN 0					1225
			PROC. REF: AMM 49 80 05 000 801, AMM 49 80 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 49 - AIRBORNE AUXILIARY POWER										
49-80-09-201 S	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT SEAL								Service	ATA:49
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 49.035	AFL		1171						54	
				PROC. REF: AMM 49 80 09 210 801						PKG:32
49-90-00-204 S	APU - GENERAL VISUAL INSPECTION OF THE APU OIL-SYSTEM COMPONENTS								Service	ATA:49
	MOS									
	HRS	1000 (+50/-50)								
	APUS									
				PROC. REF: AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49-90-00, AMM 49 90 00 210 804, AMM 49-90-00						PKG:1000
49-90-29-201 S	APU - DISCARD THE APU OIL-FILTER ELEMENT								Service	ATA:49
	MOS		19-Mar-21						34.7	
	HRS	1500 (+50/-50)	2651						0	
	APUS		2348						0	
				PROC. REF: AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49-90-29, AMM 49 90 29 961 801, AMM 49-90-29						PKG:1500
49-90-29-202 S	APU - DISCARD THE APU-GENERATOR SCAVENGE-OIL FILTER-ELEMENT								Service	ATA:49
	MOS		19-Mar-21						34.7	
	HRS	1500 (+50/-50)	2651						0	
	APUS		2348						0	
				PROC. REF: AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49-90-29, AMM 49 90 29 961 802, AMM 49-90-29						PKG:1500
490002-001	APU - WIRING HARNESS								Component	ATA:49
PN:WE3888471-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09-25866-00232	HRS		0	TSN 0					2651	
	APUS		0	TSN 0					2348	
				PROC. REF: AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
492001-001 U	APU - COMPRESSOR IMPELLER								Component ATA:49
PN:WB3822573-1	MOS		20-Dec-09	TSN 0				10-Feb-2066	169.7
SN:09-162053-22703	HRS		0	TSN 0					2651
	APUS	20000	0	TSN 0	20000	20000	17652		2348
				PROC. REF: GENERIC NO REF					
492002-001	APU - FIRST STAGE TURBINE ROTOR ASSEMBLY								Component ATA:49
PN:WK3840141-3	MOS		20-Dec-09	TSN 0				10-Feb-2066	169.7
SN:082241001646	HRS		0	TSN 0					2651
	APUS	20000	0	TSN 0	20000	20000	17652		2348
				PROC. REF: AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49-10-00					
492003-001	APU - SECOND STAGE TURBINE ROTOR ASSEMBLY								Component ATA:49
PN:WE897994-3	MOS		20-Dec-09	TSN 0				10-Feb-2066	169.7
SN:09-156101-05056	HRS		0	TSN 0					2651
	APUS	20000	0	TSN 0	20000	20000	17652		2348
				PROC. REF: AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49-10-00					
493001-001	APU - FUEL CONTROL UNIT FCU								Component ATA:49
PN:441950-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:CUB20534	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801					
494001-002	APU - STARTER MOTOR								Component ATA:49
PN:2704554-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1718	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
494101-001	APU - IGNITION EXCITER								Component ATA:49
PN:WE3876295-6	MOS/MSC	O/C	13-Jul-18	TSO 0					66.9
SN:J09500181	HRS		2214.8	TSO 0					436.2
	APUS		1957	TSO 0					391
				PROC. REF: AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801					
495101-001	APU - SURGE VALVE								Component ATA:49
PN:3291212-4	MOS/MSC	O/C	06-Sep-13	TSR 0					125.2
SN:573	HRS		950	TSR 0					1701
	APUS		876	TSR 0					1472
				PROC. REF: AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801					
495205-001	APU - LOAD CONTROL VALVE								Component ATA:49
PN:3291210-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1856	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801					
496102-001	APU - INLET PRESSURE SENSOR								Component ATA:49
PN:WE3876283-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:091121421089	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801					
496103-001	APU - SPEED SENSOR								Component ATA:49
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
496105-001	APU - NO. 1 EXHAUST GAS TEMPERATURE SENSOR								Component ATA:49
PN:WE3876352-2	MOS/MSC	O/C	11-Jul-17						79
SN:NA	HRS		1947						704
	APUS		1738						610
				PROC. REF: AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801					
496105-002	APU - NO. 2 EXHAUST GAS TEMPERATURE SENSOR								Component ATA:49
PN:WE3876352-2	MOS/MSC	O/C	11-Jul-17						79
SN:NA	HRS		1947						704
	APUS		1738						610
				PROC. REF: AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801					
499001-001	APU - OIL COOLER								Component ATA:49
PN:160534-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1780	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801					
499002-001	APU - LUBE PUMP								Component ATA:49
PN:WE3881781-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:VE2600	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: GENERIC NO REF					
499035-001	APU - DIFFERENTIAL PRESSURE-GENERATOR SWITCH								Component ATA:49
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348
				PROC. REF: GENERIC NO REF					
499053-001	APU - APU GEARBOX								Component ATA:49
PN:WK3805055-6	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:092241010465	HRS		0	TSN 0					2651
	APUS		0	TSN 0					2348

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 49 - AIRBORNE AUXILIARY POWER										
49APU1	APU								Component	ATA:49
PN:WE3800714-1	MOS/MSC	E/C								
SN:P-503	HRS									
WC#: 49.APU1	AFL									
				PROC. REF: AMM 49 10 00 000 801, AMM 49 10 00 400 801						
FAA 2010-12-09[U]	HONEYWELL INTERNATIONAL INC.: TO PREVENT FUEL LEAKAGE IN THE APU COMPARTMENT WHICH COULD LEAD TO IGNITION OF FUEL VAPOR, CREATING A FIRE AND EXPLOSION HAZARD RESULTING IN INJURY AND DAMAGE TO THE APU AND THE AIRPLANE								AD	ATA:49
	MOS/MSC	-	26-Dec-14						109.5	
	HRS		1518.9						2582.4	
	AFL		566						659	
SB 3615880-49-8149 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin	ATA:49
	MOS/MSC	-	EFF							
	HRS									
	APUS									
SB 3615880-49-8149 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin	ATA:49
	MOS/MSC	-								
	HRS									
	APUS									
SB 3822101-49-8148 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin	ATA:49
	MOS/MSC	-	EFF							
	HRS									
	APUS									
SB 3822101-49-8148 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin	ATA:49
	MOS/MSC	-								
	HRS									
	APUS									
SB 49-7933 R02	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN								Bulletin	ATA:49
	MOS/MSC	-								
	HRS									
	APUS									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
SB 49-7933 R03	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7933 R04	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7933 R05	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7933 R06	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7933 R07	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7933 R08	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7997 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7997 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
SB 49-7997 R03	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7997 R04	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 49-7997 R05	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 700-49-001	MODIFICATION - AUTOMATIC CONTROL SYSTEM - REPLACEMENT OF THE AUXILIARY POWER UNIT (APU) FULL-AUTHORITY DIGITAL ENGINE-CONTROLLER (FADEC) UNIT, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-001 REV 01	MODIFICATION - AUTOMATIC CONTROL SYSTEM - REPLACEMENT OF THE AUXILIARY POWER UNIT (APU) FULL-AUTHORITY DIGITAL ENGINE-CONTROLLER (FADEC) UNIT, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-002	MODIFICATION - EXHAUST - AUXILIARY POWER UNIT (APU) EXHAUST DUCT REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-002 REV 01	MODIFICATION - EXHAUST - AUXILIARY POWER UNIT (APU) EXHAUST DUCT REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
SB 700-49-006	MODIFICATION - AIR-INLET DOOR SYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-006 REV 01	MODIFICATION - AIR-INLET DOOR SYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-006 REV 02	MODIFICATION - AIR-INLET DOOR SYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-006 REV 03	MODIFICATION - AIR-INLET DOOR SYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-007	MODIFICATION - BLEED AIR DUCTING - REPLACEMENT OF THE APU BLEED AIR SHROUD ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-010	MODIFICATION - INLET DOOR - LINEAR ACTUATOR, ACTUATOR ARM AND TAIL-CONE AFT FITTING REPLACEMENT (A/C 9002 TO 9085), SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-010 REV 01	MODIFICATION - INLET DOOR - LINEAR ACTUATOR, ACTUATOR ARM AND TAIL-CONE AFT FITTING REPLACEMENT (A/C 9002 TO 9085), SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
SB 700-49-011	MODIFICATION - AIR-INLET DOOR SYSTEM - INTRODUCTION OF A NEW AIR-INLET DOOR AND SURROUNDING STRUCTURE (A/C 9001 TO 9085), SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-012	REWORK - POWER PLANT - REPAIR OF APU COMPRESSOR SHROUD, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-013	MODIFICATION - AUTOMATIC CONTROL SYSTEM - REPLACEMENT OF THE SECONDARY POWER WIRE FOR THE AUXILIARY POWER UNIT (APU) FULL-AUTHORITY DIGITAL ENGINE-CONTROLLER (FADAC) (A/C 9002 TO 9129), SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-49-014	MODIFICATION – AIR INLET DOOR SYSTEM – RELOCATION OF THE BONDING JUMPER, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-	29-Jun-11						151.4
	HRS		47.4						4053.9
	AFL		17						1208
SB 700-49-014 REV 01	MODIFICATION - AIR INLET DOOR SYSTEM - RELOCATION OF THE BONDING JUMPER, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-49-015[U]	APU - MODOFICATION - INDICATING - APU EXHAUST GS TEMPERATURE SENSOR UPGRADE, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-	29-Jun-11						151.4
	HRS		89						2562
	APUS		129						2219
SB 700-49-015	MODIFICATION - INDICATING - AUXILIARY POWER UNIT (APU) EXHAUST-GAS TEMPERATURE SENSOR UPGRADE TO PART NUMBER WE3876352-2 WITH SERIAL NUMBER 50413-1000204 OR ABOVE, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
SB 700-49-016	SPECIAL CHECK/MODIFICATION - AUTOMATIC CONTROL SYSTEM - VISUAL INSPECTION AND SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE (EGT) SENSOR, PART NUMBER WE3876352-1 AND WE3876352-2, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	AFL		817						408
SB 70721598-49-8168 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-	EFF						
	HRS								
	APUS								
SB 70721598-49-8168 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB 70721725-49-8152 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-	EFF						
	HRS								
	APUS								
SB 70721725-49-8152 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-7634 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE COMPRESSOR ROTOR, PN WB3822380-3 WITH PN WB3822573-1, COMPRESSOR SHROUD, PN WB3827383-1 WITH PN WB3827395-1, RADIAL DIFFUSER, PN WB3827373-1 WITH PN WB3827396-1, AND SCROLL HOUSING, PN WB3827380-1 WITH PN WB3827380-2, ON RE220 AUXILIARY POWER UNITS (APU)S, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-8039	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE STARTER MOTOR, PN 2704554-2 WITH PN 2704554-3, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	T:A/R							
	HRS								
	APUS								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
SB RE220-49-8039 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE STARTER MOTOR, PN 2704554-2 WITH PN 2704554-3, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-8085	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE (RETURN) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-1 WITH OIL RETURN TUBE, PN WE70721494-1, AND (SUPPLY) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-2 WITH OIL SUPPLY TUBE, PN WE70721495-1, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-8085 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE (RETURN) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-1 WITH OIL RETURN TUBE, PN WE70721494-1, AND (SUPPLY) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-2 WITH OIL SUPPLY TUBE, PN WE70721495-1, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-8169	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE SENSOR, PN WE3876352-2, ON RE220 APUS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-8169 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE SENSOR, PN WE3876352-1, -2, ON RE220 APUS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-8169 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE SENSOR, PN WE3876352-1, -2, ON RE220 APUS, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 49 - AIRBORNE AUXILIARY POWER									
SB RE220-49-8169 R03	APU - GAS TURBINE ENGINE - VISUAL INSPECTION AND SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE (EGT) SENSOR, PN WE3876352-1, -2, ON RE220 AUXILIARY POWER UNITS (APUS), SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-	11-Jul-17						79
	HRS		1947						704
	APUS		1738						610
SB RE220-49-8218	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE/REPLACE GENERATOR FILTER BY-PASS INDICATOR VALVE, PN WE3876294-1, ON RE220 AUXILIARY POWER UNITS (APUS), SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220-49-8218 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE/REPLACE GENERATOR FILTER BY-PASS INDICATOR VALVE, PN WE3876294-1, ON RE220 AUXILIARY POWER UNITS (APUS), SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB RE220/HGT400-49-8383	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECT SPECIFIC POPULATION OF HGT400[G], RE220[GVI] AND RE220 [GX] ENGINES FOR DUPLEX BALL BEARING DAMAGE PREVENTION, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SB WE3881600-49-7350 R02	APU - SB WE3881600-49-7350 R02 - AIRBORNE AUXILIARYPOWER- OIL PUMP ASSEMBLY - REPLACE PLUG, PN AN814-4D WITH PN AN814 -4DL, FILTER HOUSING, PN WE3881618-1 WITH PN WE3881771-1, OIL FILTER ELEMENTS, PN WE3881639-1 WITH PN WE3881767-1, AND BOLT PN MS9556-08 WITH PN MS9565-08, SERVICE BULLETIN								Bulletin ATA:49
	MOS/MSC	T:ESV							
	HRS								
	APUS								
SIL APU-49 R10	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								
SIL APU-49 R11	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER								Bulletin ATA:49
	MOS/MSC	-							
	HRS								
	APUS								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 49 - AIRBORNE AUXILIARY POWER										
SIL APU-49 R12	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER								Bulletin	ATA:49
	MOS/MSC	-								
	HRS									
	APUS									
SIL APU-49 R13	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER								Bulletin	ATA:49
	MOS/MSC	T:A/R	EFF							
	HRS									
	APUS									
ATA 52 - DOORS										
52-10-00-207[S]	LUBRICATION OF THE PASSENGER DOOR								Service	ATA:52
	MOS		19-Mar-21						34.7	
	HRS	1500 (+50/-50)	3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 12 22 00 640 808						PKG:5
52-11-00-101	DETAILED INSPECTION OF THE OUTER SKIN OF THE PASSENGER DOOR								Service	ATA:52
	MOS		20-Dec-09					21-Nov-2040	169.7	
	HRS		0						4101.3	
WC#: 52.005	AFL	T:5255	0		5255		4030		1225	
				PROC. REF: AMM 52 11 00 220 803						
52-11-00-102	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE FRAMES								Service	ATA:52
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 52.010	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-52-10-001						PKG:76
52-11-00-103	DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE-FRAMES, STOPS, SKIN AND STIFFENERS - INTERNAL								Service	ATA:52
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 52.015	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 52 11 00 220 806						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
52-11-00-105	GENERAL VISUAL INSPECTION OF THE SKIN EXTERNAL SURFACE								Service	ATA:52
	MOS							17-Aug-2034		
	HRS									
	AFL	T:3750			3750		2525			
				PROC. REF: AMM 52 11 00 210 808						
52-11-00-106	VISUAL CHECK OF THE PASSENGER-DOOR VENT-FLAP MECHANISM								Service	ATA:52
	MOS		28-Nov-23					12-Jan-2025	2.5	
	HRS	500	4099.1		4599.1		497.8		2.2	
	AFL		1223						2	
				PROC. REF: AMM 52 11 00 210 807						
52-11-00-201 S	FUNCTIONAL TEST OF THE PASSENGER DOOR MECHANISM								Service	ATA:52
	MOS		19-Mar-21						34.7	
	HRS	2000 (+50/-50)	3474.7						626.6	
WC#: 52.025	AFL		1069						156	
				PROC. REF: AMM 52 11 00 720 801						PKG:6
52-11-00-202 S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PASSENGER DOOR								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.030	AFL		1069						156	
				PROC. REF: AMM 52 11 00 220 801						PKG:38
52-11-00-203 S	DETAILED INSPECTION OF THE STOPS AND ABUTMENTS OF THE PASSENGER DOOR								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.035	AFL		1069						156	
				PROC. REF: AMM 52 11 00 220 802						PKG:38
52-11-00-205 S	VISUAL CHECK OF THE PASSENGER-DOOR VENT-FLAP MECHANISM								Service	ATA:52
	MOS		28-Nov-23						2.5	
	HRS	500 (+50/-50)	4099.1						2.2	
WC#: 52.045	AFL		1223						2	
				PROC. REF: AMM 52 11 00 210 807						PKG:2
52-11-00-900-801-01	PASSENGER DOOR ASSY								Component	ATA:52
PN:GS328-0010-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:C156	HRS		0	TSN 0					4101.3	
WC#: 52.170	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 11 00 000 801, AMM 52 11 00 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
52-11-00-900-802-01	PASSENGER DOOR ACTUATOR MOTOR								Component	ATA:52
PN:GS321-0591-9	MOS		10-Jul-23	TSR 2				19-Apr-2027	7	
SN:G0778	HRS		4002.9	TSN 228, TSR 0					98.4	
WC#: 52.175	AFL	850	1192	TSN 52, TSR 0	1990		765		33	
				PROC. REF: AMM 52 11 25 000 801, AMM 52 11 25 400 801, AMM 52 11 00 000 801, AMM 52 11 00 400 801						
52-11-21-201 S	DETAILED INSPECTION OF THE HANDRAILS ATTACHMENT TO THE FUSELAGE								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.050	AFL		1069						156	
				PROC. REF: AMM 52 11 21 220 801						PKG:38
52-11-25-101	RESTORATION OF PASSENGER DOOR ACTUATOR MOTOR , PART NO. GS321-0591-9 (GEARHEAD, PART NO. 2H4A321809A)								Service	ATA:52
PN:GS321-0591-9	MOS		10-Jul-23					19-Apr-2027	7	
SN:G0778	HRS		4002.9	TAC 228					98.4	
	AFL	850	1192	TAC 52	1990		765		33	
				PROC. REF: AMM 52 11 25 610 801						
52-11-29-900-801-01	PASSENGER DOOR AIRSTAIR								Component	ATA:52
PN:GS328-0009-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:SBGX11156	HRS		0	TSN 0					4101.3	
WC#: 52.180	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 11 29 000 801, AMM 52 11 29 400 801						
52-11-41-101	DISCARD THE NO. 1 PASSENGER DOOR TENSATOR SPRING, PART NO.GS321-0580-1								Service	ATA:52
PN:GS321-0580-1	MOS		19-Mar-21					03-Mar-2026	34.7	
SN:04915	HRS		3474.7						626.6	
	AFL	650	1069		1719		494		156	
				PROC. REF: AMM 52 11 41 961 801						
52-11-41-101	DISCARD THE NO. 2 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1								Service	ATA:52
PN:GS321-0580-1	MOS		19-Mar-21					03-Mar-2026	34.7	
SN:04916	HRS		3474.7						626.6	
	AFL	650	1069		1719		494		156	
				PROC. REF: AMM 52 11 41 961 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
52-11-41-101	DISCARD THE NO. 3 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1								Service ATA:52
PN:GS321-0580-1	MOS		19-Mar-21					03-Mar-2026	34.7
SN:04918	HRS		3474.7						626.6
	AFL	650	1069		1719		494		156
				PROC. REF: AMM 52 11 41 961 801					
52-11-41-101	DISCARD THE NO. 4 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1								Service ATA:52
PN:GS321-0580-1	MOS		19-Mar-21					03-Mar-2026	34.7
SN:04920	HRS		3474.7						626.6
	AFL	650	1069		1719		494		156
				PROC. REF: AMM 52 11 41 961 801					
52-11-41-900-801-01	NO. 1 PASSENGER DOOR TENSATOR SPRING								Component ATA:52
PN:GS321-0580-1	MOS/MSC	H/T	19-Mar-21	TSN 0					34.7
SN:04915	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801					
52-11-41-900-801-02	NO. 2 PASSENGER DOOR TENSATOR SPRING								Component ATA:52
PN:GS321-0580-1	MOS/MSC	H/T	19-Mar-21	TSN 0					34.7
SN:04916	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801					
52-11-41-900-801-03	NO. 3 PASSENGER DOOR TENSATOR SPRING								Component ATA:52
PN:GS321-0580-1	MOS/MSC	H/T	19-Mar-21	TSN 0					34.7
SN:04918	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801					
52-11-41-900-801-04	NO. 4 PASSENGER DOOR TENSATOR SPRING								Component ATA:52
PN:GS321-0580-1	MOS/MSC	H/T	19-Mar-21	TSN 0					34.7
SN:04920	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
52-21-00-103	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE OVERWING EMERGENCY EXIT								Service	ATA:52
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 52.085	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 52 21 00 210 803						
52-21-00-104	DETAILED INSPECTION OF THE OVER-WING EMERGENCY EXIT DOOR								Service	ATA:52
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 52 21 00 220 803						PKG:76
52-21-00-201 S	OPERATIONAL TEST OF THE OVER-WING EMERGENCY-EXIT								Service	ATA:52
	MOS	15 (+3m/-3m)	28-Nov-23						2.5	
	HRS		4099.1						2.2	
WC#: 52.060	AFL		1223						2	
				PROC. REF: AMM 52 21 00 710 801						PKG:31
52-21-00-202 S	FUNCTIONAL TEST OF THE OVER-WING EMERGENCY-EXIT EXIT PULL SIGN								Service	ATA:52
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 52.065	AFL		1171						54	
				PROC. REF: AMM 52 21 00 720 802						PKG:32
52-21-00-203 S	LUBRICATION OF THE OVER-WING EMERGENCY-EXIT DOOR								Service	ATA:52
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 52.070	AFL		1171						54	
				PROC. REF: AMM 12 22 00 640 805						PKG:32
52-21-00-204 S	DETAILED INSPECTION OF THE LATCH FITTINGS AND DOOR STOP FITTINGS OF THE OVER- WING EMERGENCY EXIT								Service	ATA:52
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.075	AFL		1069						156	
				PROC. REF: AMM 52 21 00 220 801						PKG:34
52-21-00-205 S	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE OVER-WING EMERGENCY EXIT								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.080	AFL		1069						156	
				PROC. REF: AMM 52 21 00 220 802						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
52-21-00-900-801-01	OVERWING EMERGENCY EXIT DOOR ASSY								Component	ATA:52
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 52.185	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 21 00 000 801, AMM 52 21 00 400 801						
52-30-00-101	DETAILED INSPECTION OF THE BAGGAGE DOOR								Service	ATA:52
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 52.090	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 52 30 00 220 809						PKG:76
52-30-00-105	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SKIN BETWEEN DOOR UPPER SKIN EDGE AND VENT DOOR								Service	ATA:52
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 52.110	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-52-31-001						PKG:76
52-30-00-106	DETAILED INSPECTION OF THE VENT DOOR OF THE BAGGAGE DOOR								Service	ATA:52
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 52.115	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 52 30 00 220 808						PKG:76
52-30-00-107	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR								Service	ATA:52
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-52-30-002						PKG:76
52-30-00-108	GENERAL VISUAL INSPECTION OF THE EXTERNAL SURFACE OF THE BAGGAGE DOOR SKIN INCLUDING DOOR HANDLE RECESS								Service	ATA:52
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 52.130	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 52 30 00 210 806						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
52-30-00-201 S	DETAILED INSPECTION OF THE SURROUND ANGLES AND STOP FITTINGS OF THE BAGGAGE DOOR								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.120	AFL		1069						156	
				PROC. REF: AMM 52 30 00 220 803						PKG:38
52-30-00-202 S	DETAILED INSPECTION OF THE INTERNAL SUPPORT STRUCTURE OF THE BAGGAGE DOOR								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.125	AFL		1069						156	
				PROC. REF: AMM 52 30 00 220 805						PKG:38
52-30-00-301 S	LUBRICATION OF THE BAGGAGE DOOR								Service	ATA:52
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
				PROC. REF: AMM 12 22 00 640 806						PKG:32
52-31-01-900-801-01	BAGGAGE COMPARTMENT DOOR ASSY								Component	ATA:52
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 52.190	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 31 01 000 801, AMM 52 31 01 400 801						
52-31-09-101	DETAILED INSPECTION OF THE BAGGAGE DOOR SEAL								Service	ATA:52
	MOS	15 (+3m/-3m)	28-Nov-23	Adj 3	31-May-25	31-Aug-25	475 d (+92)	31-May-2025	2.5	
	HRS		4099.1						2.2	
WC#: 52.135	AFL		1223						2	
				PROC. REF: AMM 52 31 09 220 801						PKG:31
52-41-00-201 S	DETAILED INSPECTION OF THE AFT EQUIPMENT-COMPARTMENT DOOR SEAL								Service	ATA:52
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 52.140	AFL		1171						54	
				PROC. REF: AMM 52 41 09 220 801						PKG:32
52-41-00-900-801-01	REAR EQUIPMENT BAY DOOR								Component	ATA:52
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 52.195	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 41 00 000 801, AMM 52 41 00 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
52-42-01-900-801-01	FORWARD EQUIPMENT COMPARTMENT DOOR								Component	ATA:52
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 52.215	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 42 01 000 801, AMM 52 42 01 400 801						
52-43-01-900-801-01	LH ASSY - ACCESS DOOR								Component	ATA:52
PN:GC219-0104-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:D71607	HRS		0	TSN 0					4101.3	
WC#: 52.200	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 42 01 000 801, AMM 52 42 01 400 801						
52-43-01-900-801-02	RH ASSY - ACCESS DOOR								Component	ATA:52
PN:GC219-0104-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:D71607	HRS		0	TSN 0					4101.3	
WC#: 52.200	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 42 01 000 801, AMM 52 42 01 400 801						
52-44-25-900-801-01	CASTING DOOR								Component	ATA:52
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 52.205	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 44 25 000 801, AMM 52 44 25 400 801						
52-44-37-900-801-01	DOOR CASTING								Component	ATA:52
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 52.210	AFL		0	TSN 0					1225	
				PROC. REF: AMM 52 44 37 000 801, AMM 52 44 37 400 801						
52-71-50-601 U S	OPERATIONAL TEST OF THE CABIN DOOR ANNUNCIATION SYSTEM								Service	ATA:52
	MOS	15	22-Nov-23						2.6	
	HRS		4099.1						2.2	
	AFL		1223						2	
										PKG:31
52-ZL-00-201 S	GENERAL VISUAL INSPECTION OF THE OVER-WING EMERGENCY EXIT - EXTERNAL								Service	ATA:52
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.145	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 52 21 00 210 804						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
52-ZL-00-202[S]	GENERAL VISUAL INSPECTION OF THE LATCH MECHANISM OF THE OVER-WING EMERGENCY EXIT								Service	ATA:52
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.150	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 52 21 00 210 802						PKG:34
52-ZL-00-203[S]	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - INBOARD SIDE								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.155	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 52 30 00 210 807						PKG:38
52-ZL-00-204[S]	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - OUTBOARD SIDE								Service	ATA:52
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 52.160	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 52 30 00 210 804						PKG:38
52-ZL-00-205	GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR - EXTERNAL								Service	ATA:52
	MOS	24 (+3m/-3m)	15-Dec-22	Adj 3	31-Mar-25	15-Jun-25	414 d (+76)	31-Mar-2025	13.9	
	HRS		3913.7						187.6	
WC#: 52.165	AFL		1171						54	
				PROC. REF: SPM 20-70-00-210-801, AMM 52 11 00 210 801						
529910-701[U]	DOOR STEP ACTUATOR								Component	ATA:52
PN:GS321-0988-13	MOS/MSC	O/C	09-Jun-11						152.1	
SN:379	HRS		41	TSN 0					4060.3	
	AFL		14	TSN 0					1211	
AW 700-52-0227 REV 2[U]	PASSENGER DOOR - TENSATOR SPRING FAILURES, ADVISORY WIRE								Bulletin	ATA:52
	MOS/MSC	-	14-Nov-12						134.9	
	HRS		714.9						3386.4	
	AFL		271						954	
AW AW700-52-0350[U]	GLOBAL EXPRESS PASSENGER DOOR - EXTERNAL HANDLE DETENT, ADVISORY WIRE								Bulletin	ATA:52
	MOS/MSC	-	09-Jun-11						152.1	
	HRS		41						4060.3	
	AFL		14						1211	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
FAA 2016-01-12	DOORS - MODIFY THE AFT EQUIPMENT BAY								AD	ATA:52
	MOS/MSC	-	29-Jan-16						96.4	
	HRS		1916.2						2185.1	
	AFL		678						547	
FAA 2016-15-03	DOORS - INCORPORATE THE NEW CONFIGURATION TO THE PASSENGER DOOR EXTERNAL HANDLE DETENT								AD	ATA:52
	MOS/MSC	-	23-Aug-16						89.6	
	HRS		2104.2						1997.1	
	AFL		733						492	
FAA 2016-17-16	DOORS - REVISING THE MAINTENANCE OR INSPECTION PROGRAM TO INCORPORATE CERTAIN TEMPORARY REVISIONS, AND REPLACING THE PASSENGER DOOR TENSATOR SPRINGS WITH NEW SPRINGS								AD	ATA:52
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2016-17-16 PARA (G)	REVISE THE MAINTENANCE OR INSPECTION PROGRAM AS APPLICABLE								AD	ATA:52
	DAYS/MSC	-	19-Mar-21						1059 d	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2016-17-16 PARA (I)	REPLACE THE PASSENGER DOOR TENSATOR SPRINGS HAVING PART NUMBER (P/N) GS321-0580-1, WITH NEW SPRINGS								AD	ATA:52
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2022-25-13	DOORS - MAINTENANCE OR INSPECTION PROGRAM TASK RESTRICTIONS								AD	ATA:52
	DAYS/MSC	-	20-Dec-22						418 d	
	HRS		3913.7						187.6	
	AFL		1171						54	
MODSUM IS700-52-000:U REV A	PAX DOOR - ABUTMENT FITTING - WATER DIVERTER INSTALLTION (A/C 9002 - 9126, 9128 - 9999), MODIFICATION SUMMARY								Bulletin	ATA:52
	MOS/MSC	T:A/R								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
MODSUM IS700-52-0004[U] REV A	KIT, REMOVAL OF THE PASSENGER DOOR AESTHETIC SIDE COVERS, MODIFICATION SUMMARY								Bulletin ATA:52
	MOS/MSC	A/R							
	HRS								
	AFL								
MODSUM IS700-52-0004[U] REV B	KIT, REMOVAL OF THE PASSENGER DOOR AESTHETIC SIDE COVERS, MODIFICATION SUMMARY								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
MODSUM IS700-52-0005[U] REV B	LUBRICATION OF PAX DOOR HANDRAIL TELESCOPIC STRUTS, MODIFICATION SUMMARY								Bulletin ATA:52
	MOS/MSC	A/R							
	HRS								
	AFL								
REO 700-52-45-00 REV B[U]	REPAIR - RAM AIR FAILING ACCESS PANEL, REPAIR ENGINEERING ORDER								Bulletin ATA:52
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-52-005	MODIFICATION - PASSENGER DOOR - REPLACEMENT OF EXTERNAL HANDLE ATTACHMENT BOLTS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-006	MODIFICATION - PASSENGER DOOR - BOTTOM STEP LIGHT REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-007	MODIFICATION - PASSENGER DOOR - INTERNAL-HANDLE COVER IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
SB 700-52-007 REV 01	MODIFICATION - PASSENGER DOOR - INTERNAL-HANDLE COVER IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-008	MODIFICATION - SERVICE DOORS - REPLACEMENT OF NO. 3 HYDRAULIC-SYSTEM SERVICING DOOR SEALS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-008 REV 01	MODIFICATION - SERVICE DOORS - REPLACEMENT OF NO. 3 HYDRAULIC-SYSTEM SERVICING DOOR SEALS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-009	MODIFICATION - PASSENGER DOOR - BOTTOM STEP STOP BRACKETS AND RUBBER STOP TO STAINLESS STEEL STOP REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-010	MODIFICATION - EMERGENCY EXIT - ADDITION OF DRAINAGE FOR OVER WING EMERGENCY EXIT DOOR, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-011	MODIFICATION – PASSENGER DOOR – UPGRADE OF THE PASSENGER DOOR ACTUATOR WITH A HIGH-TORQUE ACTUATOR, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-014	MODIFICATION - PASSENGER DOOR - REPLACEMENT OF TOP-STEP SUPPORT STRUCTURE AND REPLACEMENT OF TOP-STEP HINGE PINS AND NYLON COVER, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
SB 700-52-014 REV 01	MODIFICATION - PASSENGER DOOR - REINFORCEMENT OF TOP-STEP SUPPORT STRUCTURE AND REPLACEMENT OF TOP-STEP HINGE PINS AND NYLON COVER (A/C 9002 TO 9095), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-015	MODIFICATION - AFT EQUIPMENT-COMPARTMENT DOOR - DOOR LANYARD ATTACHMENT POINT MODIFICATION TO PREVENT PREMATURE BUSHING FAILURE, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-017	MODIFICATION - SERVICE DOOR - PREVENT FOULING CONDITION BETWEEN FOWARD TOILET WASTE SERVICE DOOR AND FUSELAGE SKIN, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-018	MODIFICATION - PASSENGER DOOR - ADDITION OF A HANDHOLD FEATURE TO ASSIST DOOR CLOSURE, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-019	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF PAX DOOR DAMPER MECHANISM FOR LOWER FOLDING-STEP (A/C EFFECTIVITY : S/N 9002 TO 9126, 9128, 9129 AND 9131 TO 9138), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-020	MODIFICATION - PASSENGER DOOR - INSTALLATION OF ADJUSTABLE BOTTOM-STEP STOPS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-021	MODIFICATION - PASSENGER DOOR - INSTALLATION OF AESTHETIC SIDE COVERS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
SB 700-52-021 REV 01	MODIFICATION - PASSENGER DOOR - INSTALLATION OF AESTHETIC SIDE COVERS (EFFECTIVITY A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-021 REV 02	MODIFICATION - PASSENGER DOOR - INSTALLATION OF AESTHETIC SIDE COVERS (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-021 REV 03	MODIFICATION - PASSENGER DOOR - INSTALLATION OF AESTHETIC SIDE COVERS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-021 REV 04	MODIFICATION - PASSENGER DOOR - INSTALLATION OF AESTHETIC SIDE COVERS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-022	MODIFICATION - PASSENGER DOOR - INTERNAL HANDLE INDICATION IMPROVEMENT (A/C 9002 TO 9095), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-024	SPECIAL CHECK/REWORK - AFT EQUIPMENT COMPARTEMENT DOOR - POSSIBLE GAPS BETWEEN APERTURE P-SEALS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-025	MODIFICATION - PASSENGER DOOR - HANDRAIL RETAINER MECHANISM (A/C 9096 TO 9999), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-025 REV 01	MODIFICATION - PASSENGER DOOR - HANDRAIL RETAINER MECHANISM, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
SB 700-52-025 REV 02	MODIFICATION - PASSENGER DOOR - HANDRAIL RETAINER MECHANISM (A/C 9096 TO 9183, AND 9002 TO 9095), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-026	MODIFICATION - PASSENGER DOOR - INSTALLATION OF RETENTION STOPS ON AIRCRAFT WITH SUPPLEMENTAL TYPE CERTIFICATE (STC)-INSTALLED HANDRAIL ASSEMBLIES (A/C 9002 TO 9095), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-027	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF NEW INSTALLATION OF PAX DOOR KEYLOCK (A/C 9002 TO 9999), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-027 REV 01	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF NEW INSTALLATION OF PAX DOOR KEYLOCK (A/C 9002 TO 9303), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-027 REV 02	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF NEW INSTALLATION OF PAX DOOR KEYLOCK (A/C 9002 TO 9303), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-029	MODIFICATION - PASSENGER DOOR - VENT FLAP IMPROVEMENTS TO PASSENGER DOOR (A/C 9002 TO 9204), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-030	MODIFICATION - PASSENGER DOOR - ADDITION OF A PAD FOR THE PASSENGER DOOR EXTERNAL HANDLE DETENT (A/C 9002 TO 9126 AND 9128 TO 9187), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
SB 700-52-031 PART (A)	MODIFICATION - PASSENGER DOOR - MIGRATION PREVENTION OF THE FORWARD AND AFT HANDRAIL SUPPORT-PIN BUSHINGS (A/C 9001 TO 9170), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-031 PART (B)	MODIFICATION - PASSENGER DOOR - MIGRATION PREVENTION OF THE FORWARD AND AFT HANDRAIL SUPPORT-PIN BUSHINGS (A/C 9171 TO 9207), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-52-032	MODIFICATION - BAGGAGE DOOR - ADDITION OF A NYLON BLOCK TO THE BAGGAGE DOOR TO PREVENT AN UNWANTED EICAS MESSAGE (A/C 9002 TO 9298), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-033	MODIFICATION - BAGGAGE DOOR - REPLACE BAGGAGE DOOR TRACK ROLLERS TO IMPROVE OPERATION (A/C 9002 TO 9314), SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-033 REV 01	MODIFICATION - BAGGAGE DOOR - REPLACE BAGGAGE DOOR TRACK ROLLERS TO IMPROVE OPERATION, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-034	MODIFICATION - BAGGAGE DOOR - INTRODUCTION OF NEW INTERNAL DOOR “T” HANDLE, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-52-034 REV 01	MODIFICATION – BAGGAGE DOOR – INTRODUCTION OF NEW INTERNAL DOOR “T” HANDLE, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
SB 700-52-035	MODIFICATION - BAGGAGE BAY DOOR - MODIFICATION TO DOOR LOCKING MECHANISM TO PREVENT LOCK ROTATION, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-035 REV 01	MODIFICATION - BAGGAGE BAY DOOR - MODIFICATION TO DOOR LOCKING MECHANISM TO PREVENT LOCK ROTATION, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-036	MODIFICATION - BAGGAGE DOOR - INSTALLATION OF A MECHANICAL STOP ON THE DOOR HANDLE, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-036 REV 01	MODIFICATION - BAGGAGE DOOR - INSTALLATION OF A MECHANICAL STOP ON THE DOOR HANDLE, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-52-037	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF VARIABLE RADIUS PULLEY AND NEW ACTUATOR, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-037 REV 01	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF VARIABLE RADIUS PULLEY AND NEW ACTUATOR, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-037 REV 02	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF VARIABLE RADIUS PULLEY AND NEW ACTUATOR, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-037 REV 03	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF VARIABLE RADIUS PULLEY AND NEW ACTUATOR, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 52 - DOORS									
SB 700-52-038	SPECIAL CHECK/REWORK - PASSENGER DOOR - REPLACEMENT OF PAX DOOR TENSATOR SPRINGS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-038 REV 01	SPECIAL CHECK/REWORK - PASSENGER DOOR - REPLACEMENT OF PAX DOOR TENSATOR SPRINGS, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-52-039	REWORK - PASSENGER DOOR - REWORK PAX DOOR AESTHETIC COVERS TO FIT NEW DOOR PULLEY, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-040	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF PAX DOOR BOTTOM STEP MOTOR WITH IMPROVED PERFORMANCE AND FILTER, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-	09-Jun-11						152.1
	HRS		41						4060.3
	AFL		14						1211
SB 700-52-040 REV 01	MODIFICATION - PASSENGER DOOR - INTRODUCTION OF PAX DOOR BOTTOM STEP MOTOR WITH IMPROVED PERFORMANCE AND FILTER, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-041	DOORS - MODIFICATION - PASSENGER DOOR - INSTALLATION OF ECCENTRIC BUSHINGS IN TOP STEP FOR IMPROVED ALIGNMENT, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-52-042	ICA - MODIFICATION - AFT EQUIPMENT-COMPARTMENT DOOR - MODIFICATION TO PREVENT FUEL INGRESS INTO THE AFT EQUIPMENT BAY, SERVICE BULLETIN								Bulletin ATA:52
	MOS/MSC	-	06-Jul-12						139.2
	HRS		541.7						3559.6
	AFL		200						1025

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
SB 700-52-043	MODIFICATION - PASSENGER DOOR - REPLACEMENT OF NYLON SCREW ON HANDRAIL EXTENSION, SERVICE BULLETIN								Bulletin	ATA:52
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-52-044	MODIFICATION - PASSENGER DOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN								Bulletin	ATA:52
	MOS/MSC	-	08-Mar-13						131.1	
	HRS		850.3						3251	
	AFL		332						893	
SB 700-52-044 REV 01	MODIFICATION - PASSENGER DOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN								Bulletin	ATA:52
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-52-044 REV 02	ICA - MODIFICATION - PASSENGER DOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN								Bulletin	ATA:52
	MOS/MSC	-	23-Aug-16						89.6	
	HRS		2104.2						1997.1	
	AFL		733						492	
SB 700-52-046	REWORK - PASSENGER DOOR - REPLACEMENT OF PAX DOOR TENSATOR SPRINGS, SERVICE BULLETIN								Bulletin	ATA:52
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-52-047	MODIFICATION - PASSENGER DOOR - VENT FLAP BEAM REPLACEMENT, SERVICE BULLETIN								Bulletin	ATA:52
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-52-048	SPECIAL CHECK/REWORK - PASSENGER DOOR - INSPECTION OF PASSENGER DOOR ACTUATOR RIGGING AND TENSATOR SPRINGS INSTALLATION, SERVICE BULLETIN								Bulletin	ATA:52
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-52-048 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - TENSATOR SPRINGS TENSION RELEASE								Bulletin	ATA:52
	MOS	T:36	EFF		20-May-25 *		464 d	20-May-2025		
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 52 - DOORS										
SB 700-52-048 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - TENSATOR SPRINGS PRE-TENSIONING AND TENSION SET FOR DOOR IN OPEN POSITION								Bulletin	ATA:52
	MOS	T:36	EFF		20-May-25 *		464 d	20-May-2025		
	HRS									
	AFL									
SB 700-52-048 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - CABLES CONNECTION								Bulletin	ATA:52
	MOS	T:36	EFF		20-May-25 *		464 d	20-May-2025		
	HRS									
	AFL									
TCCA CF-2010-14	PASSENGER DOOR - TENSATOR SPRINGS FAILURE (SUPERSEDED BY TCCA AD CF-2014-39)								AD	ATA:52
	DAYS/MSC	-	14-Feb-11						4745 d	
	HRS		7.4						4093.9	
	AFL		4						1221	
ATA 53 - FUSELAGE										
53-10-00-101	DETAILED INSPECTION OF THE NOSE WHEEL WELL AND FRAME, FS251.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.005	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 819						PKG:76
53-10-00-102	DETAILED INSPECTION OF THE LANDING GEAR BOX								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.010	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 820						PKG:76
53-10-00-103	DETAILED INSPECTION OF THE FLOOR ATTACHMENT TO THE BULKHEAD, FS202.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.015	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 821						PKG:76
53-10-00-104	DETAILED INSPECTION OF THE BULKHEAD, FS202.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.020	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 822						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-10-00-105	GENERAL VISUAL INSPECTION OF THE FRAME, FS251.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.025	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 210 822						PKG:76
53-10-00-106	SPECIAL DETAILED INSPECTION OF THE FRAME, FS280.00 − EXTERNAL								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 53.030	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-53-10-004, NDT RT-53-10-001						PKG:76
53-10-00-107	DETAILED INSPECTION OF THE FRAME, FS280.00 - INTERNAL								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.035	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 825						PKG:76
53-10-00-108	SPECIAL DETAILED INSPECTION OF THE SPLICE AT STRINGERS 16A AND 23								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.040	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-10-005						PKG:76
53-10-00-109	DETAILED INSPECTION OF THE SHEET METAL FRAME, FS210.00, FS220.00, FS235.00, FS265.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.045	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 826						PKG:76
53-10-00-110	DETAILED INSPECTION OF THE STRINGERS 16A AND 23, FROM FS202.00 TO FS280.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.050	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 827						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-10-00-112	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUND STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.060	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-10-006, NDT ET-53-10-007						PKG:76
53-10-00-114	DETAILED INSPECTION OF THE COCKPIT SKIN PANELS								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 840						PKG:76
53-10-00-115	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW CENTER POST								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-53-10-001						PKG:76
53-10-00-116	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW LOWER SILL AT THE CENTER POST ATTACHMENT NEAR BL0								Service	ATA:53
	MOS		20-Dec-09					29-Jul-2046	169.7	
	HRS		0						4101.3	
	AFL	T:6620	0		6620		5395		1225	
				PROC. REF: NDT ET-53-10-002						
53-10-00-117	DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD, FS202.75, ABOVE FLOOR								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.125	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 10 00 220 836						
53-10-00-118	DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD, FS202.75 WEB, BELOW FLOOR								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.130	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 10 00 220 811						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-10-00-119	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN, FS169.00 TO FS280.00								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.135	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 10 00 210 802						
53-10-00-120	DETAILED INSPECTION OF THE LONGITUDINAL AND CIRCUMFERENTIAL SKIN JOINTS, FS202.75 TO FS280.00								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.140	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 10 00 220 814						
53-10-00-121	DETAILED INSPECTION OF THE NLG AND PRESSURIZED PANEL CUTOUT SURROUND STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.145	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 10 00 220 815						
53-10-00-122	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW CUTOUT SURROUND STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.150	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 10 00 220 816						
53-10-00-123	DETAILED INSPECTION OF THE PRESSURIZED SURFACES OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.155	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 10 00 220 818						
53-10-00-124	DETAILED INSPECTION OF THE ACCESS PANEL SURROUND STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 839						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-10-00-125	DETAILED INSPECTION OF THE SKIN SPLICE, FS280.00 - EXTERNAL								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 10 00 220 841						PKG:76
53-10-00-126	DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUNDSTRUCTURE, GUSSET AND SIDE PLATES								Service	ATA:53
	MOS		20-Dec-09					27-Aug-2046	169.7	
	HRS		0						4101.3	
	AFL	T:6639	0		6639		5414		1225	
				PROC. REF: AMM 53 10 00 220 842						
53-10-00-201 S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS169.00 TO FS202.75, ABOVE FLOOR								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.070	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 835						PKG:34
53-10-00-202 S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS169.00 TO FS202.75, BELOW FLOOR								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.075	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 837						PKG:34
53-10-00-203	DETAILED INSPECTION OF THE INTERNAL FORWARD FUSELAGE SKIN/STRUCTURE AND FS280.00 BULKHEAD FORWARD FACE, FS202.75 TO FS280.00, ABOVE WL79.50								Service	ATA:53
	MOS	T:180 (+3m/-3m)	30-Jun-11		30-Jun-26	30-Sep-26	870 d (+92)	30-Jun-2026	151.4	
	HRS		0						4101.3	
WC#: 53.080	AFL		0						1225	
				PROC. REF: AMM 53 10 00 220 833						PKG:52
53-10-00-205 S	DETAILED INSPECTION OF THE PILOT AND COPILOT SEAT TRACKS								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.090	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 813						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-10-00-207 S	DETAILED INSPECTION OF THE FLOOR STRUCTURE, FS202.75 TO FS280.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.100	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 807						PKG:38
53-10-00-208 S	DETAILED INSPECTION OF THE FORWARD JACKING POINT, FS278.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.105	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 834						PKG:38
53-10-00-209 S	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW SURROUND STRUCTURE AND RETAINERS								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.110	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 802						PKG:38
53-10-00-210 S	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.115	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 805						PKG:34
53-10-00-211 S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS202.75 TO FS280.00, BELOW FLOOR								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.120	AFL		1069						156	
				PROC. REF: AMM 53 10 00 220 806						PKG:38
53-10-00-212	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE FLIGHT COMPARTMENT CONNECTORS								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 53 10 00 210 824						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-10-00-213	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE FORWARD FACE OF THE FORWARD PRESSURE BULKHEAD CONNECTORS, FS202.00								Service	ATA:53
	MOS	180 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-36	19-Sep-36	4523 d (+81)	30-Jun-2036	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 53 10 00 210 825						PKG:52
53-11-01-900-801-01	FLOOR - FLIGHT COMPARTMENT PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 11 01 000 801, AMM 53 11 01 400 801						
53-11-05-900-801-01	CRAWLWAY PANEL ASSY								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 11 05 000 801, AMM 53 11 05 400 801						
53-20-00-101	DETAILED INSPECTION OF THE FUSELAGE UPPER SKIN AND LONGITUDINAL JOINTS FROM, FS381.00 TO FS557.00 - EXTERNAL								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 53.160	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: AMM 53 20 00 220 864						PKG:76
53-20-00-104	SPECIAL DETAILED INSPECTION OF THE FUSELAGE KEEL BEAM								Service	ATA:53
	MOS		20-Dec-09					02-May-2044	169.7	
	HRS		0						4101.3	
WC#: 53.175	AFL	T:6082	0		6082		4857		1225	
				PROC. REF: NDT ET-53-20-001						
53-20-00-105	SPECIAL DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.180	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-20-006						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-106	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR AND THE STIFFENERS OF THE PRESSURE BULKHEAD FROM FS557.00 TO FS574.50								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.185	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-20-002						PKG:76
53-20-00-109	SPECIAL DETAILED INSPECTION OF THE SKIN AND FUSELAGE JOINTS FROM, FS281.00 TO FS557.00 - EXTERNAL								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 53.200	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-53-20-007, NDT UT-53-20-001						PKG:76
53-20-00-110	DETAILED INSPECTION OF THE FUSELAGE SKIN FROM, FS281.00 TO FS381.00 - EXTERNAL								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.205	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 20 00 220 863						PKG:76
53-20-00-117	DETAILED INSPECTION OF THE PASSENGER DOOR CUTOUT STRUCTURE AND FITTINGS								Service	ATA:53
	MOS		20-Dec-09					12-May-2043	169.7	
	HRS		0						4101.3	
WC#: 53.230	AFL	T:5848	0		5848		4623		1225	
				PROC. REF: AMM 53 20 00 220 851						
53-20-00-118	SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS381.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.235	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-20-003						PKG:76
53-20-00-119	SPECIAL DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BARREL JOINTS, FS381.00 AND FS557.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.240	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-20-005						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-120	SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.245	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-20-004						PKG:76
53-20-00-122	DETAILED INSPECTION OF THE MACHINED FITTINGS AND SKIN AROUND THE SERVICE DOOR, FS295.00 TO FS310.00 AND STR22R TO STR24R								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.255	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 20 00 220 832						PKG:76
53-20-00-123	DETAILED INSPECTION OF THE AVIONICS BAY DOOR AND SURROUNDING SKIN								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.260	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 20 00 220 862						PKG:76
53-20-00-124	DETAILED INSPECTION OF THE WING INSPECTION LIGHT INSTALLATION								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.265	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 20 00 220 865						PKG:76
53-20-00-125	DETAILED INSPECTION OF THE STRINGERS AND FRAMES FROM, FS381.00 TO FS557.00								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: AMM 53 20 00 220 860						PKG:76
53-20-00-126	DETAILED INSPECTION OF THE FUSELAGE STRINGERS AND FRAMES FROM, FS281.00 TO FS381.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 20 00 220 861						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-127	GENERAL VISUAL INSPECTION OF THE PRESSURE BULKHEAD FS557.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 20 00 210 817						PKG:76
53-20-00-128	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE, FS381.00 TO FS557.00 AND STR6L TO STR6R								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.420	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 20 00 210 801						
53-20-00-129	GENERAL VISUAL INSPECTION OF THE LOWER EXTERNAL SKIN OF THE FUSELAGE, FS381.00 TO FS557.00 AND STR6L TO STR6R								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.425	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 20 00 210 802						
53-20-00-130	DETAILED INSPECTION OF THE EXTERNAL AVIONICS- COMPARTMENT ACCESS SURROUND STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.430	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 20 00 220 834						
53-20-00-131	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.435	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 20 00 220 809						
53-20-00-132	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS557.00 TO FS574.60 AND BL46L TO BL46R								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.440	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 20 00 220 810						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
53-20-00-133	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE, FS281.00 TO FS381.00 AND STR2L TO STR7R								Service ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7
	HRS		0						4101.3
WC#: 53.445	AFL	T:3750	0		3750		2525		1225
				PROC. REF: AMM 53 20 00 210 804					
53-20-00-134	GENERAL VISUAL INSPECTION OF THE EXTERNAL LEFT SIDE AND LOWER SKIN, FS281.00 TO FS381.00 AND STR2L TO STR25L								Service ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7
	HRS		0						4101.3
WC#: 53.450	AFL	T:3750	0		3750		2525		1225
				PROC. REF: AMM 53 20 00 210 805					
53-20-00-135	DETAILED INSPECTION OF THE SILLS, FRAME, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT								Service ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7
	HRS		0						4101.3
WC#: 53.455	AFL	T:3750	0		3750		2525		1225
				PROC. REF: AMM 53 20 00 220 821					
53-20-00-136	GENERAL VISUAL INSPECTION OF THE EXTERNAL RIGHT SIDE AND LOWER SKIN, FS281.00 TO FS381.00 AND STR7R TO STR25R								Service ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7
	HRS		0						4101.3
WC#: 53.460	AFL	T:3750	0		3750		2525		1225
				PROC. REF: AMM 53 20 00 210 806					
53-20-00-137	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE WINDOW SURROUND CUTOUTS								Service ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7
	HRS		0						4101.3
WC#: 53.465	AFL	T:3750	0		3750		2525		1225
				PROC. REF: AMM 53 20 00 220 836					
53-20-00-138	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS281.00 TO FS381.00, STR2L, STR7R, STR14L, STR19R AND STR25L								Service ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7
	HRS		0						4101.3
WC#: 53.470	AFL	T:3750	0		3750		2525		1225
				PROC. REF: AMM 53 20 00 220 840					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-139	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS381.00 TO FS557.00, STR6R, STR6L, STR20R AND STR20L								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.475	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 20 00 220 838						
53-20-00-140	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE SERVICE DOOR CUTOUT, FS295.00 TO FS310.00 AND STR22R TO STR24R								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.480	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 20 00 220 835						
53-20-00-201[S]	DETAILED INSPECTION OF THE INTERNAL FUSELAGE SKIN AND STRUCTURE, FS281.00 TO FS861.00, ABOVE WL71.50								Service	ATA:53
	MOS	T:240 (+3m/-3m)	30-Jun-11						151.4	
	HRS									
WC#: 53.270	AFL									
				PROC. REF: AMM 53 20 00 220 801						PKG:56
53-20-00-202[S]	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE, FS381.00 TO FS557.00, BELOW WL71.50								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.275	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 802						PKG:38
53-20-00-203[S]	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE, FS381.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.280	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 839						PKG:34
53-20-00-204[S]	DETAILED INSPECTION OF THE KEEL BEAM, FS501.00 TO FS574.00 AND BL4.6L TO BL4.6R								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.285	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 803						PKG:38
53-20-00-205[S]	DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00 AND STR19L AND STR19R								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.290	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 805						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-206 S	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.295	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 806						PKG:38
53-20-00-207 S	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.300	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 854						PKG:38
53-20-00-208 S	DETAILED INSPECTION OF THE TOP SIDE OF THE PRESSURE FLOOR, FS557.00 TO FS574.50 AND BL46L TO BL46R								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.305	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 807						PKG:38
53-20-00-209 S	DETAILED INSPECTION FLOOR SUPPORT STRUCTURE, FS381.00 TO FS557.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.310	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 808						PKG:38
53-20-00-210 S	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS381.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.315	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 817						PKG:34
53-20-00-212 S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50, FS281.00 TO FS381.00								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.325	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 812						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-213[S]	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50, FS281.00 TO FS381.00, AS VISIBLE WITH THE FLOOR PANELS INSTALLED								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.330	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 813						PKG:34
53-20-00-214[S]	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS281.00 TO FS381.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.335	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 818						PKG:38
53-20-00-215[S]	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS281.00 TO FS381.00 AS VISIBLE FROM THE CRAWLWAY								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.340	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 819						PKG:34
53-20-00-216[S]	DETAILED INSPECTION OF THE FLOOR STRUCTURE IN THE WAY OF THE PASSENGER DOOR STEP, FS310.00 TO FS347.00								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.345	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 820						PKG:34
53-20-00-217[S]	DETAILED INSPECTION OF THE SILLS, FRAMES, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.350	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 821						PKG:34
53-20-00-218[S]	DETAILED INSPECTION OF THE INTERNAL SKIN AROUND THE PASSENGER DOOR CUTOUT								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.355	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 837						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-219[S]	DETAILED INSPECTION OF THE FITTINGS AND HINGES ON THE FUSELAGE FOR THE PASSENGER DOOR								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.360	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 822						PKG:38
53-20-00-221[S]	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS281.00 TO FS381.00, STR19R AND STR25L								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.370	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 824						PKG:38
53-20-00-223[S]	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS381.00 TO FS557.00 - STR20L AND STR20R								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.380	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 826						PKG:38
53-20-00-225[S]	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS381.00, BELOW WL71.50								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.390	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 828						PKG:38
53-20-00-227[S]	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00, BELOW WL71.50								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.400	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 830						PKG:38
53-20-00-229[S]	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR, FS295.00 TO FS310.00 AND STR22R TO STR24R								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.410	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 832						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-20-00-230[S]	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR, FS295.00 TO FS310.00 AND STR22R TO STR24R AS VISIBLE FROM THE CRAWLWAY								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.415	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 833						PKG:38
53-20-00-244[S]	DETAILED INSPECTION OF THE LOWER EXTERNAL SKIN OF THE FUSELAGE, FS381.00 TO FS557.00 AND STR6L TO STR6R COVERED BY THE FORWARD FUEL TANK (A/C 9003, 9096, 9159 AND SUBS)								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 853						PKG:38
53-20-00-246	DETAILED INSPECTION OF THE GROUND STUDS FOR L/HIRF PROTECTION IN THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 53 20 00 220 867						PKG:38
53-30-00-102	SPECIAL DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 TO FS781.00, STRINGER 6								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.490	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-002						PKG:76
53-30-00-103	DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 AND FS797.00, STRINGERS 18L TO 18R								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.495	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 836						PKG:76
53-30-00-104	DETAILED INSPECTION OF THE FUSELAGE SKIN AT THE CABIN WINDOW CUTOUTS, FS557.00 TO FS797.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.500	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 833						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-30-00-105	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTER FLANGE, FS574.00								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 53.505	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT UT-53-30-002						PKG:76
53-30-00-106	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME, FS719.30								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.510	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-004, NDT UT-53-30-001						PKG:76
53-30-00-107	DETAILED INSPECTION OF THE INTERMEDIATE FRAMES								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.515	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 839						PKG:76
53-30-00-110	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.530	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-011, NDT ET-53-30-013, NDT UT-53-30-005						PKG:76
53-30-00-111	DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS AND BEAMS FROM FS719.30 TO FS781.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.535	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 837						PKG:76
53-30-00-113	DETAILED INSPECTION OF THE KEEL BEAM, FS719.30 TO FS781.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.545	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 812						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-30-00-114	SPECIAL DETAILED INSPECTION OF THE REAR SPAR BULKHEAD, FS719.30								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.550	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-014, NDT UT-53-30-008						PKG:76
53-30-00-115	DETAILED INSPECTION OF THE FRAME, FS781.00								Service	ATA:53
	MOS		20-Dec-09					19-Sep-2046	169.7	
	HRS		0						4101.3	
WC#: 53.560	AFL	T:6654	0		6654		5429		1225	
				PROC. REF: AMM 53 30 00 220 832						
53-30-00-116	DETAILED INSPECTION OF THE REAR SPAR FRAME, FS719.30								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 834						PKG:76
53-30-00-118	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS FROM FS719.30 TO FS781.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-015, NDT UT-53-30-004						PKG:76
53-30-00-119	SPECIAL DETAILED INSPECTION OF STRINGER 6 FROM FS574.00 TO FS781.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-012						PKG:76
53-30-00-120	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTBOARD AND INBOARD FLANGES, FS574.00								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-53-30-003						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-30-00-121	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS574.00								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-53-30-008						PKG:76
53-30-00-122	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS719.30								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-005						PKG:76
53-30-00-123	SPECIAL DETAILED INSPECTION OF THE FRAME SPLICE, STRINGERS 5 AND 15, FS574.50 AND FS719.30								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-007						PKG:76
53-30-00-124	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE NOT BEHIND THE FAIRING, FS557.00 TO FS797.60								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.640	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 30 00 210 802						
53-30-00-125	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BEHIND THE FAIRING, FS557.00 TO FS797.60								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.645	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 30 00 210 804						
53-30-00-126	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVERWING EMERGENCY EXIT								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.650	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 30 00 220 803						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-30-00-127	DETAILED INSPECTION OF THE EXTERNAL SKIN OF CABIN WINDOW CUTOUTS, SURROUND STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.655	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 30 00 220 830						
53-30-00-128	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS719.30 TO FS781.00 AND BL35L TO BL35R								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.660	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 30 00 220 808						
53-30-00-129	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00 - EXTERNAL								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.665	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 30 00 220 825						
53-30-00-130	DETAILED INSPECTION OF THE CIRCUMFERENTIAL SKIN JOINT AT FS557.00 AND LONGITUDINAL SKIN JOINTS AT STR6 AND STR18, L AND R								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.670	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 30 00 220 835						
53-30-00-131	SPECIAL DETAILED INSPECTION OF THE EMERGENCY DOOR CUTOUT AND LATCH FITTING								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-006						PKG:76
53-30-00-132	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-010, NDT UT-53-30-007						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-30-00-133	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN SPLICES AT FS737.00 FROM STR15 TO STR19 AND AT STR15 BETWEEN FS737.00 AND FS787.70								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-016, NDT UT-53-30-009						PKG:76
53-30-00-134	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME OUTER-CAP, FS719.30 AT BL47.61								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT UT-53-30-003						PKG:76
53-30-00-135	DETAILED INSPECTION OF THE FUSELAGE SKIN PANEL AND STRINGER 18 - INTERNAL								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 843						PKG:76
53-30-00-136	SPECIAL DETAILED INSPECTION OF THE FRAME, FS781.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-30-017, NDT UT-53-30-010						PKG:76
53-30-00-137	DETAILED INSPECTION OF THE CENTER FUSELAGE SKINPANEL-ASSEMBLY FROM FS557.00 TO FS797.60								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 841						PKG:76
53-30-00-138	DETAILED INSPECTION OF THE FRAME SPLICE, FS574.00 TOFS781.00, STR5 AND STR15								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 30 00 220 842						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-30-00-201 S	DETAILED INSPECTION OF THE FRONT SPAR FRAME ABOVE WL71.50, FS574.50								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.565	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 801						PKG:38
53-30-00-202 S	DETAILED INSPECTION OF THE FRONT SPAR FRAME BELOW WL71.50, FS574.50								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.570	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 810						PKG:38
53-30-00-203 S	DETAILED INSPECTION OF THE REAR SPAR FRAME ABOVE WL71.50, FS719.30								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.575	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 802						PKG:38
53-30-00-204 S	DETAILED INSPECTION OF THE REAR SPAR FRAME BELOW WL71.50, FS719.30								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.580	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 813						PKG:38
53-30-00-205 S	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT -EXTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.585	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 803						PKG:34
53-30-00-206 S	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT - INTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.590	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 827						PKG:38
53-30-00-207 S	DETAILED INSPECTION OF THE FITTINGS ON THE FRAME OF THE OVER-WING EMERGENCY EXIT								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.595	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 804						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-30-00-208[S]	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE CABIN WINDOW CUTOUTS								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.600	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 805						PKG:38
53-30-00-210[S]	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BELOW WL71.50, FS557.00 TO FS797.60								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.610	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 815						PKG:38
53-30-00-211[S]	DETAILED INSPECTION OF THE TOP OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.615	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 807						PKG:38
53-30-00-212[S]	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.620	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 808						PKG:38
53-30-00-213[S]	DETAILED INSPECTION OF THE PRESSURE FLOOR BEAMS, FS713.10 TO FS781.00, BL0.0, BL9, BL19, BL27 AND BL35								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.625	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 809						PKG:38
53-30-00-214[S]	DETAILED INSPECTION OF THE KEEL BEAM STRUCTURE, FS719.30 TO FS781.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.630	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 812						PKG:38
53-30-00-215[S]	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00 - EXTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.635	AFL		1069						156	
				PROC. REF: AMM 53 30 00 220 825						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
53-31-01-900-801-01	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-02	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-03	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-04	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-05	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-06	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-07	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
53-31-01-900-801-08	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-09	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-10	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-11	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-12	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-13	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-14	CENTER FUSELAGE L/H FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
53-31-01-900-801-15	CENTER FUSELAGE R/H FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-16	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-17	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-18	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-19	CENTER FUSELAGE L/H FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-20	CENTER FUSELAGE R/H FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					
53-31-01-900-801-21	CENTER FUSELAGE FLOOR PANEL								Component ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-31-01-900-801-22	CENTER FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801						
53-31-01-900-801-23	CENTER FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801						
53-31-01-900-801-24	CENTER FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 31 01 000 801, AMM 53 31 01 400 801						
53-40-00-101	DETAILED INSPECTION OF THE FUSELAGE SKIN FROM FS781.00 TO FS861.00 - EXTERNAL								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.675	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 846						PKG:76
53-40-00-102	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN LONGITUDINAL JOINTS								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 53.680	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-53-40-009, NDT ET-53-40-010, NDT ET-53-40-015, NDT UT-53-40-005						PKG:76
53-40-00-103	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE AND PRESSURE BULKHEAD								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.685	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 833						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-104	DETAILED INSPECTION OF THE FRAMES AT FS925.00 AND FS987.00 AND THE REAR FUSELAGE LONGERON PLATFORM								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.690	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 840						PKG:76
53-40-00-105	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD AT FS861.00, AND THE FLOOR BEAMS FS789.00 TO FS861.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.695	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 832						PKG:76
53-40-00-106	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN FROM FS861.00 TO REAR SPAR FRAME - EXTERNAL								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.700	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 210 802						PKG:76
53-40-00-108	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, LOWER SILL								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.710	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 834						PKG:76
53-40-00-109	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, FRAME AND REINFORCING STRAP								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.715	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 835						PKG:76
53-40-00-110	DETAILED INSPECTION OF THE REAR-PRESSURE BULKHEAD UPPER-HORIZONTAL-BEAM								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.720	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 847						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-111	DETAILED INSPECTION OF THE PRESSURE BULKHEAD AT FS861.00 VERTICAL STIFFENERS AND BAGGAGE DOOR SILL FITTING								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.725	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 822						PKG:76
53-40-00-113	SPECIAL DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAM JOINTS								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.735	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-004						PKG:76
53-40-00-114	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT AT FS813.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.740	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-002						PKG:76
53-40-00-115	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT, FORWARD OF FS861.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.745	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-003						PKG:76
53-40-00-117	GENERAL VISUAL INSPECTION OF THE REAR FUSELAGE KEEL BEAM								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.755	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 839						PKG:76
53-40-00-119	DETAILED INSPECTION OF THE REAR-FUSELAGE SKIN ENGINE-MOUNT-CUTOUTS								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.765	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 848						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-120	SPECIAL DETAILED INSPECTION OF THE INNER FLAP TRACK SUPPORT-FITTINGS ON THE REAR FUSELAGE								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.770	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-005						PKG:76
53-40-00-121	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT-SPAR								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.775	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 849						PKG:76
53-40-00-122	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER MID-SPAR								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.780	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 843						PKG:76
53-40-00-123	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER REAR-SPAR								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.785	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 844						PKG:76
53-40-00-124	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SUPPORT FRAMES FOR THE ENGINE BEAMS, INNER FLANGE								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.790	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-001						PKG:76
53-40-00-125	SPECIAL DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT SPAR, INBOARD FLANGE								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.795	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-008						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-126	DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAMS								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 831						PKG:76
53-40-00-127	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CIRCUMFERENTIAL JOINTS								Service	ATA:53
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-53-40-011, NDT ET-53-40-013, NDT ET-53-40-014, NDT UT-53-40-003, NDT UT-53-40-004						PKG:76
53-40-00-128	DETAILED INSPECTION OF THE FUSELAGE SKIN AROUND THE BAGGAGE DOOR								Service	ATA:53
	MOS		20-Dec-09					12-Jan-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7450	0		7450		6225		1225	
				PROC. REF: AMM 53 40 00 220 820						
53-40-00-129	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF PRESSURE FUSELAGE, FS797.00 TO FS861.00								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.880	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 40 00 210 826						
53-40-00-130	DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS OF THE PRESSURE SHELL NOT COVERED BY WING -TO-FUSELAGE FAIRINGS								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.885	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 40 00 220 815						
53-40-00-131	DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.890	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 40 00 220 821						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-132	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BENEATH THE WING-TO-FUSELAGE FAIRING IN THE PRESSURIZED ZONE								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.895	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 40 00 210 808						
53-40-00-133	DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS BENEATH THE WING-TO-FUSELAGE FAIRING								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.900	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 40 00 220 816						
53-40-00-134	DETAILED INSPECTION OF THE PRESSURE BULKHEAD FORWARD WEB BELOW FLOOR								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.905	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 40 00 220 817						
53-40-00-135	DETAILED INSPECTION OF THE PRESSURE BULKHEAD WEB ABOVE FLOOR								Service	ATA:53
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 53.910	AFL	T:3750	0		3750		2525		1225	
				PROC. REF: AMM 53 40 00 220 818						
53-40-00-137	SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEADAT FS861.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-017						PKG:76
53-40-00-138	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUNDSTRUCTURE - PRESSURE BULKHEAD								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-016, NDT UT-53-40-006						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-139	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKINCUTOUTS FROM FS781.00 TO FS1066.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-53-40-012, NDT UT-53-40-002						PKG:76
53-40-00-140	DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CUTOUTS FROMFS781.00 TO FS1066.00								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 40 00 220 851						PKG:76
53-40-00-201 S	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW VERTICAL STABILIZER, FS945.00 TO THE REAR SPAR OF THE VERTICAL STABILIZER								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.800	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 803						PKG:38
53-40-00-202 S	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE PYLON, FS877.25 TO THE REAR SPAR OF THE VERTICAL STABILIZER								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.805	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 804						PKG:38
53-40-00-203 S	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE WING-TO-FUSELAGE FAIRING, AND THE AFT KEEL BEAM, FS781.00 TO FS945.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.810	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 805						PKG:38
53-40-00-204 S	DETAILED INSPECTION OF THE STOP FITTINGS OF THE BAGGAGE DOOR ON THE FUSELAGE								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.815	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 801						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-205 S	DETAILED INSPECTION OF THE INTERNAL SURROUND STRUCTURE OF THE BAGGAGE DOOR, FORWARD OF THE PRESSURE BULKHEAD								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.820	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 802						PKG:38
53-40-00-206 S	DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.825	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 821						PKG:34
53-40-00-208 S	DETAILED INSPECTION OF THE INTERNAL FUSELAGE STRUCTURE AND FORWARD FACE OF THE REAR PRESSURE BULKHEAD BELOW THE FLOOR, AND THE FLOOR STRUCTURE OF THE BAGGAGE COMPARTMENT								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.835	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 807						PKG:34
53-40-00-209	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR PRESSURE BULKHEAD ABOVE THE FLOOR								Service	ATA:53
	MOS	T:180 (+3m/-3m)	30-Jun-11		30-Jun-26	30-Sep-26	870 d (+92)	30-Jun-2026	151.4	
	HRS		0						4101.3	
WC#: 53.840	AFL		0						1225	
				PROC. REF: AMM 53 40 00 220 808						PKG:52
53-40-00-210 S	DETAILED INSPECTION OF THE STRUCTURE OF THE AFT FACE OF THE REAR PRESSURE BULKHEAD								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.845	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 809						PKG:38
53-40-00-211 S	DETAILED INSPECTION OF THE UPPER SILL AND STOP BACKUP STRUCTURE OF THE BAGGAGE DOOR, AFT OF THE PRESSURE BULKHEAD								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.850	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 810						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-40-00-212[S]	DETAILED INSPECTION OF THE AUXILIARY FUEL TANK FLOOR STRUCTURE								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.855	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 819						PKG:38
53-40-00-213[S]	DETAILED INSPECTION OF THE AFT EQUIPMENT COMPARTMENT INTERIOR STRUCTURE, FS861.00, VERTICAL-STABILIZER REAR-SPAR FRAME								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.860	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 812						PKG:34
53-40-00-214[S]	DETAILED INSPECTION OF THE AFT EQUIPMENT COMPARTMENT INTERIOR STRUCTURE ADJACENT TO THE AUXILIARY FUEL TANK, FS861.00 TO FS893.50, WL80.25 TO WL137.00								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.865	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 813						PKG:38
53-40-00-215[S]	DETAILED INSPECTION OF THE FORWARD ENGINE-MOUNT FRAME-ASSEMBLY								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 53.870	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 814						PKG:34
53-40-00-216[S]	DETAILED INSPECTION OF THE SUPPORT STRUCTURE OF THE INNER FLAP INBOARD TRACK								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.875	AFL		1069						156	
				PROC. REF: AMM 53 40 00 220 811						PKG:38
53-40-00-217	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE AFT FACE OF THE AFT PRESSURE BULKHEAD CONNECTORS - FS861.00								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-26	19-Sep-26	870 d (+81)	30-Jun-2026	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 53 40 00 210 831						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-41-01-900-801-01	AFT FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801						
53-41-01-900-801-02	AFT FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801						
53-41-01-900-801-03	AFT FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801						
53-41-01-900-801-04	AFT FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801						
53-41-01-900-801-05	AFT FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801						
53-41-01-900-801-06	AFT FUSELAGE FLOOR PANEL								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801						
53-50-00-101	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR CAP AND CRUCIFORM FITTING								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.915	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 50 00 220 806						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-50-00-102	DETAILED INSPECTION OF THE VERTICAL STABILIZER ATTACHMENT AT THE FUSELAGE FRAMES								Service	ATA:53
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 53.920	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 53 50 00 220 810						PKG:76
53-50-00-201 S	DETAILED INSPECTION OF THE AFT ENGINE-MOUNT FRAME-ASSEMBLY								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.940	AFL		1069						156	
				PROC. REF: AMM 53 50 00 220 801						PKG:34
53-50-00-202 S	DETAILED INSPECTION OF THE MID SPAR FRAME								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.945	AFL		1069						156	
				PROC. REF: AMM 53 50 00 220 802						PKG:38
53-50-00-203 S	DETAILED INSPECTION OF THE REAR SPAR FRAME								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.950	AFL		1069						156	
				PROC. REF: AMM 53 50 00 220 803						PKG:38
53-50-00-204 S	DETAILED INSPECTION OF THE STRUT ATTACH AND BACKUP FITTINGS OF THE APU MOUNT STRUCTURE								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.955	AFL		1069						156	
				PROC. REF: AMM 53 50 00 220 804						PKG:38
53-60-01-900-801-01	RADOME								Component	ATA:53
PN:GC219-0504-7	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E184213	HRS		0	TSN 0					4101.3	
WC#: 53.1125	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 60 01 000 801, AMM 53 60 01 400 801						
53-62-01-900-801-01	EVS SYSTEM - HEATED FAIRING								Component	ATA:53
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 53 62 01 000 801, AMM 53 62 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-ZL-00-201 S	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - INTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.960	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 803						PKG:38
53-ZL-00-202 S	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL LH								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.965	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 806						PKG:38
53-ZL-00-203 S	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL RH								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.970	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 807						PKG:34
53-ZL-00-204 S	GENERAL VISUAL INSPECTION OF THE NOSE WHEEL WELL								Service	ATA:53
	MOS		17-Jul-19						54.8	
	HRS		3188.8						912.5	
WC#: 53.975	AFL	450 (+50/-50)	996						229	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 818						PKG:58
53-ZL-00-205 S	GENERAL VISUAL INSPECTION OF THE MID LOWER FUSELAGE, SLAT DRIVE COMPARTMENT - INTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.980	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 53 10 00 210 809						PKG:34
53-ZL-00-206 S	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS781.00 TO FS861.00, BELOW WL71.5 - INTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.985	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 40 00 210 825						PKG:34
53-ZL-00-207 S	GENERAL VISUAL INSPECTION OF THE AFT WING-TO-FUSELAGE FAIRING - INTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.990	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 61 09 210 801						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-ZL-00-208 S	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE - EXTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.995	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 30 00 210 806						PKG:38
53-ZL-00-209 S	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR WHEEL WELL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1000	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 30 00 210 807						PKG:34
53-ZL-00-210 S	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE BETWEEN THE PRESSURE FLOOR AND THE CABIN FLOOR - INTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1005	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 30 00 210 808						PKG:38
53-ZL-00-211 S	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX LOWER SURFACE - EXTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1010	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 30 00 210 811						PKG:38
53-ZL-00-212 S	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX - INTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1015	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 30 00 210 812						PKG:38
53-ZL-00-213 S	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00 - EXTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1020	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 20 00 210 813						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-ZL-00-214[S]	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, AND BETWEEN STR22L AND STR22R - INTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1025	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 20 00 210 816						PKG:34
53-ZL-00-215[S]	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, AND BETWEEN STR18L AND STR22L, AND STR18R AND STR22R - INTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1030	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 20 00 210 814						PKG:38
53-ZL-00-216	GENERAL VISUAL INSPECTION OF THE WING-TO-FUSELAGE FAIRINGS - EXTERNAL								Service	ATA:53
	MOS		20-Dec-09					04-Jul-2026	169.7	
	HRS		0						4101.3	
WC#: 53.1035	AFL	1800 (+50/-50)	0		1800	1850	575 (+50)		1225	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 20 00 210 810						
53-ZL-00-217[S]	GENERAL VISUAL INSPECTION OF THE FUSELAGE NOSE SECTION - EXTERNAL								Service	ATA:53
	MOS		06-Jul-18						67.2	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 53.1040	AFL		921						304	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 20 00 210 815						PKG:8
53-ZL-00-218[S]	GENERAL VISUAL INSPECTION OF THE NOSE SECTION OF THE FORWARD EQUIPMENT COMPARTMENT - INTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1045	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 817						PKG:34
53-ZL-00-219[S]	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT								Service	ATA:53
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 53.1050	AFL		1171						54	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 819						PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-ZL-00-220[S]	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT, EXCLUDING THE BAGGAGE DOOR - EXTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1055	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 40 00 210 805						PKG:34
53-ZL-00-221[S]	GENERAL VISUAL INSPECTION OF THE ELECTRICAL POWER CONTROL-CENTER - EXTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1060	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 53 40 00 210 827						PKG:34
53-ZL-00-222[S]	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT - INTERNAL								Service	ATA:53
	MOS	180 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1065	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 40 00 210 830						PKG:52
53-ZL-00-223[S]	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE - EXTERNAL								Service	ATA:53
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1070	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 30 00 210 805						PKG:38
53-ZL-00-224[S]	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE COMPARTMENT ABOVE THE CABIN FLOOR - INTERNAL								Service	ATA:53
	MOS	180 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1075	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 30 00 210 809						PKG:52
53-ZL-00-225[S]	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, EXCLUDING THE PASSENGER DOOR - EXTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1080	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 20 00 210 811						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-ZL-00-226 S	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, ABOVE WL71.50, EXCLUDING THE PASSENGER DOOR - INTERNAL								Service	ATA:53
	MOS	180 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1085	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 20 00 210 812						PKG:52
53-ZL-00-227 S	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - EXTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1090	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 40 00 210 811						PKG:34
53-ZL-00-228 S	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - INTERNAL								Service	ATA:53
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 53.1095	AFL		1171						54	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 40 00 210 812						PKG:32
53-ZL-00-229 S	GENERAL VISUAL INSPECTION OF THE TAILCONE - EXTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1100	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 50 00 210 804						PKG:34
53-ZL-00-230 S	GENERAL VISUAL INSPECTION OF THE TAILCONE - INTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1105	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 50 00 210 805						PKG:34
53-ZL-00-231 S	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS987.50 TO THE VERTICAL-STABILIZER REAR-SPAR DATUM-LINE - INTERNAL								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1110	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 50 00 210 806						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
53-ZL-00-232 S	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL LH								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1115	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 820						PKG:34
53-ZL-00-233 S	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL RH								Service	ATA:53
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 53.1120	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 53 10 00 210 820						PKG:34
530000-701 U	TOW BAR PORTABLE 48" EXTENSION ASSEMBLY								Component	ATA:53
PN:01-1275-0010A1	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:9219000301	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
ASB A700-53-033 PART (A)	CHECK FOR FLUID CONTAMINATION OF SOUNDPROOFING MATERIAL AND MODIFY AND REMOVE SOUNDPROOFING MATERIAL FROM SPECIFIED AREAS (A/C 9121, 9136, 9139, 9141 AND 9143), ALERT SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-53-033 PART (B)	CHECK FOR FLUID CONTAMINATION OF SOUNDPROOFING MATERIAL AND MODIFY AND REMOVE SOUNDPROOFING MATERIAL FROM SPECIFIED AREAS (A/C 9121, 9136, 9139, 9141 AND 9143), ALERT SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-53-039	SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
ASB A700-53-039 PART (A)	INSPECTION SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
ASB A700-53-039 PART (B)	REWORK SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	22-Aug-11						149.6	
	HRS									
	AFL									
ASB A700-53-039 PART (C)	REPLACEMENT SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT SERVICE BULLETIN OF FAULTY FASTENERS								Bulletin	ATA:53
	MOS/MSC	-	22-Aug-11						149.6	
	HRS									
	AFL									
ASB A700-53-045	SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	27-Apr-12						141.5	
	HRS		443.4						3657.9	
	AFL		160						1065	
ASB A700-53-045 PART (A)	INSPECTION SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN								Bulletin	ATA:53
	DAYS/MSC	-	27-Apr-12						4307 d	
	HRS		443.4						3657.9	
	AFL		160						1065	
ASB A700-53-045 PART (B)	REWORK SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN								Bulletin	ATA:53
	DAYS/MSC	-	27-Apr-12						4307 d	
	HRS		443.4						3657.9	
	AFL		160						1065	
ASB A700-53-045 PART (C)	REPLACE SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	27-Apr-12						141.5	
	HRS		443.4						3657.9	
	AFL		160						1065	
FAA 2018-21-03	FUSELAGE - REPLACEMENT OF ATTACHMENTS FOR BELLY FAIRING ACCESS PANELS								AD	ATA:53
	MOS/MSC	-	19-Nov-18						62.7	
	HRS		3006.2						1095.1	
	AFL		949						276	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
FAA 2018-25-07	FUSELAGE - BELLY FAIRING - BLOCKED DRAINAGE HOLES								AD	ATA:53
	MOS/MSC	-	10-Jan-19						61	
	HRS		3041						1060.3	
	AFL		960						265	
FAA 2020-05-27	AFT FUSELAGE - RUDDER QUADRANT SUPPORT CHANNEL CRACKING								AD	ATA:53
	MOS/MSC	-								
	HRS									
	AFL									
FAA 2020-05-27 PARA (G)	DETAILED VISUAL INSPECTION FOR CRACKING OF THE RUDDER QUADRANT BOX ASSEMBLY (FOR AIRPLANES THAT HAVE ACCUMULATED FEWER THAN 2,900 TOTAL FC AS OF THE EFFECTIVE DATE OF THIS AD, AND THAT HAVE NOT BEEN MODIFIED AS SPECIFIED IN PARA (I))								AD	ATA:53
	MOS		19-Mar-21					17-Aug-2027	34.7	
	HRS		3474.7						626.6	
	AFL	1000	1069		2069		844		156	
FAA 2020-05-27 PARA (I[S])	ACCOMPLISH THE ACTIONS SPECIFIED IN PARA (I) (IF ANY CRACKING IS FOUND DURING ANY INSPECTION SPECIFIED IN PARA (G))								AD	ATA:53
	MOS									
	HRS									
	AFL	T:50								
FAA 2020-05-27 PARA (I)	MODIFY THE RUDDER QUADRANT BOX ASSEMBLY								AD	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
FAA 2020-05-27 PARA (K)	ACCOMPLISHING THE ACTIONS IN PARA (I) OR (J) OF THIS AD TERMINATES ALL OF THE REQUIREMENTS IN PARA (G) OF THIS AD								AD	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
IS MODSUM IS700-53-0013 REV A1	FUSELAGE - AFT TAILCONE - KIT - ADDITION OF DRAIN HOLES TO LHS AND RHS AFT TAILCONE SKINS, IN SERVICE MODIFICATION SUMMARY								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-16						94.7	
	HRS		1978.6						2122.7	
	AFL		690						535	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
MODSUM IS700-53-0002[U] REV C	INSTALATION OF EVS DRIP TRAY, MODIFICATION SUMMARY								Bulletin ATA:53
	MOS/MSC	A/R							
	HRS								
	AFL								
MODSUM IS700-53-0002[U] REV A	FUSELAGE - AVIONICS BAY - INSTALATION OF LGECU DRIP COVER (CLASSIC GX & XRS), MODIFICATION SUMMARY								Bulletin ATA:53
	MOS/MSC	A/R							
	HRS								
	AFL								
MODSUM IS700-53-0003[U] REV A	FUSELAGE - AVIONICS BAY - INSTALATION OF IRU DRIP COVER (CLASSIC GLOBAL EXPRESS, G500 & XRS), MODIFICATION SUMMARY								Bulletin ATA:53
	MOS/MSC	A/R							
	HRS								
	AFL								
MODSUM IS700-53-0004[U] REV A	FUSELAGE - AVIONICS BAY - INSTALATION OF HUD COMPUTER DRIP COVER (CLASSIC GX & XRS), MODIFICATION SUMMARY								Bulletin ATA:53
	MOS/MSC	A/R							
	HRS								
	AFL								
MODSUM IS700-53-0005[U] REV A	FUSELAGE - AVIONICS BAY - INSTALATION OF TCAS RECIEVER/TRANSMITTER DRIP COVER (CLASSIC GX & XRS), MODIFICATION SUMMARY								Bulletin ATA:53
	MOS/MSC	A/R							
	HRS								
	AFL								
REO 700-53-40-188[U]	REPAIR - CORROSION TO WING/FUSELAGE FAIRING SILL, REPAIR ENGINEERING ORDER								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
REO 700-53-53-218[U]	REPAIR - LH AND RH AFT TAILCONE SKINS, REPAIR ENGINEERING ORDER								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
REO 700-53-53-219[U]	REPAIR - CORROSION ON TAILCONE END CAP & AFT SKINS, REPAIR ENGINEERING ORDER								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-53-013	REWORK - BELLY FAIRINGS - ADDITION OF DRAIN HOLE NEAR REFUEL/DEFUEL COMPARTMENT, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-016	MODIFICATION - BELLY FAIRINGS - ADDITION OF DRAIN HOLES TO BELLY FAIRING PANELS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-016 REV 01	MODIFICATION - BELLY FAIRINGS - ADDITION OF DRAIN HOLES TO BELLY FAIRING PANELS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-016 REV 02	MODIFICATION - BELLY FAIRINGS - ADDITION OF DRAIN HOLES TO BELLY FAIRING PANELS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-018	MODIFICATION - FUSELAGE - INSTALLATION OF LOUVERS TO RAM AIR OUTLET DUCT, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-019	MODIFICATION - FORWARD FUSELAGE FLOOR - ALLOW REMOVAL OF STRUCTURAL FLOOR PANEL FOR INSPECTION AND EASE OF REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-019 REV 01	MODIFICATION - FORWARD FUSELAGE FLOOR - ALLOW REMOVAL OF STRUCTURAL FLOOR PANEL FOR INSPECTION AND EASE OF REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
SB 700-53-021	MODIFICATION - FORWARD WING-TO-FUSELAGE FAIRING - ADDITION OF SEALANT IN THE LAVATORY SERVICE BAY TO PREVENT WASTE SPILLAGE FROM ENTERING FORWARD WING-TO-FUSELAGE FAIRING, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-022	SPECIAL CHECK/REWORK - AFT FUSELAGE - CENTER-TO-AFT FUSELAGE JOINT CONFIGURATION (FS785.00), SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-024	MODIFICATION - CENTER FUSELAGE - REMOVAL OF WHEEL BIN SOUND - DAMPING BLANKETS TO REDUCE WEIGHT, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-025	MODIFICATION - WING-TO-FUSELAGE FAIRINGS - REPLACEMENT OF TEFLON SHEET ON VISOR PANEL TO PREVENT DAMAGE TO AFT OVER-WING FAIRING PAINT FINISH, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-025 REV 01	MODIFICATION - WING-TO-FUSELAGE FAIRINGS - REPLACEMENT OF TEFLON SHEET ON VISOR PANEL TO PREVENT DAMAGE TO AFT OVER-WING FAIRING PAINT FINISH (A/C 9002 TO 9043 AND 9045 TO 9163), SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-027	MODIFICATION - AFT FUSELAGE - ADDITION OF DRAINAGE PROVISIONS AT THE BAGGAGE DOORSILL, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-027 REV 01	MODIFICATION - AFT FUSELAGE - ADDITION OF DRAINAGE PROVISIONS AT THE BAGGAGE DOORSILL, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
SB 700-53-028	MODIFICATION - AFT EQUIPMENT COMPARTMENT - DRIP TRAY INSTALLATION TO PROTECT RADIO ALTIMETER AND HF TRANSCEIVER NO.2, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-53-029	SPECIAL CHECK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-029 REV 01	SPECIAL CHECK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-029 REV 02 PART (A)	SPECIAL CHECK/REWORK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9134), SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-029 REV 02 PART (B)	SPECIAL CHECK/REWORK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES (A/C 9002 TO 9126, 9128 TO 9201), SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-031	SPECIAL CHECK/REWORK - BELLY FAIRINGS - REMOVAL OF REDUNDANT AERODYNAMIC SEALANT TO ALLOW DRAINAGE OF FLUIDS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-034	MODIFICATION - FORWARD-FUSELAGE FLOOR - ADDITION OF DRAIN HOLES AT FRAME FS328.50 AND STRINGER 24LH (A/C 9002 TO 9126 AND 9128 TO 9328), SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	T:A/R							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
SB 700-53-035	MODIFICATION - EMPENNAGE/TAIL - ADDITION OF DRAIN HOLE ON RIB NO. 7 OF RUDDER, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-53-035 REV 01	MODIFICATION - EMPENNAGE/TAIL - ADDITION OF DRAIN HOLE ON RIB NO. 7 OF RUDDER (A/C 9002 TO 9126 AND 9128 TO 9294), SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-53-037	MODIFICATION - NOSE FUSELAGE - REPLACE CLIP-NUTS WITH NUT-PLATES FOR TRIM PANELS AT FS280.00, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-53-038	MODIFICATION - BELLY FAIRING - ADDITION OF DRAIN HOLES TO PREVENT WATER ACCUMULATION (A/C 9002 TO 9126 AND 9128 TO 9229), SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-53-040	MODIFICATION - AVIONICS BAY - INSTALLATION OF PROTECTIVE COVERS OVER THE FCU AND SFCU UNITS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-53-040 REV 01	MODIFICATION - AVIONICS BAY - INSTALLATION OF PROTECTIVE COVERS OVER THE FCU AND SFCU UNITS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-53-040 REV 02	MODIFICATION - AVIONICS BAY - INSTALLATION OF PROTECTIVE COVERS OVER THE FCU AND SFCU UNITS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	EFF						
	HRS								
	AFL								
SB 700-53-041	REWORK - CENTER FUSELAGE - REWORK SURFACE FINISH AT FITTING ASSEMBLY ON THE EMERGENCY EXIT DOOR, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
SB 700-53-042	SPECIAL CHECK/REWORK - AFT FUSELAGE - INSPECTION OF BOLTS ON BAGGAGE DOOR STOPS AND REPLACE IF LOOSE, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	01-Apr-11						154.3
	HRS		15.6						4085.7
	AFL		7						1218
SB 700-53-042 REV 01	ICA - SPECIAL CHECK/REWORK - AFT FUSELAGE - INSPECTION OF BOLTS ON BAGGAGE DOOR STOPS AND REPLACE IF LOOSE, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	27-Apr-12						141.5
	HRS		443.4						3657.9
	AFL		160						1065
SB 700-53-043	MODIFICATION - AFT EQUIPMENT COMPARTMENT - INSTALLATION OF STORAGE PROVISION FOR GROUND AIR SUPPLY ADAPTOR, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	06-Jul-12						139.2
	HRS		541.7						3559.6
	AFL		200						1025
SB 700-53-043 REV 01	MODIFICATION - AFT EQUIPMENT COMPARTMENT - INSTALLATION OF STORAGE PROVISION FOR GROUND AIR SUPPLY ADAPTOR, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	08-Apr-13						130.1
	HRS		902.7						3198.6
	AFL		347						878
SB 700-53-043 REV 02	MODIFICATION - AFT EQUIPMENT COMPARTMENT - INSTALLATION OF STORAGE PROVISION FOR GROUND AIR SUPPLY ADAPTOR, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-53-044	MODIFICATION - FORWARD FUSELAGE FLOOR - INSTALLATION OF A PROTECTIVE COVER OVER THE EGPWS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	24-Apr-12						141.6
	HRS		443.4						3657.9
	AFL		160						1065
SB 700-53-047	SPECIAL CHECK/REWORK - AFT FUSELAGE - REWORK WING/FUSELAGE FAIRING SILL TO PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
SB 700-53-048	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY FOR CORROSION, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	EFF						
	HRS								
	AFL								
SB 700-53-049	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FOR CORROSION, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-53-049 PART (A)	DETAILED VISUAL INSPECTION SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FOR CORROSION, SERVICE BULLETIN (DVI) OF THE TAILCONE ASSEMBLY								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-53-049 PART (B)	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FOR CORROSION, SERVICE BULLETIN LOCAL REWORK OF THE TAILCONE ASSEMBLY								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-53-049 PART (C)	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE FORWARD/AFT TAILCONE AND END CAP SKINS								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-53-049 PART (D)	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE APU DOOR SKINS								Bulletin ATA:53
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-53-049 REV 01	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 53 - FUSELAGE									
SB 700-53-049 REV 01 PART (A)	ACCOMPLISH, SERVICE BULLETIN DETAILED VISUAL INSPECTION (DVI) OF THE TAILCONE ASSEMBLY								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-53-049 REV 01 PART (B)	ACCOMPLISH, SERVICE BULLETIN LOCAL REWORK OF THE TAILCONE ASSEMBLY								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-53-049 REV 01 PART (C)	ACCOMPLISH, SERVICE BULLETIN MAJOR REWORK OF THE FORWARD/AFT TAILCONE AND END CAP SKINS								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-53-049 REV 01 PART (D)	ACCOMPLISH, SERVICE BULLETIN MAJOR REWORK OF THE APU DOOR SKINS								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-53-050	MODIFICATION - BELLY FAIRINGS - REPLACEMENT OF ATTACHMENTS FOR THE ACCESS PANELS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-53-050 REV 01	MODIFICATION - BELLY FAIRINGS - REPLACEMENT OF ATTACHMENTS FOR THE ACCESS PANELS, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	AFL		817						408
SB 700-53-051	SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT, SERVICE BULLETIN								Bulletin ATA:53
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	AFL		817						408

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
SB 700-53-051 PART (A)	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF SEALANT								Bulletin	ATA:53
	MOS/MSC	-	11-Jul-17						79	
	HRS		2473.8						1627.5	
	AFL		817						408	
SB 700-53-051 PART (B)	ACCOMPLISH, SERVICE BULLETIN REWORK - REMOVAL OF AERODYNAMIC SEALANT								Bulletin	ATA:53
	MOS/MSC	-	11-Jul-17						79	
	HRS		2473.8						1627.5	
	AFL		817						408	
SB 700-53-052	MODIFICATION - AFT FUSELAGE - REPLACEMENT AND REINFORCEMENT OF THE RUDDER QUADRANT BOX ASSEMBLY HALF RIBS, SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-53-053	SPECIAL CHECK - BELLY FAIRING ACCESS PANELS - RE-TORQUE OF THE BELLY FAIRING FASTENERS ON 185CL AND 186CR, SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-53-054	SPECIAL CHECK - AFT FUSELAGE - INSPECTION OF THE RUDDER QUADRANT BOX ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-53-055	MODIFICATION - AUXILIARY POWER UNIT (APU) ACCESS DOORS - MODIFICATION OF APU ACCESS DOORS AND FORWARD/AFT TAILCONE TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-53-055 PART A	ACCOMPLISH, SERVICE BULLETIN LEFT AND RIGHT AFT TAILCONE SKIN MODIFICATION								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 53 - FUSELAGE										
SB 700-53-055 PART B	ACCOMPLISH, SERVICE BULLETIN APPLY THE CORROSION INHIBITING COMPOUND (CIC) ON FORWARD AND AFT TAILCONE STRUCTURES								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-53-055 PART C	ACCOMPLISH, SERVICE BULLETIN APU ACCESS DOOR MODIFICATION AND APPLICATION OF CIC								Bulletin	ATA:53
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700D53-036 REV 2[U]	MODIFICATION - PROVISIONS - AFT FUSELAGE - INSTALLATION OF PROVISIONS FOR COMBINED JACKING EQUIPMENT., SERVICE BULLETIN								Bulletin	ATA:53
	MOS/MSC	A/R	01-Apr-11						154.3	
	HRS		15.6						4085.7	
	AFL		7						1218	
ATA 54 - NACELLES/PYLONS										
54-50-00-201[S]	DETAILED INSPECTION OF THE VERTICAL FLANGE OF THE PYLON DRAG ANGLES - PS30.00 TO PS151.00								Service	ATA:54
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 54.005	AFL		1069						156	
				PROC. REF: AMM 54 50 00 220 801						PKG:38
54-50-00-202[S]	DETAILED INSPECTION OF THE PYLON CENTER BOX INTERNAL STRUCTURE - PS30.00 TO PS151.00								Service	ATA:54
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 54.010	AFL		1069						156	
				PROC. REF: AMM 54 50 00 220 802						PKG:34
54-50-01-201	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE PYLONS CONNECTORS								Service	ATA:54
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 54 50 01 220 801						PKG:38
54-51-00-101	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM ATTACHMENT-LUGS								Service	ATA:54
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 54.015	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-54-50-002						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 54 - NACELLES/PYLONS										
54-51-00-102	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, UPPER AND LOWER CAPS								Service	ATA:54
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 54.020	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-54-50-004						PKG:76
54-51-00-103	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM THRUST-STRUT								Service	ATA:54
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 54.025	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-54-50-001						PKG:76
54-51-00-106	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, FUSELAGE JOINT								Service	ATA:54
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 54.040	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-54-50-003						PKG:76
54-51-00-107	DETAILED INSPECTION OF THE ENGINE PYLON SKINS AND DRAG ANGLES								Service	ATA:54
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 54 51 00 220 804						PKG:76
54-52-05-900-801-01	LH PYLON LEADING EDGE								Component	ATA:54
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 54.050	AFL		0	TSN 0					1225	
				PROC. REF: AMM 54 52 05 000 801, AMM 54 52 05 400 801						
54-52-05-900-801-02	RH PYLON LEADING EDGE								Component	ATA:54
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 54.050	AFL		0	TSN 0					1225	
				PROC. REF: AMM 54 52 05 000 801, AMM 54 52 05 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 54 - NACELLES/PYLONS										
54-ZL-00-201$	GENERAL VISUAL INSPECTION OF THE PYLON - LH EXTERNAL								Service	ATA:54
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 54.045	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 54 50 00 210 801						PKG:34
54-ZL-00-202$	GENERAL VISUAL INSPECTION OF THE PYLON - RH EXTERNAL								Service	ATA:54
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 54.045	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 54 50 00 210 801						PKG:34
ATA 55 - STABILIZERS										
55-10-00-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE-ACTUATOR FITTING-LUGS INCLUDING PINS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.005	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-003, NDT MT-55-10-003, NDT UT-55-10-001						PKG:76
55-10-00-102	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT FITTINGS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.010	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-001, NDT MT-55-10-001						PKG:76
55-10-00-103	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTING LUGS AND PINS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.015	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-002, NDT MT-55-10-002						PKG:76
55-10-00-104	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER REAR SPAR JOINT								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.020	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-007						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-10-00-105	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL-STABILIZER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.025	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 10 00 220 807						PKG:76
55-10-00-108	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PCU FITTINGS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.040	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-004, NDT PT-55-10-001						PKG:76
55-10-00-109	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTINGS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: AMM 55 10 00 220 811						PKG:76
55-10-00-110	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER FRONT SPAR JOINT								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-008						PKG:76
55-10-00-201 S	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS AND STRAPS OF THE HORIZONTAL STABILIZER								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.045	AFL		1069						156	
				PROC. REF: AMM 55 10 00 220 802						PKG:38
55-10-00-202 S	DETAILED INSPECTION OF THE CENTER BOX RIBS AND FITTINGS OF THE HORIZONTAL STABILIZER								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.050	AFL		1069						156	
				PROC. REF: AMM 55 10 00 220 804						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-10-00-203[S]	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER HINGE, SUPPORT, AND BACKUP FITTINGS AT RIBS 4, 5, 9 AND 12								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.055	AFL		1069						156	
				PROC. REF: AMM 55 10 00 220 805						PKG:38
55-10-00-204	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE HORIZONTAL STABILIZER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.060	AFL	T:7500 (+50/-50)	0		7500	7550	6275 (+50)		1225	
				PROC. REF: AMM 55 10 00 220 806						PKG:76
55-10-00-205	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL STABILIZER								Service	ATA:55
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 55.065	AFL	T:3750 (+50/-50)	0		3750	3800	2525 (+50)		1225	
				PROC. REF: AMM 55 10 00 220 807						
55-10-00-900-803-01	HORIZONTAL STABILIZER								Component	ATA:55
PN:GS258-0001-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B372	HRS		0	TSN 0					4101.3	
WC#: 55.360	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
55-10-05-900-801-01	BULLET FAIRING ASSY								Component	ATA:55
PN:GS248-0002-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B372	HRS		0	TSN 0					4101.3	
WC#: 55.375	AFL		0	TSN 0					1225	
				PROC. REF: AMM 55 10 05 000 801, AMM 55 10 05 400 801						
55-10-05-900-813-01	LH TIP FAIRING								Component	ATA:55
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 55.365	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
55-10-05-900-813-02	RH TIP FAIRING								Component	ATA:55
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 55.370	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-10-09-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE BASEPLATE								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.070	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-006						PKG:76
55-10-09-102	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE CENTER-LINE JOINT-STRAPS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.075	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-005						PKG:76
55-10-09-103	DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.080	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: AMM 55 10 09 220 803						PKG:76
55-10-09-104	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: AMM 55 10 09 220 801						PKG:76
55-10-09-105	SPECIAL DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER YAW RESTRAINT								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-10-009						PKG:76
55-20-00-101	SPECIAL DETAILED INSPECTION OF THE ELEVATOR, ACTUATOR AND HINGE FITTING								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.085	AFL	T:7500	0		7500 (M)		6275		1225	
				PROC. REF: NDT ET-55-20-001						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-20-00-102	DETAILED INSPECTION OF THE ELEVATOR - COMPOSITE PARTS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.090	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 20 00 220 802						PKG:76
55-20-00-201	SPECIAL DETAILED INSPECTION OF THE UPPER AND LOWER SKINS OF THE ELEVATOR								Service	ATA:55
	MOS		20-Dec-09					26-Oct-2026	169.7	
	HRS		0						4101.3	
WC#: 55.095	AFL	T:1875 (+50/-50)	0		1875	1925	650 (+50)		1225	
				PROC. REF: AMM 55 20 00 280 801						
55-20-00-202	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE ELEVATOR								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.100	AFL	T:7500 (+50/-50)	0		7500	7550	6275 (+50)		1225	
				PROC. REF: AMM 55 20 00 220 801						PKG:76
55-20-05-201[S]	DETAILED INSPECTION OF THE FITTINGS OF THE ELEVATOR								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.105	AFL		1069						156	
				PROC. REF: AMM 55 20 05 220 801						PKG:38
55-30-00-102	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGER PANELS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.115	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 00 210 810						PKG:76
55-30-00-103	SPECIAL DETAILED INSPECTION OF THE SURROUND STRUCTURE OF THE ACCES HOLE ON VERTICAL STABILIZER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.120	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-30-003						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-30-00-104	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER PIVOT AND ACTUATOR FITTINGS FOR THE HORIZONTAL STABILIZER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.125	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-30-002, NDT ET-55-30-006, NDT ET-55-30-007, NDT ET-55-30-008, NDT UT-55-30-001						PKG:76
55-30-00-105	DETAILED INSPECTION OF THE BACKUP STRUCTURE OF THE HORIZONTAL-STABILIZER ACTUATOR ATTACHMENT TO THE VERTICAL STABILIZER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.130	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 00 220 809						PKG:76
55-30-00-106	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR STRAP								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.135	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 00 220 804, AMM 55 30 00 220 810						PKG:76
55-30-00-107	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER RUDDER HINGE FITTINGS AND PINS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.140	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-30-001, NDT PT-55-30-001						PKG:76
55-30-00-111	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TRIM-ACTUATOR PIN								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.160	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT MT-55-30-001						PKG:76
55-30-00-112	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER DRAG ANGLES								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.165	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 00 210 809						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-30-00-113	DETAILED INSPECTION OF THE VERTICAL STABILIZER SIDE-STAYS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.170	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-30-005						PKG:76
55-30-00-114	DETAILED INSPECTION OF THE VERTICAL STABILIZER CLOSING RIB								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.175	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 00 220 807						PKG:76
55-30-00-115	SPECIAL DETAILED INSPECTION OF THE RUDDER WISHBONE								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.180	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-30-004						PKG:76
55-30-00-116	DETAILED INSPECTION OF THE RUDDER WISHBONE								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 00 220 808						PKG:76
55-30-00-117	DETAILED INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGER PANELS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 00 220 806						PKG:76
55-30-00-118	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER DRAG ANGLES								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-30-009						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-30-00-202[S]	DETAILED INSPECTION OF THE STABILIZER DRAG ANGLES - FRONT SPAR DATUM TO REAR SPAR DATUM								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.190	AFL		1069						156	
				PROC. REF: AMM 55 30 00 220 802						PKG:38
55-30-00-203[S]	DETAILED INSPECTION OF THE FRONT SPAR, WEB AND STRAPS OF THE VERTICAL STABILIZER								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.195	AFL		1069						156	
				PROC. REF: AMM 55 30 00 220 805						PKG:38
55-30-00-205[S]	GENERAL VISUAL INSPECTION OF THEVERTICAL-STABILIZER SKIN OUTER-SURFACESCOVERED BY ACCESS PANELS AND RUDDER SEAL								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 55 30 00 210 812						PKG:34
55-30-00-206	GENERAL VISUAL INSPECTION OF THEVERTICAL-STABILIZER SKIN OUTER-SURFACESCOVERED BY THE DORSAL AND BULLET FAIRINGS								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21		19-Mar-26	19-Jun-26	767 d (+92)	19-Mar-2026	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 55 30 00 210 813						PKG:34
55-30-00-405[U]	DETAILED INSPECTION OF THE VERTICAL STABILIZER SKIN - LOCATION: RH; FRONT SPAR DATUM TO STR2 DATUM AND V/STAB FUSELAGE INTERSECTION DATUM TO RIB NO. 1 DATUM - ZONE: 340								Service	ATA:55
	MOS							29-Mar-2050		
	HRS									
	AFL	T:7500	0		7500		6275		1225	
55-30-00-900-803-01	VERTICAL STAB BOX ASSY								Component	ATA:55
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 55.385	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
55-30-01-101	GENERAL VISUAL INSPECTION OF THE CAPS OF THE REAR SPAR OF THE VERTICAL STABILIZER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.200	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 01 210 801						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-30-01-102	DETAILED INSPECTION OF THE VERTICAL STABILIZER MID-SPAR CAP								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.205	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 30 01 220 808						PKG:76
55-30-01-201 S	DETAILED INSPECTION OF THE HORIZONTAL LEGS, FRONT-SPAR JOINT LEGS, AND SHEAR ANGLE OF THE VERTICAL-STABILIZER FRONT SPAR-TO-FUSELAGE INTERFACE-FITTINGS								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.210	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 803						PKG:34
55-30-01-203 S	DETAILED INSPECTION OF THE FITTINGS AND WISHBONE ATTACHMENTS OF THE RUDDER AND REAR SPAR AFT FACE AND RUDDER HINGE OF THE VERTICAL STABILIZER								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.215	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 806						PKG:38
55-30-01-204 S	DETAILED INSPECTION OF THE TIP CANTED RIB AND THE RIB FITTINGS OF THE VERTICAL STABILIZER								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 55.220	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 807						PKG:34
55-30-01-205 S	DETAILED INSPECTION OF THE INTERNAL STRUCTURE AND REAR SPAR FORWARD FACE OF THE VERTICAL STABILIZER AND WISHBONE ATTACHEMENTS TO THE VERTICAL STABILIZER								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 55.225	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 809						PKG:34
55-30-01-206 S	DETAILED INSPECTION OF THE ATTACHMENTS AND FITTINGS OF THE WISHBONE TO THE VERTICAL STABILIZER								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.230	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 810						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-30-01-207 S	DETAILED INSPECTION OF THE LOWER ATTACHMENT PINS OF THE PITCH TRIM ACTUATOR								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.235	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 811						PKG:38
55-30-01-208 S	DETAILED INSPECTION OF THE LOWER ATTACHMENT BOLTS OF THE PITCH TRIM ACTUATOR								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.240	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 812						PKG:34
55-30-01-209 S	DETAILED INSPECTION OF THE RUDDER HINGE PINS								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.245	AFL		1069						156	
				PROC. REF: AMM 55 30 01 220 813						PKG:38
55-30-09-900-801-01	VERTICAL STABILIZER LEADING EDGE								Component	ATA:55
PN:GS248-0003-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:B373	HRS		0	TSN 0					4101.3	
WC#: 55.380	AFL		0	TSN 0					1225	
				PROC. REF: AMM 55 30 09 000 801, AMM 55 30 09 400 801						
55-40-00-101	SPECIAL DETAILED INSPECTION OF THE RUDDER ACTUATOR BRACKET LUGS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.250	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-40-001						PKG:76
55-40-00-102	DETAILED INSPECTION OF THE RUDDER STRUCTURE - COMPOSITE PARTS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.255	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 55 40 00 220 803						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-40-00-103	SPECIAL DETAILED INSPECTION OF THE RUDDER HINGE FITTINGS								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.260	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-55-40-002						PKG:76
55-40-00-201	SPECIAL DETAILED INSPECTION OF THE SKINS OF THE RUDDER, EXTERNAL								Service	ATA:55
	MOS		20-Dec-09					26-Oct-2026	169.7	
	HRS		0						4101.3	
WC#: 55.265	AFL	T:1875 (+50/-50)	0		1875	1925	650 (+50)		1225	
				PROC. REF: AMM 55 40 00 280 801						
55-40-00-203	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE RUDDER								Service	ATA:55
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 55.270	AFL	T:7500 (+50/-50)	0		7500	7550	6275 (+50)		1225	
				PROC. REF: AMM 55 40 00 220 801						PKG:76
55-40-00-205[S]	DETAILED INSPECTION OF THE BACKUP FITTINGS OF THE RUDDER								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.275	AFL		1069						156	
				PROC. REF: AMM 55 40 00 220 805						PKG:38
55-ZL-00-201[S]	GENERAL VISUAL INSPECTION OF THE RAM AIR INTAKE AND DORSAL FAIRING - INTERNAL								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.280	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 30 05 210 801						PKG:38
55-ZL-00-202[S]	GENERAL VISUAL INSPECTION OF THE RAM AIR DORSAL FAIRING AND THE LEADING EDGE OF THE VERTICAL STABILIZER - EXTERNAL								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.285	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 30 00 210 802						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-ZL-00-203 S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL LH								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.290	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 30 00 210 803						PKG:34
55-ZL-00-204 S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL RH								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.295	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 30 00 210 803						PKG:34
55-ZL-00-205 S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - INTERNAL								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.300	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 30 00 210 804						PKG:38
55-ZL-00-206 S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL-STABILIZER BULLET FAIRING - EXTERNAL								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.305	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 05 210 801						PKG:34
55-ZL-00-207 S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL- STABILIZER BULLET FAIRING - INTERNAL								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.310	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 05 210 802						PKG:38
55-ZL-00-208 S	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER LEADING EDGE - INTERNAL								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.315	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 30 09 210 801						PKG:38
55-ZL-00-209 S	GENERAL VISUAL INSPECTION OF THE LEADING EDGE OF THE RUDDER - INTERNAL								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.320	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 40 00 210 802						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
55-ZL-00-210 S	GENERAL VISUAL INSPECTION OF THE RUDDER - EXTERNAL								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.325	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 40 00 210 801						PKG:38
55-ZL-00-211 S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL LH								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.330	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 00 210 803						PKG:38
55-ZL-00-212 S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL RH								Service	ATA:55
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.335	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 00 210 803						PKG:38
55-ZL-00-213	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL LH								Service	ATA:55
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 55.340	AFL	3750 (+50/-50)	0		3750	3800	2525 (+50)		1225	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 00 210 806						
55-ZL-00-214	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL RH								Service	ATA:55
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 55.345	AFL	3750 (+50/-50)	0		3750	3800	2525 (+50)		1225	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 00 210 806						
55-ZL-00-215 S	GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL LH								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.350	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 00 210 808						PKG:34
55-ZL-00-216 S	GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL RH								Service	ATA:55
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 55.355	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 55 10 00 210 808						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 55 - STABILIZERS									
REO 700-55-30-334 REV[U] A	REPAIR - LH AND RH VERTICAL STABILIZER UPPER SKIN CORROSION BLENDED, REPAIR ENGINEERING ORDER								Bulletin ATA:55
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-55-002	MODIFICATION/REWORK - ELEVATOR CONTROL SURFACES - ELIMINATE GAP BETWEEN ELEVATOR AND BULLET FAIRING, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-55-002 REV 01	MODIFICATION/REWORK - ELEVATOR CONTROL SURFACES - ELIMINATE GAP BETWEEN ELEVATOR AND BULLET FAIRING, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-55-004 PART (A)	MODIFICATION - HORIZONTAL STABILIZER - ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION AND ADDITION OF RIVETS ON THE ACCESS PANELS NUTPLATE ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-55-004 PART (B)	MODIFICATION - HORIZONTAL STABILIZER - ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION AND ADDITION OF RIVETS ON THE ACCESS PANELS NUTPLATE ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-55-005	SPECIAL CHECK/REWORK - HORIZONTAL STABILIZER - INSPECT THE L/H AND R/H INBOARD LEADING EDGES AND REPLACE, IF NECESSARY, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-55-006	MODIFICATION - HORIZONTAL STABILIZER - ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	-	08-Mar-13						131.1
	HRS		850.3						3251
	AFL		332						893

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 55 - STABILIZERS									
SB 700-55-007	MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-55-007 PART (A)	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE NUTPLATE RETAINERS								Bulletin ATA:55
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-55-007 PART (B)	ACCOMPLISH, SERVICE BULLETIN VERTICAL STAB BULLET FAIRINGS MODIFICATION								Bulletin ATA:55
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-55-007 PART (C)	ACCOMPLISH, SERVICE BULLETIN DORSAL FAIRING MODIFICATION								Bulletin ATA:55
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-55-007 REV 01	MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:55
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	AFL		817						408
SB 700-55-007 REV 01 PART (A)	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE NUTPLATE RETAINERS								Bulletin ATA:55
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	AFL		817						408
SB 700-55-007 REV 01 PART (B)	ACCOMPLISH, SERVICE BULLETIN VERTICAL STAB BULLET FAIRINGS MODIFICATION								Bulletin ATA:55
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	AFL		817						408

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 55 - STABILIZERS										
SB 700-55-007 REV 01 PART (C)	ACCOMPLISH, SERVICE BULLETIN DORSAL FAIRING MODIFICATION								Bulletin	ATA:55
	MOS/MSC	-	11-Jul-17						79	
	HRS		2473.8						1627.5	
	AFL		817						408	
SB 700-55-007 REV 02	MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN								Bulletin	ATA:55
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-55-007 REV 02 PART A	ACCOMPLISH MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN REPLACEMENT OF THE NUTPLATE RETAINERS								Bulletin	ATA:55
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-55-007 REV 02 PART B	ACCOMPLISH MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN VERTICAL STAB BULLET FAIRINGS MODIFICATION								Bulletin	ATA:55
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-55-007 REV 02 PART C	ACCOMPLISH MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN DORSAL FAIRING MODIFICATION								Bulletin	ATA:55
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
ATA 56 - WINDOWS										
56-10-01-900-801-01	LH WINDSHIELD ASSEMBLY								Component	ATA:56
PN:GC331-0001-11	MOS/MSC	O/C	30-Dec-13	TSN 0					121.4	
SN:2627	HRS		1176.4	TSN 0					2924.9	
WC#: 56.005	AFL		464	TSN 0					761	
	PROC. REF: CMM 56-10-01, AMM 56 10 01 000 801, AMM 56 10 01 400 801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
56-10-01-900-801-02	RH WINDSHIELD ASSEMBLY								Component ATA:56
PN:GC331-0001-14	MOS/MSC	O/C	19-Mar-21	TSN 4					34.7
SN:5250	HRS		3474.7	TSN 0					626.6
WC#: 56.005	AFL		1069	TSN 0					156
				PROC. REF: CMM 56-10-01, AMM 56 10 01 000 801, AMM 56 10 01 400 801					
56-10-01-900-802-01	SIDE POST (LH) SPLICE STRAP								Component ATA:56
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 56.010	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
56-10-01-900-802-02	SIDE POST (RH) SPLICE STRAP								Component ATA:56
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 56.010	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
56-10-05-900-801-01	LH SIDE WINDOW								Component ATA:56
PN:GC331-0003-5	MOS/MSC	O/C	02-Mar-17	TSN 0					83.3
SN:3547	HRS		2326.7	TSN 0					1774.6
WC#: 56.015	AFL		784	TSN 0					441
				PROC. REF: CMM 56-10-02, AMM 56 10 05 000 801, AMM 56 10 05 400 801					
56-10-05-900-801-02	RH SIDE WINDOW								Component ATA:56
PN:GC331-0003-8	MOS/MSC	O/C	21-Jan-22	TSN 0					24.7
SN:5828	HRS		3689.6	TSN 0					411.7
WC#: 56.015	AFL		1117	TSN 0					108
				PROC. REF: CMM 56-10-02, AMM 56 10 05 000 801, AMM 56 10 05 400 801					
56-20-01-900-801-01	LEFT NO.1 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14098	HRS		0	TSN 0					4101.3
WC#: 56.020	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-02	RIGHT NO. 1 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14197	HRS		0	TSN 0					4101.3
WC#: 56.020	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
56-20-01-900-801-03	LEFT NO.2 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14099	HRS		0	TSN 0					4101.3
WC#: 56.025	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-04	RIGHT NO. 2 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14198	HRS		0	TSN 0					4101.3
WC#: 56.025	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-05	LEFT NO.3 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14102	HRS		0	TSN 0					4101.3
WC#: 56.030	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-06	RIGHT NO. 3 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14201	HRS		0	TSN 0					4101.3
WC#: 56.030	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-07	LEFT NO.4 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14105	HRS		0	TSN 0					4101.3
WC#: 56.035	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-08	RIGHT NO. 4 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14205	HRS		0	TSN 0					4101.3
WC#: 56.035	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-09	LEFT NO.5 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:141111	HRS		0	TSN 0					4101.3
WC#: 56.040	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
56-20-01-900-801-10	RIGHT NO. 5 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14206	HRS		0	TSN 0					4101.3
WC#: 56.040	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-11	LEFT NO.6 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14113	HRS		0	TSN 0					4101.3
WC#: 56.050	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-12	RIGHT NO. 6 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14207	HRS		0	TSN 0					4101.3
WC#: 56.050	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-13	LEFT NO.7 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	29-Jun-11	TSN 0					151.4
SN:17099	HRS		47.4	TSN 0					4053.9
WC#: 56.055	AFL		17	TSN 0					1208
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-14	RIGHT NO. 7 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:14208	HRS		0	TSN 0					4101.3
WC#: 56.055	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-15	LEFT NO.8 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13285	HRS		0	TSN 0					4101.3
WC#: 56.060	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-16	RIGHT NO. 8 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13586	HRS		0	TSN 0					4101.3
WC#: 56.060	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
56-20-01-900-801-17	LEFT NO.9 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13286	HRS		0	TSN 0					4101.3
WC#: 56.065	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-18	RIGHT NO. 9 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13587	HRS		0	TSN 0					4101.3
WC#: 56.065	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-19	LEFT NO.10 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13287	HRS		0	TSN 0					4101.3
WC#: 56.070	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-20	RIGHT NO. 10 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13-12-08	MOS/MSC	O/C	17-May-11	TSN 0					152.8
SN:16823	HRS		28.5	TSN 0					4072.8
WC#: 56.070	AFL		9	TSN 0					1216
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-21	LEFT NO.11 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13291	HRS		0	TSN 0					4101.3
WC#: 56.075	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-22	RIGHT NO. 11 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13588	HRS		0	TSN 0					4101.3
WC#: 56.075	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-23	LEFT NO.12 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13292	HRS		0	TSN 0					4101.3
WC#: 56.080	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
56-20-01-900-801-24	RIGHT NO. 12 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13589	HRS		0	TSN 0					4101.3
WC#: 56.080	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-25	LEFT NO.13 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13293	HRS		0	TSN 0					4101.3
WC#: 56.085	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-26	RIGHT NO. 13 ASSY CABIN WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13592	HRS		0	TSN 0					4101.3
WC#: 56.085	AFL		0	TSN 0					1225
				PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801					
56-20-01-900-801-27	#14 RH FWD PASS WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13295	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
56-20-01-900-801-28	#15 RH FWD PASS WINDOW								Component ATA:56
PN:GC333-0001-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:13296	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
560001-701 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4724	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-702 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4725	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
560001-703 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4726	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-704 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4727	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-705 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4728	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-706 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	09-Jul-15	TSN 49, TSR 0					103.1
SN:4729	HRS		1705.4	TSN 1658, TSR 0					2395.9
	AFL		617	TSN 600, TSR 0					608
560001-707 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4730	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-708 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4731	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-709 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4732	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-710 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4733	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
560001-711 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4734	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-712 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4735	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-713 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4736	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-714 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4737	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-715 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4738	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-716 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4739	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-717 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4740	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-718 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4741	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 56 - WINDOWS									
560001-719 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3TA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4742	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-720 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3TA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4743	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-721 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3TA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4744	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-722 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3TA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4745	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-723 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B3TC-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4746	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-724 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B4BA-BA-A03-BC-E	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4747	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-725 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B6NA-BA-A03-BC-A	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4748	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208
560001-726 U	WINDOW SHADE ASSEMBLY								Component ATA:56
PN:B6NA-BA-A03-BC-A	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4
SN:4749	HRS		47.4	TSN 0					4053.9
	AFL		17	TSN 0					1208

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 56 - WINDOWS										
560001-727 U	WINDOW SHADE ASSEMBLY								Component	ATA:56
PN:B6NA-BA-A03-BC-A	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:4750	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
560001-728 U	WINDOW SHADE ASSEMBLY								Component	ATA:56
PN:B6NA-BA-A03-BC-A	MOS/MSC	O/C	30-Jun-11	TSN 0					151.4	
SN:4751	HRS		47.4	TSN 0					4053.9	
	AFL		17	TSN 0					1208	
ASB A700-53-026 PART (B)	SPECIAL CHECK/REWORK - WINDOWS - EXAMINE INBOARD SKIN PERIPHERY AROUND CABIN WINDOWS FOR CORROSION, ALERT SERVICE BULLETIN								Bulletin	ATA:56
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-56-001	MODIFICATION - PASSENGER COMPARTMENT - OPTIONAL CABIN WINDOW(S), SERVICE BULLETIN								Bulletin	ATA:56
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-56-006	MODIFICATION - ELECTRIC WINDOW SHADE ASSEMBLY - REMOVAL OF SHEAR SHADE FROM WINDOW, SERVICE BULLETIN								Bulletin	ATA:56
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-56-007	SPECIAL CHECK/REWORK - FLIGHT COMPARTMENT - INSPECT THE WINDSHIELD/SIDE WINDOW AND IF NECESSARY REPAIR SEAL, SERVICE BULLETIN								Bulletin	ATA:56
	MOS/MSC	-	01-Apr-13						130.3	
	HRS		902.7						3198.6	
	AFL		347						878	
ATA 57 - WINGS										
57-00-00-900-801-01	LEFT HAND WING ASSEMBLY								Component	ATA:57
PN:GM118-1001-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0375	HRS		0	TSN 0					4101.3	
WC#: 57.695	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-00-00-900-801-02	RIGHT HAND WING ASSEMBLY								Component	ATA:57
PN:GM118-1001-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0375	HRS		0	TSN 0					4101.3	
WC#: 57.695	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-10-00-101	SPECIAL DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL ACCESS-HOLES								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.005	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-10-003						PKG:76
57-10-00-102	DETAILED INSPECTION OF THE AC TRANSFER-PUMP LOWER PANEL								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.010	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 811						PKG:76
57-10-00-103	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE-STAY FITTING								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.015	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-10-008						PKG:76
57-10-00-104	SPECIAL DETAILED INSPECTION OF THE CENTER WING LOWER PANEL SPLICE, BL47.61								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.020	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-10-004, NDT UT-57-10-001						PKG:76
57-10-00-106	DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.025	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 813						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-10-00-107	DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER WING								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 57.030	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: AMM 57 10 00 220 817						PKG:76
57-10-00-108	DETAILED INSPECTION OF THE CENTER-WING UPPER PANEL								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 57.035	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: AMM 57 10 00 220 814						PKG:76
57-10-00-109	DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.040	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 815						PKG:76
57-10-00-110	SPECIAL DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 TRUSS SUPPORT PLATE								Service	ATA:57
	MOS		20-Dec-09					28-Oct-2049	169.7	
	HRS		0						4101.3	
WC#: 57.045	AFL	T:7400	0		7400		6175		1225	
				PROC. REF: NDT ET-57-10-005, NDT MT-57-10-002						
57-10-00-111	SPECIAL DETAILED INSPECTION OF THE LOWER-CAP OF THE CENTER-WING FRONT SPAR								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 57.050	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-57-10-012						PKG:76
57-10-00-112	DETAILED INSPECTION OF THE LOWER CAP OF THE CENTER-WING REAR SPAR								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 818						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-10-00-113	DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 CHORD FLANGES								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.060	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 816						PKG:76
57-10-00-114	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 810						PKG:76
57-10-00-115	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL SPLICE, BL47.61								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 812						PKG:76
57-10-00-116	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE LOWER CAP								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-10-006, NDT UT-57-10-003						PKG:76
57-10-00-117	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER-WING								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-57-10-014						PKG:76
57-10-00-118	SPECIAL DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75								Service	ATA:57
	MOS		20-Dec-09					11-Apr-2034	169.7	
	HRS		0						4101.3	
	AFL	T:3666	0		3666		2441		1225	
				PROC. REF: NDT ET-57-10-002, NDT MT-57-10-001						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-10-00-119	SPECIAL DETAILED INSPECTION OF THE REAR−SPAR LOWER−CAP, BL44.00 TO BL47.60								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT RT-57-10-003						PKG:76
57-10-00-121	SPECIAL DETAILED INSPECTION OF THE REAR-SPAR LOWER-CAP AND WING SKIN BETWEEN LBL44.00 AND RBL44.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT RT-57-10-005						PKG:76
57-10-00-122	DETAILED INSPECTION OF THE KEEL BEAM RIB TRUSS-BEAM PINS, BL4.75								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 820						PKG:76
57-10-00-123	SPECIAL DETAILED INSPECTION OF THE WING FRONT-SPAR LOWER-CAP AND WEB AT KEEL BEAM ATTACHMENTS, BL4.75								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT UT-57-10-002						PKG:76
57-10-00-124	DETAILED INSPECTION OF THE FRONT SPAR LOWER CAP OF THE CENTER WING FROM LBL47.60 TO RBL47.60								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 10 00 220 819						PKG:76
57-10-00-125	SPECIAL DETAILED INSPECTION OF THE CENTER WING FRONT-SPAR LOWER-CAP AND WEB AT FS574.50 FROM LBL47.60 TO RBL47.60								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT RT-57-10-004						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-10-00-201[S]	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.065	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 801						PKG:38
57-10-00-202[S]	DETAILED INSPECTION OF THE CENTER WING FRONT SPAR AFT FACE, AND CENTER WING UPPER PANEL, LOWER PANEL AND RIBS - INTERNAL LBL47.6 TO RBL47.6								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 57.070	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 802						PKG:34
57-10-00-203[S]	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.075	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 803						PKG:38
57-10-00-204[S]	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.080	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 804						PKG:38
57-10-00-205[S]	DETAILED INSPECTION OF THE UPPER FACE OF THE CENTER WING UPPER PANEL								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.085	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 805						PKG:38
57-10-00-206[S]	DETAILED INSPECTION OF THE LOWER FACE OF THE CENTER WING LOWER PANEL								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 57.090	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 806						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-10-00-208[S]	DETAILED INSPECTION OF THE OUTER FACE OF THE CENTER WING ROOT RIB								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 57.095	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 808						PKG:34
57-10-00-209[S]	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE STAY FITTING								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 57.100	AFL		1069						156	
				PROC. REF: AMM 57 10 00 220 809						PKG:34
57-20-00-101	DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WCS537.40								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.105	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 826						PKG:76
57-20-00-102	DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - EXTERNAL								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.110	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 827						PKG:76
57-20-00-103	DETAILED INSPECTION OF THE WING LOWER-SKIN FUEL-SYSTEM-HOLES								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.115	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 813						PKG:76
57-20-00-104	SPECIAL DETAILED INSPECTION OF THE LOWER WING-PLANK STRINGER-RUNOUT								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 57.120	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-57-20-014						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-20-00-105	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) LOWER STRAP, WS85.50								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.125	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-013, NDT RT-57-20-005						PKG:76
57-20-00-106	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) FITTING JOINT								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.130	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-008, NDT RT-57-20-002						PKG:76
57-20-00-108	SPECIAL DETAIL INSPECTION OF THE REAR SPAR SPLICE, WS178.00								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 57.140	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-57-20-002						PKG:76
57-20-00-109	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE, WS287.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.145	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-009, NDT RT-57-20-007						PKG:76
57-20-00-110	SPECIAL DETAILED INSPECTION OF THE LOWER SKIN SPLICE AT THE FRONT SPAR, CANTED RIB NO. 2 TO CWS390.90								Service	ATA:57
	MOS		20-Dec-09					13-Nov-2034	169.7	
	HRS		0						4101.3	
WC#: 57.150	AFL	T:3808	0		3808		2583		1225	
				PROC. REF: NDT ET-57-20-001						
57-20-00-111	DETAILED INSPECTION OF THE LOWER-SKIN SPANWISE-SPLICE								Service	ATA:57
	MOS		20-Dec-09					16-Dec-2044	169.7	
	HRS		0						4101.3	
WC#: 57.155	AFL	T:6232	0		6232		5007		1225	
				PROC. REF: AMM 57 20 00 220 824						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-20-00-112	DETAILED INSPECTION OF THE OUTER WING FRONT AND REAR SPAR CAPS AND SKIN								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.160	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 829						PKG:76
57-20-00-113	GENERAL VISUAL INSPECTION OF THE WING UPPER-SKIN								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.165	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 210 814						PKG:76
57-20-00-114	DETAILED INSPECTION OF THE WING RIBS AT WS66.00, WS178.00, WS287.00 AND CWS464.20								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.170	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 816						PKG:76
57-20-00-115	DETAILED INSPECTION OF THE WING RIB AT WS85.50								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.175	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 817						PKG:76
57-20-00-116	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS66.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.180	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-003						PKG:76
57-20-00-119	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION-FITTING								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.195	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-007, NDT RT-57-20-001						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-20-00-120	SPECIAL DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WC537.40								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-012						PKG:76
57-20-00-121	DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - INTERNAL								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 830						PKG:76
57-20-00-122	DETAILED INSPECTION OF THE LOWER SKIN AT THE SPANWISE-SPLICE								Service	ATA:57
	MOS		20-Dec-09					03-Feb-2039	169.7	
	HRS		0						4101.3	
	AFL	T:4823	0		4823		3598		1225	
				PROC. REF: AMM 57 20 00 220 815						
57-20-00-123	DETAILED INSPECTION OF THE LOWER SKIN AT THE FRONT AND REAR SPAR JOINTS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 831						PKG:76
57-20-00-125	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS178.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-004						PKG:76
57-20-00-126	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS287.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-005						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-20-00-127	SPECIAL DETAILED INSPECTION OF THE WING RIB AT CWS464.20								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-006						PKG:76
57-20-00-128	DETAILED INSPECTION OF THE WING RIB AT WS85.50								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 20 00 220 832						PKG:76
57-20-00-129	SPECIAL DETAILED INSPECTION OF THE LOWER SPLICE OF THE FRONT SPAR, WS275.60 AND WS549.55								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-20-011, NDT UT-57-20-001						PKG:76
57-20-00-201[S]	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE WING								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.200	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 801						PKG:38
57-20-00-202[S]	DETAILED INSPECTION OF THE AFT FACE OF THE FRONT SPAR OF THE WING - BL47.61 TO CWS537.40								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.205	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 802						PKG:38
57-20-00-203[S]	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE WING - BL47.61 TO CWS537.40								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.210	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 803						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-20-00-204[S]	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR AND AUXILIARY SPAR OF THE WING								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.215	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 804						PKG:34
57-20-00-205[S]	DETAILED INSPECTION OF THE LOWER WING SURFACE COVERED BY THE FUEL ACCESS PANELS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 57.220	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 805						PKG:34
57-20-00-206[S]	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - BL47.61 TO CWS537.40								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 57.225	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 806						PKG:34
57-20-00-207[S]	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - CWS537.40 TO WS536.50								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
WC#: 57.230	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 807						PKG:34
57-20-00-210[S]	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION FITTING AND BAY								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.245	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 810						PKG:38
57-20-00-212[S]	DETAILED INSPECTION OF THE AILERON SUPPORT FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.250	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 812						PKG:38
57-20-00-213[S]	DETAILED INSPECTION OF THE INTERNAL WING STRUCTURE BETWEEN THE REAR SPAR AND AUXILIARY SPAR, WS85.00 TO WS178.00								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21	Adj 3					34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 57 20 00 220 821						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-20-00-415[U]	DETAILED INSPECTION OF THE OUTER WING, LOWER SKIN AT THE FRONT AND REAR SPAR JOINTS - LOCATION: LH; WS154.75 TO WS265.50, FRONT SPAR - ZONE: 500								Service	ATA:57
	MOS							25-Aug-2039		
	HRS									
	AFL	T:4956	0		4956		3731		1225	
57-20-00-420[U]	DETAILED INSPECTION OF THE WING PLANK, LOWER, SKIN- LOCATION: RH, WS265.50 TO CWS488.60, FRONT SPAR DATUM TO STR11								Service	ATA:57
	MOS							11-Mar-2047		
	HRS									
	AFL	T:6768			6768		5543			
57-20-00-422[U]	DETAILED INSPECTION OF THE FRONT-SPAR-LOWER-CAP AND WEB - LOCATION: LH; WS154.75 TO WS265.50 - ZONE: 500								Service	ATA:57
	MOS							25-Aug-2039		
	HRS									
	AFL	T:4956	0		4956		3731		1225	
57-20-00-424[U]	DETAILED INSPECTION OF THE REAR−SPAR−LOWER−CAP AND WEB LOCATION: RH, WS287.00 TO CANTED RIB NO. 1								Service	ATA:57
	MOS							11-Mar-2047		
	HRS									
	AFL	T:6768			6768		5543			
57-20-00-448[U]	DETAILED INSPECTION OF THE WING FRONT SPAR LOCATION: RH, WS265.50 TOCWS488.60								Service	ATA:57
	MOS							11-Mar-2047		
	HRS									
	AFL	T:6768			6768		5543			
57-30-00-101	SPECIAL DETAILED INSPECTION OF THE WINGLET INSTALLATION								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.255	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-30-001						PKG:76
57-30-00-102	DETAILED INSPECTION OF THE WINGLET - EXTERNAL SURFACES								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 30 00 220 804						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-30-00-202 S	DETAILED INSPECTION OF THE WINGLET ATTACHMENT FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.265	AFL		1069						156	
				PROC. REF: AMM 57 30 00 220 802						PKG:38
57-30-00-900-801-01	LEFT WINGLET								Component	ATA:57
PN:GM178-1000-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0375	HRS		0	TSN 0					4101.3	
WC#: 57.700	AFL		0	TSN 0					1225	
				PROC. REF: AMM 57 30 00 000 801, AMM 57 30 00 400 801						
57-30-00-900-801-02	RIGHT WINGLET								Component	ATA:57
PN:GM178-1000-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0375	HRS		0	TSN 0					4101.3	
WC#: 57.700	AFL		0	TSN 0					1225	
				PROC. REF: AMM 57 30 00 000 801, AMM 57 30 00 400 801						
57-30-01-900-801-01	LH WING TIP LENS								Component	ATA:57
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 57.705	AFL		0	TSN 0					1225	
				PROC. REF: CMM 33-42-22, AMM 57 30 01 000 801, AMM 57 30 01 400 801						
57-30-01-900-801-02	RH WING TIP LENS								Component	ATA:57
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 57.705	AFL		0	TSN 0					1225	
				PROC. REF: CMM 33-42-22, AMM 57 30 01 000 801, AMM 57 30 01 400 801						
57-42-00-101	SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TRACKS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.270	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT MT-57-42-002						PKG:76
57-42-00-103	SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TRACKS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.275	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT MT-57-42-003						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-42-00-104	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TRACKS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.280	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT MT-57-42-004						PKG:76
57-42-00-105	SPECIAL DETAILED INSPECTION OF THE NO. 4 SLAT TRACKS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.285	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT MT-57-42-005						PKG:76
57-42-00-107	SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TO TRACK ATTACHMENTS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.290	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-42-007						PKG:76
57-42-00-108	SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TO TRACK ATTACHMENTS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.295	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-42-006						PKG:76
57-42-00-109	DETAILED INSPECTION OF THE SLAT TRACK ATTACHMENT LUGS, SLAT NO. 3 AND NO. 4								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.300	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 42 02 220 809						PKG:76
57-42-00-111	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TO TRACK ATTACHMENTS								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-57-42-008						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-42-00-201[S]	DETAILED INSPECTION OF THE NO. 1 SLAT SUPPORT FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.310	AFL		1069						156	
				PROC. REF: AMM 57 42 00 220 801						PKG:38
57-42-00-202[S]	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT SUPPORT FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.315	AFL		1069						156	
				PROC. REF: AMM 57 42 00 220 802						PKG:38
57-42-02-101	DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 1 AND NO. 2								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.320	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 42 02 220 810						PKG:76
57-42-02-103	DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 3 AND NO. 4								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.330	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 42 02 220 811						PKG:76
57-42-02-104	SPECIAL DETAILED INSPECTION OF THE NO. 4 SLAT BODIES INTERCONNECT PIN								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.335	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-42-004, NDT MT-57-42-006						PKG:76
57-42-02-105	SPECIAL DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 ROLLER PINS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.340	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT MT-57-42-001, NDT PT-57-42-001						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-42-02-106	DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 SUPPORT RIBS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 42 02 220 812						PKG:76
57-42-02-201 S	DETAILED INSPECTION OF THE NO. 1 SLAT TRACK RAILS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.345	AFL		1069						156	
				PROC. REF: AMM 57 42 02 220 801						PKG:34
57-42-02-202 S	DETAILED INSPECTION OF THE NO. 1 SLAT RAIL SUPPORT FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.350	AFL		1069						156	
				PROC. REF: AMM 57 42 02 220 802						PKG:38
57-42-02-203 S	DETAILED INSPECTION OF THE NO. 1 SLAT BODY								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.355	AFL		1069						156	
				PROC. REF: AMM 57 42 02 220 803						PKG:38
57-42-02-204 S	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT TRACK RAILS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.360	AFL		1069						156	
				PROC. REF: AMM 57 42 02 220 804						PKG:34
57-42-02-205 S	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT RAIL SUPPORT FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.365	AFL		1069						156	
				PROC. REF: AMM 57 42 02 220 805						PKG:38
57-42-02-206 S	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT BODIES								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.370	AFL		1069						156	
				PROC. REF: AMM 57 42 02 220 806						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-51-00-101	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS47.80								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.375	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-003, NDT MT-57-51-001						PKG:76
57-51-00-102	SPECIAL DETAILED INSPECTION OF THE FLAP SUPPORT STRUCTURE, WS178.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.380	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-004, NDT MT-57-51-002						PKG:76
57-51-00-103	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS287.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.385	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-001, NDT MT-57-51-003						PKG:76
57-51-00-104	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS404.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.390	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-002, NDT MT-57-51-004						PKG:76
57-51-00-105	SPECIAL DETAILED INSPECTION OF THE FLAP CARRIAGE, WS47.80, WS178.00, WS287.00 AND WS404.00.								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.395	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-005						PKG:76
57-51-00-106	SPECIAL DETAILED INSPECTION OF THE FLAP SIDE FITTING, WS47.80								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.400	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-006, NDT MT-57-51-006, NDT PT-57-51-006						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-51-00-107	SPECIAL DETAILED INSPECTION OF THE FLAP RAIL FORWARD FITTING, WS287.00 AND WS404.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.405	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-007, NDT MT-57-51-007						PKG:76
57-51-00-108	SPECIAL DETAILED INSPECTION OF THE FLAP BODY FITTING (METALLIC), WS178.00, WS287.00 AND WS404.00								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.410	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-51-008						PKG:76
57-51-00-109	SPECIAL DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAP (METALLIC) END RIBS								Service	ATA:57
	MOS							29-Mar-2050	169.7	
	HRS								4101.3	
WC#: 57.415	AFL	T:7500	EFF		7500 *		6275		1225	
				PROC. REF: NDT ET-57-51-009						PKG:76
57-51-00-110	DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAPS (COMPOSITE)								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.420	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 51 00 220 802						PKG:76
57-51-00-201[S]	SPECIAL DETAILED INSPECTION OF THE INBOARD-FLAP INTERNALRIBS AND INBOARD FITTINGS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 57 51 00 290 801						PKG:34
57-51-00-202[S]	SPECIAL DETAILED INSPECTION OF THE MID-FLAP INTERNAL RIBS								Service	ATA:57
	MOS	T:120 (+3m/-3m)	20-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
	APH		0						1947	
	APS		0						1738	
										PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-51-00-203 S	SPECIAL DETAILED INSPECTION OF THE OUTBOARD-FLAP INTERNAL RIBS								Service	ATA:57
	MOS	T:120 (+3m/-3m)	20-Dec-09						169.7	
	HRS		0						4101.3	
	AFL		0						1225	
	APH		0						1947	
	APS		0						1738	
										PKG:38
57-51-05-201 S	DETAILED INSPECTION OF THE FLAP TRACK RAILS - WS47.80, WS178.00, WS287.00 AND WS404.00								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.425	AFL		1069						156	
				PROC. REF: AMM 57 51 05 220 801						PKG:34
57-51-05-202 S	DETAILED INSPECTION OF THE FLAP SUPPORT FITTINGS - WS47.80, WS178.00, WS287.00 AND WS404.00								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.430	AFL		1069						156	
				PROC. REF: AMM 57 51 05 220 817						PKG:38
57-51-05-203 S	DETAILED INSPECTION OF THE INNER-FLAP INNER-FITTINGS AND END RIBS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.435	AFL		1069						156	
				PROC. REF: AMM 57 51 05 220 809						PKG:34
57-51-05-204 S	DETAILED INSPECTION OF THE INNER-FLAP OUTER-FITTINGS AND THE MIDDLE-FLAP INNER-FITTINGS AND END RIBS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.440	AFL		1069						156	
				PROC. REF: AMM 57 51 05 220 810						PKG:34
57-51-05-205 S	DETAILED INSPECTION OF THE MIDDLE-FLAP OUTER-FITTINGS AND THE OUTER-FLAP INNER-FITTINGS AND END RIBS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.445	AFL		1069						156	
				PROC. REF: AMM 57 51 05 220 811						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-51-05-206$	DETAILED INSPECTION OF THE OUTER-FLAP OUTER-FITTINGS AND END RIBS								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.450	AFL		1069						156	
				PROC. REF: AMM 57 51 05 220 812						PKG:34
57-51-05-207	DETAILED INSPECTION OF THE INNER FLAPS UPPER AND LOWER SKIN								Service	ATA:57
	MOS		20-Dec-09					26-Oct-2026	169.7	
	HRS		0						4101.3	
WC#: 57.455	AFL	T:1875 (+50/-50)	0		1875	1925	650 (+50)		1225	
				PROC. REF: AMM 57 51 05 220 813						
57-51-05-208	SPECIAL DETAILED INSPECTION OF THE INNER FLAPS TRAILING EDGE UPPER AND LOWER SKIN AND CORE								Service	ATA:57
	MOS		27-Jul-16					03-Mar-2026	90.5	
	HRS		2078.9						2022.4	
WC#: 57.460	AFL	950 (+50/-50)	719	Adj 50	1719	1769	494 (+50)		506	
				PROC. REF: AMM 57 51 05 280 801						PKG:60
57-51-05-209	DETAILED INSPECTION OF THE MIDDLE/OUTBOARD UPPER AND LOWER FLAPS SKIN								Service	ATA:57
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 57.465	AFL	T:3750 (+50/-50)	0		3750	3800	2525 (+50)		1225	
				PROC. REF: AMM 57 51 05 220 815						
57-51-05-210	SPECIAL DETAILED INSPECTION OF THE MIDDLE/OUTER FLAP PANEL TRAILING EDGE UPPER AND LOWER SKIN AND CORE								Service	ATA:57
	MOS		20-Dec-09					26-Oct-2026	169.7	
	HRS		0						4101.3	
WC#: 57.470	AFL	T:1875 (+50/-50)	0		1875	1925	650 (+50)		1225	
				PROC. REF: AMM 57 51 05 280 802						
57-60-00-101	SPECIAL DETAILED INSPECTION OF THE AILERON CENTER-HINGE ASSEMBLY								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.475	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-60-001, NDT PT-57-60-001						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-60-00-103	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE AND OUTER−HINGE PINS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.480	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT PT-57-60-002						PKG:76
57-60-00-104	DETAILED INSPECTION OF THE AILERONS								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.485	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 60 00 220 805						PKG:76
57-60-00-105	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE AND OUTER-HINGE FITTING ASSEMBLIES								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: NDT ET-57-60-002						PKG:76
57-60-00-201[S]	DETAILED INSPECTION OF THE AILERON HINGE FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.490	AFL		1069						156	
				PROC. REF: AMM 57 60 00 220 804						PKG:38
57-60-00-202	SPECIAL DETAILED INSPECTION OF THE AILERON SKIN								Service	ATA:57
	MOS		20-Dec-09					26-Oct-2026	169.7	
	HRS		0						4101.3	
WC#: 57.495	AFL	T:1875 (+50/-50)	0		1875	1925	650 (+50)		1225	
				PROC. REF: AMM 57 60 00 280 801						
57-60-00-203	DETAILED INSPECTION OF THE AILERON SPAR								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.500	AFL	T:7500 (+50/-50)	0		7500	7550	6275 (+50)		1225	
				PROC. REF: AMM 57 60 00 220 803						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-60-00-900-802-01	LEFT AILERON								Component	ATA:57
PN:GM158-1000-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0383	HRS		0	TSN 0					4101.3	
WC#: 57.725	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-60-00-900-802-02	RIGHT AILERON								Component	ATA:57
PN:GM158-1000-6	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0382	HRS		0	TSN 0					4101.3	
WC#: 57.725	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-70-00-101	SPECIAL DETAILED INSPECTION OF THE SPOILERS (NO. 1 TO NO. 6) HINGE FITTINGS								Service	ATA:57
	MOS		20-Dec-09					11-Oct-2031	169.7	
	HRS		0						4101.3	
WC#: 57.505	AFL	T:3066	0		3066		1841		1225	
				PROC. REF: NDT ET-57-70-001, NDT PT-57-70-001						
57-70-00-102	DETAILED INSPECTION OF THE SPOILERS NO. 1 TO NO. 6								Service	ATA:57
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 57.510	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 57 70 00 220 801						PKG:76
57-71-00-201[S]	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.515	AFL		1069						156	
				PROC. REF: AMM 57 71 00 220 803						PKG:38
57-71-00-202[S]	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS - BL47.61AND WS178.00								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.520	AFL		1069						156	
				PROC. REF: AMM 57 71 00 220 801						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-71-00-203	SPECIAL DETAILED INSPECTION OF THE GROUND SPOILER SKIN								Service	ATA:57
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 57.525	AFL	T:3750 (+50/-50)	0		3750	3800	2525 (+50)		1225	
				PROC. REF: AMM 57 71 00 280 801						
57-71-00-900-801-01	GROUND OUTBOARD LH SPOILER								Component	ATA:57
PN:GM168-1200-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0383	HRS		0	TSN 0					4101.3	
WC#: 57.730	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-71-00-900-801-02	GROUND INBOARD LH SPOILER								Component	ATA:57
PN:GM168-1100-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0385	HRS		0	TSN 0					4101.3	
WC#: 57.730	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-71-00-900-801-03	GROUND INBOARD RH SPOILER								Component	ATA:57
PN:GM168-1100-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0385	HRS		0	TSN 0					4101.3	
WC#: 57.735	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-71-00-900-801-04	GROUND OUTBOARD RH SPOILER								Component	ATA:57
PN:GM168-1200-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0385	HRS		0	TSN 0					4101.3	
WC#: 57.735	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-72-00-201[S]	DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SUPPORT-FITTINGS								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.530	AFL		1069						156	
				PROC. REF: AMM 57 72 00 220 801						PKG:38
57-72-00-202[S]	DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER HINGE FITTINGS - WS178.00 AND WS404.00								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.535	AFL		1069						156	
				PROC. REF: AMM 57 72 00 220 803						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-72-00-203	SPECIAL DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SKIN - WS178.00 AND WS404.00								Service	ATA:57
	MOS		20-Dec-09					17-Aug-2034	169.7	
	HRS		0						4101.3	
WC#: 57.540	AFL	T:3750 (+50/-50)	0		3750	3800	2525 (+50)		1225	
				PROC. REF: AMM 57 72 00 280 801						
57-72-00-900-801-01	OUTBOARD LEFT SPOILERON								Component	ATA:57
PN:GM168-1800-31	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0379	HRS		0	TSN 0					4101.3	
WC#: 57.740	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-72-00-900-801-02	INBOARD LEFT SPOILERON								Component	ATA:57
PN:GM168-1700-31	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0384	HRS		0	TSN 0					4101.3	
WC#: 57.745	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-72-00-900-801-03	INBOARD RIGHT SPOILERON								Component	ATA:57
PN:GM168-1700-32	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0377	HRS		0	TSN 0					4101.3	
WC#: 57.745	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-72-00-900-801-04	OUTBOARD RIGHT SPOILERON								Component	ATA:57
PN:GM168-1800-32	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0384	HRS		0	TSN 0					4101.3	
WC#: 57.740	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
57-ZL-00-201 S	GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL LH								Service	ATA:57
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 57.545	AFL		1171						54	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 40 00 210 802						PKG:32
57-ZL-00-202 S	GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL RH								Service	ATA:57
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 57.550	AFL		1171						54	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 40 00 210 802						PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-ZL-00-203 S	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL LH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.555	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00, AMM 57 40 00 210 801, AMM 57 40 00 210 803						PKG:34
57-ZL-00-204 S	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL RH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.560	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00, AMM 57 40 00 210 801, AMM 57 40 00 210 803						PKG:34
57-ZL-00-205 S	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL LH								Service	ATA:57
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 57.565	AFL		1171						54	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 804						PKG:32
57-ZL-00-206 S	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL RH								Service	ATA:57
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 57.570	AFL		1171						54	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 804						PKG:32
57-ZL-00-207 S	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL LH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.575	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 805						PKG:38
57-ZL-00-208 S	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL RH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.580	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 805						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-ZL-00-209[S]	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL LH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.585	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, SPM 51-23-00-390-821, AMM 57 20 00 210 815						PKG:38
57-ZL-00-210[S]	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL RH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.590	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 815						PKG:38
57-ZL-00-211[S]	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL LH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.595	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 806						PKG:34
57-ZL-00-212[S]	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL RH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.600	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 806						PKG:34
57-ZL-00-213[S]	GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL LH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.605	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 807						PKG:38
57-ZL-00-214[S]	GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL RH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.610	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 807						PKG:38

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-ZL-00-215[S]	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL LH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.615	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 808						PKG:34
57-ZL-00-216[S]	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL RH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.620	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 808						PKG:34
57-ZL-00-217[S]	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL LH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.625	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 809						PKG:38
57-ZL-00-218[S]	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL RH								Service	ATA:57
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.630	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 809						PKG:38
57-ZL-00-219[S]	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL LH								Service	ATA:57
	MOS		27-Jul-16						90.5	
	HRS		2078.9						2022.4	
WC#: 57.635	AFL	900 (+50/-50)	719						506	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 810						PKG:60
57-ZL-00-220[S]	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL RH								Service	ATA:57
	MOS		27-Jul-16						90.5	
	HRS		2078.9						2022.4	
WC#: 57.640	AFL	900 (+50/-50)	719						506	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 20 00 210 810						PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-ZL-00-221[S]	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL LH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.645	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 30 00 210 801						PKG:34
57-ZL-00-222[S]	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL RH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.650	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 30 00 210 801						PKG:34
57-ZL-00-223	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL LH								Service	ATA:57
	MOS		20-Dec-09					04-Jul-2026	169.7	
	HRS		0						4101.3	
WC#: 57.655	AFL	1800 (+50/-50)	0		1800	1850	575 (+50)		1225	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 51 00 210 801						
57-ZL-00-224	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL RH								Service	ATA:57
	MOS		20-Dec-09					04-Jul-2026	169.7	
	HRS		0						4101.3	
WC#: 57.660	AFL	1800 (+50/-50)	0		1800	1850	575 (+50)		1225	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 51 00 210 801						
57-ZL-00-225[S]	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - LH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.665	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 51 00 210 802						PKG:34
57-ZL-00-226[S]	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - RH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.670	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 51 00 210 802						PKG:34
57-ZL-00-227[S]	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL LH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.675	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 00 00 210 801						PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
57-ZL-00-228[S]	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL RH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.680	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 00 00 210 801						PKG:34
57-ZL-00-229[S]	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - LH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.685	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 00 00 210 802						PKG:34
57-ZL-00-230[S]	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - RH								Service	ATA:57
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 57.690	AFL		1069						156	
				PROC. REF: SPM 20-70-00-210-801, AMM 57 00 00 210 802						PKG:34
ASB A700-57-045	SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - ENSURE WING SEALING DOES NOT PERMIT FREEZING OF THE AILERON CONTROL, ALERT SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-	20-Apr-12						141.7	
	HRS		443.4						3657.9	
	AFL		160						1065	
ASB A700-57-045 PART (A)	INSPECT SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - ENSURE WING SEALING DOES NOT PERMIT FREEZING OF THE AILERON CONTROL, ALERT SERVICE BULLETIN								Bulletin	ATA:57
	DAYS/MSC	-	20-Apr-12						4314 d	
	HRS		443.4						3657.9	
	AFL		160						1065	
ASB A700-57-045 PART (B)	REWORK SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - ENSURE WING SEALING DOES NOT PERMIT FREEZING OF THE AILERON CONTROL, ALERT SERVICE BULLETIN								Bulletin	ATA:57
	DAYS/MSC	-	20-Apr-12						4314 d	
	HRS		443.4						3657.9	
	AFL		160						1065	
MODSUM IS700-57-0003[U]	WINGS - FLAP CANOE WS404 FAIRING, CHAFFING PROTECTION, MODIFICATION SUMMARY								Bulletin	ATA:57
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	AFL		719						506	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
REO 700-57-20-540[U]	REPAIR - RH AFT LOWER WING PLANK SKIN, REPAIR ENGINEERING ORDER								Bulletin ATA:57
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
REO 700-57-20-926[U]	REPAIR - CORROSION DAMAGE TO LH WING LOWER SKIN, REPAIR ENGINEERING ORDER								Bulletin ATA:57
	MOS/MSC	-	13-Jan-20						48.9
	HRS		3338.3						763
	AFL		1038						187
REO 700-57-51-263 REV[U] B	GENERAL REPAIR FOR CORROSION ON FITTING, LNBD FLAP CLOSURE RIB, WS 178, LOWER AND UPPER SURFACE, REPAIR ENGINEERING ORDER								Bulletin ATA:57
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
REO 700-57-51-264 REV[U] A	GENERAL REPAIR FOR CORROSION ON FITTING, OUTBD AFT, OUTBD FLAP (WS 404), REPAIR ENGINEERING ORDER								Bulletin ATA:57
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-57-019	CANCELLED PRIOR TO ISSUE, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-021	REWORK - LEADING EDGE SLATS - AERODYNAMIC CLEAN-UP - (A/C 9006), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-021 REV 01	REWORK - LEADING EDGE SLATS - AERODYNAMIC CLEAN-UP - (A/C 9006), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-021 REV 02	REWORK - LEADING EDGE SLATS - AERODYNAMIC CLEAN-UP (A/C 9006), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-022	MODIFICATION - CENTER WING - OVER-WING FAIRINGS AND UNDER-WING FAIRINGS SEALS REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-023	MODIFICATION - OUTER WING - REVISE SEAL OF WING LOWER TRAILING EDGE TO INBOARD FLAP, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-024	MODIFICATION - LEADING EDGE SLATS - SLAT ACTUATOR NO. 8 AERODYNAMIC SEAL IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-024 REV 01	MODIFICATION - LEADING EDGE SLATS - SLAT ACTUATOR NO. 8 AERODYNAMIC SEAL IMPROVEMENT, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-025	MODIFICATION - FLAP FAIRINGS - ADDITION OF DRAIN HOLES IN FLAP FAIRING ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-027	MODIFICATION - LEADING EDGE AND LEADING EDGE DEVICES - REPLACEMENT OF FASTENERS ON THE FIXED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-027 REV 01 PART (A)	MODIFICATION - LEADING EDGE AND LEADING EDGE DEVICES - REPLACEMENT OF FASTENERS ON THE FIXED LEADING EDGES (A/C 9002 AND 9004 TO 9064), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-027 REV 01 PART (B)	MODIFICATION - LEADING EDGE AND LEADING EDGE DEVICES - REPLACEMENT OF FASTENERS ON THE FIXED LEADING EDGES (A/C 9002 AND 9004 TO 9064), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-028 PART (A)	SPECIAL CHECK/REWORK - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACER ON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO.2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-028 PART (B)	MODIFICATION - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACER ON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO.2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-028 REV 01 PART (A)	SPECIAL CHECK/REWORK - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACER ON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO.2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-028 REV 01 PART (B)	MODIFICATION - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACER ON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO.2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-030	MODIFICATION - OUTER WING - ADDITION OF A DRAINAGE HOLE AT THE LOWEST POINT OF THE WING LOWER SURFACE AFT OF THE REAR SPAR TO PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-030 REV 01	MODIFICATION - OUTER WING - ADDITION OF A DRAINAGE HOLE AT THE LOWEST POINT OF THE WING LOWER SURFACE AFT OF THE REAR SPAR TO PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-031	MODIFICATION - OUTER WING - INTRODUCTION OF SCREEN ASSEMBLY AT THE AUXILIARY SPAR VENT HOLE COVER TO PREVENT F.O.D., SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-031 REV 01	MODIFICATION - OUTER WING - INTRODUCTION OF SCREEN ASSEMBLY AT THE AUXILIARY SPAR VENT HOLE COVER TO PREVENT F.O.D. (A/C 9002 TO 9153), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 PART (A)	MODIFICATION - WINGLET AND REAR SPAR BUSHING (APPLICABLE TO AIRCRAFT 9002 TO 9068), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 PART (B)	SPECIAL CHECK/MODIFICATION - BUSHINGS AND WASHERS (APPLICABLE TO AIRCRAFT 9002 TO 9113), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 REV 01 PART (A)	MODIFICATION - WINGLET AND REAR SPAR BUSHING (APPLICABLE TO AIRCRAFT 9002, AND 9004 TO 9068), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 REV 01 PART (B)	SPECIAL CHECK/MODIFICATION - BUSHINGS AND WASHERS (APPLICABLE TO AIRCRAFT 9002 TO 9113), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 REV 02 PART (A)	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART A EFFECTIVITY 9002 AND 9004 TO 9068), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-032 REV 02 PART (B)	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART B EFFECTIVITY 9002 TO 9113), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 REV 02 PART (C) RETRO	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART C EFFECTIVITY 9002 TO 9134) - RETROACTIVE ACTION, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 REV 03 PART (A)	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART A EFFECTIVITY 9002 AND 9004 TO 9068), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 REV 03 PART (B)	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART B EFFECTIVITY 9002 TO 9113), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-032 REV 03 PART (C) RETRO	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART C EFFECTIVITY 9114 TO 9134) - RETROACTIVE ACTION, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-033 PART (A)	SPECIAL CHECK/REWORK - GENERAL - CORROSION PREVENTION ON THE EDGE OF THE WING-TANK ACCESS PANELS AND THE FUEL ACCESS OPENINGS AT THE LOWER WING PLANK, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-033 PART (B)	SPECIAL CHECK/REWORK - GENERAL - CORROSION PREVENTION ON THE EDGE OF THE WING-TANK ACCESS PANELS AND THE FUEL ACCESS OPENINGS AT THE LOWER WING PLANK, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-034	SPECIAL CHECK/REWORK - CENTER WING - UPPER SKIN/STRINGER FASTENER HOLES, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-035	SPECIAL CHECK/REWORK - OUTER WING - ADDITION OF DRAIN HOLES IN OUTBOARD LOWER WING PLANK, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-036	MODIFICATION - FLAP SYSTEM - INBOARD FLAP COTTER PINS REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-037 PART (A)	SPECIAL CHECK/REWORK WING AFT-LOWER SKIN) CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-037 PART (B)	SPECIAL CHECK/REWORK WING AFT-LOWER SKIN) CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-037 PART (C)	SPECIAL CHECK/REWORK WING AFT-LOWER SKIN) CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-037 REV 01 PART (A)	SPECIAL CHECK/REWORK - WING AFT-LOWER SKIN - CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR (A/C 9007 TO 9112), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-037 REV 01 PART (B)	SPECIAL CHECK/REWORK - WING AFT-LOWER SKIN - CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR (A/C 9002 TO 9126, 9128 AND 9129), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-037 REV 01 PART (C)	SPECIAL CHECK/REWORK - WING AFT-LOWER SKIN - CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE (BETWEEN WING LOWER SKIN AND FRONT SPAR (A/C 9002 TO 9118), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-039 PART (A)	ADDITION OF DRAINAGE HOLES AT THE WING FIXED TRAILING EDGES (A/C 9002 TO 9223), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	A/R							
	HRS								
	AFL								
SB 700-57-039 PART (B)	ADDITION OF DRAINAGE HOLES AT THE PYLON TRAILING EDGES (A/C 9002 TO 9099), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-040	SPECIAL CHECK/MODIFICATION - LEADING EDGES - CHECK FOR CRACKED SHROUDS AND REPLACE OR MODIFY AS NECESSARY, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	N/A							
	HRS								
	AFL								
SB 700-57-041	MODIFICATION - OUTER WING - ADDITION OF SEALANT BETWEEN THE VISOR PANEL AND THE UPPER WING SURFACE (EFFECTIVITY 9002 TO 9299), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-041 REV 01	MODIFICATION - OUTER WING - ADDITION OF SEALANT BETWEEN THE VISOR PANEL AND THE UPPER WING SURFACE, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-041 REV 02	ICA - MODIFICATION - OUTER WING - ADDITION OF SEALANT BETWEEN THE VISOR PANEL AND THE UPPER WING SURFACE, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-043	REWORK - OUTER WING - SEAL DRAIN HOLE AND AROUND SUPPORT FITTING, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	T:A/R							
	HRS								
	AFL								
SB 700-57-044	MODIFICATION – GENERAL – APPLICATION OF ADDITIONAL SEALANT AND ADD WATER DRAINAGE IN THE COLLECTOR BOX, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-	17-Jun-11						151.8
	HRS		43.3						4058
	AFL		15						1210
SB 700-57-046	SPECIAL CHECK/REWORK - GENERAL - APPLICATION OF AERODYNAMIC SEALANT ON INBOARD AND OUTBOARD WINGLETS AND FORWARD WING TO BODY FAIRINGS/BELLY FAIRINGS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-047	SPECIAL CHECK/MODIFICATION - LEADING EDGES - REPLACEMENT OF THE ATTACHMENT ANGLES AND MODIFICATION OF SHROUD PANEL MOUNTING HOLES, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-	27-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-57-048[S]	MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING (ON HOLD), SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
SB 700-57-048 PART (A)[S]	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING (ON HOLD), SERVICE BULLETIN INSPECTION OF THE SPIGOT TUBE BUSHING FOR MIGRATION								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-048 PART (B)[S]	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING (ON HOLD), SERVICE BULLETIN REPLACEMENT OF THE SPIGOT TUBE BUSHING(S)								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-048 REV 01	MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-048 REV 01 PART A	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN INSPECTION OF THE SPIGOT TUBE BUSHING FOR MIGRATION								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-048 REV 01 PART B	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN REPLACEMENT OF THE SPIGOT TUBE BUSHING(S)								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-048 REV 02	MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-57-048 REV 02 PART A	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN INSPECTION OF THE SPIGOT TUBE BUSHING FOR MIGRATION								Bulletin	ATA:57
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
SB 700-57-048 REV 02 PART B	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN REPLACEMENT OF THE SPIGOT TUBE BUSHING(S)								Bulletin	ATA:57
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-57-050	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS, SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-050 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF INNER FLAP FOR CORROSION								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-050 PART B	ACCOMPLISH, SERVICE BULLETIN INNER FLAP CORROSION PREVENTION								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-050 PART C	ACCOMPLISH, SERVICE BULLETIN INNER FLAP - CORROSION REMOVAL REWORK								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-050 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS, SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-050 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF INNER FLAP FOR CORROSION								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-050 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN INNER FLAP CORROSION PREVENTION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-050 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN INNER FLAP - CORROSION REMOVAL REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-050 REV 02	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-050 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF INBOARD FLAP FOR CORROSION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-050 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN INBOARD FLAP DRAINAGE IMPROVEMENT								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-050 REV 02 PART C	ACCOMPLISH, SERVICE BULLETIN INBOARD FLAP CORROSION PREVENTION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-050 REV 02 PART D	ACCOMPLISH, SERVICE BULLETIN INBOARD FLAP - CORROSION REMOVAL/REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-050 REV 02 PART E	ACCOMPLISH, SERVICE BULLETIN INBOARD FLAP DRAIN HOLE COVERS INSTALLATION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-050 REV 03	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-57-050 REV 03 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INSPECTION OF INBOARD FLAP FOR CORROSION								Bulletin ATA:57
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-57-050 REV 03 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP DRAINAGE IMPROVEMENT								Bulletin ATA:57
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-57-050 REV 03 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP CORROSION PREVENTION								Bulletin ATA:57
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-57-050 REV 03 PART D	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP - CORROSION REMOVAL/REWORK								Bulletin ATA:57
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-57-050 REV 03 PART E	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP DRAIN HOLE COVERS INSTALLATION								Bulletin ATA:57
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 57 - WINGS										
SB 700-57-051	SPECIAL CHECK/REWORK - FLAP - CHAFING PROTECTION AT FLAP CANOE FAIRING (W.S. 404.00), SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-051 REV 01	SPECIAL CHECK/REWORK - FLAP - CHAFING PROTECTION AT FLAP CANOE FAIRING (W.S. 404.00), SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-052	MODIFICATION - GENERAL - WING-TANK ACCESS PANEL AND WING-PLANK FRETTING CORROSION PREVENTION, SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-57-053	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-053 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN MIDDLE FLAP DRAINAGE IMPROVEMENT								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-053 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN INSPECTION OF MIDDLE FLAP FOR CORROSION								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									
SB 700-57-053 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN MIDDLE FLAP CORROSION PREVENTION								Bulletin	ATA:57
	MOS/MSC	-								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-053 PART D	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN MIDDLE FLAP - CORROSION REMOVAL/REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-053 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-053 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP DRAINAGE IMPROVEMENT								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-053 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF MIDDLE FLAP FOR CORROSION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-053 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP CORROSION PREVENTION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-053 REV 01 PART D	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP - CORROSION REMOVAL/REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-053 REV 01 PART E	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP - LEADING EDGE REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-053 REV 01 PART F	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP - TRAILING EDGE REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN OUTER FLAP DRAINAGE IMPROVEMENT								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN INSPECTION OF OUTER FLAP FOR CORROSION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN OUTER FLAP CORROSION PREVENTION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 PART D	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN OUTER FLAP - CORROSION REMOVAL/REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-054 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN OUTER FLAP DRAINAGE IMPROVEMENT								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF OUTER FLAP FOR CORROSION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN OUTER FLAP CORROSION PREVENTION								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 REV 01 PART D	ACCOMPLISH, SERVICE BULLETIN OUTER FLAP - CORROSION REMOVAL/REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 REV 01 PART E	ACCOMPLISH, SERVICE BULLETIN OUTER FLAP - LEADING EDGE REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-054 REV 01 PART F	ACCOMPLISH, SERVICE BULLETIN OUTER FLAP - TRAILING EDGE REWORK								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-055	MODIFICATION - OUTER WING - INSTALLATION OF DRAIN HOLE COVERS ON MIDDLE AND OUTER FLAPS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 57 - WINGS									
SB 700-57-055 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE MIDDLE FLAP								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-055 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE OUTER FLAP								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-055 REV 01	MODIFICATION - OUTER WING - INSTALLATION OF DRAIN HOLE COVERS ON MIDDLE AND OUTER FLAPS, SERVICE BULLETIN								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-055 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE MIDDLE FLAP								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-57-055 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION OF THE OUTER FLAP								Bulletin ATA:57
	MOS/MSC	-							
	HRS								
	AFL								
ATA 70 - STANDARD PRACTICES - ENGINES									
SB BR700-70-900040 R10	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R10	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 70 - STANDARD PRACTICES - ENGINES									
SB BR700-70-900040 R11	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R11	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R12	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R12	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R13	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R13	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R14	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R14	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 70 - STANDARD PRACTICES - ENGINES									
SB BR700-70-900040 R15	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R15	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R16	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900040 R16	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R02	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R02	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R03	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 70 - STANDARD PRACTICES - ENGINES									
SB BR700-70-900295 R03	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R04	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R04	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R05	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R05	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R06	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-70-900295 R06	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:70
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 70 - STANDARD PRACTICES - ENGINES										
SB BR700-70-900295 R07	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:70
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-70-900295 R07	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:70
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-70-900387 R01	NO. 1 ENGINE - WORKSCOPE FOR SAMPLING PROGRAM, SERVICE BULLETIN								Bulletin	ATA:70
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-70-900387 R01	NO. 2 ENGINE - WORKSCOPE FOR SAMPLING PROGRAM, SERVICE BULLETIN								Bulletin	ATA:70
	MOS/MSC	-								
	HRS									
	ENC									
ATA 71 - POWER PLANT										
71-00-00-201	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE COMPONENTS ELECTRICAL CONNECTORS								Service	ATA:71
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 71 00 00 220 801						PKG:38
71-10-00-201[S]	GENERAL VISUAL INSPECTION OF THE COWLS								Service	ATA:71
	MOS		19-Mar-21						34.7	
	HRS	1500 (+50/-50)	3474.7						626.6	
WC#: 71.005	AFL		1069						156	
				PROC. REF: AMM 71 10 00 210 801						PKG:5
71-10-00-202[S]	GENERAL VISUAL INSPECTION OF THE COWL DOOR SEALS								Service	ATA:71
	MOS		19-Mar-21						34.7	
	HRS	1500 (+50/-50)	3474.7						626.6	
WC#: 71.010	AFL		1069						156	
				PROC. REF: AMM 71 10 00 210 802						PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-11-01-201	DETAILED INSPECTION OF THE INLET-COWL AERODYNAMIC SURFACES								Service	ATA:71
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 71.015	AFL		690						535	
				PROC. REF: AMM 71 11 01 220 802						PKG:8
71-11-01-202	DETAILED INSPECTION OF THE INLET-COWL FASTENERS AND ATTACHMENT RING								Service	ATA:71
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 71.020	AFL		690						535	
				PROC. REF: AMM 71 11 01 220 803						PKG:8
71-11-01-203	GENERAL VISUAL INSPECTION OF THE INLET-COWL REAR-BULKHEAD FIREWALL-MATERIAL (EXTERNAL SURFACES)								Service	ATA:71
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 71.025	AFL		690						535	
				PROC. REF: AMM 71 11 01 210 802						PKG:8
71-11-02-900-801-01	LH ENGINE NOSE COWL								Component	ATA:71
PN:07C0001-005	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E371	HRS		0	TSN 0					4101.3	
WC#: 71.105	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-11-02-900-801-02	RH ENGINE NOSE COWL								Component	ATA:71
PN:07C0001-006	MOS/MSC	O/C	14-Feb-11	TSR 0					155.9	
SN:E368	HRS		7.4	TSR 0					4093.9	
WC#: 71.105	AFL		4	TSR 0					1221	
				PROC. REF: GENERIC NO REF						
71-12-01-101	DETAILED INSPECTION OF THE UPPER FAN-COWL-DOOR								Service	ATA:71
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 71.030	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 71 12 01 220 801						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-12-01-201 S	DETAILED INSPECTION OF THE UPPER COWLS								Service	ATA:71
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 71.035	AFL		1069						156	
				PROC. REF: AMM 71 12 01 220 801						PKG:38
71-12-01-202	SPECIAL DETAILED INSPECTION OF THE UPPER COWLS								Service	ATA:71
	MOS		20-Dec-09					26-Oct-2026	169.7	
	HRS		0						4101.3	
WC#: 71.040	AFL	T:1875 (+50/-50)	0		1875	1925	650 (+50)		1225	
				PROC. REF: AMM 71 12 01 280 801						
71-12-01-900-801-01	LH ENGINE FAN DOOR UPPER COWL								Component	ATA:71
PN:07D4001-001	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E381/SB4245	HRS		0	TSN 0					4101.3	
WC#: 71.110	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 12 01 000 801, AMM 71 12 01 400 801						
71-12-01-900-801-02	RH ENGINE FAN DOOR UPPER COWL								Component	ATA:71
PN:07D4001-002	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E381/SB4246	HRS		0	TSN 0					4101.3	
WC#: 71.110	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 12 01 000 801, AMM 71 12 01 400 801						
71-13-01-201 S	FUNCTIONAL TEST OF THE LOWER-COWL PRESSURE-RELIEF DOORS								Service	ATA:71
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
WC#: 71.045	AFL		1171						54	
				PROC. REF: AMM 71 13 01 720 801						PKG:32
71-13-01-900-801-01	LH ENGINE FAN DOOR LOWER COWL								Component	ATA:71
PN:07D4002-001	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E381/SB4247	HRS		0	TSN 0					4101.3	
WC#: 71.115	AFL		0	TSN 0					1225	
				PROC. REF: CMM 71-13-51, AMM 71 13 01 000 801, AMM 71 13 01 400 801						
71-13-01-900-801-02	RH ENGINE FAN DOOR LOWER COWL								Component	ATA:71
PN:07D4003-001	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E381/SB4248	HRS		0	TSN 0					4101.3	
WC#: 71.115	AFL		0	TSN 0					1225	
				PROC. REF: CMM 71-13-52, AMM 71 13 01 000 801, AMM 71 13 01 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-14-01-201	GENERAL VISUAL INSPECTION OF THE FIXED COWL SEALS								Service	ATA:71
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 71.050	AFL		690						535	
				PROC. REF: AMM 71 14 01 210 801						PKG:8
71-14-01-202	DETAILED INSPECTION OF THE FIXED COWL								Service	ATA:71
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		4979	5029	877.7 (+50)		2122.3	
WC#: 71.055	AFL		690						535	
				PROC. REF: AMM 71 14 01 220 801						PKG:8
71-20-00-201 S	DETAILED INSPECTION OF THE MOUNTS								Service	ATA:71
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 71.060	AFL		1069						156	
				PROC. REF: AMM 71 20 00 220 801						PKG:38
71-20-00-202 S	DETAILED INSPECTION OF THE CASING LUGS FOR THE FRONT MOUNTS								Service	ATA:71
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 71.065	AFL		1069						156	
				PROC. REF: AMM 71 20 00 220 802						PKG:34
71-21-01-101	SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT BEAM AND LINKS								Service	ATA:71
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 71.070	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: GENERIC NO REF						PKG:76
71-21-01-102	SPECIAL DETAILED INSPECTION OF THE THRUST STRUT								Service	ATA:71
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 71.075	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: GENERIC NO REF						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-21-01-103	SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT LINK PINS, THRUST STRUT PINS, THRUST PIN AND PYLON ATTACHMENT PINS								Service	ATA:71
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 71.080	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: GENERIC NO REF						PKG:76
71-21-02-900-801-01	NO. 1 MOUNT TO BEAM ATTACH PIN								Component	ATA:71
PN:BRR15812	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:201844049	HRS		0	TSN 0					4101.3	
WC#: 71.130	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-02-900-801-02	NO. 2 MOUNT TO BEAM ATTACH PIN								Component	ATA:71
PN:BRR15812	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:201844050	HRS		0	TSN 0					4101.3	
WC#: 71.130	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-02-900-801-03	NO. 3 MOUNT TO BEAM ATTACH PIN								Component	ATA:71
PN:BRR15812	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:201844056	HRS		0	TSN 0					4101.3	
WC#: 71.130	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-02-900-801-04	NO. 4 MOUNT TO BEAM ATTACH PIN								Component	ATA:71
PN:BRR15812	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:201844051	HRS		0	TSN 0					4101.3	
WC#: 71.130	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-03-900-801-01	FWD LH UPPER PYLON ATTACHMENT PIN								Component	ATA:71
PN:BRR15805	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037A1738	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-03-900-801-02	FWD LH LOWER PYLON ATTACHMENT PIN								Component	ATA:71
PN:BRR15805	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037A1720	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-21-03-900-801-03	FWD RH UPPER PYLON ATTACHMENT PIN								Component	ATA:71
PN:BRR15805	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037A1746	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-03-900-801-04	FWD RH LOWER PYLON ATTACHMENT PIN								Component	ATA:71
PN:BRR15805	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037A1757	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-05-900-801-01	FWD, L/H PIN								Component	ATA:71
PN:BRR15809	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200492028	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-05-900-801-02	FWD, R/H PIN								Component	ATA:71
PN:BRR15809	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200492026	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-06-900-801-01	AFT L/H PIN								Component	ATA:71
PN:BRR15824	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:201747049	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-21-06-900-801-02	AFT R/H PIN								Component	ATA:71
PN:BRR15824	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:201747045	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-22-01-101	SPECIAL DETAILED INSPECTION OF THE REAR MOUNT BEAM AND LINKS								Service	ATA:71
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 71.085	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: GENERIC NO REF						PKG:76

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-22-01-102	SPECIAL DETAILED INSPECTION OF THE REAR MOUNT LINK PINS AND PYLON ATTACHMENT PINS								Service	ATA:71
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 71.090	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: GENERIC NO REF						PKG:76
71-22-02-900-801-01	AFT LH LOWER MOUNT BEAM TO LINK PIN								Component	ATA:71
PN:BRR15835	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037B1686	HRS		0	TSN 0					4101.3	
WC#: 71.145	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-22-02-900-801-02	AFT RH LOWER MOUNT BEAM TO LINK PIN								Component	ATA:71
PN:BRR15835	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037B1688	HRS		0	TSN 0					4101.3	
WC#: 71.145	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-22-02-900-801-03	AFT LH UPPER MOUNT BEAM TO LINK PIN								Component	ATA:71
PN:BRR15835	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037B1687	HRS		0	TSN 0					4101.3	
WC#: 71.145	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-22-02-900-801-04	AFT RH UPPER MOUNT BEAM TO LINK PIN								Component	ATA:71
PN:BRR15835	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:20037B1700	HRS		0	TSN 0					4101.3	
WC#: 71.145	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-22-03-900-801-01	AFT LH UPPER MOUNT BEAM TO PYLON PIN								Component	ATA:71
PN:BRR15840	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037D1630	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
71-22-03-900-801-02	AFT LH LOWER MOUNT BEAM TO PYLON PIN								Component	ATA:71
PN:BRR15840	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:200037D1635	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
71-22-03-900-801-03	AFT RH UPPER MOUNT BEAM TO PYLON PIN								Component ATA:71
PN:BRR15840	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:200037D1636	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-03-900-801-04	AFT RH LOWER MOUNT BEAM TO PYLON PIN								Component ATA:71
PN:BRR15840	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:200037D1638	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-03-900-802-01	L/H BEAM REAR MOUNT ASSEMBLY								Component ATA:71
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-03-900-802-02	R/H BEAM REAR MOUNT ASSEMBLY								Component ATA:71
PN:BRR24400	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:BSTK0458	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-03-900-802-03	L/H BEAM OF REAR MOUNT ASSEMBLY								Component ATA:71
PN:BRR24407	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7
SN:228537AABL813	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: GENERIC NO REF					
71-22-03-900-802-04	R H BEAM OF REAR MOUNT ASSEMBLY								Component ATA:71
PN:BRR24407	MOS/MSC	O/C	19-Mar-21	TSN 0					34.7
SN:228537AABM345	HRS		3474.7	TSN 0					626.6
	AFL		1069	TSN 0					156
				PROC. REF: GENERIC NO REF					
71-22-04-900-801-01	L/H APRON ASSY								Component ATA:71
PN:07E0001-023	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:E383	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
71-22-04-900-801-02	R/H APRON ASSY								Component ATA:71
PN:07E0001-024	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:E383	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-07-900-801-01	LINK TO MOUNT RING, L/H LOWER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:200037C1733	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-07-900-801-02	LINK TO MOUNT RING L/H UPPER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:200037C1726	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-07-900-801-03	LINK TO MOUNT RING, R/H LOWER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:200037C1741	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-22-07-900-801-04	LINK TO MOUNT RING, R/H UPPER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:200037C1737	HRS		0	TSN 0					4101.3
	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
71-23-01-900-801-01	LEFT UPPER FRONT MOUNT LINK ASSEMBLY								Component ATA:71
PN:BRR24405	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:THEAP12172	HRS		0	TSN 0					4101.3
WC#: 71.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801					
71-23-01-900-801-02	RIGHT UPPER FRONT MOUNT LINK ASSEMBLY								Component ATA:71
PN:BRR24405	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:THEAP12130	HRS		0	TSN 0					4101.3
WC#: 71.120	AFL		0	TSN 0					1225
				PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-23-01-900-801-03	LEFT LOWER FRONT MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR24405	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:THEAP12270	HRS		0	TSN 0					4101.3	
WC#: 71.125	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801						
71-23-01-900-801-04	RIGHT LOWER FRONT MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR24405	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:THEAP12134	HRS		0	TSN 0					4101.3	
WC#: 71.125	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801						
71-24-01-900-801-01	LEFT UPPER REAR MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR24413	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:THEAP12353	HRS		0	TSN 0					4101.3	
WC#: 71.135	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801						
71-24-01-900-801-02	RIGHT UPPER REAR MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR24413	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:THEAP12358	HRS		0	TSN 0					4101.3	
WC#: 71.135	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801						
71-24-01-900-801-03	LEFT LOWER REAR MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR24413	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:THEAP12364	HRS		0	TSN 0					4101.3	
WC#: 71.140	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801						
71-24-01-900-801-04	RIGHT LOWER REAR MOUNT LINK ASSEMBLY								Component	ATA:71
PN:BRR24413	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:THEAP12365	HRS		0	TSN 0					4101.3	
WC#: 71.140	AFL		0	TSN 0					1225	
				PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801						
71-ZL-00-201[S]	GENERAL VISUAL INSPECTION OF THE NACELLE - RH								Service	ATA:71
	MOS		08-Jul-18						67.1	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 71.095	AFL		921						304	
				PROC. REF: SPM 20-70-00-210-801, AMM 71 00 00 210 802						PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
71-ZL-00-202 S	GENERAL VISUAL INSPECTION OF THE NACELLE - LH								Service	ATA:71
	MOS		08-Jul-18						67.1	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 71.095	AFL		921						304	
				PROC. REF: SPM 20-70-00-210-801, AMM 71 00 00 210 802						PKG:8
71-ZL-00-203 S	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL LH								Service	ATA:71
	MOS		10-Jul-18						67	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 71.100	AFL		921						304	
				PROC. REF: SPM 20-70-00-210-801, AMM 71 00 00 210 801						PKG:8
71-ZL-00-204 S	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL RH								Service	ATA:71
	MOS		10-Jul-18						67	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 71.100	AFL		921						304	
				PROC. REF: SPM 20-70-00-210-801, AMM 71 00 00 210 801						PKG:8
710005	NO. 1 ENGINE - ENGINE MIDLIFE INSPECTION								Service	ATA:71
	MOS/MSC	A/R	20-Dec-09						169.7	
	HRS		0						4101.3	
	ENC		0						1228	
				PROC. REF: GENERIC NO REF						
710005	NO. 2 ENGINE - ENGINE MIDLIFE INSPECTION								Service	ATA:71
	MOS/MSC	A/R	20-Dec-09						169.7	
	HRS		0						4101.3	
	ENC		0						1228	
				PROC. REF: GENERIC NO REF						
710009	NO. 1 ENGINE - ENGINE OVERHAUL								Service	ATA:71
	MOS/MSC	A/R	20-Dec-09						169.7	
	HRS		0						4101.3	
	ENC		0						1228	
				PROC. REF: GENERIC NO REF						
710009	NO. 2 ENGINE - ENGINE OVERHAUL								Service	ATA:71
	MOS/MSC	A/R	20-Dec-09						169.7	
	HRS		0						4101.3	
	ENC		0						1228	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
717102-001	NO. 1 ENGINE - DRAINS EJECTOR PUMP								Component	ATA:71
PN:CV41-14-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:08-1212141	HRS		0	TSN 0					4101.3	
WC#: 71.005	ENC		0	TSN 0					1228	
				PROC. REF: AMM 73 12 15 210 801						
717102-001	NO. 2 ENGINE - DRAINS EJECTOR PUMP								Component	ATA:71
PN:CV41-14-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:08-0918361	HRS		0	TSN 0					4101.3	
WC#: 71.005	ENC		0	TSN 0					1228	
				PROC. REF: AMM 73 12 15 210 801						
71EN1	NO. 1 ENGINE								Component	ATA:71
PN:BR710	MOS/MSC	E/C								
SN:12843	HRS									
WC#: 71.EN1	AFL									
				PROC. REF: AMM 71 00 00 000 801, AMM 71 00 00 400 801						
71EN2	NO. 2 ENGINE								Component	ATA:71
PN:BR710	MOS/MSC	E/C								
SN:12844	HRS									
WC#: 71.EN2	AFL									
				PROC. REF: AMM 71 00 00 000 801, AMM 71 00 00 400 801						
FAA 2021-21-04	REDISTRIBUTION OF LOAD/STRESS ON THE MOUNT COMPONENTS								AD	ATA:71
	MOS/MSC	-	17-Jan-22						24.8	
	HRS		3689.6						411.7	
	AFL		1117						108	
SB 700-71-001	MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN								Bulletin	ATA:71
	MOS/MSC	-	27-Jan-14						120.5	
	HRS		1208.9						2892.4	
	AFL		478						747	
SB 700-71-001 REV 01	MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN								Bulletin	ATA:71
	MOS/MSC	-	22-Jul-14						114.6	
	HRS		1387.8						2713.5	
	AFL		534						691	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB 700-71-001 REV 01 PART (A)	REMOVE MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN THE ACCESS PANEL - DRILL A DRAIN HOLE IN THE ACCESS PANEL AND FIXED COWL ON THE AIRCRAFT - IDENTIFY THE ACCESS PANEL AND FIXED COWL AND INSTALL THE ACCESS PANEL								Bulletin ATA:71
	MOS/MSC	-	22-Jul-14						114.6
	HRS		1387.8						2713.5
	AFL		534						691
SB 700-71-001 REV 01 PART (B)	REIDENTIFY MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN THE FIXED COWL ACCESS PANEL ON THE RH NACELLE								Bulletin ATA:71
	MOS/MSC	-	22-Jul-14						114.6
	HRS		1387.8						2713.5
	AFL		534						691
SB 700-71-002	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-	26-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-71-002 PART (A)	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES								Bulletin ATA:71
	MOS/MSC	-	26-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-71-002 PART (B)	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE HARDWARE								Bulletin ATA:71
	MOS/MSC	-	26-Jul-16						90.5
	HRS		2078.9						2022.4
	AFL		719						506
SB 700-71-002 REV 01	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-	10-Aug-16						90
	HRS								
	AFL								
SB 700-71-002 REV 01 PART (A)	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES								Bulletin ATA:71
	MOS/MSC	-	10-Aug-16						90
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 71 - POWER PLANT										
SB 700-71-002 REV 01 PART (B)	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN REPLACEMENT OF THE HARDWARE								Bulletin	ATA:71
	MOS/MSC	-	10-Aug-16						90	
	HRS									
	AFL									
SB 700-71-003	MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:71
	MOS/MSC	-	11-Jul-17						79	
	HRS		2473.8						1627.5	
	AFL		817						408	
SB 700-71-003 PART (A)	ACCOMPLISH, SERVICE BULLETIN MEASUREMENT OF THE GAPS ON THE ENGINE REAR MOUNT ASSEMBLY HARDWARE								Bulletin	ATA:71
	MOS/MSC	-	11-Jul-17						79	
	HRS		2473.8						1627.5	
	AFL		817						408	
SB 700-71-003 PART (B) S	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE ENGINE REAR MOUNT ASSEMBLY HARDWARE								Bulletin	ATA:71
	MOS	T:12	11-Jul-17						79	
	HRS	T:1000	2473.8						1627.5	
	AFL		817						408	
SB 700-71-005	SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN								Bulletin	ATA:71
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-71-005 PART A	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15811) AT THE UPPER AND LOWER SIDE OF FRONT MOUNT BEAM								Bulletin	ATA:71
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
SB 700-71-005 PART B	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15808) AT THE THRUST STRUT FRONT LOCATION								Bulletin	ATA:71
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB 700-71-005 PART C	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15823) AT THE THRUST STRUT AIRCRAFT PYLON INTERFACE								Bulletin ATA:71
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-71-005 PART D	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15804) AT THE FRONT MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION								Bulletin ATA:71
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-71-005 PART E	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15841) AT THE REAR MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION								Bulletin ATA:71
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	AFL		1069						156
SB 700-71-005 REV 01	SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	AFL								
SB 700-71-005 REV 01 PART A	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15811) AT THE UPPER AND LOWER SIDE OF FRONT MOUNT BEAM								Bulletin ATA:71
	MOS/MSC	-	EFF						
	HRS		EFF						
	AFL								
SB 700-71-005 REV 01 PART B	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15808) AT THE THRUST STRUT FRONT LOCATION								Bulletin ATA:71
	MOS/MSC	-	EFF						
	HRS		EFF						
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB 700-71-005 REV 01 PART C	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15823) AT THE THRUST STRUT AIRCRAFT PYLON INTERFACE								Bulletin ATA:71
	MOS/MSC	-	EFF						
	HRS		EFF						
	AFL								
SB 700-71-005 REV 01 PART D	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15804) AT THE FRONT MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION								Bulletin ATA:71
	MOS/MSC	-	EFF						
	HRS		EFF						
	AFL								
SB 700-71-005 REV 01 PART E	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15841) AT THE REAR MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION								Bulletin ATA:71
	MOS/MSC	-	EFF						
	HRS		EFF						
	AFL								
SB BR700-71-100602	NO. 1 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-100602	NO. 2 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-100830	NO. 1 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF A WEIGHT DECREASEDTHRUST TRUNNION WITH REVISED DRY FILM LUBRICANT (DFL), SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-100830	NO. 2 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF A WEIGHT DECREASEDTHRUST TRUNNION WITH REVISED DRY FILM LUBRICANT (DFL), SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101279	NO. 1 ENGINE - LEFT AND RIGHT UPPER COWL - INTRODUCTION OF CHANGES TO THE VENT INLET DUCT ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101279	NO. 2 ENGINE - LEFT AND RIGHT UPPER COWL - INTRODUCTION OF CHANGES TO THE VENT INLET DUCT ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101357	NO. 1 ENGINE - POWER PLANT - BREATHER OUTLET TUBES AND FITTINGS - INTRODUCTION OF CHANGES RELATED TO A NEW OIL TUBE ROUTING BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER (FCOC), SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101357	NO. 2 ENGINE - POWER PLANT - BREATHER OUTLET TUBES AND FITTINGS - INTRODUCTION OF CHANGES RELATED TO A NEW OIL TUBE ROUTING BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER (FCOC), SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101569 R01	NO. 1 ENGINE - POWER PLANT - LEFT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101569 R01	NO. 2 ENGINE - POWER PLANT - LEFT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-101570 R01	NO. 1 ENGINE - POWER PLANT - RIGHT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101570 R01	NO. 2 ENGINE - POWER PLANT - RIGHT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101571 R01	NO. 1 ENGINE - POWER PLANT - LEFT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101571 R01	NO. 2 ENGINE - POWER PLANT - LEFT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101572 R01	NO. 1 ENGINE - POWER PLANT - RIGHT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101572 R01	NO. 2 ENGINE - POWER PLANT - RIGHT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101581	NO. 1 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-101581	NO. 2 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101675	NO. 1 ENGINE - POWER PLANT - VARIOUS NACELLE AND ENGINE BUILD UNIT (EBU) SYSTEMS - INTRODUCTION OFAMENDMENTS AND CORRECTIONS TO THE BASELINE DEFINITION OF THE SPAREABLE PARTS FOR THENACELLE AND EBU FOR SPARES ORDERING PURPOSES, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101675	NO. 2 ENGINE - POWER PLANT - VARIOUS NACELLE AND ENGINE BUILD UNIT (EBU) SYSTEMS - INTRODUCTION OFAMENDMENTS AND CORRECTIONS TO THE BASELINE DEFINITION OF THE SPAREABLE PARTS FOR THENACELLE AND EBU FOR SPARES ORDERING PURPOSES, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101830	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-	09-Jul-13						127.1
	HRS		1009.7						3091.6
	ENC		393						835
SB BR700-71-101830	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-	09-Jul-13						127.1
	HRS		1009.7						3091.6
	ENC		393						835
SB BR700-71-101830 R01	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-101830 R01	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101883	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER AND LOWER FIXED COWL HOOKS WITH A SLIGHTLY MODIFIED CONTOUR, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101883	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER AND LOWER FIXED COWL HOOKS WITH A SLIGHTLY MODIFIED CONTOUR, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101974	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A MODIFIED FIRE BOX CENTRE PIECE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101974	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A MODIFIED FIRE BOX CENTRE PIECE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101975	NO. 1 ENGINE - POWER PLANT - REAR SUSPENSION-ENGINE MOUNTS REAR LINKS AND ATTACHING PARTS ANDENGINE/AIRCRAFT ATTACH PARTS - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101975	NO. 2 ENGINE - POWER PLANT - REAR SUSPENSION-ENGINE MOUNTS REAR LINKS AND ATTACHING PARTS ANDENGINE/AIRCRAFT ATTACH PARTS - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-101975 R01	NO. 1 ENGINE - POWER PLANT - REAR SUSPENSION-ENGINE MOUNTS REAR LINKS AND ATTACHING PARTS AND ENGINE / AIRCRAFT ATTACH PARTS - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	ENC		820						408
SB BR700-71-101975 R01	NO. 2 ENGINE - POWER PLANT - REAR SUSPENSION-ENGINE MOUNTS REAR LINKS AND ATTACHING PARTS AND ENGINE / AIRCRAFT ATTACH PARTS - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-	11-Jul-17						79
	HRS		2473.8						1627.5
	ENC		820						408
SB BR700-71-101976	NO. 1 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE/AIRCRAFT ATTACH PARTS AND LEFT AND RIGHT ENGINE FRONT SUSPENSION-AIRCRAFT MOUNTED - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-101976	NO. 2 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE/AIRCRAFT ATTACH PARTS AND LEFT AND RIGHT ENGINE FRONT SUSPENSION-AIRCRAFT MOUNTED - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102013	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102013	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-102013 PART 1	NO. 1 ENGINE - ACCOMPLISH POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE, SERVICE BULLETIN APPLICABLE FOR ENGINES WHICH HAVE THE EEC LANE A HARNESS 1C, P/N FW39246 INSTALLED (SERVICE BULLETIN SB-BR700-73-101559 STANDARD OR SERVICE BULLETIN SB-BR700-73-101634 STANDARD INCORPORATED) AND THE EEC LANE B HARNESS 1F, P/N BRR23979 INSTALLED (SERVICE BULLETIN SB-BR700-71-100892 STANDARD INCORPORATED).								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102013 PART 1	NO. 2 ENGINE - ACCOMPLISH POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE, SERVICE BULLETIN APPLICABLE FOR ENGINES WHICH HAVE THE EEC LANE A HARNESS 1C, P/N FW39246 INSTALLED (SERVICE BULLETIN SB-BR700-73-101559 STANDARD OR SERVICE BULLETIN SB-BR700-73-101634 STANDARD INCORPORATED) AND THE EEC LANE B HARNESS 1F, P/N BRR23979 INSTALLED (SERVICE BULLETIN SB-BR700-71-100892 STANDARD INCORPORATED).								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102013 PART 2	NO. 1 ENGINE - ACCOMPLISH POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE, SERVICE BULLETIN APPLICABLE FOR ENGINES WHICH HAVE THE EEC LANE A HARNESS 1C, P/N BRR23978 INSTALLED (SERVICE BULLETIN SB-BR700-71-100892 STANDARD INCORPORATED, BUT SERVICE BULLETIN SB-BR700-73-101559 STANDARD OR SERVICE BULLETIN SB-BR700-73-101634 STANDARD NOT INCORPORATED).								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102013 PART 2	NO. 2 ENGINE - ACCOMPLISH POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE, SERVICE BULLETIN APPLICABLE FOR ENGINES WHICH HAVE THE EEC LANE A HARNESS 1C, P/N BRR23978 INSTALLED (SERVICE BULLETIN SB-BR700-71-100892 STANDARD INCORPORATED, BUT SERVICE BULLETIN SB-BR700-73-101559 STANDARD OR SERVICE BULLETIN SB-BR700-73-101634 STANDARD NOT INCORPORATED).								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102026	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEWPRESSURE REGULATING VALVE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-102026	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEWPRESSURE REGULATING VALVE, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102085	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER MIDDLE FIXED COWL HOOKS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102085	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER MIDDLE FIXED COWL HOOKS, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102124	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEW RIGID V-CLAMP FOR THE INSTALLATION OF THE HYDRAULIC PUMP UNIT, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102124	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEW RIGID V-CLAMP FOR THE INSTALLATION OF THE HYDRAULIC PUMP UNIT, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102131	NO. 1 ENGINE - POWER PLANT - DRAINS SYSTEM COLLECTION TANK - INTRODUCTION OF A THICKER BRACKET FOR THE FUEL DRAINS TANK, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-102131	NO. 2 ENGINE - POWER PLANT - DRAINS SYSTEM COLLECTION TANK - INTRODUCTION OF A THICKER BRACKET FOR THE FUEL DRAINS TANK, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 71 - POWER PLANT									
SB BR700-71-900282	NO. 1 ENGINE - INSPECTION OF FIRE WALL CABLE FOR WEAR, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-71-900282	NO. 2 ENGINE - INSPECTION OF FIRE WALL CABLE FOR WEAR, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-71-900377	NO. 1 ENGINE - ENGINE - ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESSES 1A AND 1B - INSPECTION AND CORRECTION OF TIGHT CLEARENCE BETWEEN THE ELECTRICAL CONNECTOR BRR1066 OR P1066 AT THE STARTER AIR VALVE (SAV) AND THE ADJACENT EEC LANE A, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-900377	NO. 2 ENGINE - ENGINE - ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESSES 1A AND 1B - INSPECTION AND CORRECTION OF TIGHT CLEARENCE BETWEEN THE ELECTRICAL CONNECTOR BRR1066 OR P1066 AT THE STARTER AIR VALVE (SAV) AND THE ADJACENT EEC LANE A, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-900675	NO. 1 ENGINE - POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-71-900675	NO. 2 ENGINE - POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:71
	MOS/MSC	-							
	HRS								
	ENC								
ATA 72 - ENGINE									
72-21-04-900-801-01	LH THRUST STRUT								Component ATA:72
PN:BRR17672	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:204756RF5842	HRS		0	TSN 0					4101.3
WC#: 72.005	AFL		0	TSN 0					1225

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
				PROC. REF: GENERIC NO REF					
72-21-04-900-801-02	RH THRUST STRUT								Component ATA:72
PN:BRR15817	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:204756RF5827	HRS		0	TSN 0					4101.3
WC#: 72.005	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
72-30-01-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS								Service ATA:72
	MOS		19-Mar-21					30-Sep-2026	34.7
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6
WC#: 72.005	ENC		1072						156
				PROC. REF: AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 50 00 220 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801					PKG:6
72-30-01-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS								Service ATA:72
	MOS		19-Mar-21					30-Sep-2026	34.7
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6
WC#: 72.005	ENC		1072						156
				PROC. REF: AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 50 00 220 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801					PKG:6
72-31-02-201[S]	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES								Service ATA:72
	MOS		06-Dec-23						2.2
	HRS	1000 (+50/-50)	4099.1						2.2
WC#: 72.010	ENC		1226						2
				PROC. REF: AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801					PKG:4
72-31-02-201[S]	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES								Service ATA:72
	MOS		06-Dec-23						2.2
	HRS	1000 (+50/-50)	4099.1						2.2
WC#: 72.010	ENC		1226						2
				PROC. REF: AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801					PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
72-31-02-202[S]	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS								Service ATA:72
	MOS		30-Nov-23						2.4
	HRS	1000 (+50/-50)	4099.1						2.2
WC#: 72.015	ENC		1226						2
				PROC. REF: AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802					PKG:4
72-31-02-202[S]	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS								Service ATA:72
	MOS		06-Dec-23						2.2
	HRS	1000 (+50/-50)	4099.1						2.2
WC#: 72.015	ENC		1226						2
				PROC. REF: AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802					PKG:4
72-31-02-203	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]								Service ATA:72
	MOS/MSC	N/A	20-Dec-09						169.7
	HRS		0						4101.3
WC#: 72.510	ENC		0						1228
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					
72-31-02-203	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]								Service ATA:72
	MOS/MSC	N/A	20-Dec-09						169.7
	HRS		0						4101.3
WC#: 72.510	ENC		0						1228
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					
72-31-02-203 OPT 1	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (*** OPTION 1)] NOTE: +/-400 HOURS								Service ATA:72
	MOS		20-Dec-09					04-Dec-2023	169.7
	HRS	4000 (+400/-400)	0		(4000) 4000	4400	TOL (+298.7)		4101.3
WC#: 72.515	ENC	3000	0		(3000) 2997		1772		1228
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
72-31-02-203 OPT 1	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (*** OPTION 1)] NOTE: +/-400 HOURS								Service ATA:72
	MOS		20-Dec-09					04-Dec-2023	169.7
	HRS	4000 (+400/-400)	0		(4000) 4000	4400	TOL (+298.7)		4101.3
WC#: 72.515	ENC	3000	0		(3000) 2997		1772		1228
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					
72-31-02-203 OPT 2/1	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (*** OPTION 2 - FIRST REQUIREMENT)								Service ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					
72-31-02-203 OPT 2/1	NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (*** OPTION 2 - FIRST REQUIREMENT)								Service ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					
72-31-02-203 OPT 2/2	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (*** OPTION 2 - SECOND REQUIREMENT)								Service ATA:72
	MOS/MSC	-							
	HRS								
WC#: 72.525	ENC								
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					
72-31-02-203 OPT 2/2	NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (*** OPTION 2 - SECOND REQUIREMENT)								Service ATA:72
	MOS/MSC	-							
	HRS								
WC#: 72.525	ENC								
				PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
72-31-02-301	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE LP-COMPRESSOR FAN-TRACK-LINER (PRE SB BR700-72-100981)								Service	ATA:72
	MOS/MSC	N/A								
	HRS									
	ENC									
				PROC. REF: AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801						
72-31-02-301	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE LP-COMPRESSOR FAN-TRACK-LINER (PRE SB BR700-72-100981)								Service	ATA:72
	MOS/MSC	N/A								
	HRS									
	ENC									
				PROC. REF: AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801						
72-32-02-201[S]	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES								Service	ATA:72
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.020	ENC		1226						2	
				PROC. REF: AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801						PKG:4
72-32-02-201[S]	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES								Service	ATA:72
	MOS		15-Dec-23						1.9	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.020	ENC		1226						2	
				PROC. REF: AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801						PKG:4
72-32-02-202[S]	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES								Service	ATA:72
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.025	ENC		1226						2	
				PROC. REF: AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802						PKG:4
72-32-02-202[S]	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES								Service	ATA:72
	MOS		06-Dec-23						2.2	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.025	ENC		1226						2	
				PROC. REF: AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802						PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
72-33-00-301	NO. 1 ENGINE - LUBRICATION OF THE VARIABLE STATOR VANES (VSV) ACTUATING MECHANISM (PRE SB BR700-72-101414)								Service	ATA:72
	MOS/MSC	N/A	20-Dec-09						169.7	
	HRS		0						4101.3	
WC#: 72.030	ENC		0						1228	
				PROC. REF: AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801						
72-33-00-301	NO. 2 ENGINE - LUBRICATION OF THE VARIABLE STATOR VANES (VSV) ACTUATING MECHANISM (PRE SB BR700-72-101414)								Service	ATA:72
	MOS/MSC	N/A	20-Dec-09						169.7	
	HRS		0						4101.3	
WC#: 72.030	ENC		0						1228	
				PROC. REF: AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801, AMM 75 31 01 640 801						
72-34-01-201[S]	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE KEVLAR-WRAP								Service	ATA:72
	MOS		10-Jul-18						67	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 72.035	ENC		924						304	
				PROC. REF: AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802						PKG:8
72-34-01-201[S]	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE KEVLAR-WRAP								Service	ATA:72
	MOS		10-Jul-18						67	
	HRS	3000 (+50/-50)	2892.3						1209	
WC#: 72.035	ENC		924						304	
				PROC. REF: AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802, AMM 72 34 01 210 802						PKG:8
72-38-01-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTAKE ROTATING FAIRING								Service	ATA:72
	MOS		19-Mar-21					30-Sep-2026	34.7	
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6	
WC#: 72.040	ENC		1072						156	
				PROC. REF: AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801						PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
72-38-01-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTAKE ROTATING FAIRING								Service	ATA:72
	MOS		19-Mar-21					30-Sep-2026	34.7	
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6	
WC#: 72.040	ENC		1072						156	
				PROC. REF: AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801						PKG:6
72-40-00-203S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER								Service	ATA:72
	MOS		03-Dec-23						2.3	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.045	ENC		1226						2	
				PROC. REF: AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801						PKG:4
72-40-00-203S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER								Service	ATA:72
	MOS		03-Dec-23						2.3	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.045	ENC		1226						2	
				PROC. REF: AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801						PKG:4
72-40-00-204S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES								Service	ATA:72
	MOS		03-Dec-23						2.3	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.050	ENC		1226						2	
				PROC. REF: AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802						PKG:4
72-40-00-204S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES								Service	ATA:72
	MOS		03-Dec-23						2.3	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.050	ENC		1226						2	
				PROC. REF: AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802						PKG:4
72-40-00-205S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES								Service	ATA:72
	MOS		03-Dec-23						2.3	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 72.055	ENC		1226						2	
				PROC. REF: AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803						PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
72-40-00-205[S]	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES								Service ATA:72
	MOS		03-Dec-23						2.3
	HRS	1000 (+50/-50)	4099.1						2.2
WC#: 72.055	ENC		1226						2
				PROC. REF: AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803					PKG:4
72-50-00-204	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM								Service ATA:72
	MOS							10-Oct-2025	
	HRS	5000 (+50/-50)	0		(5000) 5000	5050	898.7 (+50)		4101.3
WC#: 72.520	ENC								
				PROC. REF: AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801					
72-50-00-204	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM								Service ATA:72
	MOS							10-Oct-2025	
	HRS	5000 (+50/-50)	0		(5000) 5000	5050	898.7 (+50)		4101.3
WC#: 72.520	ENC								
				PROC. REF: AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801					
72-50-00-205	NO. 1 ENGINE - DETAILED INSPECTION OF THE EMERGENCY SHUTDOWNSYSTEM								Service ATA:72
	MOS							10-Oct-2025	
	HRS	5000 (+50/-50)	EFF		(5000) 5000 * (M)	5050	898.7 (+50)		4101.3
	ENC								
				PROC. REF: AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801					
72-50-00-205	NO. 2 ENGINE - DETAILED INSPECTION OF THE EMERGENCY SHUTDOWNSYSTEM								Service ATA:72
	MOS							10-Oct-2025	
	HRS	5000 (+50/-50)	EFF		(5000) 5000 * (M)	5050	898.7 (+50)		4101.3
	ENC								
				PROC. REF: AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
72-71-00-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT								Service	ATA:72
	MOS		19-Mar-21					30-Sep-2026	34.7	
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6	
WC#: 72.060	ENC		1072						156	
				PROC. REF: AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801						PKG:6
72-71-00-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT								Service	ATA:72
	MOS		19-Mar-21					30-Sep-2026	34.7	
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6	
WC#: 72.060	ENC		1072						156	
				PROC. REF: AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801						PKG:6
720001-001	NO. 1 ENGINE - 31 LP COMPRESSOR FAN MODULE								Component	ATA:72
PN:M31-113	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:31101877	HRS		0	TSN 0					4101.3	
WC#: 72.065	ENC		0	TSN 0					1228	
				PROC. REF: EMM 72-31-01, EMM 72-31-01						
720001-001	NO. 2 ENGINE - 31 LP COMPRESSOR FAN MODULE								Component	ATA:72
PN:M31-113	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:31101878	HRS		0	TSN 0					4101.3	
WC#: 72.065	ENC		0	TSN 0					1228	
				PROC. REF: EMM 72-31-01, EMM 72-31-01						
720002-001	NO. 1 ENGINE - 32 INTERMEDIATE CASE MODULE								Component	ATA:72
PN:M32-121	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:32121744	HRS		0	TSN 0					4101.3	
WC#: 72.070	ENC		0	TSN 0					1228	
				PROC. REF: GENERIC NO REF						
720002-001	NO. 2 ENGINE - 32 INTERMEDIATE CASE MODULE								Component	ATA:72
PN:M32-121	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:32121745	HRS		0	TSN 0					4101.3	
WC#: 72.070	ENC		0	TSN 0					1228	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
720003-001	NO. 1 ENGINE - 33 HP COMPRESSOR MODULE								Component ATA:72
PN:M33-114	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:33121746	HRS		0	TSN 0					4101.3
WC#: 72.075	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
720003-001	NO. 2 ENGINE - 33 HP COMPRESSOR MODULE								Component ATA:72
PN:M33-114	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:33121747	HRS		0	TSN 0					4101.3
WC#: 72.075	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
720004-001	NO. 1 ENGINE - 34 LP COMPRESSOR CASE MODULE								Component ATA:72
PN:M34-110	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:34101865	HRS		0	TSN 0					4101.3
WC#: 72.080	ENC		0	TSN 0					1228
				PROC. REF: EMM 72-31-01, EMM 72-31-01					
720004-001	NO. 2 ENGINE - 34 LP COMPRESSOR CASE MODULE								Component ATA:72
PN:M34-110	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:34101866	HRS		0	TSN 0					4101.3
WC#: 72.080	ENC		0	TSN 0					1228
				PROC. REF: EMM 72-31-01, EMM 72-31-01					
720005-001	NO. 1 ENGINE - MODULE 41 - COMBUSTION & HP TURBINE								Component ATA:72
PN:M41-125	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:41121745	HRS		0	TSN 0					4101.3
WC#: 72.085	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
720005-001	NO. 2 ENGINE - MODULE 41 - COMBUSTION & HP TURBINE								Component ATA:72
PN:M41-125	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:41121746	HRS		0	TSN 0					4101.3
WC#: 72.085	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
720006-001	NO. 1 ENGINE - 51 LP TURBINE MODULE								Component ATA:72
PN:M51-111	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:51101865	HRS		0	TSN 0					4101.3
WC#: 72.090	ENC		0	TSN 0					1228
				PROC. REF: EMM 72-31-01, EMM 72-31-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
720006-001	NO. 2 ENGINE - 51 LP TURBINE MODULE								Component ATA:72
PN:M51-111	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:51101866	HRS		0	TSN 0					4101.3
WC#: 72.090	ENC		0	TSN 0					1228
				PROC. REF: EMM 72-31-01, EMM 72-31-01					
720007-001	NO. 1 ENGINE - 61 ACCESSORY GEARBOX MODULE								Component ATA:72
PN:M61-204	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:61121744	HRS		0	TSN 0					4101.3
WC#: 72.095	ENC		0	TSN 0					1228
				PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01					
720007-001	NO. 2 ENGINE - 61 ACCESSORY GEARBOX MODULE								Component ATA:72
PN:M61-204	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:61121745	HRS		0	TSN 0					4101.3
WC#: 72.095	ENC		0	TSN 0					1228
				PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01					
723204-001	NO. 1 ENGINE - NO 3 BEARING								Component ATA:72
PN:BRR22056	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1608	HRS		0	TSN 0					4101.3
WC#: 72.360	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723204-001	NO. 2 ENGINE - NO 3 BEARING								Component ATA:72
PN:BRR22056	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1598	HRS		0	TSN 0					4101.3
WC#: 72.360	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723205-001	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6266	HRS		0	TSN 0					4101.3
WC#: 72.365	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723205-001	NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6258	HRS		0	TSN 0					4101.3
WC#: 72.365	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
723205-002	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6267	HRS		0	TSN 0					4101.3
WC#: 72.370	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723205-002	NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6259	HRS		0	TSN 0					4101.3
WC#: 72.370	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723205-003	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6268	HRS		0	TSN 0					4101.3
WC#: 72.375	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723205-003	NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6260	HRS		0	TSN 0					4101.3
WC#: 72.375	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723205-004	NO. 1 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6269	HRS		0	TSN 0					4101.3
WC#: 72.380	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723205-004	NO. 2 ENGINE - LPC TRIM BALANCE PROBE								Component ATA:72
PN:1022-1-11	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:6261	HRS		0	TSN 0					4101.3
WC#: 72.380	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723206-001	NO. 1 ENGINE - BEARING OUTER RING								Component ATA:72
PN:BRR12474	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1646	HRS		0	TSN 0					4101.3
WC#: 72.385	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
723206-001	NO. 2 ENGINE - BEARING OUTER RING								Component ATA:72
PN:BRR12474	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1644	HRS		0	TSN 0					4101.3
WC#: 72.385	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723206-002	NO. 1 ENGINE - BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.390	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723206-002	NO. 2 ENGINE - BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.390	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723207-001	NO. 1 ENGINE - INNER REAR BEARING								Component ATA:72
PN:BRR23643	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1174	HRS		0	TSN 0					4101.3
WC#: 72.395	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723207-001	NO. 2 ENGINE - INNER REAR BEARING								Component ATA:72
PN:BRR23643	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1384	HRS		0	TSN 0					4101.3
WC#: 72.395	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723208-001	NO. 1 ENGINE - FRONT LPC BEARING								Component ATA:72
PN:BRR24148	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1512	HRS		0	TSN 0					4101.3
WC#: 72.400	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723208-001	NO. 2 ENGINE - FRONT LPC BEARING								Component ATA:72
PN:BRR24148	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1442	HRS		0	TSN 0					4101.3
WC#: 72.400	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
723303-001	NO. 1 ENGINE - ASSEMBLY OF HPC NOZZLE								Component ATA:72
PN:FW32678	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1183	HRS		0	TSN 0					4101.3
WC#: 72.415	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723303-001	NO. 2 ENGINE - ASSEMBLY OF HPC NOZZLE								Component ATA:72
PN:FW32678	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1208	HRS		0	TSN 0					4101.3
WC#: 72.415	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723802-001	NO. 1 ENGINE - NOSE CONE ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.425	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
723802-001	NO. 2 ENGINE - NOSE CONE ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.425	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
725123-001	NO. 1 ENGINE - STUB SHAFT ASSEMBLY								Component ATA:72
PN:BRR40703	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1436	HRS		0	TSN 0					4101.3
WC#: 72.480	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
725123-001	NO. 2 ENGINE - STUB SHAFT ASSEMBLY								Component ATA:72
PN:BRR40703	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1438	HRS		0	TSN 0					4101.3
WC#: 72.480	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
725613-001	NO. 1 ENGINE - REAR MOUNT RING								Component ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 72.490	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
725613-001	NO. 2 ENGINE - REAR MOUNT RING								Component	ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.490	ENC		0	TSN 0					1228	
				PROC. REF: GENERIC NO REF						
726100-001	NO. 1 ENGINE - ACCESSORY GEARBOX								Component	ATA:72
PN:39600221	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:5191	HRS		0	TSN 0					4101.3	
WC#: 72.495	ENC		0	TSN 0					1228	
				PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01						
726100-001	NO. 2 ENGINE - ACCESSORY GEARBOX								Component	ATA:72
PN:39600221	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:5193	HRS		0	TSN 0					4101.3	
WC#: 72.495	ENC		0	TSN 0					1228	
				PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01						
726102-001	NO. 1 ENGINE - GRAVITY OIL FILLER								Component	ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.500	ENC		0	TSN 0					1228	
				PROC. REF: GENERIC NO REF						
726102-001	NO. 2 ENGINE - GRAVITY OIL FILLER								Component	ATA:72
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 72.500	ENC		0	TSN 0					1228	
				PROC. REF: GENERIC NO REF						
AD 1997-325[U]	NO. 1 ENGINE - ENGINE ACCESSORY GEARBOX - REMOVAL OF NON-CONFORMING PARTS FORM APT GEARBOXES								AD	ATA:72
	MOS/MSC	-	08-Jun-09						176.1	
	HRS									
	ENC									
AD 1997-325[U]	NO. 2 ENGINE - ENGINE ACCESSORY GEARBOX - REMOVAL OF NON-CONFORMING PARTS FORM APT GEARBOXES								AD	ATA:72
	MOS/MSC	-	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
AD 2000-348 REV 5[U]	NO. 1 ENGINE - LP COMPRESSOR INSPECTION OF THE FAN DISK FOR CRACKS								AD	ATA:72
	MOS/MSC	-	28-Jun-09						175.5	
	HRS									
	ENC									
AD 2000-348 REV 5[U]	NO. 2 ENGINE - LP COMPRESSOR INSPECTION OF THE FAN DISK FOR CRACKS								AD	ATA:72
	MOS/MSC	-	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	
ASB A700-72-003	REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-72-003 REV 01	ICA - REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	AFL									
ASB A700-72-003 REV 02	ICA - REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
ASB BR700-72-A101523 R03	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	
ASB BR700-72-A101523 R03	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900229 R07	NO. 1 ENGINE - BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900229 R07	NO. 2 ENGINE - BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900229 R07 PART 1	NO. 1 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO A VISUAL INSPECTION OF THE FAN DISC.								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900229 R07 PART 1	NO. 2 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO A VISUAL INSPECTION OF THE FAN DISC.								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900229 R07 PART 2	NO. 1 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO AN ULTRASONIC INSPECTION OF THE FAN DISC.								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900229 R07 PART 2	NO. 2 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO AN ULTRASONIC INSPECTION OF THE FAN DISC.								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900297	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS		EFF						
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900297	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS		EFF						
	ENC								
ASB BR700-72-A900298	NO. 1 ENGINE - ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS		EFF						
	ENC								
ASB BR700-72-A900298	NO. 2 ENGINE - ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS		EFF						
	ENC								
ASB BR700-72-A900298 R01	NO. 1 ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900298 R01	NO. 2 ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900497	NO. 1 ENGINE - HPT ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN								Bulletin ATA:72
	DAYS/MSC	-	25-Nov-10						4826 d
	HRS								
	ENC								
ASB BR700-72-A900497	NO. 2 ENGINE - HPT ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN								Bulletin ATA:72
	DAYS/MSC	-	25-Nov-10						4826 d
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900497 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF THE HP TURBINE STAGE 1 AND STAGE 2 DISCS - NON-MODIFICATION (CANCELLED), ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900497 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF THE HP TURBINE STAGE 1 AND STAGE 2 DISCS - NON-MODIFICATION (CANCELLED), ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900504	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	25-Nov-10						158.5
	HRS								
	ENC								
ASB BR700-72-A900504	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	25-Nov-10						158.5
	HRS								
	ENC								
ASB BR700-72-A900504 R01	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN								Bulletin ATA:72
	DAYS/MSC	-	14-Feb-11						4745 d
	HRS		7.4						4093.9
	ENC		4						1224
ASB BR700-72-A900504 R01	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN								Bulletin ATA:72
	DAYS/MSC	-	14-Feb-11						4745 d
	HRS		7.4						4093.9
	ENC		4						1224
ASB BR700-72-A900508	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	15-Aug-12						137.9
	HRS		578						3523.3
	ENC		219						1009

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900508	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	15-Aug-12						137.9
	HRS		578						3523.3
	ENC		219						1009
ASB BR700-72-A900508 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900508 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900509	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900509	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900509 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900509 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900509 R02	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS		EFF						
	ENC								
ASB BR700-72-A900509 R02	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS		EFF						
	ENC								
ASB BR700-72-A900509 R03	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900509 R03	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900509 R04	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	ENC		1072						156
ASB BR700-72-A900509 R04	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	19-Mar-21						34.7
	HRS		3474.7						626.6
	ENC		1072						156
ASB BR700-72-A900556 R02	NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR SPECIAL FLIGHT PROFILE - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900556 R02	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR SPECIAL FLIGHT PROFILE - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900584	NO. 1 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	03-Mar-17						83.3
	HRS								
	ENC								
ASB BR700-72-A900584	NO. 2 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	03-Mar-17						83.3
	HRS								
	ENC								
ASB BR700-72-A900584 R01	NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	31-Oct-17						75.4
	HRS		2595.4						1505.9
	ENC		865						363
ASB BR700-72-A900584 R01	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	31-Oct-17						75.4
	HRS		2595.4						1505.9
	ENC		865						363
ASB BR700-72-A900584 R01 PART A	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION								Bulletin ATA:72
	DAYS/MSC	-	31-Oct-17						2294 d
	HRS		2595.4						1505.9
	ENC		865						363

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900584 R01 PART A	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION								Bulletin ATA:72
	DAYS/MSC	-	31-Oct-17						2294 d
	HRS		2595.4						1505.9
	ENC		865						363
ASB BR700-72-A900584 R01 PART B	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED								Bulletin ATA:72
	MOS/MSC	-	31-Oct-17						75.4
	HRS		2595.4						1505.9
	ENC		865						363
ASB BR700-72-A900584 R01 PART B	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED								Bulletin ATA:72
	MOS/MSC	-	31-Oct-17						75.4
	HRS		2595.4						1505.9
	ENC		865						363
ASB BR700-72-A900584 R02	NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900584 R02	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900584 R02 PART A	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION								Bulletin ATA:72
	DAYS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900584 R02 PART A	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION								Bulletin ATA:72
	DAYS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900584 R02 PART B	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900584 R02 PART B	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900659	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900659	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900659 PART A	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900659 PART A	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900659 PART B	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900659 PART B	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-72-A900659 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	19-Aug-21						29.7
	HRS		3633.5						467.8
	ENC		1107						121

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
ASB BR700-72-A900659 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	19-Aug-21						29.7
	HRS		3633.5						467.8
	ENC		1107						121
ASB BR700-72-A900659 R01 PART A	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON -MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	19-Aug-21						29.7
	HRS		3633.5						467.8
	ENC		1107						121
ASB BR700-72-A900659 R01 PART A	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON -MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	19-Aug-21						29.7
	HRS		3633.5						467.8
	ENC		1107						121
ASB BR700-72-A900659 R01 PART B	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON -MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS								Bulletin ATA:72
	MOS/MSC	-	19-Aug-21						29.7
	HRS		3633.5						467.8
	ENC		1107						121
ASB BR700-72-A900659 R01 PART B	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON -MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS								Bulletin ATA:72
	MOS/MSC	-	19-Aug-21						29.7
	HRS		3633.5						467.8
	ENC		1107						121
ASB BR700-72-A900732	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - VISUAL INSPECTION OF THE LP COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
ASB BR700-72-A900732	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - VISUAL INSPECTION OF THE LP COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
ASB BR700-72-A900732 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - VISUAL INSPECTION OF THE LP - COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
ASB BR700-72-A900732 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - VISUAL INSPECTION OF THE LP - COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
EASA 2010-0075	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION								AD	ATA:72
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	ENC		4						1224	
EASA 2010-0075	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION								AD	ATA:72
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	ENC		4						1224	
EASA 2010-0077	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT								AD	ATA:72
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	ENC		4						1224	
EASA 2010-0077	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT								AD	ATA:72
	MOS/MSC	-	14-Feb-11						155.9	
	HRS		7.4						4093.9	
	ENC		4						1224	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
FAA 1998-24-03 R01	NO. 1 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
FAA 1998-24-03 R01	NO. 2 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2001-05-06 ULTRASONIC INSP	NO. 1 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	N/A	08-Jun-09						176.1	
	HRS									
	ENC									
FAA 2001-05-06 ULTRASONIC INSP	NO. 2 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	N/A	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2001-05-06 VISUAL INSP	NO. 1 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	N/A	08-Jun-09						176.1	
	HRS									
	ENC									
FAA 2001-05-06 VISUAL INSP	NO. 2 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	N/A	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2003-07-11 PART B	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	-	08-Jun-09						176.1	
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
FAA 2003-07-11 PART B	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	-	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2003-07-11 PART F	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	-	08-Jun-09						176.1	
	HRS									
	ENC									
FAA 2003-07-11 PART F	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS								AD	ATA:72
	MOS/MSC	-	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2005-21-05 PART 1	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE FAN DISC								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
FAA 2005-21-05 PART 1	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE FAN DISC								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2005-21-05 PART 2	NO. 1 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
FAA 2005-21-05 PART 2	NO. 2 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2005-21-05 PART L	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER 05-10-01 (BR700-710A2-20).								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
FAA 2005-21-05 PART L	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER 05-10-01 (BR700-710A2-20).								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
FAA 2010-25-05	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2ASSEMBLY LIFE LIMITS - MODIFICATION								AD	ATA:72
	DAYS/MSC	-	14-Feb-11						4745 d	
	HRS		7.4						4093.9	
	ENC		4						1224	
FAA 2010-25-05	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2ASSEMBLY LIFE LIMITS - MODIFICATION								AD	ATA:72
	DAYS/MSC	-	14-Feb-11						4745 d	
	HRS		7.4						4093.9	
	ENC		4						1224	
FAA 2011-22-01	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT								AD	ATA:72
	MOS/MSC	-	03-Nov-11						147.3	
	HRS		227.8						3873.5	
	ENC		103						1125	
FAA 2011-22-01	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT								AD	ATA:72
	MOS/MSC	-	03-Nov-11						147.3	
	HRS		227.8						3873.5	
	ENC		103						1125	
FAA 2011-22-01 (E) (1), (2)	NO. 1 ENGINE - REVISE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM (REFERENCE THE TIME LIMITS MANUAL (TLM), CHAPTERS 05-00-01 AND 05-00-02 OF THE APPLICABLE ENGINE MANUALS (EMS))								AD	ATA:72
	DAYS/MSC	-	03-Nov-11						4483 d	
	HRS		227.8						3873.5	
	ENC		103						1125	
FAA 2011-22-01 (E) (1), (2)	NO. 2 ENGINE - REVISE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM (REFERENCE THE TIME LIMITS MANUAL (TLM), CHAPTERS 05-00-01 AND 05-00-02 OF THE APPLICABLE ENGINE MANUALS (EMS))								AD	ATA:72
	DAYS/MSC	-	03-Nov-11						4483 d	
	HRS		227.8						3873.5	
	ENC		103						1125	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
FAA 2011-22-01 PARA (E) (3)	NO. 1 ENGINE - DETERMINE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOOTS THAT EACH INDIVIDUAL CRITICAL PART EXCEPT THE FAN SHAFT AND LP TURBINE ROTOR SHAFT HAS EXPERIENCED SINCE ENTRY INTO SERVICE FOR PILOT TRAINING								AD	ATA:72
	DAYS/MSC	-	03-Nov-11						4483 d	
	HRS		227.8						3873.5	
	ENC		103						1125	
FAA 2011-22-01 PARA (E) (3)	NO. 2 ENGINE - DETERMINE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOOTS THAT EACH INDIVIDUAL CRITICAL PART EXCEPT THE FAN SHAFT AND LP TURBINE ROTOR SHAFT HAS EXPERIENCED SINCE ENTRY INTO SERVICE FOR PILOT TRAINING								AD	ATA:72
	DAYS/MSC	-	03-Nov-11						4483 d	
	HRS		227.8						3873.5	
	ENC		103						1125	
FAA 2013-03-17	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION								AD	ATA:72
	MOS/MSC	-	07-Mar-13						131.1	
	HRS		850.3						3251	
	ENC		335						893	
FAA 2013-03-17	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION								AD	ATA:72
	MOS/MSC	-	07-Mar-13						131.1	
	HRS		850.3						3251	
	ENC		335						893	
FAA 2013-05-13	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING (SUPERSEDED BY FAA AD 2022-26-02)								AD	ATA:72
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	ENC		1072						156	
FAA 2013-05-13	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING (SUPERSEDED BY FAA AD 2022-26-02)								AD	ATA:72
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	ENC		1072						156	
FAA 2016-13-12	NO. 1 ENGINE - ENGINE - PAWL CARRIER PIVOT PINS, PART NUMBER (P/N) BRR17117, - REMOVE FROM SERVICE / REPLACE								AD	ATA:72
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
FAA 2016-13-12	NO. 2 ENGINE - ENGINE - PAWL CARRIER PIVOT PINS, PART NUMBER (P/N) BRR17117, - REMOVE FROM SERVICE / REPLACE								AD	ATA:72
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	
FAA 2016-25-18	ENGINE - INSPECTION FOR DISCREPANCIES OF THE ENGINE REAR MOUNT ASSEMBLIES AND REPLACE MISSING PARTS IF ANY DISCREPANCY IS DETECTED (INCLUDING MISSING OR BROKEN BOLTS, MISSING NUTS, INCORRECT TORQUE VALUES, AND AN INCORRECT GAP BETWEEN THE BUSHING AND WASHER) (SUPERSEDED BY FAA AD 2018-09-15)								AD	ATA:72
	MOS/MSC	-	22-Dec-16						85.6	
	HRS		2265.8						1835.5	
	AFL		770						455	
FAA 2018-09-15	ENGINE - REAR MOUNT RETAINING BOLT FAILURE								AD	ATA:72
	MOS/MSC	-	08-Jun-18						68.1	
	HRS		2892.3						1209	
	AFL		921						304	
FAA 2018-09-15 PARA (G)	INSPECTION FOR DISCREPANCIES OF THE ENGINE REAR MOUNT ASSEMBLIES (INCLUDING MISSING OR BROKEN BOLTS, MISSING NUTS, INCORRECT TORQUE VALUES, AND AN INCORRECT GAP BETWEEN THE BUSHING AND WASHER) AND REPLACE MISSING PARTS AND CORRECT NONCOMPLIANT GAPS AND BOLT TORQUE (IF ANY DISCREPANCY IS DETECTED DURING THE INSPECTION REQUIRED BY PARA (G)) (THIS PARA RESTATES THE REQUIREMENTS OF PARA (G) OF AD 2016-25-18, WITH NO CHANGES)								AD	ATA:72
	MOS/MSC	-	08-Jun-18						68.1	
	HRS		2892.3						1209	
	AFL		921						304	
FAA 2018-09-15 PARA (J)	MEASURE THE GAPS BETWEEN THE APPLICABLE SHOULDERED BUSHING FITTED ON THE MOUNT BEAM AND THE WASHER; AND BETWEEN THE APPLICABLE ENGINE RING LUG AND THE HEAD OF THE MOUNT PIN TO DETERMINE IF THE GAPS ARE WITHIN ACCEPTABLE LIMITS AND REPAIR (IF ANY GAP IS DETECTED, DURING ANY MEASUREMENT REQUIRED BY PARA (J) / (K), THAT IS NOT WITHIN THE APPLICABLE LIMITS SPECIFIED IN THE SERVICE INFORMATION SPECIFIED IN PARAS (J)(1) THRU (J)(4))								AD	ATA:72
	MOS/MSC	-	08-Jun-18						68.1	
	HRS		2892.3						1209	
	AFL		921						304	
FAA 2018-09-15 PARA (K)	REPLACE THE NUTS HAVING P/N AS54365 AND THE BOLTS HAVING P/N AS54020 AND AS54002 IN THE ENGINE REAR MOUNT ASSEMBLY WITH NEW NUTS AND NEW BOLTS; AND DO THE GAP MEASUREMENT TO DETERMINE IF THE GAP IS WITHIN ACCEPTABLE LIMITS AND REPAIR (IF ANY GAP IS DETECTED, DURING ANY MEASUREMENT REQUIRED BY PARA (J) / (K), THAT IS NOT WITHIN THE APPLICABLE LIMITS SPECIFIED IN THE SERVICE INFORMATION SPECIFIED IN PARAS (J)(1) THRU (J)(4))								AD	ATA:72
	MOS/MSC	-	08-Jun-18						68.1	
	HRS		2892.3						1209	
	AFL		921						304	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
FAA 2021-12-07	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) STAGE 1 DISK - REPLACE								AD	ATA:72
	MOS/MSC	-	19-Aug-21						29.7	
	HRS		3633.5						467.8	
	ENC		1107						121	
FAA 2021-12-07	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) STAGE 1 DISK - REPLACE								AD	ATA:72
	MOS/MSC	-	19-Aug-21						29.7	
	HRS		3633.5						467.8	
	ENC		1107						121	
FAA 2021-21-12	NO. 1 ENGINE - TURBINE ENGINE COMPRESSOR SECTION - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT								AD	ATA:72
	MOS/MSC	-	17-Jan-22						24.8	
	HRS		3689.6						411.7	
	ENC		1120						108	
FAA 2021-21-12	NO. 2 ENGINE - TURBINE ENGINE COMPRESSOR SECTION - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT								AD	ATA:72
	MOS/MSC	-	17-Jan-22						24.8	
	HRS		3689.6						411.7	
	ENC		1120						108	
FAA 2021-21-12 PARA (G)(1)	NO. 1 ENGINE - RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP								AD	ATA:72
	DAYS/MSC	-	17-Jan-22						755 d	
	HRS		3689.6						411.7	
	ENC		1120						108	
FAA 2021-21-12 PARA (G)(1)	NO. 2 ENGINE - RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP								AD	ATA:72
	DAYS/MSC	-	17-Jan-22						755 d	
	HRS		3689.6						411.7	
	ENC		1120						108	
FAA 2021-21-12 PARA (C[S])(2)	NO. 1 ENGINE - CALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP (FOR ENGINES INSTALLED AND OPERATED ON A PRE-MOD AIRPLANE, AFTER PERFORMING THE INITIAL RECALCULATIONS REQUIRED BY PARA (G)(1))								AD	ATA:72
	MOS/MSC	BF/F	17-Jan-22						24.8	
	HRS		3689.6						411.7	
	ENC		1120						108	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
FAA 2021-21-12 PARA (G[S]) (2)	NO. 2 ENGINE - CALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP (FOR ENGINES INSTALLED AND OPERATED ON A PRE-MOD AIRPLANE, AFTER PERFORMING THE INITIAL RECALCULATIONS REQUIRED BY PARA (G)(1))								AD	ATA:72
	MOS/MSC	BF/F	17-Jan-22						24.8	
	HRS		3689.6						411.7	
	ENC		1120						108	
FAA 2021-21-12 PARA (G) (3)	NO. 1 ENGINE - REMOVE EACH AFFECTED LLP								AD	ATA:72
	DAYS/MSC	-	17-Jan-22						755 d	
	HRS		3689.6						411.7	
	ENC		1120						108	
FAA 2021-21-12 PARA (G) (3)	NO. 2 ENGINE - REMOVE EACH AFFECTED LLP								AD	ATA:72
	DAYS/MSC	-	17-Jan-22						755 d	
	HRS		3689.6						411.7	
	ENC		1120						108	
FAA 2022-24-06	NO. 1 ENGINE - ENGINE - LOW PRESSURE COMPRESSOR ROTOR (FAN) DISC - INSPECTION								AD	ATA:72
	DAYS/MSC	-	22-Dec-22						416 d	
	HRS		3913.7						187.6	
	ENC		1174						54	
FAA 2022-24-06	NO. 2 ENGINE - ENGINE - LOW PRESSURE COMPRESSOR ROTOR (FAN) DISC - INSPECTION								AD	ATA:72
	DAYS/MSC	-	22-Dec-22						416 d	
	HRS		3913.7						187.6	
	ENC		1174						54	
LBA D-2000-348 REV 6 [U] PART 4	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSP FAN DISC, P/N BRR20791								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
LBA D-2000-348 REV 6 [U] PART 4	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSP FAN DISC, P/N BRR20791								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
LBA D-2000-348 REV 6 U PART 5	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
LBA D-2000-348 REV 6 U PART 5	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS								AD	ATA:72
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
SB BR700-72-100044 R03	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-72-100044 R03	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-72-100207 R03	NO. 1 ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-72-100207 R03	NO. 2 ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-72-100263 R01	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-100263 R01	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100266 R01	NO. 1 ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LOW PRESSURE (LP) TURBINE EXHAUST CASE FUEL SHUT-OFF EXIT RADIUS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100266 R01	NO. 2 ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LOW PRESSURE (LP) TURBINE EXHAUST CASE FUEL SHUT-OFF EXIT RADIUS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100296 R01	NO. 1 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO.2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100296 R01	NO. 2 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO.2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100561 R01	NO. 1 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF TRANSPORTATION PARTS FOR THE INTERMEDIATE CASE MODULE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-100561 R01	NO. 2 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF TRANSPORTATION PARTS FOR THE INTERMEDIATE CASE MODULE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100563 R01	NO. 1 ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-72-100563 R01	NO. 2 ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-72-100741 R02	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF PART NUMBERS OF SPAREABLE ITEMS OF THE APT GEARBOX THAT MAY BE REPLACED ON AIRCRAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100741 R02	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF PART NUMBERS OF SPAREABLE ITEMS OF THE APT GEARBOX THAT MAY BE REPLACED ON AIRCRAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100746 R01	NO. 1 ENGINE - ACCESSORY GEARBOX - RE-ITEMIZATION OF THE ACCESSORY GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-100746 R01	NO. 2 ENGINE - ACCESSORY GEARBOX - RE-ITEMIZATION OF THE ACCESSORY GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-100879 R01	NO. 1 ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-72-100879 R01	NO. 2 ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-72-100900 R01	NO. 1 ENGINE - HP COMPRESSOR AND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS								
	ENC								
SB BR700-72-100900 R01	NO. 2 ENGINE - HP COMPRESSOR AND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-100914 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF A NEW PROCEDURE FOR MANUFACTURE OF THE HP TURBINE STAGE 2 BLADES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-72-100914 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF A NEW PROCEDURE FOR MANUFACTURE OF THE HP TURBINE STAGE 2 BLADES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-72-101117 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101117 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101139 R01	NO. 1 ENGINE - HPC ROTOR SHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	03-Nov-09						171.3
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101139 R01	NO. 2 ENGINE - HPC ROTOR SHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	05-Nov-09						171.2
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101195 R01	NO. 1 ENGINE - INTRODUCTION OF AN INTERMEDIATE CASE MANUFACTURED FROM A NEW CASTING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101195 R01	NO. 2 ENGINE - INTRODUCTION OF AN INTERMEDIATE CASE MANUFACTURED FROM A NEW CASTING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101197 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101197 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101218 R01	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101218 R01	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101222	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101222	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101234 R02	NO. 1 ENGINE - LOW PRESSURE/HIGH PRESSURE (LP/HP) TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF REWORKED REAR BEARING SUPPORT STRUCTURES (RBSS) OF EARLIER STANDARDS, REWORKED HP AND LP TURBINE BEARING RETAINERS AND NEW STAGE 4 AIR TUBES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-72-101234 R02	NO. 2 ENGINE - LOW PRESSURE/HIGH PRESSURE (LP/HP) TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF REWORKED REAR BEARING SUPPORT STRUCTURES (RBSS) OF EARLIER STANDARDS, REWORKED HP AND LP TURBINE BEARING RETAINERS AND NEW STAGE 4 AIR TUBES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101246 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101246 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101258 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101258 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101260 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101260 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101326	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101326	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101326 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101326 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101419 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	06-Jun-09						176.2
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101419 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101419 R02	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	10-Apr-12						142
	HRS		431.8						3669.5
	ENC		157						1071
SB BR700-72-101419 R02	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	10-Apr-12						142
	HRS		431.8						3669.5
	ENC		157						1071

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101436 R02	NO. 1 ENGINE - RE-SOURCING LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101436 R02	NO. 2 ENGINE - RE-SOURCING LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101440	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101440	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101453 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR STATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101453 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR STATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101469 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101469 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101471	NO. 1 ENGINE - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-101471	NO. 2 ENGINE - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-101471 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A	06-Jun-09						176.2
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101471 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101471 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-72-101471 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	A/R							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101473	NO. 1 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-101473	NO. 2 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-101473 R01	NO. 1 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-101473 R01	NO. 2 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-101473 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF DRY FLIM LUBIRCANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-72-101473 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF DRY FLIM LUBIRCANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-72-101474	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101474	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101474 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101474 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101474 R01 PART 1	NO. 1 ENGINE - REIDENTIFICATION LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN OF A NON-FLOWN LP COMPRESSOR ROTOR DISC								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101474 R01 PART 1	NO. 2 ENGINE - REIDENTIFICATION LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN OF A NON-FLOWN LP COMPRESSOR ROTOR DISC								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101474 R01 PART 2	NO. 1 ENGINE - REMOVAL LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN AND INSTALLATION OF THE LP COMPRESSOR ROTOR DISC								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101474 R01 PART 2	NO. 2 ENGINE - REMOVAL LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN AND INSTALLATION OF THE LP COMPRESSOR ROTOR DISC								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101476 R01	NO. 1 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101476 R01	NO. 2 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101476 R02	NO. 1 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101476 R02	NO. 2 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101498	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIER PART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101498	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIER PART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101500	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-72-101500	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-72-101523 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101523 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101523 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:ESV							
	HRS								
	ENC								
SB BR700-72-101523 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:ESV							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101526	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101526	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101527	NO. 1 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIR TURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101527	NO. 2 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIR TURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101538	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - INTRODUCTION OF A DIFFERENT STANDARD OF HP COMPRESSOR REAR INNER CASES STAGES 5 TO 10, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101538	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - INTRODUCTION OF A DIFFERENT STANDARD OF HP COMPRESSOR REAR INNER CASES STAGES 5 TO 10, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101540	NO. 1 ENGINE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101540	NO. 2 ENGINE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101540 R02	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101540 R02	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101540 R03	NO. 1 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101540 R03	NO. 2 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101540 R04	NO. 1 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101540 R04	NO. 2 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101549	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - REWORK OF IN-SERVICE LP COMPRESSOR BLADES TO APPLY METCO 58 COATING ON THE BLADE ROOT FLANK, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101549	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - REWORK OF IN-SERVICE LP COMPRESSOR BLADES TO APPLY METCO 58 COATING ON THE BLADE ROOT FLANK, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101573	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR - INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101573	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR - INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101580	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101580	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101584	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BLACK OXIDE TREATMENT FROM THE LINE 1 BEVEL GEAR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101584	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BLACK OXIDE TREATMENT FROM THE LINE 1 BEVEL GEAR ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101618	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101618	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101623	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FOR THE ACCESSORY GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101623	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FOR THE ACCESSORY GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101663	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101663	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101664 R02	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO.2 BEARING SUPPORT HOUSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	03-Nov-09						171.3
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101664 R02	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO.2 BEARING SUPPORT HOUSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	05-Nov-09						171.2
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-101699	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101699	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101705	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR ROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-72-101705	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR ROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-72-101722	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101722	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101728	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101728	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101731	NO. 1 ENGINE - ENGINE - BYPASS SERVICE FAIRING - INTRODUCTION OF ALTERNATIVE SPLITTER FAIRING ASSEMBLY RIVETS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101731	NO. 2 ENGINE - ENGINE - BYPASS SERVICE FAIRING - INTRODUCTION OF ALTERNATIVE SPLITTER FAIRING ASSEMBLY RIVETS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101734	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101734	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101734 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101734 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101757	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW ALTERNATIVE HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A MORE ROBUST DESIGN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101757	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW ALTERNATIVE HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A MORE ROBUST DESIGN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101774	NO. 1 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101774	NO. 2 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101794	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101794	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101805 R02	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101805 R02	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101805 R03	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101805 R03	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101805 R04	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	30-Apr-21						33.4
	HRS		3533.7						567.6
	ENC		1085						143
SB BR700-72-101805 R04	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	30-Apr-21						33.4
	HRS		3533.7						567.6
	ENC		1085						143

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101813	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA (SUPERSEDED BY SB BR700-72-101971), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101813	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA (SUPERSEDED BY SB BR700-72-101971), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101817	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FOR INSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101817	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FOR INSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101817 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FOR INSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101817 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FOR INSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101837	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INTRODUCTION OF AN HP TURBINE STAGE 1 DISC MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101837	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INTRODUCTION OF AN HP TURBINE STAGE 1 DISC MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101855	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR FRONT CASE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101855	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR FRONT CASE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 1	NO. 1 ENGINE - REPLACEMENT HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY (P/N BRR24357) WITH THE NEW HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY (P/N KH41254 OR P/N KH45069)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101858 PART 1	NO. 2 ENGINE - REPLACEMENT HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY (P/N BRR24357) WITH THE NEW HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY (P/N KH41254 OR P/N KH45069)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 2	NO. 1 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR24357) TO THE NEW STANDARD (P/N KH43396)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 2	NO. 2 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR24357) TO THE NEW STANDARD (P/N KH43396)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 3	NO. 1 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25673) TO THE NEW STANDARD (P/N KH43119)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 3	NO. 2 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25673) TO THE NEW STANDARD (P/N KH43119)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 4	NO. 1 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25671) TO THE NEW STANDARD (P/N KH43077)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101858 PART 4	NO. 2 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25671) TO THE NEW STANDARD (P/N KH43077)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 5	NO. 1 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25672) TO THE NEW STANDARD (P/N KH43108)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 5	NO. 2 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25672) TO THE NEW STANDARD (P/N KH43108)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 6	NO. 1 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25670) TO THE NEW STANDARD (P/N KH43066)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 PART 6	NO. 2 ENGINE - REWORK HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD (P/N BRR25670) TO THE NEW STANDARD (P/N KH43066)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101858 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101858 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101880	NO. 1 ENGINE - BYPASS DUCT - INTRODUCTION OF A WEIGHT REDUCED BYPASS DUCT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101880	NO. 2 ENGINE - BYPASS DUCT - INTRODUCTION OF A WEIGHT REDUCED BYPASS DUCT ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101881	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101881	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101884	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR OUTER CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR REAR OUTER CASE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101884	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR OUTER CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR REAR OUTER CASE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101887	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR MODULE - INTRODUCTION OF INCREASED TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 6 TO 9 STATOR VANES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101887	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR MODULE - INTRODUCTION OF INCREASED TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 6 TO 9 STATOR VANES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101888	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING WITH A REVISED PRESSURE RELIEF VALVE (PRV) PORT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101888	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING WITH A REVISED PRESSURE RELIEF VALVE (PRV) PORT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101890 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R01 PART 1	NO. 1 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R01 PART 1	NO. 2 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R01 PART 2	NO. 1 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R01 PART 2	NO. 2 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R02	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101890 R02	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R02 PART 1	NO. 1 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R02 PART 1	NO. 2 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R02 PART 2	NO. 1 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R02 PART 2	NO. 2 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R03	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101890 R03	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R03 PART 1	NO. 1 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223) (APPLICABLE FOR ENGINES WHICH HAVE THE SB-BR700-72-101888 STANDARD INCORPORATED)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R03 PART 1	NO. 2 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223) (APPLICABLE FOR ENGINES WHICH HAVE THE SB-BR700-72-101888 STANDARD INCORPORATED)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R03 PART 2	NO. 1 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224) (APPLICABLE FOR ENGINES WHICH HAVE THE SB-BR700-72-101623 STANDARD INCORPORATED)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101890 R03 PART 2	NO. 2 ENGINE - ACCOMPLISH ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224) (APPLICABLE FOR ENGINES WHICH HAVE THE SB-BR700-72-101623 STANDARD INCORPORATED)								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101893	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101893	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101893 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101893 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101895	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INTRODUCTION OF A NEW FAIRING PANEL (CHANNEL) WITH ADJUSTED DIMENSIONS AND DELETED BLANKING PLATE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101895	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INTRODUCTION OF A NEW FAIRING PANEL (CHANNEL) WITH ADJUSTED DIMENSIONS AND DELETED BLANKING PLATE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101897	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF AN ALTERNATIVE STANDARD OF HP COMPRESSOR STAGE 1 BLADE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101897	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF AN ALTERNATIVE STANDARD OF HP COMPRESSOR STAGE 1 BLADE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101901	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101901	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101901 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF NEW HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101901 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF NEW HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101908	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A DECREASED OUTER DIAMETER TO PROVIDE AN INCREASED SQUEEZE FILM DAMPER GAP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101908	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A DECREASED OUTER DIAMETER TO PROVIDE AN INCREASED SQUEEZE FILM DAMPER GAP, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101909	NO. 1 ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF ALTERNATIVE REAR MOUNT SUPPORT STRUTS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101909	NO. 2 ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF ALTERNATIVE REAR MOUNT SUPPORT STRUTS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101911	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF SILVER-FREE NUTS AT THE HP COMPRESSOR FRONT DRUM TO REAR DRUM JOINT FLANGE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101911	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF SILVER-FREE NUTS AT THE HP COMPRESSOR FRONT DRUM TO REAR DRUM JOINT FLANGE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101916	NO. 1 ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A REVISED NL SPEED PROBE HARNESS ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101916	NO. 2 ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A REVISED NL SPEED PROBE HARNESS ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101917	NO. 1 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF ALTERNATIVE BEARING ASSEMBLIES FOR THE RADIAL DRIVE SHAFT (RDS), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101917	NO. 2 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF ALTERNATIVE BEARING ASSEMBLIES FOR THE RADIAL DRIVE SHAFT (RDS), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101922	NO. 1 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW ALTERNATIVE LOCK NUT ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101922	NO. 2 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW ALTERNATIVE LOCK NUT ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101931	NO. 1 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDIATE CASE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101931	NO. 2 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDIATE CASE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101931 R01	NO. 1 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDIATE CASE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101931 R01	NO. 2 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDIATE CASE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101933	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 7 TO 10 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101933	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 7 TO 10 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101934	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101934	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101934 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101934 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101937	NO. 1 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - DELETION OF THE BEVEL WHEEL SHIELD FROM THE INTERNAL GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101937	NO. 2 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - DELETION OF THE BEVEL WHEEL SHIELD FROM THE INTERNAL GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101939	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR STATIC AND BEARING SEALS - INTRODUCTION OF AN INTEGRATED INTERNAL GEARBOX FRONT BUFFER SEAL ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101939	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR STATIC AND BEARING SEALS - INTRODUCTION OF AN INTEGRATED INTERNAL GEARBOX FRONT BUFFER SEAL ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101940	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 2 TO 6 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101940	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 2 TO 6 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101946	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE ROTOR SHAFT - INTRODUCTION OF AN ALTERNATIVE LP TURBINE SHAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101946	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE ROTOR SHAFT - INTRODUCTION OF AN ALTERNATIVE LP TURBINE SHAFT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101947	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLIES AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANE (VSV) ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101947	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLIES AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANE (VSV) ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101949	NO. 1 ENGINE - COMBUSTION FRONT INNER CASE AND VANES - INTRODUCTION OF AN ALTERNATIVE COMBUSTION FRONT INNER CASING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101949	NO. 2 ENGINE - COMBUSTION FRONT INNER CASE AND VANES - INTRODUCTION OF AN ALTERNATIVE COMBUSTION FRONT INNER CASING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101952	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF AN LP COMPRESSOR ROTOR DISC PRODUCED IN ACCORDANCE WITH A DIFFERENT MANUFACTURING PROCESS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101952	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF AN LP COMPRESSOR ROTOR DISC PRODUCED IN ACCORDANCE WITH A DIFFERENT MANUFACTURING PROCESS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101953	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101953	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101959	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE CASE - INTRODUCTION OF A NEW HP TURBINE CASE ASSEMBLY WITH A MODIFIED FRONT HOOK TO AXIALLY POSITION THE SEAL STRIPS FOR THE HP TURBINE STAGE 1 LINERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101959	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE CASE - INTRODUCTION OF A NEW HP TURBINE CASE ASSEMBLY WITH A MODIFIED FRONT HOOK TO AXIALLY POSITION THE SEAL STRIPS FOR THE HP TURBINE STAGE 1 LINERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101960	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE VANES (NGV) AND LINERS - INTRODUCTION OF MODIFIED HP TURBINE STAGE 2 NGV ASSEMBLIES AND LINER ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101960	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE VANES (NGV) AND LINERS - INTRODUCTION OF MODIFIED HP TURBINE STAGE 2 NGV ASSEMBLIES AND LINER ASSEMBLIES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101964	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE CASE IMPINGEMENT COOLING MANIFOLD, LOW PRESSURE (LP) TURBINE FAIRINGS AND BYPASS DUCT - INTRODUCTION OF ALTERNATIVE RIVETS FOR THE HP TURBINE COOLING MANIFOLD, THE LP TURBINE FAIRINGS AND THE INTRASCOPE BLANKS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101964	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE CASE IMPINGEMENT COOLING MANIFOLD, LOW PRESSURE (LP) TURBINE FAIRINGS AND BYPASS DUCT - INTRODUCTION OF ALTERNATIVE RIVETS FOR THE HP TURBINE COOLING MANIFOLD, THE LP TURBINE FAIRINGS AND THE INTRASCOPE BLANKS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101969	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR SHAFT - INTRODUCTION OF A NEW FAN SHAFT ASSEMBLY WITH AN ADDITIONAL INSPECTION METHOD DURING THE MANUFACTURING PROCESS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-101969	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR SHAFT - INTRODUCTION OF A NEW FAN SHAFT ASSEMBLY WITH AN ADDITIONAL INSPECTION METHOD DURING THE MANUFACTURING PROCESS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101971	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS MANUFACTURED IN ACCORDANCE WITH AN UPDATED MACHINING PROCESS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101971	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS MANUFACTURED IN ACCORDANCE WITH AN UPDATED MACHINING PROCESS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101990	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REVISED ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY WITH A NEW DEFINITION FOR HOLE DIMENSIONS AND ASSOCIATED MATCHING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-101990	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REVISED ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY WITH A NEW DEFINITION FOR HOLE DIMENSIONS AND ASSOCIATED MATCHING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102038	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX AIR DISTRIBUTION TUBES - INTRODUCTION OF A NEW AIR MANIFOLD HOUSING MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102038	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX AIR DISTRIBUTION TUBES - INTRODUCTION OF A NEW AIR MANIFOLD HOUSING MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-102098	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF ALTERNATIVE DRAIN PLUGS AT THE ENGINE OIL TANK DRAIN LOCATION OF THE ACCESSORY GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102098	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF ALTERNATIVE DRAIN PLUGS AT THE ENGINE OIL TANK DRAIN LOCATION OF THE ACCESSORY GEARBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102102	NO. 1 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF AN INTERMEDIATE CASE WITH ALTERNATIVE BUSHES MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102102	NO. 2 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF AN INTERMEDIATE CASE WITH ALTERNATIVE BUSHES MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102139	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR NOSE CONE ASSEMBLY - INTRODUCTION OF A NOSE CONE ASSEMBLY WITH A MODIFIED NOSE CONE COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102139	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR NOSE CONE ASSEMBLY - INTRODUCTION OF A NOSE CONE ASSEMBLY WITH A MODIFIED NOSE CONE COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102167	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF (FSO) CABLE AND FITTINGS - INTRODUCTION OF A NEW CONDUIT ASSEMBLY FOR THE FUEL SHUT-OFF MECHANISM, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-102167	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF (FSO) CABLE AND FITTINGS - INTRODUCTION OF A NEW CONDUIT ASSEMBLY FOR THE FUEL SHUT-OFF MECHANISM, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102169	NO. 1 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF AN ALTERNATIVE SPIRALOCK INSERT FOR THE RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102169	NO. 2 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF AN ALTERNATIVE SPIRALOCK INSERT FOR THE RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102187	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) AND HP COMPRESSOR STAGE 1 VARIABLE STATOR VANE (VSV) BUSHES FOR THE HP COMPRESSOR FRONT SPLIT CASE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102187	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) AND HP COMPRESSOR STAGE 1 VARIABLE STATOR VANE (VSV) BUSHES FOR THE HP COMPRESSOR FRONT SPLIT CASE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-102280	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE AND ATTACHING PARTS AND FITTINGS - INTRODUCTION OF ALTERNATIVE ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-102280	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE AND ATTACHING PARTS AND FITTINGS - INTRODUCTION OF ALTERNATIVE ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900229 R02	NO. 1 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	08-Jun-09						176.1
	HRS								
	ENC								
SB BR700-72-900229 R02	NO. 2 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900229 R04	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	08-Jun-09						176.1
	HRS								
	ENC								
SB BR700-72-900229 R04	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900229 R05	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	08-Jun-09						176.1
	HRS								
	ENC								
SB BR700-72-900229 R05	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900229 R06	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900229 R06	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900229 R06 PART 1	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSP OF THE FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS								
	ENC								
SB BR700-72-900229 R06 PART 1	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSP OF THE FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900229 R06 PART 2	NO. 1 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS								
	ENC								
SB BR700-72-900229 R06 PART 2	NO. 2 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	09-Dec-09						170.1
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900307 R01	NO. 1 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	07-Jul-12						139.1
	HRS		541.7						3559.6
	ENC		203						1025
SB BR700-72-900307 R01	NO. 2 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	07-Jul-12						139.1
	HRS		541.7						3559.6
	ENC		203						1025

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900307 R02	NO. 1 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	07-Jul-12						139.1
	HRS		541.7						3559.6
	ENC		203						1025
SB BR700-72-900307 R02	NO. 2 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	07-Jul-12						139.1
	HRS		541.7						3559.6
	ENC		203						1025
SB BR700-72-900307 R03	NO. 1 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	07-Jul-12						139.1
	HRS		541.7						3559.6
	ENC		203						1025
SB BR700-72-900307 R03	NO. 2 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	07-Jul-12						139.1
	HRS		541.7						3559.6
	ENC		203						1025
SB BR700-72-900315	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900315	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900315 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900315 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900341	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - BORESCOPE BLENDING REPAIR OF THE HP COMPRESSOR STAGE 1 ROTOR BLADES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-72-900341	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - BORESCOPE BLENDING REPAIR OF THE HP COMPRESSOR STAGE 1 ROTOR BLADES, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-72-900369 R02 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CIRCLE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R02 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CIRCLE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R02 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CIRCLE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R02 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CIRCLE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R02 PART 3	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CIRCLE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900369 R02 PART 3	NO. 2 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CIRCLE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R03 PART 1	NO. 1 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CASE (CRIC) , SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R03 PART 1	NO. 2 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CASE (CRIC) , SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R03 PART 2	NO. 1 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CASE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R03 PART 2	NO. 2 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CASE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900369 R03 PART 3	NO. 1 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CASE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900369 R03 PART 3	NO. 2 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REAR INNER CASE (CRIC), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900375	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900375	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900375 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900375 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900375 R02	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900375 R02	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900375 R03	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-900375 R03	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-72-900388 R02	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR BLADES- BORESCOPE INSPECTION OF THE HP COMPRESSOR STAGE 1 BLADES FOR DEFLECTION AT THE LEADING EDGE NEAR THE SNUBBER- NON- MODIFICATION SB, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900388 R02	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR BLADES- BORESCOPE INSPECTION OF THE HP COMPRESSOR STAGE 1 BLADES FOR DEFLECTION AT THE LEADING EDGE NEAR THE SNUBBER- NON- MODIFICATION SB, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900392 R02	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INSTALLATION OF CUT ICE IMPACT TRAY BOX ASSEMBLIES BY INCORPORATION OF THE ORIGINAL REPAIR BRG1431 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900392 R02	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INSTALLATION OF CUT ICE IMPACT TRAY BOX ASSEMBLIES BY INCORPORATION OF THE ORIGINAL REPAIR BRG1431 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900409 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INCORPORATION OF THE REPAIR BRG1299 NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900409 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INCORPORATION OF THE REPAIR BRG1299 NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900455 R02 PART A	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R02 PART A	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R02 PART B	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R02 PART B	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R03 PART A	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900455 R03 PART A	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R03 PART B	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R03 PART B	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R04 PART A	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R04 PART A	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R04 PART B	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-72-900455 R04 PART B	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900455 R05 PART A	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900455 R05 PART A	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900455 R05 PART B	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900455 R05 PART B	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900455 R06	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT AND VISUAL INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900455 R06	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT AND VISUAL INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900456	NO. 1 ENGINE - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900456	NO. 2 ENGINE - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900493	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE RELIEF VALVE - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900493	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE RELIEF VALVE - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900500 R02	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - REMOVAL AND INSTALLATION OF THE NO.2 BEARING SUPPORT HOUSING - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900500 R02	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - REMOVAL AND INSTALLATION OF THE NO.2 BEARING SUPPORT HOUSING - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900506	NO. 1 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900506	NO. 2 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900506 R01	NO. 1 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900506 R01	NO. 2 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900506 R02	NO. 1 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	10-Aug-11						150
	HRS								
	ENC								
SB BR700-72-900506 R02	NO. 2 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	10-Aug-11						150
	HRS								
	ENC								
SB BR700-72-900510 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE SUPPORT AND OUTER BEARINGS - INSPECTION AND REPAIR OF REAR BEARING SUPPORT STRUCTURES (RBSS) THAT HAVE BEEN MACHINED BY ELECTRICAL DISCHARGE MACHINING (EDM) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-72-900510 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE SUPPORT AND OUTER BEARINGS - INSPECTION AND REPAIR OF REAR BEARING SUPPORT STRUCTURES (RBSS) THAT HAVE BEEN MACHINED BY ELECTRICAL DISCHARGE MACHINING (EDM) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900515	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR - INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900515	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR - INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900515 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR - INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT - NON-MODIFICATION SERVICE BULLETIN (SERVICE BULLETIN SB-BR700-72-900515 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900515 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR - INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT - NON-MODIFICATION SERVICE BULLETIN (SERVICE BULLETIN SB-BR700-72-900515 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 PART A	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	01-Dec-11						146.3
	HRS		276.5						3824.8
	ENC		121						1107
SB BR700-72-900521 PART A	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	01-Dec-11						146.3
	HRS		276.5						3824.8
	ENC		121						1107

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900521 PART B	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	01-Dec-11						146.3
	HRS		276.5						3824.8
	ENC		121						1107
SB BR700-72-900521 PART B	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	01-Dec-11						146.3
	HRS		276.5						3824.8
	ENC		121						1107
SB BR700-72-900521 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R01 PART A	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R01 PART A	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900521 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R02 PART A	NO. 1 ENGINE - VERIFICATION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP)COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R02 PART A	NO. 2 ENGINE - VERIFICATION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP)COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R02 PART B	NO. 1 ENGINE - EDDY CURRENT ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN INSPECTION OF THE AFFECTED LOW PRESSURE (LP)COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R02 PART B	NO. 2 ENGINE - EDDY CURRENT ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN INSPECTION OF THE AFFECTED LOW PRESSURE (LP)COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900521 R03	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	29-Oct-12						135.4
	HRS		648.9						3452.4
	ENC		251						977

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900521 R03	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	29-Oct-12						135.4
	HRS		648.9						3452.4
	ENC		251						977
SB BR700-72-900521 R03 PART A	NO. 1 ENGINE - PERFORM ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN VERIFICATION OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	29-Oct-12						135.4
	HRS		648.9						3452.4
	ENC		251						977
SB BR700-72-900521 R03 PART A	NO. 2 ENGINE - PERFORM ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN VERIFICATION OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	29-Oct-12						135.4
	HRS		648.9						3452.4
	ENC		251						977
SB BR700-72-900521 R03 PART B	NO. 1 ENGINE - PERFORM ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN EDDY CURRENT INSPECTION OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	29-Oct-12						135.4
	HRS		648.9						3452.4
	ENC		251						977
SB BR700-72-900521 R03 PART B	NO. 2 ENGINE - PERFORM ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN EDDY CURRENT INSPECTION OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	29-Oct-12						135.4
	HRS		648.9						3452.4
	ENC		251						977
SB BR700-72-900521 R04	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	05-Aug-13						126.2
	HRS		1029.2						3072.1
	ENC		406						822

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900521 R04	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	05-Aug-13						126.2
	HRS		1029.2						3072.1
	ENC		406						822
SB BR700-72-900521 R04 PART A	NO. 1 ENGINE - VERIFICATION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	05-Aug-13						126.2
	HRS		1029.2						3072.1
	ENC		406						822
SB BR700-72-900521 R04 PART A	NO. 2 ENGINE - VERIFICATION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	05-Aug-13						126.2
	HRS		1029.2						3072.1
	ENC		406						822
SB BR700-72-900521 R04 PART B	NO. 1 ENGINE - EDDY CURRENT INSPECTION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	05-Aug-13						126.2
	HRS		1029.2						3072.1
	ENC		406						822
SB BR700-72-900521 R04 PART B	NO. 2 ENGINE - EDDY CURRENT INSPECTION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS								Bulletin ATA:72
	MOS/MSC	-	05-Aug-13						126.2
	HRS		1029.2						3072.1
	ENC		406						822
SB BR700-72-900525	NO. 1 ENGINE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900525	NO. 2 ENGINE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900525 R01	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900525 R01	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900526	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900526	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900526 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900526 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900571	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - REPLACEMENT OF UNWANTED PARTS TO RECTIFY THE ENGINE CONFIGURATION IN LINE WITH THE REQUIREMENTS OF SB SB-BR700-72-101901 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900571	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - REPLACEMENT OF UNWANTED PARTS TO RECTIFY THE ENGINE CONFIGURATION IN LINE WITH THE REQUIREMENTS OF SB SB-BR700-72-101901 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900580	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900580	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900580 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900580 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 72 - ENGINE									
SB BR700-72-900637	NO. 1 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900637	NO. 2 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-72-900668	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION UNDER THE FAN TRACK LINER ON LP COMPRESSOR CASES OF PRE SB-BR700-72-100981 STANDARD - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:ESV							
	HRS								
	ENC								
SB BR700-72-900668	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION UNDER THE FAN TRACK LINER ON LP COMPRESSOR CASES OF PRE SB-BR700-72-100981 STANDARD - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	T:ESV							
	HRS								
	ENC								
SB BR700-72-900743	NO. 1 ENGINE - BR700-72-900743 - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - ULTRASONIC INSPECTION OF THE LP COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS		EFF						
	ENC		EFF						
SB BR700-72-900743	NO. 2 ENGINE - BR700-72-900743 - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - ULTRASONIC INSPECTION OF THE LP COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-	EFF						
	HRS		EFF						
	ENC		EFF						
SB BR700-72-A900297 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:72
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 72 - ENGINE										
SB BR700-72-A900297 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-72-A900509 R05	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									
SB BR700-72-A900509 R05	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									
ATA 73 - ENGINE FUEL AND CONTROL										
73-00-00-201[S]	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS								Service	ATA:73
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 73.005	ENC		1226						2	
				PROC. REF: AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801						PKG:4
73-00-00-201[S]	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS								Service	ATA:73
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 73.005	ENC		1226						2	
				PROC. REF: AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801						PKG:4
73-12-01-201[S]	NO. 1 ENGINE - DISCARD THE LP FUEL FILTER								Service	ATA:73
	MOS		01-Dec-23						2.3	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 73.010	ENC		1226						2	
				PROC. REF: AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801						PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 73 - ENGINE FUEL AND CONTROL										
73-12-01-201 S	NO. 2 ENGINE - DISCARD THE LP FUEL FILTER								Service	ATA:73
	MOS		06-Dec-23						2.2	
	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 73.010	ENC		1226						2	
				PROC. REF: AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801						PKG:4
73-21-05-201	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE T20/P20 SENSORS CONNECTORS								Service	ATA:73
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 73 21 05 220 801						PKG:38
731101-001	NO. 1 ENGINE - FUEL PUMP								Component	ATA:73
PN:828200-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:1870	HRS		0	TSN 0					4101.3	
WC#: 73.030	ENC		0	TSN 0					1228	
				PROC. REF: EMM 73-11-01, EMM 73-11-01						
731101-001	NO. 2 ENGINE - FUEL PUMP								Component	ATA:73
PN:828200-2	MOS/MSC	O/C	16-Oct-20	TSO 0					39.8	
SN:0753	HRS		3472.9	TSN 9867.4, TSO 0					628.4	
WC#: 73.030	ENC		1071	TSN 6558, TSO 0					157	
				PROC. REF: EMM 73-11-01, EMM 73-11-01						
731102-001	NO. 1 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR								Component	ATA:73
PN:0154HY	MOS/MSC	O/C	12-Jul-22	TSN 0					19	
SN:V2551	HRS		3802.1	TSN 0					299.2	
WC#: 73.185	ENC		1148	TSN 0					80	
731102-001	NO. 2 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR								Component	ATA:73
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 73.185	ENC		0	TSN 0					1228	
731201-001	NO. 1 ENGINE - TUBE ASSY								Component	ATA:73
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 73.035	ENC		0	TSN 0					1228	
				PROC. REF: EMM 73-11-01, EMM 73-11-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
731201-001	NO. 2 ENGINE - TUBE ASSY								Component ATA:73
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 73.035	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-11-01, EMM 73-11-01					
731301-001	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30810	HRS		0	TSN 0					4101.3
WC#: 73.040	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-001	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32341	HRS		0	TSN 0					4101.3
WC#: 73.040	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-002	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30811	HRS		0	TSN 0					4101.3
WC#: 73.045	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-002	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32342	HRS		0	TSN 0					4101.3
WC#: 73.045	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-003	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30812	HRS		0	TSN 0					4101.3
WC#: 73.050	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-003	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32343	HRS		0	TSN 0					4101.3
WC#: 73.050	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
731301-004	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30813	HRS		0	TSN 0					4101.3
WC#: 73.055	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-004	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32344	HRS		0	TSN 0					4101.3
WC#: 73.055	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-005	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30814	HRS		0	TSN 0					4101.3
WC#: 73.060	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-005	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32345	HRS		0	TSN 0					4101.3
WC#: 73.060	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-006	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30815	HRS		0	TSN 0					4101.3
WC#: 73.065	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-006	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32346	HRS		0	TSN 0					4101.3
WC#: 73.065	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-007	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30816	HRS		0	TSN 0					4101.3
WC#: 73.070	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
731301-007	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32347	HRS		0	TSN 0					4101.3
WC#: 73.070	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-008	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30817	HRS		0	TSN 0					4101.3
WC#: 73.075	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-008	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32348	HRS		0	TSN 0					4101.3
WC#: 73.075	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-009	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30818	HRS		0	TSN 0					4101.3
WC#: 73.080	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-009	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32349	HRS		0	TSN 0					4101.3
WC#: 73.080	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-010	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30819	HRS		0	TSN 0					4101.3
WC#: 73.085	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-010	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32350	HRS		0	TSN 0					4101.3
WC#: 73.085	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
731301-011	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30820	HRS		0	TSN 0					4101.3
WC#: 73.090	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-011	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32351	HRS		0	TSN 0					4101.3
WC#: 73.090	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-012	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30821	HRS		0	TSN 0					4101.3
WC#: 73.095	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-012	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32352	HRS		0	TSN 0					4101.3
WC#: 73.095	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-013	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30822	HRS		0	TSN 0					4101.3
WC#: 73.100	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-013	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32353	HRS		0	TSN 0					4101.3
WC#: 73.100	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-014	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30823	HRS		0	TSN 0					4101.3
WC#: 73.105	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
731301-014	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32354	HRS		0	TSN 0					4101.3
WC#: 73.105	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-015	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30824	HRS		0	TSN 0					4101.3
WC#: 73.110	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-015	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32355	HRS		0	TSN 0					4101.3
WC#: 73.110	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-016	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30825	HRS		0	TSN 0					4101.3
WC#: 73.115	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-016	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32356	HRS		0	TSN 0					4101.3
WC#: 73.115	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-017	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30826	HRS		0	TSN 0					4101.3
WC#: 73.120	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-017	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32357	HRS		0	TSN 0					4101.3
WC#: 73.120	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
731301-018	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30827	HRS		0	TSN 0					4101.3
WC#: 73.125	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-018	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32358	HRS		0	TSN 0					4101.3
WC#: 73.125	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-019	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30828	HRS		0	TSN 0					4101.3
WC#: 73.130	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-019	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32359	HRS		0	TSN 0					4101.3
WC#: 73.130	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-020	NO. 1 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N30829	HRS		0	TSN 0					4101.3
WC#: 73.135	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731301-020	NO. 2 ENGINE - FUEL BURNER								Component ATA:73
PN:6940426E14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:N32360	HRS		0	TSN 0					4101.3
WC#: 73.135	ENC		0	TSN 0					1228
				PROC. REF: GENERIC NO REF					
731302-001	NO. 1 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD								Component ATA:73
PN:8910-214	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:16529034	HRS		0	TSN 0					4101.3
WC#: 73.140	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-13-02, EMM 73-13-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
731302-001	NO. 2 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD								Component ATA:73
PN:8910-214	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:16548856	HRS		0	TSN 0					4101.3
WC#: 73.140	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-13-02, EMM 73-13-02					
731303-001	NO. 1 ENGINE - FUEL RETURN TANK TRANFERS VALVE								Component ATA:73
PN:8910-312	MOS/MSC	O/C	03-Sep-15						101.3
SN:17899273	HRS		1748.9	TSN 2283.1					2352.4
WC#: 73.145	ENC		649	TSN 838					579
				PROC. REF: EMM 73-14-01, EMM 73-14-01					
731303-001	NO. 2 ENGINE - FUEL RETURN TANK TRANFERS VALVE								Component ATA:73
PN:8910-312	MOS/MSC	O/C	03-Sep-15	TSN 69					101.3
SN:16412237	HRS		1748.9	TSN 1748.9					2352.4
WC#: 73.145	ENC		649	TSN 649					579
				PROC. REF: EMM 73-14-01, EMM 73-14-01					
732101-001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC								Component ATA:73
PN:EECU1000-01AD	MOS/MSC	O/C	06-May-22						21.2
SN:BX960251	HRS		3754.2						347.1
WC#: 73.150	ENC		1136						92
				PROC. REF: EMM 73-21-01, EMM 73-21-01, EMM 73-21-01, EMM 73-21-01					
732101-001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC								Component ATA:73
PN:EECU1000-01AD	MOS/MSC	O/C	06-May-22						21.2
SN:BX960247	HRS		3754.2						347.1
WC#: 73.150	ENC		1136						92
				PROC. REF: EMM 73-21-01, EMM 73-21-01, EMM 73-21-01, EMM 73-21-01					
732102-001	NO. 1 ENGINE - FUEL UNIT METER								Component ATA:73
PN:8061-977	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:16403152	HRS		0	TSN 0					4101.3
WC#: 73.155	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-03, EMM 73-21-03					
732102-001	NO. 2 ENGINE - FUEL UNIT METER								Component ATA:73
PN:8061-977	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:16541838	HRS		0	TSN 0					4101.3
WC#: 73.155	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-03, EMM 73-21-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
732103-001	NO. 1 ENGINE - DEDICATED GENERATOR ROTOR								Component ATA:73
PN:83311-430242	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5204	HRS		0	TSN 0					4101.3
WC#: 73.160	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-04, EMM 73-21-04					
732103-001	NO. 2 ENGINE - DEDICATED GENERATOR ROTOR								Component ATA:73
PN:83311-430242	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5207	HRS		0	TSN 0					4101.3
WC#: 73.160	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-04, EMM 73-21-04					
732104-001	NO. 1 ENGINE - DEDICATED GENERATOR STATOR								Component ATA:73
PN:83311-430117	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5231	HRS		0	TSN 0					4101.3
WC#: 73.165	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-04, EMM 73-21-04					
732104-001	NO. 2 ENGINE - DEDICATED GENERATOR STATOR								Component ATA:73
PN:83311-430117	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5235	HRS		0	TSN 0					4101.3
WC#: 73.165	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-04, EMM 73-21-04					
732104-002	NO. 1 ENGINE - DATA ENTRY PLUG								Component ATA:73
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 73.170	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-02, EMM 73-21-02					
732104-002	NO. 2 ENGINE - DATA ENTRY PLUG								Component ATA:73
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 73.170	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-02, EMM 73-21-02					
732105-001	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAD2626	HRS		0	TSN 0					4101.3
WC#: 73.175	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-07, EMM 73-21-07					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
732105-001	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAD2630	HRS		0	TSN 0					4101.3
WC#: 73.175	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-07, EMM 73-21-07					
732105-002	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAD2550	HRS		0	TSN 0					4101.3
WC#: 73.180	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-07, EMM 73-21-07					
732105-002	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE								Component ATA:73
PN:TC428-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAD2505	HRS		0	TSN 0					4101.3
WC#: 73.180	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-21-07, EMM 73-21-07					
733101-001	NO. 1 ENGINE - FUEL FLOW TRANSMITTER								Component ATA:73
PN:9-217-49	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:170436-646	HRS		0	TSN 0					4101.3
WC#: 73.190	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-31-01, EMM 73-31-01					
733101-001	NO. 2 ENGINE - FUEL FLOW TRANSMITTER								Component ATA:73
PN:9-217-49	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:170436-649	HRS		0	TSN 0					4101.3
WC#: 73.190	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-31-01, EMM 73-31-01					
733303-001	NO. 1 ENGINE - FUEL LOW PRESSURE SWITCH								Component ATA:73
PN:21SN04-433	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:K007615	HRS		0	TSN 0					4101.3
WC#: 73.195	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-33-01, EMM 73-33-01, EMM 73-33-01, EMM 73-33-01					
733303-001	NO. 2 ENGINE - FUEL LOW PRESSURE SWITCH								Component ATA:73
PN:21SN04-433	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:J032421	HRS		0	TSN 0					4101.3
WC#: 73.195	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-33-01, EMM 73-33-01, EMM 73-33-01, EMM 73-33-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
733401-001	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH								Component ATA:73
PN:21SN04-430	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:K008363	HRS		0	TSN 0					4101.3
WC#: 73.200	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-34-01, EMM 73-34-01					
733401-001	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH								Component ATA:73
PN:21SN04-430	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:J033300	HRS		0	TSN 0					4101.3
WC#: 73.200	ENC		0	TSN 0					1228
				PROC. REF: EMM 73-34-01, EMM 73-34-01					
ASB A700-73-007	MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE CONTROL (FADEC) - INTRODUCTION OF EEC SOFTWARE UPGRADE X1.1 (A/C 9249 AND 9255 TO 9274), ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	AFL								
ASB BR700-73-A101977 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A101977 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A101977 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A101977 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
ASB BR700-73-A101977 R05	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A101977 R05	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A900083	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A900083	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A900083 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A900083 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
ASB BR700-73-A900083 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 73 - ENGINE FUEL AND CONTROL										
ASB BR700-73-A900083 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	-								
	HRS									
	ENC									
ASB BR700-73-A900451	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FOR REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN								Bulletin	ATA:73
	DAYS/MSC	-	09-Dec-09						5177 d	
	HRS									
	ENC									
ASB BR700-73-A900451	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FOR REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN								Bulletin	ATA:73
	DAYS/MSC	-	09-Dec-09						5177 d	
	HRS		0						4101.3	
	ENC		0						1228	
LBA D-2007-352[U]	NO. 1 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES - TEST OF THE OVERSPEED SHUTOFF SOLENOID VALVE IOP COIL WIRING ON FUEL METERING UNIT (FMU) OF CORRECT POLARITY.								AD	ATA:73
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
LBA D-2007-352[U]	NO. 2 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES - TEST OF THE OVERSPEED SHUTOFF SOLENOID VALVE IOP COIL WIRING ON FUEL METERING UNIT (FMU) OF CORRECT POLARITY.								AD	ATA:73
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
SB 700-73-006	MODIFICATION - DISTRIBUTION - ENGINE PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-73-006 REV 01	MODIFICATION - DISTRIBUTION - ENGINE PROVISION INSTALLATION FOR THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB 700-73-008	MODIFICATION - FULL AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C.8.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	10-Apr-12						142
	HRS		431.8						3669.5
	AFL		154						1071
SB 700-73-009	MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	17-Jul-17						78.8
	HRS		2477.5						1623.8
	AFL		818						407
SB 700-73-009 PART (A)	ACCOMPLISH MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN INSPECT THE EEC TYPE NO. AND AIRCRAFT SETUP								Bulletin ATA:73
	MOS/MSC	-	17-Jul-17						78.8
	HRS		2477.5						1623.8
	AFL		818						407
SB 700-73-009 PART (B)	ACCOMPLISH MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN MODIFICATION - UPGRADE OF THE EEC								Bulletin ATA:73
	MOS/MSC	-	17-Jul-17						78.8
	HRS		2477.5						1623.8
	AFL		818						407
SB BR700-73-100827 R01	NO. 1 ENGINE - FUEL FLOW TRANSMITTER - INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R	06-Jun-09						176.2
	HRS		0						4101.3
	ENC		0						1228
SB BR700-73-100827 R01	NO. 2 ENGINE - FUEL FLOW TRANSMITTER - INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-73-101106	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF NEW FUEL METERING UNIT WITH CHANGES TO COMBINED OVERSPEED AND SHUTOFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 73 - ENGINE FUEL AND CONTROL										
SB BR700-73-101106	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF NEW FUEL METERING UNIT WITH CHANGES TO COMBINED OVERSPEED AND SHUTOFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-73-101106 R01	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	A/R	06-Jun-09						176.2	
	HRS		0						4101.3	
	ENC		0						1228	
SB BR700-73-101106 R01	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	A/R	13-Aug-09						173.9	
	HRS		0						4101.3	
	ENC		0						1228	
SB BR700-73-101145 R03	NO. 1 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR 05B HARDWARE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	A/R								
	HRS									
	ENC									
SB BR700-73-101145 R03	NO. 2 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR 05B HARDWARE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	A/R								
	HRS									
	ENC									
SB BR700-73-101367	NO. 1 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	A/R								
	HRS									
	ENC									
SB BR700-73-101367	NO. 2 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	A/R								
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101472	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101472	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101472 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R	06-Jun-09						176.2
	HRS		0						4101.3
	ENC		0						1228
SB BR700-73-101472 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-73-101504	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101504	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101504 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEWSTANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101504 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEWSTANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101509	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-73-101509	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-73-101547	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A DEP WITH THE APPLICABLE IDENTIFICATION SLEEVE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101547	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A DEP WITH THE APPLICABLE IDENTIFICATION SLEEVE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101558 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101558 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101559	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101559	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101559 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101559 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101559 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTIONOF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101559 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTIONOF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101559 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101559 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101617 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101617 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101628	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101628	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101628 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	06-Jun-09						176.2
	HRS		0						4101.3
	ENC		0						1228
SB BR700-73-101628 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101634	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101634	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101634 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTIONOF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101634 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTIONOF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101634 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101634 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101761	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01 PART 1	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SERVICE BULLETINSB-BR700-73-101509 STANDARD OR SERVICE BULLETIN SB-BR700-73-101625STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC09)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01 PART 1	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SERVICE BULLETINSB-BR700-73-101509 STANDARD OR SERVICE BULLETIN SB-BR700-73-101625STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC09)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01 PART 2	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SERVICE BULLETINSB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD1520KDC08)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101761 R01 PART 2	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SERVICE BULLETINSB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD1520KDC08)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01 PART 3	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 2 OF THE SERVICE BULLETINSB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD1520KDC07)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01 PART 3	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 2 OF THE SERVICE BULLETINSB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD1520KDC07)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01 PART 4	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 4 OF THE SERVICE BULLETINSB-BR700-73-101472 STANDARD INCORPORATED OR PART 1 OF THE SERVICEBULLETIN SB-BR700-73-101034 STANDARD INCORPORATED (EEC HARDWARESTANDARD 1520KDC05)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R01 PART 4	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 4 OF THE SERVICE BULLETINSB-BR700-73-101472 STANDARD INCORPORATED OR PART 1 OF THE SERVICEBULLETIN SB-BR700-73-101034 STANDARD INCORPORATED (EEC HARDWARESTANDARD 1520KDC05)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101761 R02	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02 PART 1	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SB-BR700-73-101509 STANDARD OR SB-BR700-73-101625 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC09)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02 PART 1	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SB-BR700-73-101509 STANDARD OR SB-BR700-73-101625 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC09)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02 PART 2	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC08)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02 PART 2	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 1 OF THE SB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC08)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02 PART 3	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 2 OF THE SB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC07)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101761 R02 PART 3	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 2 OF THE SB-BR700-73-101472 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC07)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02 PART 4	NO. 1 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 4 OF THE SB-BR700-73-101472 STANDARD INCORPORATED OR PART 1 OF THE SB-BR700-73-101034 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC05)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101761 R02 PART 4	NO. 2 ENGINE - ACCOMPLISH CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN ENGINES WHICH HAVE PART 4 OF THE SB-BR700-73-101472 STANDARD INCORPORATED OR PART 1 OF THE SB-BR700-73-101034 STANDARD INCORPORATED (EEC HARDWARE STANDARD 1520KDC05)								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101806	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101806	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101806 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101806 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101815	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF MODIFIED EEC IDENTIFICATION LABELS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101815	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF MODIFIED EEC IDENTIFICATION LABELS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101833 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-73-101833 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-73-101833 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101833 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101856	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101856	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101856 R01	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FORTHE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101856 R01	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FORTHE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101856 R02	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101856 R02	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101865	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE (FRTV) - CORRECTION OF PART NUMBERS FOR EXTERNAL REPLACEABLE PARTS OF THE FRTV, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101865	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE (FRTV) - CORRECTION OF PART NUMBERS FOR EXTERNAL REPLACEABLE PARTS OF THE FRTV, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101966	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	17-Jul-17						78.8
	HRS		2477.5						1623.8
	ENC		821						407
SB BR700-73-101966	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	17-Jul-17						78.8
	HRS		2477.5						1623.8
	ENC		821						407
SB BR700-73-101966 R01	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101966 R01	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101966 R02	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101966 R02	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-101966 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-101966 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900087	NO. 1 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900087	NO. 2 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900087 R05	NO. 1 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900087 R05	NO. 2 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900252	NO. 1 ENGINE - ENGINE AND FUEL CONTROL-AMPLITUDE MEASUREMENT OF ARINC WAVEFORM, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-900252	NO. 2 ENGINE - ENGINE AND FUEL CONTROL-AMPLITUDE MEASUREMENT OF ARINC WAVEFORM, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-73-900270	NO. 1 ENGINE - INSPECTION OF LOW PRESSURE (LP) FUEL TUBE FOR DAMAGE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900270	NO. 2 ENGINE - INSPECTION OF LOW PRESSURE (LP) FUEL TUBE FOR DAMAGE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900270 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INSPECTION OF THE LOW PRESSURE (LP) FUEL TUBE FOR DAMAGE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-73-900270 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INSPECTION OF THE LOW PRESSURE (LP) FUEL TUBE FOR DAMAGE, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	A/R							
	HRS								
	ENC								
SB BR700-73-900301 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - REMOVAL/INSTALLATION OF FUEL METERING UNIT TO INSPECT COILS FOR QUALITY DEFECT, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	N/A							
	HRS								
	ENC								
SB BR700-73-900301 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - REMOVAL/INSTALLATION OF FUEL METERING UNIT TO INSPECT COILS FOR QUALITY DEFECT, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	N/A							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-900423	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	09-Jul-13						127.1
	HRS		1009.7						3091.6
	ENC		393						835
SB BR700-73-900423	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	09-Jul-13						127.1
	HRS		1009.7						3091.6
	ENC		393						835
SB BR700-73-900423 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900423 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900423 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	31-Mar-15						106.4
	HRS		1624.1						2477.2
	ENC		601						627
SB BR700-73-900423 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	31-Mar-15						106.4
	HRS		1624.1						2477.2
	ENC		601						627
SB BR700-73-900423 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-900423 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900423 R04	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (THIS NON-MODIFICATION SB-BR700-73-9000423 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900423 R04	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (THIS NON-MODIFICATION SB-BR700-73-9000423 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900463	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - REMOVAL OF THE EEC FOR C15 CAPACITOR REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-73-900463	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - REMOVAL OF THE EEC FOR C15 CAPACITOR REPLACEMENT, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	T:A/R							
	HRS								
	ENC								
SB BR700-73-900494	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FOR FADEC SYSTEM FAULTS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	18-Jan-12						144.8
	HRS		360.1						3741.2
	ENC		142						1086

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 73 - ENGINE FUEL AND CONTROL									
SB BR700-73-900494	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FOR FADEC SYSTEM FAULTS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	18-Jan-12						144.8
	HRS		360.1						3741.2
	ENC		142						1086
SB BR700-73-900494 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FOR FADEC SYSTEM FAULTS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	18-Jan-12						144.8
	HRS		360.1						3741.2
	ENC		142						1086
SB BR700-73-900494 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FOR FADEC SYSTEM FAULTS, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-	18-Jan-12						144.8
	HRS		360.1						3741.2
	ENC		142						1086
SB BR700-73-900539	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900539	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-73-900539 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:73
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 73 - ENGINE FUEL AND CONTROL										
SB BR700-73-900539 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-73-A101977 R04	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-73-A101977 R04	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-73-A900083 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (THIS SB IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-73-A900083 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (THIS SB IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	-								
	HRS									
	ENC									
ATA 74 - IGNITION										
74-30-01-201[S]	LH ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH								Service	ATA:74
	MOS		22-Nov-23						2.6	
	HRS	500 (+50/-50)	4099.1						2.2	
	AFL		1226						-1	
				PROC. REF: AMM 74 30 01 710 801						PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 74 - IGNITION										
74-30-01-201[S]	RH ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH								Service	ATA:74
	MOS		22-Nov-23						2.6	
	HRS	500 (+50/-50)	4099.1						2.2	
	AFL		1226						-1	
				PROC. REF: AMM 74 30 01 710 801						PKG:2
741001-001	NO. 1 ENGINE - EXCITER UNIT IGNITION								Component	ATA:74
PN:9060440-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:08079640	HRS		0	TSN 0					4101.3	
WC#: 74.010	ENC		0	TSN 0					1228	
				PROC. REF: EMM 74-10-01, EMM 74-10-01						
741001-001	NO. 2 ENGINE - EXCITER UNIT IGNITION								Component	ATA:74
PN:9060440-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09151008	HRS		0	TSN 0					4101.3	
WC#: 74.010	ENC		0	TSN 0					1228	
				PROC. REF: EMM 74-10-01, EMM 74-10-01						
741001-002	NO. 1 ENGINE - EXCITER UNIT IGNITION								Component	ATA:74
PN:9060440-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09118385	HRS		0	TSN 0					4101.3	
WC#: 74.015	ENC		0	TSN 0					1228	
				PROC. REF: EMM 74-10-01, EMM 74-10-01						
741001-002	NO. 2 ENGINE - EXCITER UNIT IGNITION								Component	ATA:74
PN:9060440-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:09159942	HRS		0	TSN 0					4101.3	
WC#: 74.015	ENC		0	TSN 0					1228	
				PROC. REF: EMM 74-10-01, EMM 74-10-01						
742001-001	NO. 1 ENGINE - LH IGNITOR PLUG								Component	ATA:74
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 74.020	ENC		0	TSN 0					1228	
				PROC. REF: EMM 74-20-02, EMM 74-20-02						
742001-001	NO. 2 ENGINE - LH IGNITOR PLUG								Component	ATA:74
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 74.020	ENC		0	TSN 0					1228	
				PROC. REF: EMM 74-20-02, EMM 74-20-02						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 74 - IGNITION									
742001-002	NO. 1 ENGINE - RH IGNITOR PLUG								Component ATA:74
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 74.025	ENC		0	TSN 0					1228
				PROC. REF: EMM 74-20-02, EMM 74-20-02					
742001-002	NO. 2 ENGINE - RH IGNITOR PLUG								Component ATA:74
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 74.025	ENC		0	TSN 0					1228
				PROC. REF: EMM 74-20-02, EMM 74-20-02					
SB BR700-74-102193	NO. 1 ENGINE - IGNITION - IGNITOR PLUG - INTRODUCTION OF A NEW IGNITOR PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN								Bulletin ATA:74
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-74-102193	NO. 2 ENGINE - IGNITION - IGNITOR PLUG - INTRODUCTION OF A NEW IGNITOR PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN								Bulletin ATA:74
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-74-102193 R01	NO. 1 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN								Bulletin ATA:74
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-74-102193 R01	NO. 2 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN								Bulletin ATA:74
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-74-102193 R02	NO. 1 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN								Bulletin ATA:74
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 74 - IGNITION										
SB BR700-74-102193 R02	NO. 2 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN								Bulletin	ATA:74
	MOS/MSC	-								
	HRS									
	ENC									
ATA 75 - AIR										
752201-001	NO. 1 ENGINE - AIR BUFFER VALVE								Component	ATA:75
PN:8910-512	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:13437884	HRS		0	TSN 0					4101.3	
WC#: 75.010	ENC		0	TSN 0					1228	
				PROC. REF: EMM 75-22-01, EMM 75-22-01						
752201-001	NO. 2 ENGINE - AIR BUFFER VALVE								Component	ATA:75
PN:8910-512	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:13393897	HRS		0	TSN 0					4101.3	
WC#: 75.010	ENC		0	TSN 0					1228	
				PROC. REF: EMM 75-22-01, EMM 75-22-01						
753101-001	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component	ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:HCB570	HRS		0	TSN 0					4101.3	
WC#: 75.015	ENC		0	TSN 0					1228	
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03						
753101-001	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component	ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:HCB587	HRS		0	TSN 0					4101.3	
WC#: 75.015	ENC		0	TSN 0					1228	
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03						
753101-002	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component	ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:HCB599	HRS		0	TSN 0					4101.3	
WC#: 75.020	ENC		0	TSN 0					1228	
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 75 - AIR									
753101-002	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:HCB588	HRS		0	TSN 0					4101.3
WC#: 75.020	ENC		0	TSN 0					1228
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03					
753101-003	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:HCB600	HRS		0	TSN 0					4101.3
WC#: 75.025	ENC		0	TSN 0					1228
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03					
753101-003	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:HCB589	HRS		0	TSN 0					4101.3
WC#: 75.025	ENC		0	TSN 0					1228
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03					
753101-004	NO. 1 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:HCB601	HRS		0	TSN 0					4101.3
WC#: 75.030	ENC		0	TSN 0					1228
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03					
753101-004	NO. 2 ENGINE - HPC BLEED HANDLING VALVE								Component ATA:75
PN:EB100420D	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:HCB606	HRS		0	TSN 0					4101.3
WC#: 75.030	ENC		0	TSN 0					1228
				PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03					
753102-001	NO. 1 ENGINE - BLEED SOLENOID BLOCK VALVE								Component ATA:75
PN:EA100118G	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:HEA065	HRS		0	TSN 0					4101.3
WC#: 75.035	ENC		0	TSN 0					1228
				PROC. REF: EMM 75-31-02, EMM 75-31-02					
753102-001	NO. 2 ENGINE - BLEED SOLENOID BLOCK VALVE								Component ATA:75
PN:EA100118G	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:HEB132	HRS		0	TSN 0					4101.3
WC#: 75.035	ENC		0	TSN 0					1228
				PROC. REF: EMM 75-31-02, EMM 75-31-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 75 - AIR										
753103-001	NO. 1 ENGINE - VANE STATOR VARIABLE ACTUATOR								Component	ATA:75
PN:8100-115	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:16469271	HRS		0	TSN 0					4101.3	
WC#: 75.040	ENC		0	TSN 0					1228	
				PROC. REF: EMM 75-31-01, EMM 75-31-01						
753103-001	NO. 2 ENGINE - VANE STATOR VARIABLE ACTUATOR								Component	ATA:75
PN:8100-115	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:16535749	HRS		0	TSN 0					4101.3	
WC#: 75.040	ENC		0	TSN 0					1228	
				PROC. REF: EMM 75-31-01, EMM 75-31-01						
SB BR700-75-101130	NO. 1 ENGINE - AIR BLEED VALVES-INTRODUCTION OF NEW IIP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-75-101130	NO. 2 ENGINE - AIR BLEED VALVES-INTRODUCTION OF NEW IIP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-75-101130 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC	A/R								
	HRS									
	ENC									
SB BR700-75-101130 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC	A/R								
	HRS									
	ENC									
SB BR700-75-101161 R01	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC	T:-	06-Jun-09						176.2	
	HRS		0						4101.3	
	ENC		0						1228	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 75 - AIR									
SB BR700-75-101161 R01	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	T:-	13-Aug-09						173.9
	HRS		0						4101.3
	ENC		0						1228
SB BR700-75-101161 R02	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101161 R02	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101161 R03	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101161 R03	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101381 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101381 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 75 - AIR									
SB BR700-75-101447 R01	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101447 R01	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101447 R02	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101447 R02	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101694	NO. 1 ENGINE - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-101694	NO. 2 ENGINE - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900308	NO. 1 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900308	NO. 2 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 75 - AIR									
SB BR700-75-900308 R01	NO. 1 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900308 R01	NO. 2 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900308 R02	NO. 1 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900308 R02	NO. 2 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900308 R03	NO. 1 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900308 R03	NO. 2 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900311 R01	NO. 1 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM TORQUE CHECK - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 75 - AIR									
SB BR700-75-900311 R01	NO. 2 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM TORQUE CHECK - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900633	NO. 1 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900633	NO. 2 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900633 R01	NO. 1 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900633 R01	NO. 2 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900693	NO. 1 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-75-900693	NO. 2 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:75
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 76 - ENGINE CONTROLS										
76-10-01-900-801-01	THROTTLE QUADRANT								Component	ATA:76
PN:GH562-3001-5	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:E0410	HRS		0	TSN 0					4101.3	
WC#: 76.005	AFL		0	TSN 0					1225	
				PROC. REF: AMM 76 10 01 000 801, AMM 76 10 01 400 801						
FAA 2018-18-14	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT								AD	ATA:76
	MOS/MSC	-	05-Apr-21						34.2	
	HRS		3474.7						626.6	
	ENC		1072						156	
FAA 2018-18-14	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT								AD	ATA:76
	MOS/MSC	-	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	ENC		1072						156	
SB 700-76-002	MODIFICATION - POWER CONTROL - INSTALLATION OF PROTECTIVE GUARDS FOR ENGINE RUN SWITCHES (EFFECTIVITY: 9002 TO 9182), SERVICE BULLETIN								Bulletin	ATA:76
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-76-003	MODIFICATION - THROTTLE QUADRANT - INSTALLATION OF THROTTLE QUADRANT ASSEMBLY WITH IMPROVED ENGINE RUN SWITCHES (EFFECTIVITY 9002 TO 9126 AND 9128 TO 9222), SERVICE BULLETIN								Bulletin	ATA:76
	MOS/MSC	-								
	HRS									
	AFL									
ATA 77 - ENGINE INDICATING										
77-31-04-900-801-01	EVMU ENGINE VIBRATION MONITORING UNIT								Component	ATA:77
PN:GB544-1001-1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:AE20342	HRS		0	TSN 0					4101.3	
WC#: 77.005	AFL		0	TSN 0					1225	
				PROC. REF: AMM 77 31 04 000 801, AMM 77 31 04 400 801						
771201-001	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component	ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:5126	HRS		0	TSN 0					4101.3	
WC#: 77.010	ENC		0	TSN 0					1228	
				PROC. REF: EMM 77-12-01, EMM 77-12-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 77 - ENGINE INDICATING									
771201-001	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2901	HRS		0	TSN 0					4101.3
WC#: 77.010	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-12-01, EMM 77-12-01					
771201-002	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5134	HRS		0	TSN 0					4101.3
WC#: 77.015	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-12-01, EMM 77-12-01					
771201-002	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5138	HRS		0	TSN 0					4101.3
WC#: 77.015	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-12-01, EMM 77-12-01					
771201-003	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5186	HRS		0	TSN 0					4101.3
WC#: 77.020	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-12-01, EMM 77-12-01					
771201-003	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5196	HRS		0	TSN 0					4101.3
WC#: 77.020	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-12-01, EMM 77-12-01					
771201-004	NO. 1 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5297	HRS		0	TSN 0					4101.3
WC#: 77.025	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-12-01, EMM 77-12-01					
771201-004	NO. 2 ENGINE - N2 SHAFT SPEED PROBE								Component ATA:77
PN:889-3-13	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:5302	HRS		0	TSN 0					4101.3
WC#: 77.025	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-12-01, EMM 77-12-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 77 - ENGINE INDICATING									
772101-001	NO. 1 ENGINE - NO. 1 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05633	HRS		0	TSN 0					4101.3
WC#: 77.030	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-001	NO. 2 ENGINE - NO. 1 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05114	HRS		0	TSN 0					4101.3
WC#: 77.030	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-002	NO. 1 ENGINE - NO. 2 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05641	HRS		0	TSN 0					4101.3
WC#: 77.035	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-002	NO. 2 ENGINE - NO. 2 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05121	HRS		0	TSN 0					4101.3
WC#: 77.035	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-003	NO. 1 ENGINE - NO. 3 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05668	HRS		0	TSN 0					4101.3
WC#: 77.040	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-003	NO. 2 ENGINE - NO. 3 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05122	HRS		0	TSN 0					4101.3
WC#: 77.040	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-004	NO. 1 ENGINE - NO. 4 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05669	HRS		0	TSN 0					4101.3
WC#: 77.045	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 77 - ENGINE INDICATING									
772101-004	NO. 2 ENGINE - NO. 4 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05199	HRS		0	TSN 0					4101.3
WC#: 77.045	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-005	NO. 1 ENGINE - NO. 5 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05673	HRS		0	TSN 0					4101.3
WC#: 77.050	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-005	NO. 2 ENGINE - NO. 5 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05611	HRS		0	TSN 0					4101.3
WC#: 77.050	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-006	NO. 1 ENGINE - NO. 6 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05675	HRS		0	TSN 0					4101.3
WC#: 77.055	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-006	NO. 2 ENGINE - NO. 6 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05613	HRS		0	TSN 0					4101.3
WC#: 77.055	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-007	NO. 1 ENGINE - NO. 7 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05684	HRS		0	TSN 0					4101.3
WC#: 77.060	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					
772101-007	NO. 2 ENGINE - NO. 7 THERMOCOUPLE PROBE								Component ATA:77
PN:TC429-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:RRAE05649	HRS		0	TSN 0					4101.3
WC#: 77.060	ENC		0	TSN 0					1228
				PROC. REF: EMM 77-21-01, EMM 77-21-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 77 - ENGINE INDICATING										
772201-001	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component	ATA:77
PN:920-4-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3265	HRS		0	TSN 0					4101.3	
WC#: 77.065	ENC		0	TSN 0					1228	
				PROC. REF: EMM 77-23-01, EMM 77-23-01						
772201-001	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component	ATA:77
PN:920-4-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3263	HRS		0	TSN 0					4101.3	
WC#: 77.065	ENC		0	TSN 0					1228	
				PROC. REF: EMM 77-23-01, EMM 77-23-01						
772201-002	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component	ATA:77
PN:920-4-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3266	HRS		0	TSN 0					4101.3	
WC#: 77.070	ENC		0	TSN 0					1228	
				PROC. REF: EMM 77-23-01, EMM 77-23-01						
772201-002	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE								Component	ATA:77
PN:920-4-14	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:3264	HRS		0	TSN 0					4101.3	
WC#: 77.070	ENC		0	TSN 0					1228	
				PROC. REF: EMM 77-23-01, EMM 77-23-01						
SB BR700-77-101534	NO. 1 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-77-101534	NO. 2 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-77-101544	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC	-								
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 77 - ENGINE INDICATING									
SB BR700-77-101544	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101553	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101553	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101560	NO. 1 ENGINE - INTRODUCTION OF AN ENGINE VIBRATION MONITORING UNIT, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101560	NO. 2 ENGINE - INTRODUCTION OF AN ENGINE VIBRATION MONITORING UNIT, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101875	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-	27-Jul-14						114.5
	HRS		1387.8						2713.5
	ENC		537						691
SB BR700-77-101875	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-	27-Jul-14						114.5
	HRS		1387.8						2713.5
	ENC		537						691

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 77 - ENGINE INDICATING									
SB BR700-77-101875 R01	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101875 R01	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101875 R02	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-101875 R02	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-900251 R01	NO. 1 ENGINE - ENGINE INDICATING - TGT THERMOCOUPLE PROBES - ELECTRICAL RESISTANCE CHECK OF THE TGT THERMOCOUPLE PROBES, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-900251 R01	NO. 2 ENGINE - ENGINE INDICATING - TGT THERMOCOUPLE PROBES - ELECTRICAL RESISTANCE CHECK OF THE TGT THERMOCOUPLE PROBES, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-77-900329	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FOR POTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN								Bulletin ATA:77
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 77 - ENGINE INDICATING										
SB BR700-77-900329	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FOR POTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-77-900329 R01	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FOR POTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC	-	08-Jul-13						127.1	
	HRS		1009.7						3091.6	
	ENC		393						835	
SB BR700-77-900329 R01	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FOR POTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC	-	08-Jul-13						127.1	
	HRS		1009.7						3091.6	
	ENC		393						835	
ATA 78 - EXHAUST										
78-10-01-201[S]	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE								Service	ATA:78
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
	ENC		1226						2	
				PROC. REF: AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801						PKG:4
78-10-01-201[S]	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE								Service	ATA:78
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
	ENC		1226						2	
				PROC. REF: AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801						PKG:4
78-10-02-201[S]	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST CONE								Service	ATA:78
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
	ENC		1226						2	
				PROC. REF: AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801						PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 78 - EXHAUST										
78-10-02-201 S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST CONE								Service	ATA:78
	MOS		30-Nov-23						2.4	
	HRS	1000 (+50/-50)	4099.1						2.2	
	ENC		1226						2	
				PROC. REF: AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801						PKG:4
78-30-00-201 S	GENERAL VISUAL INSPECTION OF THE THRUST-REVERSER THERMAL BLANKET								Service	ATA:78
	MOS		19-Mar-21						34.7	
	HRS	3000 (+50/-50)	3474.7						626.6	
WC#: 78.015	AFL		1069						156	
				PROC. REF: AMM 78 30 00 210 805						PKG:8
78-30-00-204 S	FUNCTIONAL TEST OF THE THRUST REVERSER								Service	ATA:78
	MOS									
	HRS	4500 (+50/-50)	0						4101.3	
WC#: 78.025	AFL									
				PROC. REF: AMM 78 30 00 720 802						PKG:10
78-30-00-205 S	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER P-SEALS AND SEAL DEPRESSORS/SUPPORT								Service	ATA:78
	MOS	30 (+3m/-3m)	30-Dec-22						13.4	
	HRS		3913.7						187.6	
	AFL		1171						54	
				PROC. REF: AMM 78 30 00 210 808						PKG:32
78-30-00-206	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE THRUST REVERSERS ELECTRICAL CONNECTORS								Service	ATA:78
	MOS	120 (+3m/-3m)	19-Mar-21	Adj 3	30-Jun-31	19-Sep-31	2696 d (+81)	30-Jun-2031	34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 78 30 00 220 801						PKG:38
78-30-00-900-801-01	LEFT THRUST REVERSER								Component	ATA:78
PN:07G0001-013	MOS/MSC	O/C	19-Mar-21	TSN 135, TSR 1					34.7	
SN:LH753	HRS		3474.7	TSN 3474.7, TSR 0					626.6	
WC#: 78.070	AFL		1069	TSN 1069, TSR 0					156	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 78 - EXHAUST										
78-30-00-900-801-02	RIGHT THRUST REVERSER								Component	ATA:78
PN:07G0001-015	MOS/MSC	O/C	19-Mar-21	TSN 135, TSR 0					34.7	
SN:RH754	HRS		3474.7	TSN 3474.7, TSR 0					626.6	
WC#: 78.070	AFL		1069	TSN 1069, TSR 0					156	
				PROC. REF: GENERIC NO REF						
78-31-01-101	DETAILED INSPECTION OF THE THRUST REVERSER UPPER DOOR								Service	ATA:78
	MOS		20-Dec-09					29-Mar-2050	169.7	
	HRS		0						4101.3	
WC#: 78.030	AFL	T:7500	0		7500		6275		1225	
				PROC. REF: AMM 78 31 01 220 803						PKG:76
78-31-01-201 S	DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (METALLIC)								Service	ATA:78
	MOS	120 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
WC#: 78.035	AFL		1069						156	
				PROC. REF: AMM 78 31 01 220 802						PKG:38
78-31-01-202	SPECIAL DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (COMPOSITE)								Service	ATA:78
	MOS		20-Dec-09					26-Oct-2026	169.7	
	HRS		0						4101.3	
WC#: 78.040	AFL	T:1875 (+50/-50)	0		1875	1925	650 (+50)		1225	
				PROC. REF: AMM 78 31 01 280 801						
78-31-01-900-801-01	UPPER LEFT THRUST REVERSER DOOR								Component	ATA:78
PN:04G2037-003	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UL1540	HRS		0	TSN 0					4101.3	
WC#: 78.065	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
78-31-01-900-801-02	LOWER LEFT THRUST REVERSER DOOR								Component	ATA:78
PN:07G2039-001	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:LL1338	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
78-32-01-900-801-01	UPPER RIGHT THRUST REVERSER DOOR								Component	ATA:78
PN:04G2037-004	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UR1554	HRS		0	TSN 0					4101.3	
WC#: 78.065	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 78 - EXHAUST										
78-32-01-900-801-02	LOWER RIGHT THRUST REVERSER DOOR								Component	ATA:78
PN:07G2039-002	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:LR1337	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
78-33-01-900-801-01	LH ISOLATION THRUST REVERSER VALVE								Component	ATA:78
PN:P472A0001-02	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:A0065739	HRS		0	TSN 0					4101.3	
WC#: 78.070	AFL		0	TSN 0					1225	
				PROC. REF: AMM 78 33 01 000 801, AMM 78 33 01 400 801						
78-33-01-900-801-02	RH ISOLATION THRUST REVERSER VALVE								Component	ATA:78
PN:P72A0001-02	MOS/MSC	O/C	19-Mar-16	TSR 20					94.7	
SN:DAW271-01	HRS		1978.6	TSR 0					2122.7	
WC#: 78.070	AFL		690	TSR 0					535	
				PROC. REF: AMM 78 33 01 000 801, AMM 78 33 01 400 801						
78-33-02-900-801-01	LH DIRECTIONAL CONTROL UNIT DCU								Component	ATA:78
PN:P473A0001-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:A0066376	HRS		0	TSN 0					4101.3	
WC#: 78.075	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
78-33-02-900-801-02	RH DIRECTIONAL CONTROL UNIT DCU								Component	ATA:78
PN:P473A0001-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:A0066375	HRS		0	TSN 0					4101.3	
WC#: 78.075	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
78-33-03-201 S	DETAILED INSPECTION OF THE THRUST REVERSER UNIT (TRU) PRIMARY-DOOR ACTUATOR-ROD END								Service	ATA:78
	MOS	60 (+3m/-3m)	19-Mar-21						34.7	
	HRS		3474.7						626.6	
	AFL		1069						156	
				PROC. REF: AMM 78 33 03 220 801						PKG:34
78-33-03-900-801-01	LEFT UPPER THRUST REVERSER DOOR ACTUATOR								Component	ATA:78
PN:P471A0001-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:A0064414	HRS		0	TSN 0					4101.3	
WC#: 78.080	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
78-33-03-900-801-02	LEFT LOWER THRUST REVERSER DOOR ACTUATOR								Component ATA:78
PN:P471A0001-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A0064413	HRS		0	TSN 0					4101.3
WC#: 78.080	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-33-03-900-801-03	RIGHT UPPER THRUST REVERSER DOOR ACTUATOR								Component ATA:78
PN:P471A0001-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A0068088	HRS		0	TSN 0					4101.3
WC#: 78.085	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-33-03-900-801-04	RIGHT LOWER THRUST REVERSER DOOR ACTUATOR								Component ATA:78
PN:P471A0001-01	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A0068085	HRS		0	TSN 0					4101.3
WC#: 78.085	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-33-04-900-801-01	LOB PRIMARY LOCK ACTUATOR								Component ATA:78
PN:P466A0001-02	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A0068719	HRS		0	TSN 0					4101.3
WC#: 78.090	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-33-04-900-801-02	LIB PRIMARY LOCK ACTUATOR								Component ATA:78
PN:P466A0001-02	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A0068742	HRS		0	TSN 0					4101.3
WC#: 78.095	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-33-04-900-801-03	RIB PRIMARY LOCK ACTUATOR								Component ATA:78
PN:P466A0001-02	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A0068708	HRS		0	TSN 0					4101.3
WC#: 78.095	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-33-04-900-801-04	ROB PRIMARY LOCK ACTUATOR								Component ATA:78
PN:P466A0001-02	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A0068709	HRS		0	TSN 0					4101.3
WC#: 78.090	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 78 - EXHAUST										
78-33-05-101	OPERATIONAL TEST OF THE TERTIARY LOCK								Service	ATA:78
	MOS		04-Sep-12					31-Dec-2025	137.2	
	HRS	4500 (+50/-50)	621		5121	5171	1019.7 (+50)		3480.3	
WC#: 78.045	AFL		233						992	
				PROC. REF: AMM 78 33 05 710 801						PKG:10
78-33-05-201 S	GENERAL VISUAL INSPECTION OF THE TERTIARY LOCK HOOK								Service	ATA:78
	MOS		19-Mar-21						34.7	
	HRS	3000 (+50/-50)	3474.7						626.6	
WC#: 78.050	AFL		1069						156	
				PROC. REF: AMM 78 33 05 210 802						PKG:8
78-33-05-203 S	GENERAL VISUAL INSPECTION OF THE PIVOTING DOOR KEEPER BAR								Service	ATA:78
	MOS		20-Dec-09						169.7	
	HRS	3000 (+50/-50)	0						4101.3	
	AFL		0						1225	
				PROC. REF: AMM 78 33 05 210 803						PKG:8
78-33-05-900-801-01	LEFT UPPER T/R TERTIARY LOCK								Component	ATA:78
PN:P516A0001-00	MOS/MSC	O/C	04-Sep-12	TSN 0					137.2	
SN:A0113937	HRS		621	TSN 0					3480.3	
WC#: 78.095	AFL		233	TSN 0					992	
				PROC. REF: GENERIC NO REF						
78-33-05-900-801-02	LEFT LOWER T/R TERTIARY LOCK								Component	ATA:78
PN:P516A0001-00	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:DAW3514-09	HRS		0	TSN 0					4101.3	
WC#: 78.100	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
78-33-05-900-801-03	RIGHT UPPER T/R TERTIARY LOCK								Component	ATA:78
PN:P516A0001-00	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:DAW3544-09	HRS		0	TSN 0					4101.3	
WC#: 78.095	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						
78-33-05-900-801-04	RIGHT LOWER T/R TERTIARY LOCK								Component	ATA:78
PN:P516A0001-00	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:DAW3543-09	HRS		0	TSN 0					4101.3	
WC#: 78.100	AFL		0	TSN 0					1225	
				PROC. REF: GENERIC NO REF						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
78-34-01-900-801-01	LEFT UPPER INBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	08-Mar-13	TSN 1					131.1
SN:4502	HRS		850.3	TSN 0					3251
WC#: 78.110	AFL		332	TSN 0					893
				PROC. REF: GENERIC NO REF					
78-34-01-900-801-02	LEFT UPPER OUTBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1015	HRS		0	TSN 0					4101.3
WC#: 78.115	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-01-900-801-03	LEFT LOWER OUTBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1043	HRS		0	TSN 0					4101.3
WC#: 78.120	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-01-900-801-04	LEFT LOWER INBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1061	HRS		0	TSN 0					4101.3
WC#: 78.125	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-01-900-801-05	RIGHT UPPER INBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1145	HRS		0	TSN 0					4101.3
WC#: 78.110	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-01-900-801-06	RIGHT UPPER OUTBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1062	HRS		0	TSN 0					4101.3
WC#: 78.115	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-01-900-801-07	RIGHT LOWER OUTBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1178	HRS		0	TSN 0					4101.3
WC#: 78.120	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
78-34-01-900-801-08	RIGHT LOWER INBOARD STOW SWITCH								Component ATA:78
PN:T7013-2	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1083	HRS		0	TSN 0					4101.3
WC#: 78.125	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-02-900-801-01	NO. 1 DOOR POSITION (LDVT) TRANSMITTER								Component ATA:78
PN:133F025-005	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A102074	HRS		0	TSN 0					4101.3
WC#: 78.105	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-02-900-801-02	NO. 2 DOOR POSITION (LDVT) TRANSMITTER								Component ATA:78
PN:133F025-005	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A102072	HRS		0	TSN 0					4101.3
WC#: 78.105	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-02-900-801-03	NO. 3 DOOR POSITION (LDVT) TRANSMITTER								Component ATA:78
PN:133F025-005	MOS/MSC	O/C	12-Jul-22	TSN 24					19
SN:A106210	HRS		3802.1	TSN 0					299.2
WC#: 78.105	AFL		1144	TSN 0					81
				PROC. REF: GENERIC NO REF					
78-34-02-900-801-04	NO. 4 DOOR POSITION (LDVT) TRANSMITTER								Component ATA:78
PN:133F025-005	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:A102069	HRS		0	TSN 0					4101.3
WC#: 78.105	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-34-03-900-801-01	THRUST REVERSER BOX								Component ATA:78
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:UNKNOWN	HRS		0	TSN 0					4101.3
WC#: 78.060	AFL		0	TSN 0					1225
				PROC. REF: GENERIC NO REF					
78-ZL-00-201	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - LH								Service ATA:78
	MOS		20-Dec-09					04-Jul-2026	169.7
	HRS		0						4101.3
WC#: 78.055	AFL	1800 (+50/-50)	0		1800	1850	575 (+50)		1225
				PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 78 30 00 210 801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 78 - EXHAUST										
78-ZL-00-202	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - RH								Service	ATA:78
	MOS		20-Dec-09					04-Jul-2026	169.7	
	HRS		0						4101.3	
WC#: 78.055	AFL	1800 (+50/-50)	0		1800	1850	575 (+50)		1225	
				PROC. REF: SPM 20-70-00-210-801, SPM 51-25-00-110-801, AMM 78 30 00 210 801						
SB 700-78-002	SPECIAL CHECK/REWORK - THRUST REVERSER ACTUATING SYSTEM - INSPECTION AND CLEANING OF THE SPHERICAL BEARING ON THE PRIMARY DOOR LOCK ACTUATOR (9002 TO 9126, 9128 TO 9179, 9181 AND 9182), SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	N/A								
	HRS									
	AFL									
SB BR700-78-100783 R06	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-100783 R06	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-100783 R07	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-100783 R07	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-101529	NO. 1 ENGINE - EXHAUST - PRIMARY LOCK ACTUATOR AND MECHANISM - INTRODUCTION OF A NEW PRIMARY DOOR LOCK ACTUATOR (PDLA) SB-BR700-78-101529, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 78 - EXHAUST										
SB BR700-78-101529	NO. 2 ENGINE - EXHAUST - PRIMARY LOCK ACTUATOR AND MECHANISM - INTRODUCTION OF A NEW PRIMARY DOOR LOCK ACTUATOR (PDLA) SB-BR700-78-101529, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-101607	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-	06-Oct-09						172.2	
	HRS		0						4101.3	
	ENC		0						1228	
SB BR700-78-101607	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-	16-Jun-09						175.8	
	HRS		0						4101.3	
	ENC		0						1228	
SB BR700-78-101607 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-101607 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-101716	NO. 1 ENGINE - THRUST REVERSER ATTACH PARTS AND FITTINGS - CLARIFICATION AND CORRECTION OF THE THRUST REVERSER UNIT (TRU) ATTACHING PART DEFINITION, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-78-101716	NO. 2 ENGINE - THRUST REVERSER ATTACH PARTS AND FITTINGS - CLARIFICATION AND CORRECTION OF THE THRUST REVERSER UNIT (TRU) ATTACHING PART DEFINITION, SERVICE BULLETIN								Bulletin	ATA:78
	MOS/MSC	-								
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
SB BR700-78-101788	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DEFINITION OF EXISTING PARTS OF THE PIVOTING DOOR ACTUATOR (PDA) ROD END ASSEMBLY AS SPAREABLE ITEMS AND CORRECTION TO THE DEFINITION OF SPAREABLE PARTS IN THE CONFIGURATION BASELINE, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101788	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DEFINITION OF EXISTING PARTS OF THE PIVOTING DOOR ACTUATOR (PDA) ROD END ASSEMBLY AS SPAREABLE ITEMS AND CORRECTION TO THE DEFINITION OF SPAREABLE PARTS IN THE CONFIGURATION BASELINE, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101944	NO. 1 ENGINE - EXHAUST - DOOR POSITION SENSOR - INTRODUCTION OF A NEW LINEAR VARIABLE TRANSMITTER (LVT) BONDING STRAP, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101944	NO. 2 ENGINE - EXHAUST - DOOR POSITION SENSOR - INTRODUCTION OF A NEW LINEAR VARIABLE TRANSMITTER (LVT) BONDING STRAP, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101983 R01	NO. 1 ENGINE - CAMPAIGN SB - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101983 R01	NO. 2 ENGINE - CAMPAIGN SB - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
SB BR700-78-101983 R02	NO. 1 ENGINE - CAMPAIGN SB - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101983 R02	NO. 2 ENGINE - CAMPAIGN SB - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101996	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF REVISED SEAL SUPPORTS AND INHIBITION KEEPER, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101996	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF REVISED SEAL SUPPORTS AND INHIBITION KEEPER, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101997	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) VARIOUS LOCATIONS - INTRODUCTION OF NEW FASTENER DEFINITIONS WHICH ARE USED TO MOUNT THE TRU ACCESS PANELS ONTO THE TRU STRUCTURE, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-101997	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) VARIOUS LOCATIONS - INTRODUCTION OF NEW FASTENER DEFINITIONS WHICH ARE USED TO MOUNT THE TRU ACCESS PANELS ONTO THE TRU STRUCTURE, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-102008	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
SB BR700-78-102008	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-102008 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-	08-Jun-18						68.1
	HRS		2892.3						1209
	ENC		924						304
SB BR700-78-102008 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-	08-Jun-18						68.1
	HRS		2892.3						1209
	ENC		924						304
SB BR700-78-900350	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900350	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900350 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900350 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
SB BR700-78-900350 R02	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-	07-Jan-20						49.1
	HRS		3338.3						763
	ENC		1041						187
SB BR700-78-900350 R02	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-	07-Jan-20						49.1
	HRS		3338.3						763
	ENC		1041						187
SB BR700-78-900474	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INSPECTION OF FIXED STRUCTURE TORQUE BOX DRAINAGE HOLES, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-78-900474	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INSPECTION OF FIXED STRUCTURE TORQUE BOX DRAINAGE HOLES, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-	20-Dec-09						169.7
	HRS		0						4101.3
	ENC		0						1228
SB BR700-78-900535 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900535 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900535 R02	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 78 - EXHAUST									
SB BR700-78-900535 R02	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900547	NO. 1 ENGINE - ENGINE - THRUST REVERSER - INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900547	NO. 2 ENGINE - ENGINE - THRUST REVERSER - INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS - NON-MODIFICATION, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900547 R01	NO. 1 ENGINE - ENGINE - THRUST REVERSER - INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900547 R01	NO. 2 ENGINE - ENGINE - THRUST REVERSER - INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900617	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INSPECTION OF THRUST REVERSER UNIT(TRU) PIVOT DOOR INTERNAL SURFACES - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-78-900617	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INSPECTION OF THRUST REVERSER UNIT(TRU) PIVOT DOOR INTERNAL SURFACES - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin ATA:78
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 78 - EXHAUST										
TV 165797 ISSUE 1U	NO. 1 ENGINE - CORROSION ON BOTH TRU ENGINE MOUNT RING FLANGES - A/C 9375 (OSD 17247), TECHNICAL VARIANCE								Bulletin	ATA:78
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	
TV 165797 ISSUE 1U	NO. 2 ENGINE - CORROSION ON BOTH TRU ENGINE MOUNT RING FLANGES - A/C 9375 (OSD 17247), TECHNICAL VARIANCE								Bulletin	ATA:78
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	
TV 165885 ISSUE 1U	NO. 1 ENGINE - CORROSION ON BOTH TRU ENGINE MOUNT RING FLANGES - OSD CASE 17247 - A/C 9375, TECHNICAL VARIANCE								Bulletin	ATA:78
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	
TV 165885 ISSUE 1U	NO. 2 ENGINE - CORROSION ON BOTH TRU ENGINE MOUNT RING FLANGES - OSD CASE 17247 - A/C 9375, TECHNICAL VARIANCE								Bulletin	ATA:78
	MOS/MSC	-	27-Jul-16						90.5	
	HRS		2078.9						2022.4	
	ENC		722						506	
ATA 79 - OIL										
79-11-00-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK								Service	ATA:79
	MOS		19-Mar-21					30-Sep-2026	34.7	
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6	
WC#: 79.005	ENC		1072						156	
				PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801						PKG:6
79-11-00-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK								Service	ATA:79
	MOS		19-Mar-21					30-Sep-2026	34.7	
	HRS	2000 (+50/-50)	3474.7	Adj 50	(5524.7) 5524.7	5574.7	1423.4 (+50)		626.6	
WC#: 79.005	ENC		1072						156	
				PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801						PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 79 - OIL										
79-11-00-202	NO. 1 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK								Service	ATA:79
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		(4979) 4979	5029	877.7 (+50)		2122.3	
WC#: 79.010	ENC		693						535	
				PROC. REF: AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801						PKG:8
79-11-00-202	NO. 2 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK								Service	ATA:79
	MOS		19-Mar-16					26-Sep-2025	94.7	
	HRS	3000 (+50/-50)	1979		(4979) 4979	5029	877.7 (+50)		2122.3	
WC#: 79.010	ENC		693						535	
				PROC. REF: AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801						PKG:8
79-11-00-204	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)								Service	ATA:79
	MOS/MSC	N/A	30-Jun-11						151.4	
	HRS		0						4101.3	
WC#: 79.015	ENC		0						1228	
				PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801						
79-11-00-204	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)								Service	ATA:79
	MOS/MSC	N/A	30-Jun-11						151.4	
	HRS		0						4101.3	
WC#: 79.015	ENC		0						1228	
				PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801						
79-12-01-900-801-01	OIL REPLENISHMENT TANK ASSY								Component	ATA:79
PN:GC639-0011-3	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0430	HRS		0	TSN 0					4101.3	
WC#: 79.005	AFL		0	TSN 0					1225	
				PROC. REF: AMM 79 12 01 000 801, AMM 79 12 01 400 801						
79-12-02-900-801-01	OIL REPLENISHMENT PUMP								Component	ATA:79
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
	AFL		0	TSN 0					1225	
				PROC. REF: AMM 79 12 02 000 801, AMM 79 12 02 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 79 - OIL										
79-12-04-900-801-01	SELECTOR VALVE								Component	ATA:79
PN:GC639-0012-1	MOS/MSC	O/C	18-Nov-12	TSN 1					134.8	
SN:550	HRS		714.9	TSN 0					3386.4	
WC#: 79.010	AFL		271	TSN 0					954	
				PROC. REF: AMM 79 12 04 000 801, AMM 79 12 04 400 801						
79-21-02-201 S	NO. 1 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT								Service	ATA:79
PN:PN-UNKNOWN	MOS		01-Dec-23						2.3	
SN:UNKNOWN	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 79.020	ENC		1226						2	
				PROC. REF: AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801						PKG:4
79-21-02-201 S	NO. 2 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT								Service	ATA:79
PN:PN-UNKNOWN	MOS		08-Dec-23						2.1	
SN:UNKNOWN	HRS	1000 (+50/-50)	4099.1						2.2	
WC#: 79.020	ENC		1226						2	
				PROC. REF: AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801						PKG:4
79-21-04-201	NO. 1 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR								Service	ATA:79
	MOS		01-Dec-23					19-Jan-2026	2.3	
	HRS	1000 (+50/-50)	4099.1	Adj 50	(5149.1) 5149.1	5199.1	1047.8 (+50)		2.2	
WC#: 79.025	ENC		1226						2	
				PROC. REF: AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801						PKG:4
79-21-04-201	NO. 2 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR								Service	ATA:79
	MOS		08-Dec-23					19-Jan-2026	2.1	
	HRS	1000 (+50/-50)	4099.1	Adj 50	(5149.1) 5149.1	5199.1	1047.8 (+50)		2.2	
WC#: 79.025	ENC		1226						2	
				PROC. REF: AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801						PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 79 - OIL										
79-21-04-202	NO. 1 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR								Service	ATA:79
	MOS		01-Dec-23					19-Jan-2026	2.3	
	HRS	1000 (+50/-50)	4099.1	Adj 50	(5149.1) 5149.1	5199.1	1047.8 (+50)		2.2	
WC#: 79.030	ENC		1226						2	
				PROC. REF: AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802						PKG:4
79-21-04-202	NO. 2 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR								Service	ATA:79
	MOS		08-Dec-23					19-Jan-2026	2.1	
	HRS	1000 (+50/-50)	4099.1	Adj 50	(5149.1) 5149.1	5199.1	1047.8 (+50)		2.2	
WC#: 79.030	ENC		1226						2	
				PROC. REF: AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802						PKG:4
79-21-04-203	NO. 1 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR								Service	ATA:79
	MOS		01-Dec-23					19-Jan-2026	2.3	
	HRS	1000 (+50/-50)	4099.1	Adj 50	(5149.1) 5149.1	5199.1	1047.8 (+50)		2.2	
WC#: 79.035	ENC		1226						2	
				PROC. REF: AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803						PKG:4
79-21-04-203	NO. 2 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR								Service	ATA:79
	MOS		08-Dec-23					19-Jan-2026	2.1	
	HRS	1000 (+50/-50)	4099.1	Adj 50	(5149.1) 5149.1	5199.1	1047.8 (+50)		2.2	
WC#: 79.035	ENC		1226						2	
				PROC. REF: AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803						PKG:4
79-31-02-900-801-01	OIL PROBE								Component	ATA:79
PN:PN	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:UNKNOWN	HRS		0	TSN 0					4101.3	
WC#: 79.015	AFL		0	TSN 0					1225	
				PROC. REF: AMM 79 31 02 000 801, AMM 79 31 02 400 801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 79 - OIL									
792101-001	NO. 1 ENGINE - OIL UNIT PUMP								Component ATA:79
PN:LR47000C	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:C0774	HRS		0	TSN 0					4101.3
WC#: 79.045	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-21-01, EMM 79-21-01					
792101-001	NO. 2 ENGINE - OIL UNIT PUMP								Component ATA:79
PN:LR47000C	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:C0771	HRS		0	TSN 0					4101.3
WC#: 79.045	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-21-01, EMM 79-21-01					
792102-001	NO. 1 ENGINE - PRESSURE FILTER ELEMENT								Component ATA:79
PN:PN-UNKNOWN	MOS/MSC	H/T	01-Dec-23						2.3
SN:UNKNOWN	HRS		4099.1						2.2
WC#: 79.050	ENC		1226						2
				PROC. REF: EMM 79-21-02, EMM 79-21-02					
792102-001	NO. 2 ENGINE - PRESSURE FILTER ELEMENT								Component ATA:79
PN:PN-UNKNOWN	MOS/MSC	H/T	08-Dec-23						2.1
SN:UNKNOWN	HRS		4099.1						2.2
WC#: 79.050	ENC		1226						2
				PROC. REF: EMM 79-21-02, EMM 79-21-02					
792201-001	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U3896	HRS		0	TSN 0					4101.3
WC#: 79.055	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-001	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U3879	HRS		0	TSN 0					4101.3
WC#: 79.055	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-002	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U4118	HRS		0	TSN 0					4101.3
WC#: 79.060	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 79 - OIL									
792201-002	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U3894	HRS		0	TSN 0					4101.3
WC#: 79.060	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-003	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U4122	HRS		0	TSN 0					4101.3
WC#: 79.065	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-003	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U4115	HRS		0	TSN 0					4101.3
WC#: 79.065	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-004	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	28-Dec-13						121.5
SN:V1133	HRS		1176.4	TSN 0					2924.9
WC#: 79.070	ENC		467						761
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-004	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U4325	HRS		0	TSN 0					4101.3
WC#: 79.070	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-005	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	28-Dec-13						121.5
SN:CL945	HRS		1176.4	TSN 0					2924.9
WC#: 79.075	ENC		467						761
				PROC. REF: EMM 79-32-01, EMM 79-32-01					
792201-005	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER								Component ATA:79
PN:1122806	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:U4334	HRS		0	TSN 0					4101.3
WC#: 79.075	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-32-01, EMM 79-32-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 79 - OIL									
792202-001	NO. 1 ENGINE - OIL, FUEL COOLED COOLER								Component ATA:79
PN:55007001-41	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:55007-1385	HRS		0	TSN 0					4101.3
WC#: 79.080	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-22-01, EMM 79-22-01					
792202-001	NO. 2 ENGINE - OIL, FUEL COOLED COOLER								Component ATA:79
PN:55007001-41	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:55007-1380	HRS		0	TSN 0					4101.3
WC#: 79.080	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-22-01, EMM 79-22-01					
793301-001	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001M1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2918240	HRS		0	TSN 0					4101.3
WC#: 79.085	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-33-01, EMM 79-33-01					
793301-001	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001M1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2925624	HRS		0	TSN 0					4101.3
WC#: 79.085	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-33-01, EMM 79-33-01					
793301-002	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001M1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2879058	HRS		0	TSN 0					4101.3
WC#: 79.090	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-33-01, EMM 79-33-01					
793301-002	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER								Component ATA:79
PN:PDCR300164001M1	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:2927517	HRS		0	TSN 0					4101.3
WC#: 79.090	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-33-01, EMM 79-33-01					
793401-001	NO. 1 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH								Component ATA:79
PN:21SN04-472	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:K008360	HRS		0	TSN 0					4101.3
WC#: 79.095	ENC		0	TSN 0					1228
				PROC. REF: EMM 79-34-01, EMM 79-34-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 79 - OIL										
793401-001	NO. 2 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH								Component	ATA:79
PN:21SN04-472	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:K008357	HRS		0	TSN 0					4101.3	
WC#: 79.095	ENC		0	TSN 0					1228	
				PROC. REF: EMM 79-34-01, EMM 79-34-01						
793402-001	NO. 1 ENGINE - OIL FILTER POP-UP INDICATOR								Component	ATA:79
PN:QA07508	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:RT3-5714	HRS		0	TSN 0					4101.3	
WC#: 79.100	ENC		0	TSN 0					1228	
				PROC. REF: EMM 79-34-02, EMM 79-34-02						
793402-001	NO. 2 ENGINE - OIL FILTER POP-UP INDICATOR								Component	ATA:79
PN:QA07508	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:RT3-5712	HRS		0	TSN 0					4101.3	
WC#: 79.100	ENC		0	TSN 0					1228	
				PROC. REF: EMM 79-34-02, EMM 79-34-02						
FAA 2001-01-01	NO. 1 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - REPLACE								AD	ATA:79
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
FAA 2001-01-01	NO. 2 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - REPLACE								AD	ATA:79
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
SB 700-79-005	MODIFICATION - OIL REPLENISHMENT SYSTEM - POWER SOURCE CHANGE TO BATTERY POWER ON AIRCRAFT POST BUILD 4, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	N/A								
	HRS									
	AFL									
SB 700-79-005 REV 01	MODIFICATION - OIL REPLENISHMENT SYSTEM - POWER SOURCE CHANGE TO BATTERY POWER ON AIRCRAFT POST BUILD 4, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	N/A								
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 79 - OIL									
SB BR700-79-100323 R01	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-79-100323 R01	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-	EFF						
	HRS								
	ENC								
SB BR700-79-101739	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101739	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101744	NO. 1 ENGINE - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101744	NO. 2 ENGINE - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101744 R01	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 79 - OIL									
SB BR700-79-101744 R01	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101803	NO. 1 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101803	NO. 2 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101803 R01	NO. 1 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101803 R01	NO. 2 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101885	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-101885	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 79 - OIL										
SB BR700-79-101885 R01	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-79-101885 R01	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-79-900215 R02	NO. 1 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-	09-Dec-09						170.1	
	HRS									
	ENC									
SB BR700-79-900215 R02	NO. 2 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-	09-Dec-09						170.1	
	HRS		0						4101.3	
	ENC		0						1228	
SB BR700-79-900448	NO. 1 ENGINE - OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-	EFF							
	HRS									
	ENC									
SB BR700-79-900448	NO. 2 ENGINE - OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-	EFF							
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 79 - OIL									
SB BR700-79-900448 PART A	NO. 1 ENGINE - INTRODUCTION OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN OF A REVISED FRONT BEARING CHAMBER (FBC) MAGNETIC CHIP DETECTOR (MCD) INSPECTION INTERVAL FOR ALL POTENTIALLY AFFECTED ENGINES								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-900448 PART A	NO. 2 ENGINE - INTRODUCTION OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN OF A REVISED FRONT BEARING CHAMBER (FBC) MAGNETIC CHIP DETECTOR (MCD) INSPECTION INTERVAL FOR ALL POTENTIALLY AFFECTED ENGINES								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-900448 PART B	NO. 1 ENGINE - INSTRUCTIONS OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN FOR THE REMOVAL OF POTENTIALLY AFFECTED HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES FROM SERVICE								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-900448 PART B	NO. 2 ENGINE - INSTRUCTIONS OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN FOR THE REMOVAL OF POTENTIALLY AFFECTED HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES FROM SERVICE								Bulletin ATA:79
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-79-900541	NO. 1 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-	04-Nov-11						147.2
	HRS		227.8						3873.5
	ENC		103						1125
SB BR700-79-900541	NO. 2 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN								Bulletin ATA:79
	MOS/MSC	-	04-Nov-11						147.2
	HRS		227.8						3873.5
	ENC		103						1125

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 79 - OIL										
SB BR700-79-900541 R01	NO. 1 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	T:A/R								
	HRS									
	ENC									
SB BR700-79-900541 R01	NO. 2 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	T:A/R								
	HRS									
	ENC									
SB BR700-79-900541 R02	NO. 1 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-79-900541 R02	NO. 2 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC	-								
	HRS									
	ENC									
ATA 80 - STARTING										
80-11-01-203[S]	NO. 1 ENGINE - DISCARD THE AIR TURBINE STARTER OIL								Service	ATA:80
	MOS		06-Dec-23						2.2	
	HRS	500 (+50/-50)	4099.1						2.2	
WC#: 80.030	ENC		1226						2	
				PROC. REF: AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801						PKG:2
80-11-01-203[S]	NO. 2 ENGINE - DISCARD THE AIR TURBINE STARTER OIL								Service	ATA:80
	MOS		06-Dec-23						2.2	
	HRS	500 (+50/-50)	4099.1						2.2	
WC#: 80.030	ENC		1226						2	
				PROC. REF: AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801, AMM 80 11 01 961 801						PKG:2
801101-001	NO. 1 ENGINE - AIR TURBINE STARTER ASSY								Component	ATA:80
PN:3505934-8	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7	
SN:0109-2285	HRS		0	TSN 0					4101.3	
WC#: 80.015	ENC		0	TSN 0					1228	
				PROC. REF: EMM 80-11-01, EMM 80-11-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 80 - STARTING									
801101-001	NO. 2 ENGINE - AIR TURBINE STARTER ASSY								Component ATA:80
PN:3505934-13	MOS/MSC	O/C	17-Jul-19	TSR 4					54.8
SN:0910-2590	HRS		3188.8	TSN 4255.9, TSR 0					912.5
WC#: 80.015	ENC		999	TSN 1227, TSR 0					229
				PROC. REF: EMM 80-11-01, EMM 80-11-01					
801102-001	NO. 1 ENGINE - AIR STARTER VALVE								Component ATA:80
PN:3291182-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1108-2395	HRS		0	TSN 0					4101.3
WC#: 80.020	ENC		0	TSN 0					1228
				PROC. REF: EMM 80-11-03, EMM 80-11-03					
801102-001	NO. 2 ENGINE - AIR STARTER VALVE								Component ATA:80
PN:3291182-4	MOS/MSC	O/C	20-Dec-09	TSN 0					169.7
SN:1108-2396	HRS		0	TSN 0					4101.3
WC#: 80.020	ENC		0	TSN 0					1228
				PROC. REF: EMM 80-11-03, EMM 80-11-03					
SB BR700-80-101729	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101729	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101741	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101741	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 80 - STARTING									
SB BR700-80-101795	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF AN ALTERNATIVE SEAL RING FOR THESTARTER OUTPUT SHAFT, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101795	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF AN ALTERNATIVE SEAL RING FOR THESTARTER OUTPUT SHAFT, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900 PART 1	NO. 1 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REPLACEMENT OF THE OLD AIR TURBINE STARTER (P/N 3505934-12) WITH A NEW PRODUCTION STANDARD AIR TURBINE STARTER (P/N 3505934-14) AND REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-12) TO THE NEW STANDARD (P/N 3505934-14) WHICH HAVE THE SERVICE BULLETIN SB-BR700-80-101741 STANDARD INCORPORATED.								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900 PART 1	NO. 2 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REPLACEMENT OF THE OLD AIR TURBINE STARTER (P/N 3505934-12) WITH A NEW PRODUCTION STANDARD AIR TURBINE STARTER (P/N 3505934-14) AND REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-12) TO THE NEW STANDARD (P/N 3505934-14) WHICH HAVE THE SERVICE BULLETIN SB-BR700-80-101741 STANDARD INCORPORATED.								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 80 - STARTING									
SB BR700-80-101900 PART 2	NO. 1 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-11) TO THE NEW STANDARD (P/N 3505934-13) WHICH HAVE THE SERVICE BULLETIN SB-BR700-80-101729 STANDARD INCORPORATED								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900 PART 2	NO. 2 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-11) TO THE NEW STANDARD (P/N 3505934-13) WHICH HAVE THE SERVICE BULLETIN SB-BR700-80-101729 STANDARD INCORPORATED								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900 R01	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900 R01	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900 R01 PART 1	NO. 1 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REPLACEMENT OF THE OLD AIR TURBINE STARTER (P/N 3505934-12) WITH A NEW PRODUCTION STANDARD AIR TURBINE STARTER (P/N 3505934-14) AND REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-12) TO THE NEW STANDARD (P/N 3505934-14) WHICH HAVE THE SB SB-BR700-80-101741 STANDARD INCORPORATED								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								
SB BR700-80-101900 R01 PART 1	NO. 2 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REPLACEMENT OF THE OLD AIR TURBINE STARTER (P/N 3505934-12) WITH A NEW PRODUCTION STANDARD AIR TURBINE STARTER (P/N 3505934-14) AND REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-12) TO THE NEW STANDARD (P/N 3505934-14) WHICH HAVE THE SB SB-BR700-80-101741 STANDARD INCORPORATED								Bulletin ATA:80
	MOS/MSC	-							
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 80 - STARTING										
SB BR700-80-101900 R01 PART 2	NO. 1 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-11) TO THE NEW STANDARD (P/N 3505934-13) WHICH HAVE THE SB SB-BR700-80-101729 STANDARD INCORPORATED								Bulletin	ATA:80
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-80-101900 R01 PART 2	NO. 2 ENGINE - ACCOMPLISH STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-11) TO THE NEW STANDARD (P/N 3505934-13) WHICH HAVE THE SB SB-BR700-80-101729 STANDARD INCORPORATED								Bulletin	ATA:80
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-80-900340	NO. 1 ENGINE - INSPECTION OF THE AIR TURBINE STARTER OIL LEVEL, SERVICE BULLETIN								Bulletin	ATA:80
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-80-900340	NO. 2 ENGINE - INSPECTION OF THE AIR TURBINE STARTER OIL LEVEL, SERVICE BULLETIN								Bulletin	ATA:80
	MOS/MSC	-								
	HRS									
	ENC									
SB BR700-80-900340 R01	NO. 1 ENGINE - INSPECTION OF THE AIR TURBINE STARTER OIL LEVEL, SERVICE BULLETIN								Bulletin	ATA:80
	MOS/MSC	-	10-Aug-11						150	
	HRS									
	ENC									
SB BR700-80-900340 R01	NO. 2 ENGINE - INSPECTION OF THE AIR TURBINE STARTER OIL LEVEL, SERVICE BULLETIN								Bulletin	ATA:80
	MOS/MSC	-	10-Aug-11						150	
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued	
ATA 83 - ACCESSORY GEAR-BOXES										
FAA 2022-26-02	NO. 1 ENGINE - ACCESSORY GEARBOXES - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT								AD	ATA:83
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									
FAA 2022-26-02	NO. 2 ENGINE - ACCESSORY GEARBOXES - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT								AD	ATA:83
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									
FAA 2022-26-02 PARA (C[S]) EASA (1.1)	NO. 1 ENGINE - REPLACE EACH COMPONENT BEFORE EXCEEDING THE APPLICABLE LIFE LIMIT OR BEFORE EXCEEDING THE APPLICABLE THRESHOLD, OR WITHIN THE SPECIAL COMPLIANCE TIMES SPECIFIED IN TABLE 1 OF THIS AD								AD	ATA:83
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									
FAA 2022-26-02 PARA (C[S]) EASA (1.1)	NO. 2 ENGINE - REPLACE EACH COMPONENT BEFORE EXCEEDING THE APPLICABLE LIFE LIMIT OR BEFORE EXCEEDING THE APPLICABLE THRESHOLD, OR WITHIN THE SPECIAL COMPLIANCE TIMES SPECIFIED IN TABLE 1 OF THIS AD								AD	ATA:83
	MOS/MSC	-	11-Jan-23						13	
	HRS		3915.7						185.6	
	ENC									
FAA 2022-26-02 PARA (G) EASA (3)	NO. 1 ENGINE - INCORPORATING THE ACTIONS AND ASSOCIATED THRESHOLDS AND INTERVALS, INCLUDING LIFE LIMITS AND MAINTENANCE TASKS, INTO THE EXISTING APPROVED MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE								AD	ATA:83
	DAYS/MSC	-	11-Jan-23						396 d	
	HRS		3915.7						185.6	
	ENC									
FAA 2022-26-02 PARA (G) EASA (3)	NO. 2 ENGINE - INCORPORATING THE ACTIONS AND ASSOCIATED THRESHOLDS AND INTERVALS, INCLUDING LIFE LIMITS AND MAINTENANCE TASKS, INTO THE EXISTING APPROVED MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE								AD	ATA:83
	DAYS/MSC	-	11-Jan-23						396 d	
	HRS		3915.7						185.6	
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

Status Report

Model: GLOBAL EXPRESS XRS Serial: 9375 RegNo: N416BD HRS: 4101.3 AFL: 1225 As Of: 02-Feb-2024

11-Feb-2024 02:17 PM

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Est. Due	Time Accrued
ATA 95 - UNKNOWN									
95-00-CUS-701[U]	REREGISTRATION OF AIRCRAFT								Service ATA:95
	MOS	36	28-Jul-23		31-Jul-26		901 d	31-Jul-2026	6.5
	HRS		4002.9						98.4
	AFL		1192						33
95-00-CUS-702[U]	RESEARCH AD								Service ATA:95
	DAYS	90	10-Dec-23		09-Mar-24		27 d	09-Mar-2024	63 d
	HRS		4099.1						2.2
	AFL		1223						2
95-00-CUS-703[U]	RENEWAL CUSTOMS DECAL								Service ATA:95
	MOS	12	11-Dec-23		31-Dec-24		324 d	31-Dec-2024	2
	HRS		4099.1						2.2
	AFL		1223						2
95-00-CUS-704[U]	RENEWAL FCC RADIO LICENSE								Service ATA:95
	MOS	120	09-Apr-21		30-Apr-31		2635 d	30-Apr-2031	34.1
	HRS		3504.8						596.5
	AFL		1076						149

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS